Clinton Municipal Airport

PAVEMENT MANAGEMENT REPORT



PREPARED BY

Applied Pavement Technology, Inc. 115 West Main Street, Suite 400 Urbana, Illinois 61801 (217) 398-3977 www.appliedpavement.com

JULY 2022





The preparation of this document was financed in part through an Airport Improvement Program grant from the Federal Aviation Administration (Project Number 3-19-0000-028-2021) as provided under Section 505 of the Airport and Airway Improvement Act of 1982, as amended. The contents do not necessarily reflect the DOT's official views or the policy of the FAA. Acceptance of this report by the FAA does not in any way constitute a commitment on the part of the United States to participate in any development depicted therein nor does it indicate the proposed development is environmentally acceptable in accordance with appropriate public laws.

CLINTON MUNICIPAL AIRPORT PAVEMENT MANAGEMENT REPORT

Prepared For:



Iowa Department of Transportation Modal Transportation Bureau – Aviation 800 Lincoln Way Ames, Iowa 50010 515-239-1691 https://iowadot.gov/aviation/

Prepared By:



Applied Pavement Technology, Inc. 115 West Main Street, Suite 400 Urbana, Illinois 61801 217-398-3977 https://www.appliedpavement.com

In Association With:



Robinson Engineering Company Consulting Engineers 819 Second Street NE Independence, Iowa 50644 319-334-7211

TABLE OF CONTENTS

INTRODUCTION
PAVEMENT INVENTORY
PAVEMENT EVALUATION
Pavement Evaluation Procedure
Pavement Evaluation Results7
Inspection Comments
Runways13
Taxiways13
Aprons14
T-Hangar14
PAVEMENT MAINTENANCE AND REHABILITATION PROGRAM15
Analysis Parameters
Critical PCIs15
Localized Preventive Maintenance Policies and Unit Costs
Major Rehabilitation Unit Costs
Budget and Inflation Rate
Analysis Approach15
Analysis Results
General Maintenance Recommendations17
FAA Requirements (Public Law 103-305)17
FAA Advisory Circular 150/5830-7B, Appendix A. Pavement Management Program (PMP)
SUMMARY

LIST OF FIGURES

Figure 1. Pavement condition versus cost of repair	1
Figure 2. Pavement area by branch use at Clinton Municipal Airport	
Figure 3. Clinton Municipal Airport network definition map.	
Figure 4. Visual representation of PCI scale on typical pavement surfaces	6
Figure 5. PCI versus repair type.	
Figure 6. Pavement area by PCI range at Clinton Municipal Airport.	
Figure 7. Area-weighted PCI by branch use at Clinton Municipal Airport	
Figure 8. Clinton Municipal Airport PCI map	

LIST OF TABLES

Table 1. 2021 pavement evaluation results	10
Table 2. 5-year M&R program under an unlimited funding analysis scenario	16
Table 3. Pavement inspection report	20

APPENDIXES

Appendix A. Cause of Distress Tables	A-1
Appendix B. Inspection Photographs	B-1
Appendix C. Inspection Report	
Appendix D. Work History Report	
Appendix E. Localized Preventive Maintenance Policies and Unit Cost Tables	
Appendix F. Year 2022 Localized Preventive Maintenance Details	

INTRODUCTION

Applied Pavement Technology, Inc. (APTech), with assistance from Robinson Engineering Company, updated the Airport Pavement Management System (APMS) for the Iowa Department of Transportation, Modal Transportation Bureau – Aviation (Iowa DOT). The APMS provides a means to monitor the condition of the pavements within the state of Iowa and to proactively plan for their preservation.

As part of this project, pavement conditions at Clinton Municipal Airport were assessed in November 2021 using the Pavement Condition Index (PCI) procedure. During a PCI inspection, the types, severities, and amounts of distress present in a pavement are quantified. This information is then used to develop a composite index that represents the overall condition of the pavement in numerical terms, ranging from 0 (failed) to 100 (excellent). The PCI provides an overall measure of condition and an indication of the level of work that will be required to maintain or repair a pavement. The distress information also provides insight into what is causing the pavement to deteriorate, which is the first step in selecting the appropriate repair action to correct the problem.

Programmed into an APMS, PCI information is used to determine when preventive maintenance actions (such as crack or joint sealing) are advisable and to identify the most cost-effective time to perform major rehabilitation (such as an overlay or whitetopping). Delaying maintenance and rehabilitation (M&R) until a pavement structure has seriously degraded can cost many times more than if M&R was applied earlier in a pavement's life cycle, as shown in Figure 1. From a safety perspective, pavement distresses, such as cracks and loose debris, may pose risks in terms of the potential for aircraft tire damage and the ability of a pilot to safely control aircraft.




Figure 1. Pavement condition versus cost of repair.

The pavement evaluation results for Clinton Municipal Airport are presented within this report and can be used by Clinton Municipal Airport, the Iowa DOT, and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement M&R actions at the airport. In addition to this report, the interactive pavement management data visualization tool IDEA, containing the pavement management information collected during this project, was updated and may be accessed from the Iowa DOT's website (<u>https://iowadot.gov/aviation</u>).

PAVEMENT INVENTORY

The project began with a review of the existing inventory information pertaining to the pavements at Clinton Municipal Airport. The date of original construction, along with the date of any subsequent rehabilitation; the location of completed work; and the type of work undertaken were gathered. The information was used to update the pavement management database and associated maps as necessary to account for pavement-related work that had been undertaken since the last time the airport was evaluated in 2018.

The pavement network at Clinton Municipal Airport was then divided into branches, sections, and sample units. A branch is a single entity that serves a distinct function. For example, a runway is considered a branch because it serves a single function (allowing aircraft to take off and land). Taxiways, aprons, and T-hangars are also separate branches.

Each branch was further divided into sections. Traditionally, sections are defined as parts of the branch that share common attributes, such as cross-section, date of last construction, traffic level, and performance. Using this approach, if a runway was built in 1968 and then extended in 1984, it would contain two separate sections.

To estimate the overall condition of a pavement section, each section was subdivided into sample units. Portions of these sample units were evaluated during the pavement inspection, and the collected information was extrapolated to predict the overall section condition and quantities of distress.

Approximately 1,348,100 square feet of pavement were evaluated at Clinton Municipal Airport, as illustrated in Figure 2. This figure also shows the area-weighted age, in years, of the pavements at the time of the inspection. Figure 3 provides a map that details how the pavement network was divided into management units and identifies the sample units that were evaluated during the pavement inspection at Clinton Municipal Airport.





Figure 2. Pavement area by branch use at Clinton Municipal Airport.



PAVEMENT EVALUATION

Pavement Evaluation Procedure

APTech inspected the pavements at Clinton Municipal Airport using the PCI procedure described in:

- FAA Advisory Circular 150/5380-6C, *Guidelines and Procedures for Maintenance of Airport Pavements* (<u>https://www.faa.gov/documentLibrary/media/Advisory_Circular/150-5380-6C.pdf</u>).
- FAA Advisory Circular 150/5380-7B, *Airport Pavement Management Program (PMP)* (https://www.faa.gov/documentLibrary/media/Advisory_Circular/150-5380-7B.pdf).
- ASTM D5340-20, Standard Test Method for Airport Pavement Condition Index Surveys.

The PCI provides a numerical indication of overall pavement condition, as illustrated in Figure 4. The types and amounts of deterioration are used to calculate the PCI of the section. The PCI ranges from a value of 0, which represents a pavement in a failed condition, to a value of 100, which represents a pavement in excellent condition. It is important to note that factors other than overall PCI need to be considered when identifying the appropriate type of repair, including types of distress present and rate of deterioration. Also, since the PCI does not assess the structural integrity or capacity of the pavement structure, further testing may be needed to validate and refine the treatment strategy.

Figure 4. Visual representation of PCI scale on typical pavement surfaces¹.



¹Photographs shown are not specific to Clinton Municipal Airport.

Generally, pavements with relatively high PCIs that are not exhibiting significant load-related distress will benefit from preventive maintenance actions, such as crack sealing or joint resealing. As the PCI drops, the pavements may require major rehabilitation, such as an overlay or whitetopping. In some situations where the PCI has dropped low enough, reconstruction may be the only viable alternative due to the substantial damage to the pavement structure. Figure 5 illustrates how the appropriate repair type varies with the PCI of a pavement section and provides the corresponding colors used for the maps and charts in this report for each range of PCIs.

PCI Range	Repair		
86-100			
71-85	Preventive Maintenance		
56-70			
41-55	Major Rehabilitation		
26-40			
11-25	Reconstruction		
0-10			

Figure 5. PCI versus repair type.

The types of distress identified during the PCI inspection provide insight into the cause of pavement deterioration, which in turn helps in selecting a rehabilitation alternative that corrects the cause, thus eliminating or delaying its recurrence. PCI distress types are characterized as load-related (such as alligator cracking on asphalt-surfaced pavements or shattered slabs on portland cement concrete [PCC] pavements), climate/durability-related (such as weathering [a climate-related distress type on asphalt-surfaced pavements] and durability cracking [a durability-related distress type on PCC pavements]), and other (distress types that cannot be attributed solely to load or climate/durability).

Appendix A identifies the distress types considered during a PCI inspection and describes the likely cause of each distress type. It should be noted that a PCI is based on visual signs of pavement deterioration and does not provide a measure of structural capacity.

Pavement Evaluation Results

The pavements at Clinton Municipal Airport were inspected in November 2021. The 2021 areaweighted condition of Clinton Municipal Airport is 86, with conditions ranging from 44 to 100 (on a scale of 0 [failed] to 100 [excellent]). During the previous pavement inspection in 2018, the area-weighted PCI of the airport was 87.

Figure 6 summarizes the overall condition of the pavements at Clinton Municipal Airport, and Figure 7 presents area-weighted condition (average PCI adjusted to account for the relative size of the pavement sections) by branch use. Figure 8 is a map that displays the condition of the evaluated pavements. Table 1 summarizes the results of the pavement evaluation. Appendix B presents photographs taken during the PCI inspection, and Appendix C contains detailed information on the distress types observed during the visual survey. Appendix D includes detailed work history information that was collected during the record review process.






Figure 6. Pavement area by PCI range at Clinton Municipal Airport.

Figure 7. Area-weighted PCI by branch use at Clinton Municipal Airport. (Values on chart are area-weighted)







		T03CN-04	4 (93)	21			
·		oplied pav	ement	115 W. Main Street, Suite 400 Urbana, IL 61801			
	Robin	CHNOLOGY son Engineeri Company ^{Consulting Engineers}		Tel: (217) 398-3977 Fax: (217) 398-4027 322 1st Street East Independence, IA 50644 Tel: (319) 334-7211			
CONDITION INDEX <u>PCI</u> 86-100 71-85	AGENCY: Iowa Department of Transportation Modal Transportation Bureau - Aviation LOCATION: Clinton Municipal Airport Clinton, Iowa						
56-70 41-55 26-40 11-25 0-10	PAGE TITLE: 202* PROJECT DATE: SEP. 2021 DRAWING SCALE: 1"=400' FILENAME: Clinto	CREATION DATE: SEP. 2021 LAST MODIFIED DATE: APR. 2022		Map JOB NUMBER: 17-020-AM05 DRAWN BY: DSP PAGE NUMBER: 9			

	Table 1. 2021 pavement evaluation results.									
Branch	Section	Surface Type	Section Area (sf)	LCD	2021 PCI	% Distress Due to Load	% Distress Due to Climate/ Durability	% Distress Due to Other	Type of Distress	
A01CN	01	PCC	22,346	6/1/1984	51	25	18	57	ASR, Corner Break, Joint Seal Damage, LTD Cracking, Shattered Slab, Small Patch	
A01CN	02	PCC	9,991	6/3/2014	89	40	60	0	Corner Break, Joint Seal Damage, LTD Cracking	
A01CN	03	AC	18,992	1/1/1995	9	42	58	0	Alligator Cracking, Block Cracking, L&T Cracking, Patching, Raveling, Weathering	
A01CN	04	PCC	8,100	4/1/2016	95	100	0	0	LTD Cracking	
A02CN	01	PCC	18,725	6/1/1981	47	58	15	27	ASR, Corner Break, Corner Spalling, Joint Spalling, Joint Seal Damage, Large Patch, LTD Cracking, Shattered Slab	
A02CN	02	PCC	33,191	5/2/2020	100	0	0	0	No Distresses	
A02CN	03	PCC	18,060	6/1/1984	23	15	9	76	ASR, Joint Seal Damage, LTD Cracking	
R03CN	01	PCC	494,870	4/2/2010	96	61	26	13	Corner Spalling, Joint Seal Damage, LTD Cracking, Scaling, Shattered Slab, Small Patch	
R03CN	02	PCC	25,000	4/2/2010	91	11	75	14	Corner Spalling, Joint Seal Damage, LTD Cracking	
R14CN	01	PCC	319,015	4/2/2010	84	23	56	21	Corner Break, Corner Spalling, Faulting, Joint Spalling, Joint Seal Damage, LTD Cracking, Small Patch	
T01CN	01	PCC	30,107	3/31/2018	100	0	0	0	No Distresses	
T01CN	02	PCC	3,450	4/2/2010	85	23	47	30	Corner Break, Corner Spalling, Joint Seal Damage, Small Patch	
T01CN	03	PCC	11,010	7/31/2018	96	100	0	0	LTD Cracking	

10

	ruble 1. 2021 pavement evaluation results (continued).										
Branch	Section	Surface Type	Section Area (sf)	LCD	2021 PCI	% Distress Due to Load	% Distress Due to Climate/ Durability	% Distress Due to Other	Type of Distress		
T02CN	01	PCC	13,644	4/2/2010	91	0	75	25	Faulting, Joint Spalling, Joint Seal Damage		
T03CN	01	PCC	30,263	8/3/2011	96	0	78	22	Corner Spalling, Faulting, Joint Seal Damage		
T03CN	02	PCC	17,928	6/3/2003	93	0	69	31	Corner Spalling, Faulting, Joint Spalling, Joint Seal Damage, Small Patch		
T03CN	03	PCC	142,497	6/3/2003	95	8	67	25	Faulting, Joint Spalling, Joint Seal Damage, LTD Cracking		
T03CN	04	PCC	8,958	6/3/2011	93	76	24	0	Corner Break, Joint Seal Damage, LTD Cracking		
T04CN	01	AAC	29,958	6/1/2002	21	33	67	0	Alligator Cracking, Block Cracking, L&T Cracking, Raveling, Weathering		
T04CN	02	PCC	3,600	1/3/2002	41	84	16	0	Joint Seal Damage, LTD Cracking		
T05CN	01	PCC	12,269	6/1/2003	90	31	63	6	Corner Break, Joint Spalling, Joint Seal Damage, LTD Cracking		
T05CN	02	PCC	4,708	6/2/2011	98	0	100	0	Joint Seal Damage		
T06CN	01	PCC	6,747	6/3/2003	89	21	17	62	ASR, Corner Break, Faulting, Joint Spalling, Joint Seal Damage, LTD Cracking		
T06CN	02	PCC	8,296	6/3/2011	98	0	83	17	Joint Spalling, Joint Seal Damage		
T07CN	01	PCC	13,646	4/2/2010	89	0	56	44	Faulting, Joint Seal Damage		
TH01CN	01	PCC	21,168	1/3/2002	44	74	21	5	Corner Break, Joint Seal Damage, LTD Cracking, Scaling, Shattered Slab		
TH01CN	02	PCC	4,550	1/1/2004	69	82	18	0	Corner Break, Joint Seal Damage, LTD Cracking, Shattered Slab		
TH01CN	03	AAC	17,012	1/1/2005	42	44	56	0	Alligator Cracking, L&T Cracking, Raveling, Weathering		

July 2022

11

Table 1. 2021 pavement evaluation results (continued).

Table Notes:

- 1. See Figure 3 for the location of the branch and section.
- 2. Surface Type: AC = asphalt cement concrete; AAC = asphalt overlay on AC; PCC = portland cement concrete; APC = asphalt overlay on PCC.
- 3. LCD = last construction date.
- 4. Distress due to load includes distress types that are attributed to a structural deficiency in the pavement, such as alligator cracking or rutting on asphaltsurfaced pavements or shattered slabs on PCC pavements.
- 5. Distress due to climate or durability includes distress types that are attributed to either the aging of the pavement and the effects of the environment (such as weathering, raveling, or block cracking on asphalt-surfaced pavements) or to a materials-related problem (such as durability cracking or alkali-silica reaction [ASR] on PCC pavements). If materials-related distresses were recorded during the inspection, further laboratory testing is required to definitively determine the type present.
- 6. Distress due to other refers to distress types that are not attributed to one factor but rather may be caused by a combination of factors.
- 7. Distress types are defined by ASTM D5340-20. L&T Cracking = Longitudinal and Transverse Cracking; LTD Cracking = Longitudinal, Transverse, and Diagonal Cracking; ASR = Alkali-Silica Reaction.

Inspection Comments

Clinton Municipal Airport was inspected on November 17-18, 2021. There were twenty-eight pavement sections defined during the inspection. Suspected alkali-silica reaction (ASR) was recorded at this airport in accordance with ASTM D5340-20. It should be noted that laboratory testing in the form of petrographic analysis is the only definitive way to validate the presence of ASR; however, the formation of a precipitate is evidence of a reaction consistent with this type of materials-related distress.

Runways

Runway 03/21 consisted of two sections. Areas of medium-severity longitudinal, transverse, and diagonal (LTD) cracking and low-severity corner spalling, joint seal damage, and shattered slab were observed in Section 01. An atypical area of low-severity scaling and small patching was identified and recorded as an additional sample unit, according to ASTM D5340-20. Section 02 contained low- and medium-severity corner spalling, medium-severity joint seal damage, and low-severity LTD cracking.

Runway 14/32 was defined by one section. Section 01 had areas of medium-severity corner break and joint spalling, low- and medium-severity corner spalling and LTD cracking, low-severity faulting and small patching, and all severities of joint seal damage observed during the inspection.

Taxiways

Taxiway 01 connected Runway 14/32 to the apron areas and consisted of three sections. Section 01 was in excellent condition with no distress noted at the time of inspection. Areas of low-severity corner break and corner spalling and medium-severity joint seal damage and small patching were observed in Section 02. Section 03 was in excellent condition with only medium-severity LTD cracking recorded.

Taxiway 02, the turnaround located at the Runway 14 approach, contained one section. Lowseverity faulting, low- and medium-severity joint seal damage, and medium-severity joint spalling were identified in Section 01.

Taxiway 03, the parallel taxiway for Runway 03/21, was defined by four sections. Section 01 contained low-severity faulting and low- and medium-severity joint seal damage and corner spalling. Low-severity corner spalling, faulting, and joint spalling; low- and medium-severity joint seal damage; and medium-severity small patching were recorded in Section 02. Section 03 had areas of low-severity faulting, low- and medium-severity joint seal damage, and medium-severity joint spalling noted. An area of low-severity LTD cracking was identified and recorded as an additional sample unit, according to ASTM D5340-20. Areas of medium-severity corner break, low-severity joint seal damage, and low- and medium-severity LTD cracking were observed in Section 04.

Taxiway 04 connected the T-Hangar area to Apron 01 and consisted of two sections. Section 01 was in poor condition with medium-severity alligator cracking and block cracking, low- and medium-severity longitudinal and transverse (L&T) cracking and weathering, and medium- and high-severity raveling recorded throughout. The low-severity cracking was unsealed, while the medium-severity cracking was noted where either crack sealant was unsatisfactory or unsealed crack widths exceeded ¹/₄ in. Section 02 contained high-severity joint seal damage and low- and medium-severity LTD cracking.

Taxiway 05 connected Runway 03/21 to Taxiway 03 and was defined by two sections. Areas of low-severity corner break and joint spalling and medium-severity joint seal damage and LTD cracking were observed in Section 01. Section 02 was in excellent condition with only low-severity joint seal damage noted throughout.

Taxiway 06 connected Runway 03/21 to Taxiway 03 and consisted of two sections. Section 01 had areas of medium-severity joint spalling and low-severity ASR, corner break, faulting, joint seal damage, and LTD cracking. Section 02 was in excellent condition with low-severity joint seal damage and joint spalling identified during the inspection.

Taxiway 07, the turnaround located at the Runway 14 approach, contained one section. Low-severity faulting and medium-severity joint seal damage were recorded in Section 01.

Aprons

Apron 01 consisted of four sections. Section 01 contained all severities of ASR; low- and medium-severity corner break; medium- and high-severity joint seal damage; and medium-severity LTD cracking, shattered slab, and small patching. Section 02 had areas of low-severity corner break, medium-severity joint seal damage, and low-severity LTD cracking. Section 03 was in poor condition with medium-severity alligator cracking, block cracking, and L&T cracking; low-severity patching; high-severity raveling; and low- and medium-severity weathering noted throughout. The medium-severity cracking was recorded where unsealed crack widths were greater than ¹/₄ in. Low-severity LTD cracking was observed in Section 04.

Apron 02 was defined by three sections. All severities of ASR; medium-severity corner break, corner spalling, joint spalling, and LTD cracking; high-severity joint seal damage; low-severity large patching; and low- and medium-severity shattered slab were recorded in Section 01. Section 02 was in excellent condition with no distress noted at the time of inspection. Section 03 was in poor condition with all severities of ASR, high-severity joint seal damage, and medium-severity LTD cracking observed at the time of inspection.

T-Hangar

The T-hangar area was divided into three sections. Section 01 contained medium-severity corner break, medium- and high-severity joint seal damage, low- and medium-severity LTD cracking and shattered slab, and high-severity scaling. Medium-severity joint seal damage and low-severity corner break, LTD cracking, and shattered slab were observed in Section 02. Section 03 had areas of all severities of alligator cracking and L&T cracking, medium- and high-severity raveling, and medium-severity weathering.

PAVEMENT MAINTENANCE AND REHABILITATION PROGRAM

Using the information collected during the pavement inspection, the PAVER pavement management software was used to develop a 5-year M&R program for Clinton Municipal Airport. In addition, a 1-year plan for localized preventive maintenance (such as crack sealing and patching) was prepared.

Analysis Parameters

Critical PCIs

PAVER uses critical PCIs to determine whether localized preventive maintenance or major rehabilitation is the appropriate repair action. Above the critical PCI, localized preventive maintenance activities are recommended. Below the critical PCI, major rehabilitation actions, such as an overlay or reconstruction, are recommended. The Iowa DOT set the critical PCIs at 65 for runways, 60 for taxiways, and 55 for aprons and T-hangars.

Localized Preventive Maintenance Policies and Unit Costs

Localized preventive maintenance policies were developed for asphalt-surfaced and PCC pavements. These policies, shown in Appendix E, identify the localized preventive maintenance actions that the Iowa DOT considered appropriate to correct for the different distress types and severities. The Iowa DOT provided unit costs for each of the localized preventive maintenance actions included in these policies, and these costs are detailed in Appendix E. Please note that this information is of a general nature for the entire state. The localized preventive maintenance policies and unit costs may require adjustment to reflect specific conditions at Clinton Municipal Airport.

Major Rehabilitation Unit Costs

PAVER estimates the cost of major rehabilitation based on the predicted PCI of the pavement section. The Iowa DOT provided the costs for major rehabilitation, and they are presented in Appendix E. If major rehabilitation is recommended in the 5-year program, further engineering investigation will be needed to identify the most appropriate rehabilitation action and to estimate the cost of such work more accurately.

Budget and Inflation Rate

An unlimited budget with a start date of July 1, 2022 and an inflation rate of 4.0 percent was used during the analysis.

Analysis Approach

The 5-year M&R program was prepared with the goal of maintaining the pavements above established critical PCIs. During this analysis, major rehabilitation was recommended for pavements in the year they dropped below their critical PCI. For the first year (2022) of the analysis only, a localized preventive maintenance plan was developed for those pavement sections that were above their critical PCI. If major rehabilitation was triggered for a section in 2023 or 2024, then localized preventive maintenance was not recommended for 2022. While localized preventive maintenance should be an annual undertaking at Clinton Municipal Airport, it is not possible to accurately predict the propagation of cracking and other distress types. Therefore, the airport should budget for maintenance every year and can use the 2022 localized

preventive maintenance plan as a baseline for that work. As the pavements age, it can be assumed that the amount of localized preventive maintenance required will increase.

Analysis Results

A summary of the M&R program for Clinton Municipal Airport is presented in Table 2. Detailed information on the recommended localized preventive maintenance plan for 2022 is provided in Appendix F.

Year	Branch	Section	Surface Type	Type of Repair	Estimated Cost
2022	A01CN	01	PCC	Major Rehabilitation	\$183,727
2022	A01CN	02	PCC	Preventive Maintenance	\$5,049
2022	A01CN	03	AC	Major Rehabilitation	\$197,791
2022	A02CN	01	PCC	Major Rehabilitation	\$216,562
2022	A02CN	03	PCC	Major Rehabilitation	\$313,922
2022	R03CN	01	PCC	Preventive Maintenance	\$1,856
2022	R03CN	02	PCC	Preventive Maintenance	\$11,185
2022	R14CN	01	PCC	Preventive Maintenance	\$118,831
2022	T01CN	02	PCC	Preventive Maintenance	\$1,436
2022	T01CN	03	PCC	Preventive Maintenance	\$85
2022	T02CN	01	PCC	Preventive Maintenance	\$6,983
2022	T03CN	01	PCC	Preventive Maintenance	\$2,733
2022	T03CN	02	PCC	Preventive Maintenance	\$3,461
2022	T03CN	03	PCC	Preventive Maintenance	\$8,811
2022	T03CN	04	PCC	Preventive Maintenance	\$692
2022	T04CN	01	AAC	Major Rehabilitation	\$311,996
2022	T04CN	02	PCC	Major Rehabilitation	\$60,729
2022	T05CN	01	PCC	Preventive Maintenance	\$6,977
2022	T06CN	01	PCC	Preventive Maintenance	\$271
2022	T07CN	01	PCC	Preventive Maintenance	\$7,613
2022	TH01CN	01	PCC	Major Rehabilitation	\$313,652
2022	TH01CN	02	PCC	Major Rehabilitation	\$37,410
2022	TH01CN	03	AAC	Major Rehabilitation	\$171,762

Table 2. 5-year M&R program under an unlimited funding analysis scenario.

Table Notes:

- 1. See Figure 3 for the location of the branch and section.
- 2. Surface Type: AC = asphalt cement concrete; AAC = asphalt overlay on AC; PCC = portland cement concrete; APC = asphalt overlay on PCC.
- 3. Type of Repair: Major Rehabilitation such as pavement reconstruction or an overlay; Localized Preventive Maintenance such as crack sealing or patching.
- 4. The estimated costs provided are of a general nature for the entire state and may require adjustment to reflect specific conditions at Clinton Municipal Airport.

The recommendations made in this report are based on a broad network-level analysis and meant to provide Clinton Municipal Airport with an indication of the type of pavement-related work required during the next 5 years. Further engineering investigation may be necessary to identify which repair action is most appropriate. In addition, the cost estimates provided are based on overall unit costs for the entire state, and Clinton Municipal Airport should adjust the plan to reflect local costs.

Because an unlimited budget was used in the analysis, it is possible that the pavement repair program may need to be adjusted to consider economic or operational constraints. The identification of a project need does not necessarily mean that state or federal funding will be available in the year it is indicated. It is important to remember that regardless of the recommendations presented within this report, Clinton Municipal Airport is responsible for repairing pavements where existing conditions pose a hazard to safe operations.

General Maintenance Recommendations

In addition to the specific maintenance actions presented in Appendix F, it is recommended that the following strategies be considered for prolonging pavement life:

- 1. Regularly inspect all safety areas of the airport and document all inspection activity. A sample form that can be used to perform these inspections is provided in Table 3 of this report.
- Provide a method of tracking all maintenance activities that occur as a result of inspections. These need to be reported to the FAA and the Iowa DOT. This information is used to update the APMS records and is required to remain in compliance with Public Law 103-305 (see the next section of this report for further information on this law).
- 3. Conduct an aggressive campaign against weed growth through timely herbicide applications and mowing programs of the safety areas. Vegetation growth in pavement cracks is destructive and significantly increases the rate of pavement deterioration.
- 4. Implement a periodic crack and joint sealing program. Keeping water and debris out of the pavement system by sealing cracks and joints is a proven and cost-effective method of extending the life of the pavement system.
- 5. Ensure that dirt does not build up along the edges of the pavements. This can create a "bathtub" effect, reducing the ability of water to drain away from the pavement system.
- 6. Closely monitor the movement of heavy equipment (particularly farming, construction, and fueling equipment) to make sure it is only operating on pavements that are designed to accommodate heavy loads. Failure to restrict heavy equipment to appropriate areas may result in the premature failure of airport pavements.

FAA Requirements (Public Law 103-305)

Because Clinton Municipal Airport is in the National Plan of Integrated Airport Systems (NPIAS), the airport sponsor is required to keep the airport in a viable operating condition. This includes maintaining airport pavements in accordance with Public Law 103-305. Public Law 103-305 states that after January 1, 1995, NPIAS airport sponsors must provide assurances or certifications that an airport has implemented an effective airport pavement maintenance management system (PMMS) before the airport will be considered for federal funding of pavement replacement or reconstruction projects. To be in full compliance with the federal law,

the PMMS must include the following components at minimum: pavement inventory, pavement inspections, record keeping, information retrieval, and program funding.

This report serves as a complete pavement inventory and detailed inspection. To remain in compliance with the law, Clinton Municipal Airport will also need to undertake monthly driveby inspections of pavement conditions and track pavement-related maintenance activities.

FAA Advisory Circular 150/5380-7B provides detailed guidance pertaining to the requirements for an acceptable pavement management program (PMP). Appendix A of the FAA Advisory Circular 150/5380-7B outlines what needs to be included in a PMP to remain in compliance with this law and Grant Assurance #11. The following is a copy of this Appendix, along with instructions for supplementing this report so that all requirements are met. Note that the italicized words are direct quotations from the FAA Advisory Circular.

FAA Advisory Circular 150/5830-7B, Appendix A. Pavement Management Program (PMP)

A-1.0. An effective PMP specifies the procedures to follow to assure that proper preventative and remedial pavement maintenance is performed. The program should identify funding or anticipated funding and other resources available to provide remedial and preventive maintenance activities. An airport sponsor may use any format deemed appropriate, but the program needs to, as a minimum, include the following:

A-1.1. Pavement Inventory. The following must be depicted:

a. Identification of all runways, taxiways, and aprons with pavement broken down into sections each having similar properties.

The network definition map provided in Figure 3 of this report shows the location of all runways, taxiways, aprons, and T-hangars at Clinton Municipal Airport. If any new pavements are constructed or any pavement areas are permanently closed, this map must be updated. Project plans should be submitted to the Iowa DOT after project completion.

b. Dimensions of pavement sections.

The dimensions of all runways, taxiways, aprons, and T-hangars are stored in the PAVER database. Appendix C provides information on length, width, and area. In addition, the network definition map (Figure 3) is drawn to scale. Any changes to pavement dimensions must be recorded.

c. Type of pavement surface.

The type of pavement for each section at Clinton Municipal Airport is listed in Table 1 of this report and is also stored in the PAVER database. Any changes to pavement type (through an overlay or reconstruction) must be recorded.

d. Year of construction and/or most recent major rehabilitation.

Dates for pavement construction, rehabilitation, or reconstruction must be recorded. The current pavement history for Clinton Municipal Airport is provided in Appendix D of this report.

e. Whether AIP [Airport Improvement Program] or PFC [Passenger Facility Charge] funds were used to construct, reconstruct, or repair the pavement.

Funding sources for all pavement projects should be recorded.

A-1.2. PMP Pavement Inspection Schedule. Airports must perform a detailed inspection of airfield pavements at least once a year for the PMP. If a pavement condition index (PCI) survey is performed, as set forth in ASTM D5340, Standard Test Method for Airport Pavement Condition Index Surveys, the frequency of the detailed inspection by PCI surveys may be extended to three years. Less comprehensive routine daily, weekly, and monthly maintenance inspections required for operations should be addressed.

This report consists of a detailed inspection that will extend the inspection period to 3 years. It is the airport sponsor's responsibility to perform monthly drive-by inspections. A sample pavement inspection report form is provided in Table 3 of this report.

A-1.3. Record Keeping. The airport must record and keep on file complete information about all detailed inspections and maintenance performed until the pavement system is replaced. The types of distress, their locations, and remedial action, scheduled or performed, must be documented. The minimum information recorded includes:

- a. Inspection date
- b. Location
- c. Distress types
- d. Maintenance scheduled or performed

Items a through c are satisfied by this inspection report. Item d is the responsibility of the airport, as is record keeping of the monthly drive-by inspections.

A-1.4. Information Retrieval. An airport sponsor may use any form of record keeping it deems appropriate so long as the information and records from the pavement survey can generate required reports, as necessary.

Keep this report, monthly drive-by inspection reports, construction updates, and all records of maintenance activities in a readily accessible location so that they can be easily retrieved as requested by the FAA.

Inspected By: _____

Date Inspected: _____

Branch	Section	Distress Description/Dimensions/Severity/ Recommended Action	Description of Repair	Date Performed	Cost	Funding Source
A01CN	01					
A01CN	02					
A01CN	03					
A01CN	04					
A02CN	01					
A02CN	02					

July 2022

Pavement Maintenance and Rehabilitation Program

20

Date Inspected: _____

Branch	Section	Distress Description/Dimensions/Severity/ Recommended Action	Description of Repair	Date Performed	Cost	Funding Source
A02CN	03					
R03CN	01					
R03CN	02					
R14CN	01					
T01CN	01					
T01CN	02					

July 2022

2

Date Inspected: _____

Branch	Section	Distress Description/Dimensions/Severity/ Recommended Action	Description of Repair	Date Performed	Cost	Funding Source
T01CN	03					
T02CN	01					
T03CN	01					
T03CN	02					
T03CN	03					
T03CN	04					

22

Clinton Municipal Airport Pavement Management Report

Date Inspected: _____

Branch	Section	Distress Description/Dimensions/Severity/ Recommended Action	Description of Repair	Date Performed	Cost	Funding Source
T04CN	01					
T04CN	02					
T05CN	01					
T05CN	02					
T06CN	01					
T06CN	02					

July 2022

Date Inspected: _____

Branch	Section	Distress Description/Dimensions/Severity/ Recommended Action	Description of Repair	Date Performed	Cost	Funding Source
T07CN	01					
TH01CN	01					
TH01CN	02					
TH01CN	03					

Table Notes:

1. See Figure 3 for the location of the branch and section.

Pavement Maintenance and Rehabilitation Program

SUMMARY

This report documents the results of the pavement evaluation conducted at Clinton Municipal Airport. A visual inspection of the pavements in 2021 found that the overall condition of the pavement network is a PCI of 86. A 5-year pavement repair program, shown in Table 2, was generated for Clinton Municipal Airport, which revealed that approximately \$1,984,000 needs to be expended on M&R. Clinton Municipal Airport should utilize these study results to assist in planning for future maintenance needs as part of the airport CIP planning process.

APPENDIX A

CAUSE OF DISTRESS TABLES

Distress Type	Probable Cause of Distress
Alligator Cracking	Fatigue failure of the asphalt surface under repeated traffic loading.
Bleeding	Excessive amounts of asphalt cement or tars in the mix or low air void content, or both.
Block Cracking	Shrinkage of the asphalt and daily temperature cycling; it is not load associated.
Corrugation	Traffic action combined with an unstable pavement layer.
Depression	Settlement of the foundation soil or can be "built up" during construction.
Jet-Blast Erosion	Bituminous binder has been burned or carbonized.
Joint Reflection Cracking	Movement of the concrete slab beneath the asphalt surface due to thermal and moisture changes.
L&T Cracking	Cracks may be caused by (1) a poorly constructed paving lane joint, (2) shrinkage of the asphalt surface due to low temperatures or hardening of the asphalt, or (3) reflective cracking caused by cracks in an underlying PCC slab.
Oil Spillage	Deterioration or softening of the pavement surface caused by the spilling of oil, fuel, or other solvents.
Patching	N/A
Polished Aggregate	Repeated traffic applications.
Raveling	Asphalt binder may have hardened significantly, causing coarse aggregate pieces to dislodge.
Rutting	Usually caused by consolidation or lateral movement of the materials due to traffic loads.
Shoving	Where PCC pavements adjoin flexible pavements, PCC "growth" may shove the asphalt pavement.
Slippage Cracking	Low strength surface mix or poor bond between the surface and the next layer of the pavement structure.
Swelling	Usually caused by frost action or by swelling soil.
Weathering	Asphalt binder and/or fine aggregate may wear away as the pavement ages and hardens.

Table A-1. Cause of pavement distress, asphalt-surfaced pavements.

Distress Type	Probable Cause of Distress			
ASR	Chemical reaction of alkalis in the portland cement with certain reactive silica minerals. ASR may be accelerated by the use of chemical pavement deicers.			
Blowup	Incompressible materials in the joints.			
Corner Break	Load repetition combined with loss of support and curling stresses.			
Durability Cracking	Concrete's inability to withstand environmental factors such as freeze-thaw cycles.			
Faulting	Upheaval or consolidation.			
Joint Seal Damage	Stripping of joint sealant, extrusion of joint sealant, weed growth, hardening of the filler (oxidation), loss of bond to the slab edges, or absence of sealant in the joint.			
LTD Cracking	Combination of load repetition, curling stresses, and shrinkage stresses.			
Patching (Small and Large)	N/A			
Popouts	Freeze-thaw action in combination with expansive aggregates.			
Pumping	Poor drainage, poor joint sealant.			
Scaling	Over finishing of concrete, deicing salts, improper construction, freeze-thaw cycles, and poor aggregate.			
Shattered Slab	Load repetition.			
Shrinkage Cracking	Setting and curing of the concrete.			
Spalling (Joint and Corner)	Excessive stresses at the joint caused by infiltration of incompressible materials or traffic loads; weak concrete at the joint combined with traffic loads.			

Table A-2. Cause of pavement distress, PCC pavements.

APPENDIX B

INSPECTION PHOTOGRAPHS

A01CN-01. Overview.



A01CN-01. ASR (Sample Unit No. 06).





A01CN-01. LTD Cracking (Sample Unit No. 05).

A01CN-02. Overview.





A01CN-02. LTD Cracking (Sample Unit No. 01).

A01CN-03. Overview.





A01CN-03. Alligator Cracking (Sample Unit No. 03).

A01CN-03. Raveling (Sample Unit No. 03).



A01CN-04. Overview.



A01CN-04. LTD Cracking (Sample Unit No. 03).



A02CN-01. Overview.



A02CN-01. ASR (Sample Unit No. 05).





A02CN-01. ASR (Sample Unit No. 06).

A02CN-01. Corner Break (Sample Unit No. 06).





A02CN-01. LTD Cracking (Sample Unit No. 06).

A02CN-02. Overview.



A02CN-03. Overview.



A02CN-03. ASR (Sample Unit No. 04).





A02CN-03. ASR (Sample Unit No. 05).

R03CN-01. Overview.





R03CN-01. LTD Cracking (Sample Unit No. 44).

R03CN-01. Scaling (Additional Sample Unit No. 110).



R03CN-02. Overview.



R03CN-02. LTD Cracking (Sample Unit No. 07).




R14CN-01. Overview.



R14CN-01. Faulting (Sample Unit No. 88).





R14CN-01. LTD Cracking (Sample Unit No. 88).


T01CN-02. Overview.





T01CN-02. Corner Break (Sample Unit No. 01).

T01CN-02. Corner Spalling (Sample Unit No. 01).



T01CN-03. Overview.



T01CN-03. LTD Cracking (Sample Unit No. 05).



T02CN-01. Overview.



T02CN-01. Joint Seal Damage (Sample Unit No. 01).



T03CN-01. Overview.



T03CN-02. Overview.





T03CN-02. Corner Spalling (Sample Unit No. 01).

T03CN-02. Small Patching (Sample Unit No. 01).



T03CN-03. Overview.



T03CN-03. LTD Cracking (Additional Sample Unit No. 42).



T03CN-04. Overview.



T03CN-04. Corner Break (Sample Unit No. 05).



T04CN-01. Overview.



T04CN-01. Alligator Cracking (Sample Unit No. 05).





T04CN-01. L&T Cracking (Sample Unit No. 05).

T04CN-02. Overview.





T04CN-02. LTD Cracking (Sample Unit No. 01).

T05CN-01. Overview.





T05CN-01. LTD Cracking (Sample Unit No. 06).

T05CN-02. Overview.



T06CN-01. Overview.



T06CN-01. Joint Spalling (Sample Unit No. 04).




T06CN-02. Overview.



T07CN-01. Overview.







TH01CN-01. Overview.





TH01CN-01. LTD Cracking (Sample Unit No. 07).

TH01CN-02. Overview.





TH01CN-02. Shattered Slab (Sample Unit No. 01).

TH01CN-03. Overview.





TH01CN-03. L&T Cracking (Sample Unit No. 02).

TH01CN-03. Raveling (Sample Unit No. 02).



APPENDIX C

INSPECTION REPORT

Pavement Database: IA 2021 Network ID: CWI Generate Date: 4/27/2022

Network ID: CVVI			Page
Branch Name: APRON 01	Branch - Section ID: A	\01CN - 01	Use: APRO
LCD: 6/1/1984 Surface Type: PCC Rank: P Section Area (sf): 22,346.00 Length (ft): 200.00 Width (ft): 180.00 From: T04CL To: END OF APRON	PCI Famil	ly: IowaPCCAPNCE_Enhanced	
Slabs: 186 Slab Length (ft): 12.00 Slab Width (ft): 10.00 Joint Length (ft): 3,860.89	Section Comments:		
Last Insp Date: 11/18/2021 PCI: 51 Total Samples: 10 Surveyed: 5	Inspection Comments:		
Sample Number: 01			
Sample Type: R Sample PCI: 10 Sample Area (Slabs): 20	Sample C	Comments:	
62 CORNER BREAK 63 LINEAR CR 65 JT SEAL DMG 72 SHAT. SLAB 76 ASR 76 ASR 76 ASR	M M H H L M	1 Slabs 3 Slabs 20 Slabs 1 Slabs 4 Slabs 7 Slabs 8 Slabs	
Sample Number: 05			
Sample Type: R Sample PCI: 52 Sample Area (Slabs): 23	Sample C	Comments:	
62 CORNER BREAK 63 LINEAR CR 65 JT SEAL DMG 76 ASR 76 ASR	L M L M	2 Slabs 2 Slabs 23 Slabs 10 Slabs 2 Slabs	
Sample Number: 06			
Sample Type: R Sample PCI: 44 Sample Area (Slabs): 20	Sample C	Comments:	
62 CORNER BREAK 63 LINEAR CR 65 JT SEAL DMG 76 ASR	L M M L	1 Slabs 3 Slabs 20 Slabs 10 Slabs	

Pavement Database: IA 2021 Network ID: CWI

Sample Number: 07			
Sample Type: R Sample PCI: 87 Sample Area (Slabs): 20	Sample C	Comments:	
65 JT SEAL DMG	М	20 Slabs	
76 ASR	L	2 Slabs	
Sample Number: 08			
Sample Type: R	Sample C	Comments:	

Sample PCI: 62		
Sample Area (Slabs): 20		
62 CORNER BREAK	Μ	1 Slabs
66 SMALL PATCH	Μ	1 Slabs
76 ASR	L	6 Slabs
76 ASR	Μ	2 Slabs

Pavement Database: IA 2021 Network ID: CWI Generate Date: 4/27/2022

	Branch - Section ID: A	01CN - 02	
Branch Name: APRON 01			Use: APRON
LCD: 6/3/2014 Surface Type: PCC Rank: P Section Area (sf): 9,991.00 Length (ft): 100.00 Width (ft): 140.00 From: A01CN-01 To: Hanger	PCI Famil	y: IowaPCCAPNCE_Enhanced	
Slabs: 83 Slab Length (ft): 10.00 Slab Width (ft): 12.00 Joint Length (ft): 1,660.41	Section Comments:		
Last Insp Date: 11/18/2021 PCI: 89 Total Samples: 4 Surveyed: 3	Inspectior	i Comments:	
Sample Number: 01			
Sample Type: R Sample PCI: 84 Sample Area (Slabs): 19	Sample C	omments:	
62 CORNER BREAK	L	1 Slabs	
63 LINEAR CR	L	1 Slabs	
65 JT SEAL DMG	М	19 Slabs	
Sample Number: 02 Sample Type: R Sample PCI: 93 Sample Area (Slabs): 24	Sample Comments:		
65 JT SEAL DMG	М	24 Slabs	
Sample Number: 04			
Sample Type: R Sample PCI: 88 Sample Area (Slabs): 17	Sample C	Sample Comments:	
63 LINEAR CR	L	1 Slabs	
65 JT SEAL DMG	Μ	17 Slabs	

Pavement Database: IA 2021 Network ID: CWI Generate Date: 4/27/2022

	Branch - Section ID: A	01CN - 03	
Branch Name: APRON 01	Brunon Coolion B. F		Use: APRON
LCD: 1/1/1995 Surface Type: AC Rank: P Section Area (sf): 18,992.00 Length (ft): 218.00 Width (ft): 85.00 From: SEE MAP To: SEE MAP	PCI Famil	y: IowaACAPNE&NCE	
Slabs: Slab Length (ft): Slab Width (ft): Joint Length (ft):	Section C	omments:	
Last Insp Date: 11/18/2021 PCI: 9 Total Samples: 4 Surveyed: 3	Inspection Comments:		
Sample Number: 01			
Sample Type: R Sample PCI: 9 Sample Area (SF): 6,535	Sample C	omments:	
41 ALLIGATOR CR 48 L & T CR 52 RAVELING 57 WEATHERING 57 WEATHERING	M M H L M	4,610 SF 245 Ft W 500 SF 3,555 SF 500 SF	
Sample Number: 03			
Sample Type: R Sample PCI: 5 Sample Area (SF): 4,700	Sample C	omments:	
41 ALLIGATOR CR 43 BLOCK CR 52 RAVELING 57 WEATHERING 57 WEATHERING	M M H L M	2,700 SF 2,000 SF w 500 SF 2,350 SF 500 SF	
Sample Number: 04			
Sample Type: R Sample PCI: 12 Sample Area (SF): 3,485	Sample Comments:		
41 ALLIGATOR CR 48 L & T CR 50 PATCHING 57 WEATHERING 57 WEATHERING	M M L L M	1,750 SF 312 Ft w 172 SF 1,750 SF 500 SF	

Pavement Database: IA 2021 Network ID: CWI Generate Date: 4/27/2022

	Branch - Section ID: A01CN - 04	
Branch Name: APRON 01		Use: APRON
LCD: 4/1/2016 Surface Type: PCC Rank: P Section Area (sf): 8,100.00 Length (ft): 162.00 Width (ft): 50.00 From: SEE MAP To: SEE MAP	PCI Family: IowaPCCAPNCE_Enhanced	
Slabs: 65 Slab Length (ft): 12.50 Slab Width (ft): 10.00 Joint Length (ft): 1,246.00	Section Comments:	
Last Insp Date: 11/18/2021 PCI: 95 Total Samples: 3 Surveyed: 3	Inspection Comments:	
Sample Number: 01		
Sample Type: R Sample PCI: 100 Sample Area (Slabs): 20 NO DISTRESS	Sample Comments:	
Sample Number: 02		
Sample Type: R Sample PCI: 100 Sample Area (Slabs): 20 NO DISTRESS	Sample Comments:	
Sample Number: 03		
Sample Type: R Sample PCI: 88 Sample Area (Slabs): 25	Sample Comments:	
63 LINEAR CR	L 4 Slabs	

Pavement Database: IA 2021 Network ID: CWI Generate Date: 4/27/2022

Branch Name: APRON 02	Branch - Section ID: A	A02CN - 01	Use: APRO
LCD: 6/1/1981 Surface Type: PCC Rank: P Section Area (sf): 18,725.00 Length (ft): 140.00 Width (ft): 130.00 From: TAXIWAY 01 To: END OF APRON	PCI Fami	ly: IowaPCCAPNCE_Enhanced	
Slabs: 187 Slab Length (ft): 10.00 Slab Width (ft): 10.00 Joint Length (ft): 3,467.21	Section Comments:		
Last Insp Date: 11/18/2021 PCI: 47 Total Samples: 7 Surveyed: 5	Inspection Comments:		
Sample Number: 01			
Sample Type: R Sample PCI: 44 Sample Area (Slabs): 21	Sample Comments:		
62 CORNER BREAK 63 LINEAR CR 65 JT SEAL DMG 72 SHAT. SLAB	M M H L	2 Slabs 7 Slabs 21 Slabs 2 Slabs	
Sample Number: 04			
Sample Type: R Sample PCI: 53 Sample Area (Slabs): 28	Sample C	comments:	
63 LINEAR CR 65 JT SEAL DMG 72 SHAT. SLAB 74 JOINT SPALL	M H L M	5 Slabs 28 Slabs 1 Slabs 1 Slabs	
75 CORNER SPALL 76 ASR	M	1 Slabs 2 Slabs	
Sample Number: 05			
Sample Type: R Sample PCI: 30 Sample Area (Slabs): 28	Sample C	comments:	
63 LINEAR CR 65 JT SEAL DMG 67 LARGE PATCH 72 SHAT. SLAB	M H L M H	6 Slabs 28 Slabs 2 Slabs 1 Slabs 1 Slabs	
76 ASR	н		

Pavement Database: IA 2021

Network ID: CWI

Sample Number: 06			
Sample Type: R Sample PCI: 59 Sample Area (Slabs): 28	Sample C	omments:	
62 CORNER BREAK	М	1 Slabs	
63 LINEAR CR	Μ	4 Slabs	
65 JT SEAL DMG	Н	28 Slabs	
75 CORNER SPALL	Μ	1 Slabs	
76 ASR	Μ	1 Slabs	

Sample Number: 07

Sample Type: R	Sample Cor	nments:
Sample PCI: 52		
Sample Area (Slabs): 20		
62 CORNER BREAK	М	1 Slabs
63 LINEAR CR	Μ	7 Slabs
65 JT SEAL DMG	Н	20 Slabs

Pavement Database: IA 2021 Network ID: CWI Generate Date: 4/27/2022

Page 8

	i ago
Branch Name: APRON 02	Branch - Section ID: A02CN - 02 Use: APROI
LCD: 5/2/2020 Surface Type: PCC Rank: P Section Area (sf): 33,191.00 Length (ft): 200.00 Width (ft): 150.00 From: T02 To: END OF APRON	PCI Family: IowaPCCAPNCE_Enhanced
Slabs: 379 Slab Length (ft): 10.00 Slab Width (ft): 8.75 Joint Length (ft): 6,725.13	Section Comments:
Last Insp Date: 11/18/2021 PCI: 100 Total Samples: 17 Surveyed: 7	Inspection Comments:
Sample Number: 01	
Sample Type: R Sample PCI: 100 Sample Area (Slabs): 25 NO DISTRESS	Sample Comments:
Sample Number: 03	
Sample Type: R Sample PCI: 100 Sample Area (Slabs): 25 NO DISTRESS	Sample Comments:
Sample Number: 06	
Sample Type: R Sample PCI: 100 Sample Area (Slabs): 20 NO DISTRESS	Sample Comments:
Sample Number: 08	
Sample Type: R Sample PCI: 100 Sample Area (Slabs): 18 NO DISTRESS	Sample Comments:
Sample Number: 09	
Sample Type: R Sample PCI: 100 Sample Area (Slabs): 20 NO DISTRESS	Sample Comments:
Sample Number: 13	
Sample Type: R Sample PCI: 100 Sample Area (Slabs): 20 NO DISTRESS	Sample Comments:

Pavement Database: IA 2021 Network ID: CWI

Sample Number: 17

Sample Type: R Sample PCI: 100 Sample Area (Slabs): 20 NO DISTRESS Generate Date: 4/27/2022 Page 9

Sample Comments:

Pavement Database: IA 2021 Network ID: CWI Generate Date: 4/27/2022

Page 10

Network ID. GWI		гауе	
Branch Name: APRON 02	Branch - Section ID: A	A02CN - 03 Use: APRO	
LCD: 6/1/1984 Surface Type: PCC Rank: P Section Area (sf): 18,060.00 Length (ft): 162.00 Width (ft): 112.00 From: A02CL02 To: T03CL	PCI Fam	PCI Family: IowaPCCAPNCE_Enhanced	
Slabs: 131 Slab Length (ft): 11.00 Slab Width (ft): 12.50 Joint Length (ft): 2,813.89	Section C	Comments:	
Last Insp Date: 11/18/2021 PCI: 23 Total Samples: 7 Surveyed: 4	Inspectio	Inspection Comments:	
Sample Number: 02			
Sample Type: R Sample PCI: 18 Sample Area (Slabs): 20	Sample 0	Comments:	
63 LINEAR CR	Μ	2 Slabs	
65 JT SEAL DMG	Н	20 Slabs	
76 ASR	Н	2 Slabs	
76 ASR	L	8 Slabs	
76 ASR	Μ	10 Slabs	
Sample Number: 04			
Sample Type: R Sample PCI: 3 Sample Area (Slabs): 20	Sample 0	Sample Comments:	
63 LINEAR CR	М	6 Slabs	
65 JT SEAL DMG	H	20 Slabs	
76 ASR	н	6 Slabs	
76 ASR	L	4 Slabs	
76 ASR	Μ	10 Slabs	
Sample Number: 05			
Sample Type: R Sample PCI: 30 Sample Area (Slabs): 20	Sample 0	Comments:	
65 JT SEAL DMG	Н	20 Slabs	
76 ASR	Н	5 Slabs	
76 ASR	L	15 Slabs	
Sample Number: 06			
Sample Type: R Sample PCI: 40 Sample Area (Slabs): 20	Sample (Comments:	
63 LINEAR CR	М	1 Slabs	
65 JT SEAL DMG	H	20 Slabs	
76 ASR	L	12 Slabs	
76 ASR	Μ	8 Slabs	

Pavement Database: IA 2021 Network ID: CWI Generate Date: 4/27/2022

Page 11

INELWOIK ID. CWI			Fage
Branch Name: RUNWAY 03/21	Branch - Section II	D: R03CN - 01	Use: RUNWA
LCD: 4/2/2010 Surface Type: PCC Rank: P Section Area (sf): 494,870.00 Length (ft): 4,955.00 Width (ft): 100.00 From: 03 APPROACH To: 21 APPROACH	PCI Family: IowaPCCRWNCE_Enhanced		
Slabs: 3,167 Slab Length (ft): 12.50 Slab Width (ft): 12.50 Joint Length (ft): 74,130.63	Sectio	on Comments:	
Last Insp Date: 11/17/2021 PCI: 96 Total Samples: 158 Surveyed: 17	Inspe	Inspection Comments:	
Sample Number: 004			
Sample Type: R Sample PCI: 98 Sample Area (Slabs): 20	Samp	le Comments:	
65 JT SEAL DMG	L	20 Slabs	
Sample Number: 013			
Sample Type: R Sample PCI: 98 Sample Area (Slabs): 20	Samp	le Comments:	
65 JT SEAL DMG	L	20 Slabs	
Sample Number: 024			
Sample Type: R Sample PCI: 98 Sample Area (Slabs): 20	Samp	le Comments:	
65 JT SEAL DMG	L	20 Slabs	
Sample Number: 033 Sample Type: R Sample PCI: 98 Sample Area (Slabs): 20	Samp	le Comments:	
65 JT SEAL DMG	L	20 Slabs	
Sample Number: 044	L	20 01000	
Sample Type: R Sample PCI: 69 Sample Area (Slabs): 20	Samp	e Comments:	
63 LINEAR CR 65 JT SEAL DMG 72 SHAT. SLAB	M L L	3 Slabs 20 Slabs 1 Slabs	
Sample Number: 053			
Sample Type: R Sample PCI: 98 Sample Area (Slabs): 20	Samp	le Comments:	
65 JT SEAL DMG	L	20 Slabs	

Pavement Database: IA 2021 Generate Date: 4/27/2022 Page 12 Sample Comments: Sample Area (Slabs): 20 65 JT SEAL DMG L 20 Slabs Sample Comments: Sample Area (Slabs): 20 20 Slabs L

Sample Comments:

Sample Comments:

Sample Comments:

Sample Comments:

Sample Comments:

20 Slabs

20 Slabs

20 Slabs

20 Slabs

1 Slabs

1 Slabs

1 Slabs

L

L

L

L

L

L

L

Sample Number: 084

Network ID: CWI

Sample Number: 064 Sample Type: R

Sample PCI: 98

Sample Number: 073 Sample Type: R

Sample PCI: 98

Sample Type: R Sample PCI: 98 Sample Area (Slabs): 20 65 JT SEAL DMG

65 JT SEAL DMG

Sample Number: 093

Sample Type: R Sample PCI: 98 Sample Area (Slabs): 20 65 JT SEAL DMG

Sample Number: 104

Sample Type: R Sample PCI: 98 Sample Area (Slabs): 20 65 JT SEAL DMG

Sample Number: 110

Sample Type: A Sample PCI: 94 Sample Area (Slabs): 20 65 JT SEAL DMG 66 SMALL PATCH 70 SCALING

75 CORNER SPALL

Sample Number: 113

Sample	Comments:	
L	20 Slabs	
Sample	Comments:	
L	20 Slabs	
	L	Sample Comments:

Sample Number: 133

Sample Type: R Sample PCI: 98 Sample Area (Slabs): 20 65 JT SEAL DMG

Pavement Database: IA 2021 Generate Date: 4/27/2022 Network ID: CWI Page 13 Sample Number: 144 Sample Type: R Sample Comments: Sample PCI: 98 Sample Area (Slabs): 20 65 JT SEAL DMG L 20 Slabs Sample Number: 153 Sample Type: R Sample Comments: Sample PCI: 98 Sample Area (Slabs): 20 65 JT SEAL DMG L 20 Slabs

Pavement Database: IA 2021 Network ID: CWI

Network ID: CVVI			Page 14
Branch Name: RUNWAY 03/21	Branch - Sectio	n ID: R03CN - 02	Use: RUNWAY
LCD: 4/2/2010 Surface Type: PCC Rank: P Section Area (sf): 25,000.00 Length (ft): 250.00 Width (ft): 100.00 From: R03CL 04 To: R03CL 03	F	PCI Family: IowaPCCRWNCE_Enhanced	
Slabs: 160 Slab Length (ft): 12.50 Slab Width (ft): 12.50 Joint Length (ft): 3,650.00	S	Section Comments:	
Last Insp Date: 11/17/2021 PCI: 91 Total Samples: 8	I	nspection Comments:	
Surveyed: 5			
Sample Number: 01			
Sample Type: R Sample PCI: 91 Sample Area (Slabs): 20	S	Sample Comments:	
65 JT SEAL DMG 75 CORNER SPALL	M L	20 Slabs 1 Slabs	
Sample Number: 04			
Sample Type: R Sample PCI: 89 Sample Area (Slabs): 20	S	Sample Comments:	
65 JT SEAL DMG 75 CORNER SPALL	M M	20 Slabs 1 Slabs	
Sample Number: 05			
Sample Type: R Sample PCI: 93 Sample Area (Slabs): 20	S	Sample Comments:	
65 JT SEAL DMG	Μ	20 Slabs	
Sample Number: 07			
Sample Type: R Sample PCI: 88 Sample Area (Slabs): 20	S	Sample Comments:	
63 LINEAR CR 65 JT SEAL DMG	L	1 Slabs 20 Slabs	
Sample Number: 08			
Sample Type: R Sample PCI: 93 Sample Area (Slabs): 20	S	Sample Comments:	
65 JT SEAL DMG	М	20 Slabs	

Pavement Database: IA 2021 Network ID: CWI Generate Date: 4/27/2022

Page 15

			i age i
Branch Name: RUNWAY 14/32	Branch - Section ID: R	14CN - 01	Use: RUNWA
LCD: 4/2/2010 Surface Type: PCC Rank: S Section Area (sf): 319,015.00 Length (ft): 4,090.00 Width (ft): 75.00 From: END OF RUNWAY 14 To: END OF RUNWAY 32	PCI Family: IowaPCCRWNCE_Enhanced		
Slabs: 2,042 Slab Length (ft): 12.50 Slab Width (ft): 12.50 Joint Length (ft): 46,710.87	Section C	omments:	
Last Insp Date: 11/18/2021 PCI: 84 Total Samples: 91 Surveyed: 10	Inspection Comments:		
Sample Number: 06			
Sample Type: R Sample PCI: 91 Sample Area (Slabs): 24	Sample C	omments:	
65 JT SEAL DMG 71 FAULTING	L	24 Slabs 2 Slabs	
Sample Number: 16			
Sample Type: R Sample PCI: 94 Sample Area (Slabs): 24 63 LINEAR CR	Sample C	omments: 1 Slabs	
65 JT SEAL DMG	L	24 Slabs	
Sample Number: 26			
Sample Type: R Sample PCI: 91 Sample Area (Slabs): 24	Sample C	omments:	
63 LINEAR CR 65 JT SEAL DMG	L	2 Slabs 24 Slabs	
Sample Number: 41			
Sample Type: R Sample PCI: 88 Sample Area (Slabs): 24	Sample C	omments:	
65 JT SEAL DMG 71 FAULTING	M	24 Slabs 2 Slabs	
Sample Number: 53			
Sample Type: R Sample PCI: 88 Sample Area (Slabs): 24	Sample C	omments:	
65 JT SEAL DMG 71 FAULTING	M L	24 Slabs 2 Slabs	

Pavement Database: IA 2021

75 CORNER SPALL

			•
Sample Number: 63			
Sample Type: R Sample PCI: 93 Sample Area (Slabs): 24	Sample Co	omments:	
65 JT SEAL DMG	М	24 Slabs	
Sample Number: 73			
Sample Type: R Sample PCI: 93 Sample Area (Slabs): 24	Sample Co	omments:	
65 JT SEAL DMG	М	24 Slabs	
Sample Number: 83			
Sample Type: R Sample PCI: 84 Sample Area (Slabs): 24	Sample Co	omments:	
63 LINEAR CR	L	2 Slabs	
65 JT SEAL DMG 75 CORNER SPALL	M	24 Slabs 1 Slabs	
Sample Number: 88	IVI		
Sample Type: R Sample PCI: 45 Sample Area (Slabs): 24	Sample Co	omments:	
62 CORNER BREAK	М	3 Slabs	
63 LINEAR CR	М	4 Slabs	
65 JT SEAL DMG	Н	24 Slabs	
71 FAULTING 74 JOINT SPALL	L	6 Slabs 2 Slabs	
Sample Number: 89			
Sample Type: R Sample PCI: 77 Sample Area (Slabs): 24	Sample Co	omments:	
65 JT SEAL DMG	Н	24 Slabs	
66 SMALL PATCH	L	2 Slabs	
71 FAULTING	L	2 Slabs	

L

3 Slabs

Pavement Database: IA 2021 Network ID: CWI Generate Date: 4/27/2022

Page 17

Network ID. CVVI	Fayer
Branch Name: TAXIWAY 01	Branch - Section ID: T01CN - 01 Use: TAXIWA
LCD: 3/31/2018 Surface Type: PCC Rank: P Section Area (sf): 30,107.00 Length (ft): 650.00 Width (ft): 45.00 From: APRON 02CL 02 To: RUNWAY 14	PCI Family: IowaPCCTWNCE_Enhanced
Slabs: 335 Slab Length (ft): 10.00 Slab Width (ft): 9.00 Joint Length (ft): 5,640.56	Section Comments:
Last Insp Date: 11/18/2021 PCI: 100 Total Samples: 16 Surveyed: 6	Inspection Comments:
Sample Number: 02	
Sample Type: R Sample PCI: 100 Sample Area (Slabs): 25 NO DISTRESS	Sample Comments:
Sample Number: 05	
Sample Type: R Sample PCI: 100 Sample Area (Slabs): 20 NO DISTRESS	Sample Comments:
Sample Number: 08	
Sample Type: R Sample PCI: 100 Sample Area (Slabs): 22 NO DISTRESS	Sample Comments:
Sample Number: 11	
Sample Type: R Sample PCI: 100 Sample Area (Slabs): 20 NO DISTRESS	Sample Comments:
Sample Number: 13	
Sample Type: R Sample PCI: 100 Sample Area (Slabs): 20 NO DISTRESS	Sample Comments:
Sample Number: 15	
Sample Type: R Sample PCI: 100 Sample Area (Slabs): 22 NO DISTRESS	Sample Comments:

Pavement Database: IA 2021 Network ID: CWI

Sample Area (Slabs): 24

62 CORNER BREAK

65 JT SEAL DMG

66 SMALL PATCH 75 CORNER SPALL Generate Date: 4/27/2022 Page 18

Branch - Section ID: T01CN - 02

Branch Name: TAXIWAY 01 Use: TAXIWAY LCD: 4/2/2010 PCI Family: IowaPCCTWNCE Enhanced Surface Type: PCC Rank: P Section Area (sf): 3,450.00 Length (ft): 63.00 Width (ft): 50.00 From: RUNWAY 14 To: TAXIWAY 04 Slabs: 24 Section Comments: slab avg Slab Length (ft): 11.50 Slab Width (ft): 12.50 Joint Length (ft): 452.24 Last Insp Date: 11/18/2021 Inspection Comments: PCI: 85 Total Samples: 1 Surveyed: 1 Sample Number: 01 Sample Type: R Sample Comments: Sample PCI: 85

L	1 Slabs
Μ	24 Slabs
Μ	1 Slabs
L	1 Slabs

Pavement Database: IA 2021 Network ID: CWI

	Branch - Section ID: T01CN - 03
Branch Name: TAXIWAY 01	Use: TAXIWAY
LCD: 7/31/2018 Surface Type: PCC Rank: P Section Area (sf): 11,010.00 Length (ft): 185.00 Width (ft): 70.00 From: SEE MAP To: SEE MAP	PCI Family: IowaPCCTWNCE_Enhanced
Slabs: 143 Slab Length (ft): 8.80 Slab Width (ft): 8.75 Joint Length (ft): 2,292.62	Section Comments:
Last Insp Date: 11/18/2021 PCI: 96 Total Samples: 8 Surveyed: 5	Inspection Comments:
Sample Number: 02	
Sample Type: R Sample PCI: 100 Sample Area (Slabs): 12 NO DISTRESS	Sample Comments:
Sample Number: 03	
Sample Type: R Sample PCI: 100 Sample Area (Slabs): 17 NO DISTRESS	Sample Comments:
Sample Number: 05	
Sample Type: R Sample PCI: 81 Sample Area (Slabs): 20	Sample Comments:
63 LINEAR CR	M 2 Slabs
Sample Number: 06 Sample Type: R Sample PCI: 100 Sample Area (Slabs): 20 NO DISTRESS	Sample Comments:
Sample Number: 08	
Sample Type: R Sample PCI: 100 Sample Area (Slabs): 20 NO DISTRESS	Sample Comments:

Pavement Database: IA 2021 Network ID: CWI

Network ID: CWI			Page 20
Branch Name: TAXIWAY 02	Branch - Section ID: T	02CN - 01	Use: TAXIWA
LCD: 4/2/2010 Surface Type: PCC Rank: P Section Area (sf): 13,644.00 Length (ft): 220.00 Width (ft): 38.00 From: RUNWAY 14 To: END	PCI Family:	lowaPCCTWNCE_Enhanced	
Slabs: 156 Slab Length (ft): 10.00 Slab Width (ft): 8.75 Joint Length (ft): 2,502.64	Section Co	nments:	
Last Insp Date: 11/18/2021 PCI: 91 Total Samples: 9 Surveyed: 5	Inspection (Comments:	
Sample Number: 01			
Sample Type: R Sample PCI: 93 Sample Area (Slabs): 20	Sample Co	mments:	
65 JT SEAL DMG	Μ	20 Slabs	
Sample Number: 03			
Sample Type: R Sample PCI: 93 Sample Area (Slabs): 20	Sample Co	mments:	
65 JT SEAL DMG	М	20 Slabs	
Sample Number: 05			
Sample Type: R Sample PCI: 87 Sample Area (Slabs): 20	Sample Co	mments:	
65 JT SEAL DMG 71 FAULTING	M L	20 Slabs 2 Slabs	
Sample Number: 07			
Sample Type: R Sample PCI: 89 Sample Area (Slabs): 20	Sample Co	mments:	
65 JT SEAL DMG	М	20 Slabs	
74 JOINT SPALL	М	1 Slabs	
Sample Number: 09			
Sample Type: R Sample PCI: 98 Sample Area (Slabs): 12	Sample Co	mments:	
65 JT SEAL DMG	L	12 Slabs	

Pavement Database: IA 2021 Network ID: CWI

65 JT SEAL DMG

Branch Name: TAXIWAY 03	Branch - Section	ID: T03CN - 01	Use: TAXIWAY
LCD: 8/3/2011 Surface Type: PCC Rank: P Section Area (sf): 30,263.00 Length (ft): 800.00 Width (ft): 35.00 From: A02CL 03 To: RUNWAY 03	PCI	Family: IowaPCCTWNCE_Enhanced	
Slabs: 393 Slab Length (ft): 8.80 Slab Width (ft): 8.75 Joint Length (ft): 5,995.12	Sec	tion Comments:	
Last Insp Date: 11/18/2021 PCI: 96 Total Samples: 19 Surveyed: 7	Insp	pection Comments:	
Sample Number: 01			
Sample Type: R Sample PCI: 95 Sample Area (Slabs): 27 65 JT SEAL DMG	San L	nple Comments: 27 Slabs	
75 CORNER SPALL	M	1 Slabs	
Sample Number: 03			
Sample Type: R Sample PCI: 98 Sample Area (Slabs): 20	San	nple Comments:	
65 JT SEAL DMG	L	20 Slabs	
Sample Number: 06			
Sample Type: R Sample PCI: 98 Sample Area (Slabs): 20	San	nple Comments:	
65 JT SEAL DMG	L	20 Slabs	
Sample Number: 09			
Sample Type: R Sample PCI: 93 Sample Area (Slabs): 20	San	nple Comments:	
65 JT SEAL DMG	М	20 Slabs	
Sample Number: 13			
Sample Type: R Sample PCI: 93 Sample Area (Slabs): 20	San	nple Comments:	
65 JT SEAL DMG 71 FAULTING	L	20 Slabs 1 Slabs	
Sample Number: 16			
Sample Type: R Sample PCI: 98 Sample Area (Slabs): 20	San	nple Comments:	

Pavement Database: IA 2021 Network ID: CWI

Sample Number: 18

Sample Type: R Sample Comments: Sample PCI: 94 Sample Area (Slabs): 20 65 JT SEAL DMG L 20 Slabs 75 CORNER SPALL L 2 Slabs

Pavement Database: IA 2021 Network ID: CWI

			1 490 20
Branch Name: TAXIWAY 03	Branch - Section	n ID: T03CN - 02	Use: TAXIWAY
LCD: 6/3/2003 Surface Type: PCC Rank: P Section Area (sf): 17,928.00 Length (ft): 515.00 Width (ft): 35.00 From: T03CL-01 To: R14CL-01	P	CI Family: IowaPCCTWNCE_Enhanced	
Slabs: 205 Slab Length (ft): 10.00 Slab Width (ft): 8.75 Joint Length (ft): 3,294.67	Se	ection Comments:	
Last Insp Date: 11/18/2021 PCI: 93 Total Samples: 11 Surveyed: 6	In	spection Comments:	
Sample Number: 01			
Sample Type: R Sample PCI: 89 Sample Area (Slabs): 23	Sa	ample Comments:	
65 JT SEAL DMG 66 SMALL PATCH 75 CORNER SPALL	L M L	23 Slabs 3 Slabs 1 Slabs	
Sample Number: 03			
Sample Type: R Sample PCI: 98 Sample Area (Slabs): 20	Sa	ample Comments:	
65 JT SEAL DMG	L	20 Slabs	
Sample Number: 05			
Sample Type: R Sample PCI: 98 Sample Area (Slabs): 20	Sa	ample Comments:	
65 JT SEAL DMG	L	20 Slabs	
Sample Number: 07			
Sample Type: R Sample PCI: 98 Sample Area (Slabs): 20	Sa	ample Comments:	
65 JT SEAL DMG	L	20 Slabs	
Sample Number: 09			
Sample Type: R Sample PCI: 87 Sample Area (Slabs): 20	Sa	ample Comments:	
65 JT SEAL DMG 71 FAULTING	M L	20 Slabs 2 Slabs	

Pavement Database: IA 2021 Network ID: CWI

Sample Number: 10

Sample Type: R Sample PCI: 91 Sample Area (Slabs): 20 65 JT SEAL DMG 74 JOINT SPALL Generate Date: 4/27/2022 Page 24

Sample Comments:

М	20 Slat	os
L	1 Slat	s

Pavement Database: IA 2021 Network ID: CWI

- 	Branch - Secti	on ID: T03CN - 03	
Branch Name: TAXIWAY 03			Use: TAXIWAY
LCD: 6/3/2003 Surface Type: PCC Rank: P Section Area (sf): 142,497.00 Length (ft): 4,039.00 Width (ft): 35.00 From: R14CL-01 To: R03CL-03		PCI Family: IowaPCCTWNCE_Enhanced	
Slabs: 1,629 Slab Length (ft): 10.00 Slab Width (ft): 8.75 Joint Length (ft): 26,428.45		Section Comments:	
Last Insp Date: 11/17/2021 PCI: 95 Total Samples: 82 Surveyed: 10		Inspection Comments:	
Sample Number: 01			
Sample Type: R Sample PCI: 98 Sample Area (Slabs): 24		Sample Comments:	
65 JT SEAL DMG	L	24 Slabs	
Sample Number: 10 Sample Type: R Sample PCI: 98 Sample Area (Slabs): 20		Sample Comments:	
65 JT SEAL DMG	L	20 Slabs	
Sample Number: 19			
Sample Type: R Sample PCI: 98 Sample Area (Slabs): 20		Sample Comments:	
65 JT SEAL DMG	L	20 Slabs	
Sample Number: 28			
Sample Type: R Sample PCI: 86 Sample Area (Slabs): 20		Sample Comments:	
65 JT SEAL DMG 71 FAULTING	L	20 Slabs 3 Slabs	
Sample Number: 36			
Sample Type: R Sample PCI: 87 Sample Area (Slabs): 20		Sample Comments:	
65 JT SEAL DMG 71 FAULTING	M L	20 Slabs 2 Slabs	

Pavement Database: IA 2021

Network ID: CWI

Sample Number: 42			
Sample Type: A Sample PCI: 89	Sample Cor	nments:	
Sample Area (Slabs): 20			
63 LINEAR CR	L	1 Slabs	
65 JT SEAL DMG	L	20 Slabs	
74 JOINT SPALL	М	1 Slabs	
Sample Number: 46			
Sample Type: R	Sample Cor	nments:	
Sample PCI: 98			
Sample Area (Slabs): 20			
65 JT SEAL DMG	L	20 Slabs	
Sample Number: 55			
Sample Type: R	Sample Cor	nments:	
Sample PCI: 98			
Sample Area (Slabs): 20			
65 JT SEAL DMG	L	20 Slabs	
Sample Number: 64			
Sample Type: R	Sample Cor	nments:	
Sample PCI: 98	• -		
Sample Area (Slabs): 20			
65 JT SEAL DMG	L	20 Slabs	
Sample Number: 73			
Sample Type: R	Sample Comments:		
Sample PCI: 98			
Sample Area (Slabs): 20			
65 JT SEAL DMG	L	20 Slabs	
	—		

Pavement Database: IA 2021 Network ID: CWI

Network ID: CWI			Page 2
	Branch - Section ID: 1	Г03CN - 04	
Branch Name: TAXIWAY 03			Use: TAXIWA
LCD: 6/3/2011 Surface Type: PCC Rank: P Section Area (sf): 8,958.00 Length (ft): 245.00 Width (ft): 35.00 From: RUNWAY 21 To: TAXIWAY 03-03	PCI Fami	ly: lowaPCCTWNCE_Enhanced	
Slabs: 102 Slab Length (ft): 10.00 Slab Width (ft): 8.75 Joint Length (ft): 1,627.07	Section C	comments:	
Last Insp Date: 11/17/2021 PCI: 93 Total Samples: 5 Surveyed: 4	Inspectior	n Comments:	
Sample Number: 02			
Sample Type: R Sample PCI: 98 Sample Area (Slabs): 22	Sample C	Comments:	
65 JT SEAL DMG	L	22 Slabs	
Sample Number: 03			
Sample Type: R Sample PCI: 98 Sample Area (Slabs): 20	Sample C	Comments:	
65 JT SEAL DMG	L	20 Slabs	
Sample Number: 04			
Sample Type: R Sample PCI: 93 Sample Area (Slabs): 20	Sample C	Comments:	
63 LINEAR CR 65 JT SEAL DMG	L	1 Slabs 20 Slabs	
Sample Number: 05			
Sample Type: R Sample PCI: 83 Sample Area (Slabs): 22	Sample C	Comments:	
62 CORNER BREAK 63 LINEAR CR 65 JT SEAL DMG	M M L	1 Slabs 1 Slabs 22 Slabs	

Pavement Database: IA 2021 Network ID: CWI Generate Date: 4/27/2022

Page 28

	Branch - Section ID:	T04CN - 01		
Branch Name: TAXIWAY 04			Use	: TAXIWAY
LCD: 6/1/2002 Surface Type: AAC Rank: P Section Area (sf): 29,958.00 Length (ft): 1,085.00 Width (ft): 25.00 From: T01CL 01 To: END OF T01CL	PCI Fam	ily: IowaAACTWNCE		
Slabs: Slab Length (ft): Slab Width (ft): Joint Length (ft):	Section (Comments:		
Last Insp Date: 11/18/2021 PCI: 21 Total Samples: 8 Surveyed: 4	Inspectio	on Comments:		
Sample Number: 04				
Sample Type: R Sample PCI: 24 Sample Area (SF): 3,000	Sample	Comments:		
41 ALLIGATOR CR 48 L & T CR 48 L & T CR 57 WEATHERING 57 WEATHERING	M L L M	300 SF 142 Ft 300 Ft 1,500 SF 1,500 SF		
Sample Number: 05				
Sample Type: R Sample PCI: 16 Sample Area (SF): 3,125	Sample	Comments:		
41 ALLIGATOR CR 48 L & T CR 48 L & T CR 52 RAVELING 52 RAVELING 57 WEATHERING	M L M H M	600 SF 70 Ft 32 Ft 100 SF 300 SF 2,725 SF	u w, fs	
Sample Number: 06				
Sample Type: R Sample PCI: 9 Sample Area (SF): 3,125	Sample	Comments:		
41 ALLIGATOR CR 43 BLOCK CR 48 L & T CR 48 L & T CR 52 RAVELING 52 RAVELING 57 WEATHERING	M M L M H M M	1,500 SF 900 SF 105 Ft 150 Ft 100 SF 500 SF 2,525 SF	u fs	

Pavement Database: IA 2021 Network ID: CWI

Sample Number: 08

•			
Sample Type: R	Sample C	Comments:	
Sample PCI: 35			
Sample Area (SF): 3,325			
43 BLOCK CR	Μ	1,600 SF	w
48 L & T CR	L	100 Ft	u
48 L & T CR	Μ	300 Ft	fs,w
52 RAVELING	Μ	25 SF	
57 WEATHERING	L	2,000 SF	
57 WEATHERING	Μ	1,300 SF	

Pavement Database: IA 2021 Network ID: CWI

63 LINEAR CR

63 LINEAR CR

65 JT SEAL DMG

Generate Date: 4/27/2022 Page 30

Branch - Section ID: T04CN - 02

Branch Name: TAXIWAY 04	Use: TAXIWAY
LCD: 1/3/2002 Surface Type: PCC Rank: P Section Area (sf): 3,600.00 Length (ft): 100.00 Width (ft): 36.00 From: SEE MAP To: SEE MAP	PCI Family: IowaPCCTWNCE_Enhanced
Slabs: 20 Slab Length (ft): 10.00 Slab Width (ft): 18.00 Joint Length (ft): 424.00	Section Comments:
Last Insp Date: 11/18/2021 PCI: 41 Total Samples: 1 Surveyed: 1	Inspection Comments:
Sample Number: 01	
Sample Type: R Sample PCI: 41 Sample Area (Slabs): 20	Sample Comments:

L	4 Slabs
Μ	12 Slabs
Н	20 Slabs

Pavement Database: IA 2021 Network ID: CWI

			i ugo o i
Branch Name: TAXIWAY 05	Branch - Section	ID: T05CN - 01	Use: TAXIWAY
LCD: 6/1/2003 Surface Type: PCC Rank: P Section Area (sf): 12,269.00 Length (ft): 266.00 Width (ft): 35.00 From: T03CL-02 To: R03CL-01	PCI	Family: IowaPCCTWNCE_Enhanced	
Slabs: 146 Slab Length (ft): 9.60 Slab Width (ft): 8.75 Joint Length (ft): 2,283.53	Sec	tion Comments:	
Last Insp Date: 11/18/2021 PCI: 90 Total Samples: 8 Surveyed: 5	Insp	pection Comments:	
Sample Number: 01			
Sample Type: R Sample PCI: 93 Sample Area (Slabs): 21	Sar	nple Comments:	
65 JT SEAL DMG	М	21 Slabs	
Sample Number: 03			
Sample Type: R Sample PCI: 93 Sample Area (Slabs): 23	Sar	nple Comments:	
65 JT SEAL DMG	М	23 Slabs	
Sample Number: 05			
Sample Type: R Sample PCI: 89 Sample Area (Slabs): 19	Sar	nple Comments:	
62 CORNER BREAK	L	1 Slabs	
65 JT SEAL DMG Sample Number: 06	М	19 Slabs	
Sample Type: R Sample PCI: 74 Sample Area (Slabs): 12	Sar	nple Comments:	
63 LINEAR CR 65 JT SEAL DMG 74 JOINT SPALL	M M L	1 Slabs 12 Slabs 2 Slabs	
Sample Number: 07			
Sample Type: R Sample PCI: 93 Sample Area (Slabs): 20	Sar	nple Comments:	
65 JT SEAL DMG	М	20 Slabs	

Pavement Database: IA 2021 Network ID: CWI

Branch - Section ID: T05CN - 02 Branch Name: TAXIWAY 05 PCI Family: IowaPCCTWNCE_Enhanced LCD: 6/2/2011 PCI Family: IowaPCCTWNCE_Enhanced Surface Type: PCC Rank: P Rank: P Section Area (sf): 4,708.00 Length (ft): 95.00 Width (ft): 95.00 Width (ft): 40.00 From: RUNWAY 03 To: TAXIWAY 05-01 Section Comments: Slabs: 59 Section Comments: Slab Length (ft): 9.10 Slabs: 59 Slab Width (ft): 8.75 Joint Length (ft): 888.16 Last Insp Date: 11/18/2021 Inspection Comments: PCI: 98 Total Samples: 3 Surveyed: 3 Sample Number: 01 Sample PCI: 98 Sample Comments: Sample PCI: 98 Sample Comments: Sample PCI: 98 Sample Reva (Slabs): 19 65 JT SEAL DMG L 19 Slabs Sample Number: 02 Sample Comments: Sample PCI: 98 Sample Comments: Sample PCI: 98 Sample Comments: Sample PCI: 98 Sample Comments:	
Surface Type: PCC Rank: P Section Area (sf): 4,708.00 Length (ft): 95.00 Width (ft): 40.00 From: RUNWAY 03 To: TAXIWAY 03 To: TAXIWAY 05-01 Slabs: 59 Slab Length (ft): 9.10 Slab Width (ft): 8.75 Joint Length (ft): 888.16 Last Insp Date: 11/18/2021 Inspection Comments: PCI: 98 Total Samples: 3 Surveyed: 3 Sample Number: 01 Sample Number: 01 Sample PCI: 98 Sample Area (Slabs): 19 65 JT SEAL DMG L 19 Slabs Sample Number: 02 Sample Type: R Sample Type: R Sample PCI: 98	Use: TAXIWAY
Slab Length (ft): 9.10 Slab Width (ft): 8.75 Joint Length (ft): 888.16 Last Insp Date: 11/18/2021 PCI: 98 Total Samples: 3 Surveyed: 3 Sample Number: 01 Sample Type: R Sample Area (Slabs): 19 65 JT SEAL DMG L 19 Slabs Sample Number: 02 Sample Type: R Sample Type: R Sample Number: 02 Sample PCI: 98 Sample PCI: 98	эd
PCI: 98 Total Samples: 3 Surveyed: 3 Sample Number: 01 Sample Type: R Sample PCI: 98 Sample Area (Slabs): 19 65 JT SEAL DMG L 19 Slabs Sample Number: 02 Sample Type: R Sample PCI: 98	
Sample Type: R Sample PCI: 98 Sample Area (Slabs): 19 65 JT SEAL DMG L 19 Slabs Sample Number: 02 Sample Type: R Sample PCI: 98	
Sample PCI: 98 Sample Area (Slabs): 19 65 JT SEAL DMG L Sample Number: 02 Sample Type: R Sample PCI: 98	
Sample Number: 02 Sample Type: R Sample Comments: Sample PCI: 98	
Sample Type: R Sample Comments: Sample PCI: 98	
65 JT SEAL DMG L 20 Slabs	
Sample Number: 03	
Sample Type: RSample Comments:Sample PCI: 98Sample Area (Slabs): 20	
65 JT SEAL DMG L 20 Slabs	

Pavement Database: IA 2021 Network ID: CWI

			i ugo oo
Branch Name: TAXIWAY 06	Branch - Section ID: T	06CN - 01	Use: TAXIWAY
LCD: 6/3/2003 Surface Type: PCC Rank: P Section Area (sf): 6,747.00 Length (ft): 117.00 Width (ft): 40.00 From: T03CL-03 To: R03CL-02	PCI Family	r: IowaPCCTWNCE_Enhanced	
Slabs: 77 Slab Length (ft): 10.00 Slab Width (ft): 8.75 Joint Length (ft): 1,219.44	Section Co	omments:	
Last Insp Date: 11/18/2021 PCI: 89 Total Samples: 5 Surveyed: 4	Inspection	Comments:	
Sample Number: 01			
Sample Type: R Sample PCI: 98 Sample Area (Slabs): 22	Sample Co	omments:	
65 JT SEAL DMG	L	22 Slabs	
Sample Number: 02			
Sample Type: R Sample PCI: 98 Sample Area (Slabs): 18	Sample Co	omments:	
65 JT SEAL DMG	L	18 Slabs	
Sample Number: 04			
Sample Type: R Sample PCI: 70 Sample Area (Slabs): 18	Sample Co	omments:	
62 CORNER BREAK	L	1 Slabs	
63 LINEAR CR	L	1 Slabs 18 Slabs	
65 JT SEAL DMG 71 FAULTING	L 	2 Slabs	
74 JOINT SPALL	L M	1 Slabs	
76 ASR	L	1 Slabs	
Sample Number: 05			
Sample Type: R Sample PCI: 89 Sample Area (Slabs): 18	Sample Co	omments:	
65 JT SEAL DMG	L	18 Slabs	
71 FAULTING	L	2 Slabs	

Pavement Database: IA 2021 Network ID: CWI

Branch - Section ID: T06CN - 02				
Branch Name: TAXIWAY 06 Use: TAXIWAY				
LCD: 6/3/2011 Surface Type: PCC Rank: P Section Area (sf): 8,296.00 Length (ft): 215.00 Width (ft): 40.00 From: TAXIWAY 06-01 To: TAXIWAY 03		PCI Family: IowaPCCTWNCE_Enhanced		
Slabs: 106 Slab Length (ft): 10.00 Slab Width (ft): 7.80 Joint Length (ft): 1,647.20		Section Comments: SLAB WIDTHS VARY		
Last Insp Date: 11/18/2021 PCI: 98 Total Samples: 5 Surveyed: 4		Inspection Comments:		
Sample Number: 02				
Sample Type: R Sample PCI: 98 Sample Area (Slabs): 18		Sample Comments:		
65 JT SEAL DMG	L	18 Slabs		
Sample Number: 03				
Sample Type: R Sample PCI: 98 Sample Area (Slabs): 22		Sample Comments:		
65 JT SEAL DMG	L	22 Slabs		
Sample Number: 04				
Sample Type: R Sample PCI: 98 Sample Area (Slabs): 20		Sample Comments:		
65 JT SEAL DMG	L	20 Slabs		
Sample Number: 05				
Sample Type: R Sample PCI: 96 Sample Area (Slabs): 20		Sample Comments:		
65 JT SEAL DMG 74 JOINT SPALL	L L	20 Slabs 1 Slabs		

Pavement Database: IA 2021 Network ID: CWI

Network ID. CVVI			Page 55
Branch Name: TAXIWAY 07	Branch - Section ID: T)7CN - 01	Use: TAXIWAY
LCD: 4/2/2010 Surface Type: PCC Rank: P Section Area (sf): 13,646.00 Length (ft): 220.00 Width (ft): 40.00 From: RUNWAY 14 To: END	PCI Family:	IowaPCCTWNCE_Enhanced	
Slabs: 156 Slab Length (ft): 10.00 Slab Width (ft): 8.75 Joint Length (ft): 2,520.97	Section Co	mments:	
Last Insp Date: 11/18/2021 PCI: 89 Total Samples: 9 Surveyed: 5	Inspection (Comments:	
Sample Number: 02			
Sample Type: R Sample PCI: 93 Sample Area (Slabs): 20	Sample Co		
65 JT SEAL DMG	Μ	20 Slabs	
Sample Number: 04 Sample Type: R Sample PCI: 75 Sample Area (Slabs): 20	Sample Co	mments:	
65 JT SEAL DMG 71 FAULTING	M L	20 Slabs 6 Slabs	
Sample Number: 06			
Sample Type: R Sample PCI: 93 Sample Area (Slabs): 12	Sample Co	mments:	
65 JT SEAL DMG	Μ	12 Slabs	
Sample Number: 07			
Sample Type: R Sample PCI: 93 Sample Area (Slabs): 24	Sample Co	mments:	
65 JT SEAL DMG	М	24 Slabs	
Sample Number: 08			
Sample Type: R Sample PCI: 93 Sample Area (Slabs): 24	Sample Co	mments:	
65 JT SEAL DMG	М	24 Slabs	

Pavement Database: IA 2021 Network ID: CWI

65 JT SEAL DMG

70 SCALING

Generate Date: 4/27/2022 Page 36

Network ID. CWI			Page 30
Branch Name: T-HANGAR 01	Branch - Section ID: TH	101CN - 01	Use: T-HANGAR
LCD: 1/3/2002 Surface Type: PCC Rank: P Section Area (sf): 21,168.00 Length (ft): 440.00 Width (ft): 35.00 From: SEE MAP To: SEE MAP	PCI Famil	ly: IowaPCCTHNorthern	
Slabs: 212 Slab Length (ft): 10.00 Slab Width (ft): 10.00 Joint Length (ft): 3,580.69	Section C	omments:	
Last Insp Date: 11/18/2021 PCI: 44 Total Samples: 8 Surveyed: 5	Inspectior	n Comments:	
Sample Number: 02			
Sample Type: R Sample PCI: 46 Sample Area (Slabs): 24	Sample C	omments:	
62 CORNER BREAK	М	1 Slabs	
63 LINEAR CR	М	8 Slabs	
65 JT SEAL DMG 72 SHAT. SLAB	M	24 Slabs 1 Slabs	
Sample Number: 04			
Sample Type: R Sample PCI: 47 Sample Area (Slabs): 21	Sample C	comments:	
63 LINEAR CR	L	4 Slabs	
63 LINEAR CR	М	6 Slabs	
65 JT SEAL DMG 72 SHAT. SLAB	M	21 Slabs 1 Slabs	
Sample Number: 05			
Sample Type: R Sample PCI: 39 Sample Area (Slabs): 15	Sample C	omments:	
63 LINEAR CR	L	5 Slabs	
63 LINEAR CR	М	5 Slabs	
65 JT SEAL DMG 72 SHAT. SLAB	H	15 Slabs 2 Slabs	
Sample Number: 06			
Sample Type: R Sample PCI: 38 Sample Area (Slabs): 15	Sample C	omments:	
63 LINEAR CR	L	5 Slabs	
63 LINEAR CR	М	5 Slabs	

Н

Н

15 Slabs

1 Slabs

Pavement Database: IA 2021 Network ID: CWI

Sample Number: 07

-			
Sample Type: R	Sample Comments:		
Sample PCI: 50			
Sample Area (Slabs): 15			
63 LINEAR CR	L	5 Slabs	
63 LINEAR CR	М	5 Slabs	
65 JT SEAL DMG	Н	15 Slabs	

Pavement Database: IA 2021 Network ID: CWI Generate Date: 4/27/2022 Page 38

Branch - Section ID: TH01CN - 02

Branch Name: T-HANGAR 01	Use: T-HANGAR
LCD: 1/1/2004 Surface Type: PCC Rank: P Section Area (sf): 4,550.00 Length (ft): 130.00 Width (ft): 35.00 From: SEE MAP To: SEE MAP	PCI Family: IowaPCCTHNorthern
Slabs: 27 Slab Length (ft): 14.40 Slab Width (ft): 11.70 Joint Length (ft): 539.86	Section Comments: avg slab width
Last Insp Date: 11/18/2021 PCI: 69 Total Samples: 1 Surveyed: 1	Inspection Comments:
Sample Number: 01	
Sample Type: R	Sample Comments:

Sample Type: R Sample PCI: 69 Sample Area (Slabs): 27 62 CORNER BREAK 63 LINEAR CR 65 JT SEAL DMG 72 SHAT. SLAB

L	1 Slabs
L	7 Slabs
Μ	27 Slabs
L	2 Slabs

Pavement Database: IA 2021 Network ID: CWI Generate Date: 4/27/2022 Page 39

Branch - Section ID: TH01CN - 03

Branch Name: T-HANGAR 01	Use: T-HANGAR
LCD: 1/1/2005 Surface Type: AAC Rank: P Section Area (sf): 17,012.00 Length (ft): 505.00 Width (ft): 35.00 From: SEE MAP To: SEE MAP	PCI Family: IowaASPHALTTHNorthern
Slabs: Slab Length (ft): Slab Width (ft): Joint Length (ft):	Section Comments:
Last Insp Date: 11/18/2021 PCI: 42 Total Samples: 4 Surveyed: 3	Inspection Comments:
Sample Number: 02	
Sample Type: R Sample PCI: 26 Sample Area (SF): 4,375	Sample Comments:

41 ALLIGATOR CR	L	50 SF
41 ALLIGATOR CR	Μ	100 SF
48 L & T CR	Н	25 Ft
48 L & T CR	L	156 Ft
48 L & T CR	Μ	525 Ft
52 RAVELING	Н	20 SF
52 RAVELING	Μ	200 SF
57 WEATHERING	Μ	4,155 SF

Sample Number: 03

Sample Type: R	Sample (Comments:	
Sample PCI: 50			
Sample Area (SF): 4,655			
41 ALLIGATOR CR	Н	3 SF	
41 ALLIGATOR CR	Μ	80 SF	
48 L & T CR	L	52 Ft	
48 L & T CR	Μ	85 Ft	
57 WEATHERING	Μ	4,655 SF	

Sample Number: 04

Sample Type: R Sample PCI: 50	Sample Comments:	
Sample Area (SF): 4,375		
41 ALLIGATOR CR	Μ	80 SF
48 L & T CR	L	72 Ft
48 L & T CR	Μ	70 Ft
57 WEATHERING	Μ	4,375 SF

APPENDIX D

WORK HISTORY REPORT

Work History Pavement Database: IA 2021

Network: CLINTON MUNICIPAL AIRPORT

A01CN - 01

Branch - Section ID:

Work	Work	Work	Cost	Thickness	Major	Comments	
Rank: P Surface: P	CC					True Area (sf):	22,346.00
Use: APR	ON					Width (ft):	180.00
LCD: 6/1/1	984					Length (ft):	200.00

Date	Code	Description		(in)	MR	
06-01-2016	SL-PC	Slab Replacement - PCC	\$0.00	0.00	False	FIELD ESTIMATE
01-01-2012	ST-MS	Surface Treatment - Micro Surface	\$0.00	0.00	False	GRIPFLEX
06-01-1984	NU-IN	New Construction - Initial	\$0.00	0.00	True	-

Branch - Section ID: A01CN - 02

LCD: 6/3/2014	
Use: APRON	
Rank: P	
Surface: PCC	

Length (ft):	100.00
Width (ft):	140.00
True Area (sf):	9,991.00

	/ork Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-03-	-2014	CR-PC	Complete Reconstruction - PCC	\$0.00	6.00	True	6" P501
06-02-	-2014	SG-CO	Subgrade - Compacted	\$0.00	6.00	False	AGG SUBGRADE
06-01-	-1984	NC-PC	New Construction - PCC	\$0.00	0.00	True	-

Branch - Section ID: A01CN - 03

Work	Work	Work	Cost	Thickness	Major	Comments	
Surface: A	C						
Rank: P						True Area (sf):	18,992.00
Use: APR	NC					Width (ft):	85.00
LCD: 1/1/1	995					Length (ft):	218.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2012	ST-SC	Surface Treatment - Seal Coat	\$0.00	0.00	False	EST
01-01-1995	CR-AC	Complete Reconstruction - AC	\$0.00	0.00	True	EST. VIA GE

Branch - Section ID: A01CN - 04

M/ a sela	M/ a sela	M/l.	0 1	Thister	Malan	0	
Surface: P	CC			-	_		
Rank: P						True Area (sf):	8,100.00
Use: APR(NC					Width (ft):	50.00
LCD: 4/1/2	2016					Length (ft):	162.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
04-01-2016	NC-PC	New Construction - PCC	\$0.00	0.00	True	FIELD EST.

Length (ft): 218.00

Work History Pavement Database: IA 2021

Branch - Section ID:

LCD: 6/1/1981 Use: APRON Rank: P Surface: PCC

Length (ft):	140.00
Width (ft):	130.00
True Area (sf):	18,725.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2021	SL-PC	Slab Replacement - PCC	\$0.00	0.00	False	EST
06-01-2021	PA-PF	Patching - PCC Full Depth	\$0.00	0.00	False	EST
06-01-2018	ST-SC	Surface Treatment - Seal Coat	\$0.00	0.00	False	-
01-01-2012	ST-MS	Surface Treatment - Micro Surface	\$0.00	0.00	False	GRIPFLEX
01-01-2012	SL-PC	Slab Replacement - PCC	\$0.00	0.00	False	-
06-01-1981	NU-IN	New Construction - Initial	\$0.00	0.00	True	-

Branch - Section ID: A02CN - 02

LCD: 5/2/2020 Use: APRON Rank: P Surface: PCC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
05-02-2020	CR-PC	Complete Reconstruction - PCC	\$323,900.00	7.00	True	7" PCC P-501
05-01-2020	SB-ST	Subbase - Stabilized	\$0.00	6.00	False	6" modified subbase
01-01-2012	ST-MS	Surface Treatment - Micro Surface	\$0.00	0.00	False	GRIPFLEX
06-10-1984	NU-IN	New Construction - Initial	\$0.00	0.00	True	-

Branch - Section ID:

A02CN - 03

A02CN - 01

LCD: 6/1/1984 Use: APRON Rank: P Surface: PCC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
01-01-2012	ST-MS	Surface Treatment - Micro Surface	\$0.00	0.00	False	GRIPFLEX
06-01-1984	NU-IN	New Construction - Initial	\$0.00	0.00	True	-

Branch - Section ID: R03CN - 01

LCD: 4/2/2010	Length (ft):	4,955.00
Use: RUNWAY	Width (ft):	100.00
Rank: P	True Area (sf):	494,870.00
Surface: PCC		

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
04.02.2010		Quarlay DCC Unhanded	0.00	9.00	True	
04-02-2010	OL-PU	Overlay - PCC Unbonded	\$0.00	8.00	True	8" P501 PCC WHITETOPPING
04-01-2010	BA-BI	Base Course - Bituminous	\$0.00	1.50	False	1.5" P403 BOND BREAKER
06-01-1994	OL-AC	Overlay - AC	\$0.00	2.00	True	2" P401 AC OVERLAY (COMPOSITE P401 THIC
06-01-1979	OL-AC	Overlay - AC	\$0.00	3.00	True	3" P401 AC OVERLAY
06-01-1969	OL-AC	Overlay - AC	\$0.00	3.00	True	3" P401 AC OVERLAY (CENTER 50')
06-03-1965	NC-AC	New Construction - AC	\$0.00	3.00	True	2-3" P401 AC
06-02-1965	BA-AG	Base Course - Aggregate	\$0.00	9.00	False	8-9" P209 CABC OR 9.5" P-304 mid RW
06-01-1965	SG-CO	Subgrade - Compacted	\$0.00	0.00	False	P152 COMPACTED SUBGRADE

Length (ft):	200.00
Width (ft):	150.00
True Area (sf):	33,191.00

Length (ft):	162.00
Width (ft):	112.00
True Area (sf):	18,060.00

Branch - Section ID:

LCD: 4/2/2010	
Use: RUNWAY	
Rank: P	
Surface: PCC	

R03CN - 02

Work Work Work Cost Thickness Major Comments Description MR Date Code (in) 04-02-2010 Overlay - PCC Unbonded 8" P501 PCC WHITETOPPING OL-PU \$0.00 8.00 True 04-01-2010 BA-BI Base Course - Bituminous \$0.00 1.00 1" P403 AC BOND BREAKER False 2" P401 AC OVERLAY 06-01-1994 OL-AC Overlay - AC \$0.00 2.00 True 3.00 06-01-1979 OL-AC Overlay - AC 3" P401 AC OVERLAY \$0.00 True 06-01-1969 OL-AC Overlay - AC \$0.00 3.00 True OUTSIDE OF INT .: 3" P401 AC OVERLAY 06-03-1965 NC-PC New Construction - PCC \$0.00 7.00 True INTERSECTION: 7" P501 PCC; OUTSIDE OF IN Base Course - Aggregate 06-02-1965 BA-AG \$0.00 8.50 False OUTSIDE OF INT .: 8-9" P209 CABC 06-02-1965 \$0.00 12.00 False INTERSECTION: 12" P154 SUBBASE (ASSUME SB-AG Subbase - Aggregate 06-01-1965 SG-CO \$0.00 0.00 False P152 COMPACTED SUBGRADE Subgrade - Compacted

Branch - Section ID: R14CN - 01

LCD: 4/2/2010 Use: RUNWAY Rank: S Surface: PCC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
04-02-2010	OL-PU	Overlay - PCC Unbonded	\$0.00	6.00	True	6" WHITETOPPING
04-01-2010	BA-BI	Base Course - Bituminous	\$0.00	1.00	False	P403 BOND BREAKER
06-03-1948	NC-PC	New Construction - PCC	\$0.00	7.00	True	7"-8" PCC
06-02-1948	SG-CO	Subgrade - Compacted	\$0.00	12.00	False	12" SAND

Branch - Section ID: T01CN - 01

LCD: 3/31/2018 Use: TAXIWAY Rank: P Surface: PCC Length (ft): Width (ft): True Area (sf):

Length (ft):

Width (ft):

True Area (sf):

Work	Work	Work	Cost	Thickness	Major	Comments
Date	Code	Description		(in)	MR	
03-31-2018	CR-PC	Complete Reconstruction - PCC	\$0.00	6.00	True	6" P501
03-30-2018	BA-AG	Base Course - Aggregate	\$0.00	6.00	False	6" Granular P-209
03-29-2018	SG-CO	Subgrade - Compacted	\$0.00	12.00	False	Subgrade
01-01-2012	ST-MS	Surface Treatment - Micro Surface	\$0.00	0.00	False	GRIPFLEX
06-01-2000	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	-
06-01-1982	NU-IN	New Construction - Initial	\$0.00	0.00	True	-

T01CN - 02

Branch - Section ID:

LCD: 4/2/2010 Use: TAXIWAY Rank: P Surface: PCC

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
04-02-2010	CR-PC	Complete Reconstruction - PCC	\$0.00	6.00	True	6" P501
04-01-2010	BA-AG	Base Course - Aggregate	\$0.00	4.00	False	4" P208
06-01-1982	NC-AC	New Construction - AC	\$0.00	0.00	True	-

Length (ft): 250.00 Width (ft): 100.00 True Area (sf): 25,000.00

Length (ft):	4,090.00
Width (ft):	75.00
True Area (sf):	319,015.00

650.00

30,107.00

45.00

63.00

50.00

3,450.00

T01CN - 03

Branch - Section ID:

LCD: 7/31/2018 Use: TAXIWAY Rank: P Surface: PCC

Length (ft):	185.00
Width (ft):	70.00
True Area (sf): 11,010.00

Work	Work	Work	Cost	Thickness	Major	Comments
Date	Code	Description		(in)	MR	
07-31-2018	CR-PC	Complete Reconstruction - PCC	\$0.00	7.00	True	7" P501
07-30-2018	BA-AG	Base Course - Aggregate	\$0.00	6.00	False	6" Granular subbase p-209
07-29-2018	SG-CO	Subgrade - Compacted	\$0.00	12.00	False	SUBGRADE
01-01-2012	ST-MS	Surface Treatment - Micro Surface	\$0.00	0.00	False	GRIPFLEX
06-01-2000	ST-SS	Surface Treatment - Slurry Seal	\$0.00	0.00	False	-
06-01-1982	NU-IN	New Construction - Initial	\$0.00	0.00	True	-

Branch - Section ID: T02CN - 01

Wo		Work	Work	Cost	Thickness	Major	Comments	
	nk: P face: P	сс					True Area (sf):	13,644.00
Use	: TAXI	WAY					Width (ft):	38.00
LCI	D: 4/2/2	010					Length (ft):	220.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
04-02-2010	NU-IN	New Construction - Initial	\$0.00	6.00	True	6" P501
04-01-2010	BA-AG	Base Course - Aggregate	\$0.00	4.00	False	4" P208

Branch - Section ID: T03CN - 01

LCD: 8/3/2011	Length (ft):	800.00
Use: TAXIWAY	Width (ft):	35.00
Rank: P	True Area (sf):	30,263.00
Surface: PCC		

Work	Work	Work	Cost	Thickness	Major	Comments
Date	Code	Description		(in)	MR	
08-03-2011	CR-PC	Complete Reconstruction - PCC	\$0.00	10.50	True	10.5" P501 PCC
08-02-2011	BA-AG	Base Course - Aggregate	\$0.00	4.00	False	4" P209 CABC
08-01-2011	SG-CO	Subgrade - Compacted	\$0.00	0.00	False	P152 COMPACTED SUBGRADE
06-01-1984	NU-IN	New Construction - Initial	\$0.00	0.00	True	-

Branch - Section ID: T03CN - 02

LCD: 6/3/2003	Length (ft):	515.00
Use: TAXIWAY	Width (ft):	35.00
Rank: P	True Area (sf):	17,928.00
Surface: PCC		

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-03-2003	NC-PC	New Construction - PCC	\$0.00	6.00	True	6" P501 PCC
06-02-2003	BA-AG	Base Course - Aggregate	\$0.00	6.00	False	6" P209 CABC
06-01-2003	SG-CO	Subgrade - Compacted	\$0.00	0.00	False	P152 COMPACTED SUBGRADE

T03CN - 03

Branch - Section ID:

LCD: 6/3/2003 Use: TAXIWAY Rank: P Surface: PCC

Surface: PCC							
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments	
06-01-2020	SL-PC	Slab Replacement - PCC	\$0.00	0.00	False	EST	
06-03-2003	NC-PC	New Construction - PCC	\$0.00	6.00	True	6" P501 PCC	
06-02-2003	BA-AG	Base Course - Aggregate	\$0.00	6.00	False	6" P209 CABC	
06-01-2003	SG-CO	Subgrade - Compacted	\$0.00	0.00	False	P152 COMPACTED SUBGRADE	

Branch - Section ID: T03CN - 04

Г	Work	Work	Work	Cost	Thickness	Major	Comments	
	Surface: P	229						
	Rank: P						True Area (sf):	8,958.00
	Use: TAXI	WAY					Width (ft):	35.00
	LCD: 6/3/2	2011					Length (ft):	245.00

Date	Code	Description	0031	(in)	MR	Comments
06-03-2011	NU-IN	New Construction - Initial	\$0.00	10.50	True	10.5" P501 PCC
06-02-2011	BA-AG	Base Course - Aggregate	\$0.00	4.00	False	4" P209 CABC
06-01-2001	SG-CO	Subgrade - Compacted	\$0.00	0.00	False	P152 COMPACTED SUBGRADE

Branch - Section ID: T04CN - 01

Work	Work	Work	Cost	Thickness	Major	Comments	
Surface: A	AC						
Rank: P						True Area (sf):	29,958.00
Use: TAXI	WAY					Width (ft):	25.00
LCD: 6/1/2	2002					Length (ft):	1,085.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
01-01-2012	ST-MS	Surface Treatment - Micro Surface	\$0.00	0.00	False	GRIPFLEX
06-01-2002	OL-AC	Overlay - AC	\$0.00	0.00	True	-
06-01-1982	NC-AC	New Construction - AC	\$0.00	0.00	True	-

Branch - Section ID: T04CN - 02

LCD: 1/3/2 Use: TAXI Rank: P Surface: P	WAY					Length (ft): Width (ft): True Area (sf):	100.00 36.00 3,600.00
Work	Work	Work	Cost	Thickness	Major	Comments	

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
01-01-2012	ST-MS	Surface Treatment - Micro Surface	\$0.00	0.00	False	EST. VIA GE
01-03-2002	NC-PC	New Construction - PCC	\$0.00	6.00	True	6" P-501 PCC
01-02-2002	SB-AG	Subbase - Aggregate	\$0.00	6.00	False	6" P-154 SUBBASE
01-01-2002	SG-CO	Subgrade - Compacted	\$0.00	6.00	False	COMPACTED SUBGRADE

Length (ft): 4,039.00 Width (ft): 35.00 True Area (sf): 142,497.00

Longth (ft).

04-02-2010

04-01-2010

NU-IN

BA-AG

New Construction - Initial

Base Course - Aggregate

Work History Pavement Database: IA 2021

		Fav		ase. IA 20	121		
Branch - S	Section	ID: T05CN - 01					
LCD: 6/1/2 Use: TAX Rank: P						Length (ft): Width (ft): True Area (sf):	266.00 35.00 12,269.00
Surface: F	PCC						12,200.00
Work	Work	Work	Cost	Thickness	Malar	Comments	
Date	Code	Description	COSI	(in)	Major MR	Comments	
06-01-2003	NU-IN	New Construction - Initial	\$93,872.00	0.00	True	Total Project Cost \$1,173,399	
Branch - S	Section	ID: T05CN - 02					
LCD: 6/2/2	2011					Length (ft):	95.00
Use: TAX	IWAY					Width (ft):	40.0
Rank: P Surface: F	PCC					True Area (sf):	4,708.0
Work	Work	Work	Cost	Thickness	Major	Comments	
Date	Code	Description		(in)	MR		
06-02-2011	NU-IN	New Construction - Initial	\$0.00	10.50	True	10.5" P501	
06-01-2011	BA-AG	Base Course - Aggregate	\$0.00	4.00	False	4" P208	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments	
06-03-2003	NC-PC	New Construction - PCC	\$0.00	6.00	True	6" P501 PCC	
06-02-2003	BA-AG	Base Course - Aggregate	\$0.00	6.00	False	6" P209 CABC	
06-01-2003	SG-CO	Subgrade - Compacted	\$0.00	0.00	False	P152 COMPACTED SUBGRADE	
Branch - S	Section	ID: T06CN - 02					
LCD: 6/3/2	2011					Length (ft):	215.0
Use: TAX	IWAY					Width (ft):	40.0
Rank: P Surface: F	occ					True Area (sf):	8,296.0
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments	
06-03-2011	NC-PC	New Construction - PCC	\$0.00	6.00	True	6" P501 PCC	
06-02-2011	BA-AG	Base Course - Aggregate	\$0.00	6.00	False	6" P209 CABC	
06-01-2011	SG-CO	Subgrade - Compacted	\$0.00	0.00	False	P152 COMPACTED SUBGRADE	
Branch - S	Section	ID: T07CN - 01					
LCD: 4/2/2	2010					Length (ft):	220.0
Use: TAX	IWAY					Width (ft):	40.0
Rank: P						True Area (sf):	13,646.0
Surface: F		NAT - sta	01	Th:-!	M - 1	lo munto	
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments	
	1	· · · · · · · · · · · · · · · · · · ·	1	i			

\$0.00

\$0.00

10.50

4.00

True

False

10.5" P501

4" P208

TH01CN - 01

Branch - Section ID:

LCD: 1/3/2002 Use: T-HANGAR Rank: P Surface: PCC

Length (ft):	440.00
Width (ft):	35.00
True Area (sf):	21,168.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
01-03-2002	NC-PC	New Construction - PCC	\$0.00	6.00	True	6" P-501 PCC
01-02-2002	SB-AG	Subbase - Aggregate	\$0.00	6.00	False	6" P-154 SUBBASE
01-01-2002	SG-CO	Subgrade - Compacted	\$0.00	6.00	False	6" P152 COMPACTED SUBGRADE

Branch - Section ID: TH01CN - 02

LCD: 1/1/2004 Use: T-HANGAR	Length (ft): Width (ft):	130.00 35.00
Rank: P	True Area (sf):	4,550.00
Surface: PCC		

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
01-01-2004	CR-PC	Complete Reconstruction - PCC	\$0.00	0.00	True	ESTIMATED

Branch - Section ID: TH01CN - 03

LCD: 1/1/2 Use: T-HA Rank: P Surface: A	NGAR					Length (ft): Width (ft): True Area (sf):	505.00 35.00 17,012.00
Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments	

Date	Work Code	Work Description	Cost	inickness (in)	Major MR	Comments
06-01-2012	ST-MS	Surface Treatment - Micro Surface	\$0.00	0.00	False	GRIPFLEX
01-01-2005	OL-AC	Overlay - AC	\$0.00	0.00	True	EST. VIA GE

APPENDIX E

LOCALIZED PREVENTIVE MAINTENANCE POLICIES AND UNIT COST TABLES

Distress Type	Severity Level	Maintenance Action
Alligator Cracking	Low	Monitor
Alligator Cracking	Medium	Asphalt Patch
Alligator Cracking	High	Asphalt Patch
Bleeding	N/A	Monitor
Block Cracking	Low	Monitor
Block Cracking	Medium	Crack Seal—Asphalt
Block Cracking	High	Crack Seal—Asphalt
Corrugation	Low	Monitor
Corrugation	Medium	Asphalt Patch
Corrugation	High	Asphalt Patch
Depression	Low	Monitor
Depression	Medium	Monitor
Depression	High	Asphalt Patch
Jet-Blast Erosion	N/A	Asphalt Patch
Joint Reflection Cracking	Low	Monitor
Joint Reflection Cracking	Medium	Crack Seal—Asphalt
Joint Reflection Cracking	High	Crack Seal—Asphalt
L&T Cracking	Low	Monitor
L&T Cracking	Medium	Crack Seal—Asphalt
L&T Cracking	High	Crack Seal—Asphalt
Oil Spillage	N/A	Asphalt Patch
Patching	Low	Monitor
Patching	Medium	Asphalt Patch
Patching	High	Asphalt Patch
Polished Aggregate	N/A	Monitor
Raveling	Low	Monitor
Raveling	Medium	Asphalt Patch
Raveling	High	Asphalt Patch
Rutting	Low	Monitor
Rutting	Medium	Monitor
Rutting	High	Asphalt Patch
Shoving	Low	Monitor
Shoving	Medium	Asphalt Patch
Shoving	High	Asphalt Patch
Slippage Cracking	N/A	Asphalt Patch
Swelling	Low	Monitor
Swelling	Medium	Monitor
Swelling	High	Asphalt Patch
Weathering	Low	Monitor
Weathering	Medium	Monitor
Weathering	High	Asphalt Patch

	Severity	
Distress Type	Level	Maintenance Action
ASR	Low	Monitor
ASR	Medium	Slab Replacement
ASR	High	Slab Replacement
Blowup	Low	Slab Replacement
Blowup	Medium	Slab Replacement
Blowup	High	Slab Replacement
Corner Break	Low	Crack Seal—PCC
Corner Break	Medium	Full Depth PCC Patch
Corner Break	High	Full Depth PCC Patch
Durability Cracking	Low	Monitor
Durability Cracking	Medium	Full Depth Patch
Durability Cracking	High	Slab Replacement
Faulting	Low	Monitor
Faulting	Medium	Grinding
Faulting	High	Slab Replacement
Joint Seal Damage	Low	Monitor
Joint Seal Damage	Medium	Joint Seal
Joint Seal Damage	High	Joint Seal
LTD Cracking	Low	Monitor
LTD Cracking	Medium	Crack Seal—PCC
LTD Cracking	High	Slab Replacement
Patching (Small and Large)	Low	Monitor
Patching (Small and Large)	Medium	Full Depth PCC Patch
Patching (Small and Large)	High	Full Depth PCC Patch
Popouts	N/A	Monitor
Pumping	N/A	Monitor
Scaling	Low	Monitor
Scaling	Medium	Partial Depth PCC Patch
Scaling	High	Slab Replacement
Shattered Slab	Low	Crack Seal—PCC
Shattered Slab	Medium	Slab Replacement
Shattered Slab	High	Slab Replacement
Shrinkage Cracking	N/A	Monitor
Spalling (Joint and Corner)	Low	Monitor
Spalling (Joint and Corner)	Medium	Partial Depth PCC Patch
Spalling (Joint and Corner)	High	Partial Depth PCC Patch

Table E-2. Localized preventive maintenance	policy, PCC pavements.
---	------------------------

Maintenance Action	Unit Cost
Asphalt Patch—Asphalt-Surfaced Pavement	\$14.66/sf
Crack Sealing—Asphalt-Surfaced Pavement	\$2.51/lf
Partial Depth PCC Patch—PCC Pavement	\$37.54/sf
Full Depth PCC Patch—PCC Pavement	\$16.76/sf
Crack Sealing—PCC Pavement	\$3.02/lf
Joint Sealing—PCC Pavement	\$3.02/lf
Grinding—PCC Pavement	\$0.36/sf
Slab Replacement—PCC Pavement	\$16.76/sf

Table E-3. 2022 unit costs for preventive maintenance actions.

Table E-4. 2022 unit costs (per square foot) based on pavement type and PCI ranges.

Pavement Type	PCI Range 0–40	PCI Range 40–50	PCI Range 50–60	PCI Range 60-70	PCI Range 70–80	PCI Range 80–90	PCI Range 90–100
AC	\$10.41	\$4.93	\$4.93	\$4.93	\$0.00	\$0.00	\$0.00
PCC	\$17.38	\$8.22	\$8.22	\$8.22	\$0.00	\$0.00	\$0.00

APPENDIX F

YEAR 2022 LOCALIZED PREVENTIVE MAINTENANCE DETAILS

Branch	Section	Distress Type	Severity	Distress Quantity	Distress Unit	Maintenance Action	Unit Cost	2022 Estimated Cost
A01CN	02	Corner Break	Low	1	Slabs	Crack Sealing - PCC	\$3.02	\$34
A01CN	02	Joint Seal Damage	Medium	83	Slabs	Joint Seal (Localized)	\$3.02	\$5,014
R03CN	01	LTD Cracking	Medium	30	Slabs	Crack Sealing - PCC	\$3.02	\$1,114
R03CN	01	Shattered Slab	Low	10	Slabs	Crack Sealing - PCC	\$3.02	\$742
R03CN	02	Corner Spalling	Medium	2	Slabs	Patching - PCC Partial Depth	\$37.54	\$162
R03CN	02	Joint Seal Damage	Medium	160	Slabs	Joint Seal (Localized)	\$3.02	\$11,023
R14CN	01	Corner Break	Medium	26	Slabs	Patching - PCC Full Depth	\$16.76	\$13,814
R14CN	01	Corner Spalling	Medium	9	Slabs	Patching - PCC Partial Depth	\$37.54	\$860
R14CN	01	Joint Seal Damage	Medium	1,021	Slabs	Joint Seal (Localized)	\$3.02	\$70,533
R14CN	01	Joint Seal Damage	High	408	Slabs	Joint Seal (Localized)	\$3.02	\$28,213
R14CN	01	Joint Spalling	Medium	17	Slabs	Patching - PCC Partial Depth	\$37.54	\$4,126
R14CN	01	LTD Cracking	Medium	34	Slabs	Crack Sealing - PCC	\$3.02	\$1,285
T01CN	02	Corner Break	Low	1	Slabs	Crack Sealing - PCC	\$3.02	\$25
T01CN	02	Joint Seal Damage	Medium	24	Slabs	Joint Seal (Localized)	\$3.02	\$1,366
T01CN	02	Small Patch	Medium	1	Slabs	Patching - PCC Full Depth	\$16.76	\$45
T01CN	03	LTD Cracking	Medium	3	Slabs	Crack Sealing - PCC	\$3.02	\$85
T02CN	01	Joint Seal Damage	Medium	136	Slabs	Joint Seal (Localized)	\$3.02	\$6,572
T02CN	01	Joint Spalling	Medium	2	Slabs	Patching - PCC Partial Depth	\$37.54	\$411
T03CN	01	Corner Spalling	Medium	3	Slabs	Patching - PCC Partial Depth	\$37.54	\$270

Table F-1. Year 2022 localized preventive maintenance details.

							1	
				D . (D . (T T •/	2022
	a		a	Distress	Distress		Unit	Estimated
Branch	Section	Distress Type	Severity	Quantity	Unit	Maintenance Action	Cost	Cost
T03CN	01	Joint Seal Damage	Medium	53	Slabs	Joint Seal (Localized)	\$3.02	\$2,463
T03CN	02	Joint Seal Damage	Medium	67	Slabs	Joint Seal (Localized)	\$3.02	\$3,236
T03CN	02	Small Patch	Medium	5	Slabs	Patching - PCC Full Depth	\$16.76	\$226
T03CN	03	Joint Seal Damage	Medium	175	Slabs	Joint Seal (Localized)	\$3.02	\$8,569
T03CN	03	Joint Spalling	Medium	1	Slabs	Patching - PCC Partial Depth	\$37.54	\$242
T03CN	04	Corner Break	Medium	1	Slabs	Patching - PCC Full Depth	\$16.76	\$657
T03CN	04	LTD Cracking	Medium	1	Slabs	Crack Sealing - PCC	\$3.02	\$34
T05CN	01	Corner Break	Low	2	Slabs	Crack Sealing - PCC	\$3.02	\$38
T05CN	01	Joint Seal Damage	Medium	146	Slabs	Joint Seal (Localized)	\$3.02	\$6,896
T05CN	01	LTD Cracking	Medium	2	Slabs	Crack Sealing - PCC	\$3.02	\$43
T06CN	01	Corner Break	Low	1	Slabs	Crack Sealing - PCC	\$3.02	\$25
T06CN	01	Joint Spalling	Medium	1	Slabs	Patching - PCC Partial Depth	\$37.54	\$246
T07CN	01	Joint Seal Damage	Medium	156	Slabs	Joint Seal (Localized)	\$3.02	\$7,613

Table F-1. Year 2022 localized preventive maintenance details (continued).

Table Notes:

- 1. See Figure 3 for the location of the branch and section.
- 2. Distress types are defined by ASTM D5340-20. L&T Cracking = Longitudinal and Transverse Cracking; LTD Cracking = Longitudinal, Transverse, and Diagonal Cracking; ASR = Alkali-Silica Reaction.
- 3. The costs provided are of a general nature for the entire state and may require adjustment to reflect specific conditions at Clinton Municipal Airport.

PREPARED FOR

lowa Department of Transportation Modal Transportation Bureau — Aviation 800 Lincoln Way Ames, Iowa 50010 515-239-1691 iowadot.gov/aviation

JULY 2022