

Davenport Municipal Airport



Pavement Management Report

PREPARED BY

Applied Pavement Technology, Inc.
115 West Main Street, Suite 400
Urbana, Illinois 61801
(217) 398-3977
www.appliedpavement.com

JULY 2023



The preparation of this document was financed in part through an Airport Improvement Program grant from the Federal Aviation Administration (Project Number 3-19-0000-030-2022) as provided under Section 505 of the Airport and Airway Improvement Act of 1982, as amended. The contents do not necessarily reflect the DOT's official views or the policy of the FAA. Acceptance of this report by the FAA does not in any way constitute a commitment on the part of the United States to participate in any development depicted therein nor does it indicate the proposed development is environmentally acceptable in accordance with appropriate public laws.

DAVENPORT MUNICIPAL AIRPORT PAVEMENT MANAGEMENT REPORT

Prepared For:




Iowa Department of Transportation
Modal Transportation Bureau
800 Lincoln Way
Ames, Iowa 50010
515-239-1691
<https://iowadot.gov/aviation/>

Prepared By:



Applied Pavement Technology, Inc.
115 West Main Street, Suite 400
Urbana, Illinois 61801
217-398-3977
<https://www.appliedpavement.com>

In Association With:



Robinson Engineering Company
Consulting Engineers
819 Second Street NE
Independence, Iowa 50644
319-334-7211

TABLE OF CONTENTS

INTRODUCTION	1
PAVEMENT INVENTORY	3
PAVEMENT EVALUATION.....	6
Pavement Evaluation Procedure	6
Pavement Evaluation Results.....	7
Inspection Comments.....	15
Runways.....	15
Taxiways.....	15
Aprons.....	16
T-Hangar	16
PAVEMENT MAINTENANCE AND REHABILITATION PROGRAM	18
Analysis Parameters.....	18
Critical PCIs.....	18
Localized Preventive Maintenance Policies and Unit Costs.....	18
Major Rehabilitation Unit Costs	18
Budget and Inflation Rate	18
Analysis Approach.....	18
Analysis Results.....	19
General Maintenance Recommendations	20
FAA Requirements (Public Law 103-305).....	20
FAA Advisory Circular 150/5830-7B, Appendix A. Pavement Management Program (PMP)	21
SUMMARY	28

LIST OF FIGURES

Figure 1. Pavement condition versus cost of repair.....	1
Figure 2. Pavement area by branch use at Davenport Municipal Airport.	4
Figure 3. Davenport Municipal Airport network definition map.	5
Figure 4. Visual representation of PCI scale on typical pavement surfaces.	6
Figure 5. PCI versus repair type.	7
Figure 6. Pavement area by PCI range at Davenport Municipal Airport.....	8
Figure 7. Area-weighted PCI by branch use at Davenport Municipal Airport.	9
Figure 8. Davenport Municipal Airport PCI map.	10

LIST OF TABLES

Table 1. 2022 pavement evaluation results.....	11
Table 2. 5-year M&R program under an unlimited funding analysis scenario.	19
Table 3. Pavement inspection report.....	23

APPENDIXES

Appendix A. Cause of Distress Tables A-1
Appendix B. Inspection PhotographsB-1
Appendix C. Inspection Report.....C-1
Appendix D. Work History Report..... D-1
Appendix E. Localized Preventive Maintenance Policies and Unit Cost TablesE-1
Appendix F. Year 2023 Localized Preventive Maintenance Details F-1


INTRODUCTION

Applied Pavement Technology, Inc. (APTech), with assistance from Robinson Engineering Company Consulting Engineers (Robinson), updated the Airport Pavement Management System (APMS) for the Iowa Department of Transportation, Modal Transportation Bureau (Iowa DOT). The APMS provides a means to monitor the condition of the pavements within the state of Iowa and to proactively plan for their preservation.

As part of this project, pavement conditions at Davenport Municipal Airport were assessed in February 2023 using the Pavement Condition Index (PCI) procedure. During a PCI inspection, the types, severities, and amounts of distress present in a pavement are quantified. This information is then used to develop a composite index that represents the overall condition of the pavement in numerical terms, ranging from 0 (failed) to 100 (excellent). The PCI provides an overall measure of condition and an indication of the level of work that will be required to maintain or repair a pavement. The distress information also provides insight into what is causing the pavement to deteriorate, which is the first step in selecting the appropriate repair action to correct the problem.

Programmed into an APMS, PCI information is used to determine when preventive maintenance actions (such as crack or joint sealing) are advisable and to identify the most cost-effective time to perform major rehabilitation (such as an overlay or whitetopping). Delaying maintenance and rehabilitation (M&R) until a pavement structure has seriously degraded can cost many times more than if M&R was applied earlier in a pavement's life cycle, as shown in Figure 1. From a safety perspective, pavement distresses, such as cracks and loose debris, may pose risks in terms of the potential for aircraft tire damage and the ability of a pilot to safely control aircraft.

Figure 1. Pavement condition versus cost of repair.



The pavement evaluation results for Davenport Municipal Airport are presented within this report and can be used by Davenport Municipal Airport, the Iowa DOT, and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement M&R actions at the airport. In addition to this report, the web-based interactive pavement data visualization tool IDEA, containing the information collected during this project, was updated and may be accessed from the [Iowa DOT's website](#) or directly ([Iowa APMS IDEA](#)).

PAVEMENT INVENTORY

The project began with a review of the existing inventory information pertaining to the pavements at Davenport Municipal Airport. The date of original construction, along with the date of any subsequent rehabilitation; the location of completed work; and the type of work undertaken were gathered. The information was used to update the pavement management database and associated maps, as necessary, to account for pavement-related work that had been undertaken since the last time the airport was evaluated in 2019.

The pavement network at Davenport Municipal Airport was then divided into branches, sections, and sample units. A branch is a single entity that serves a distinct function. For example, a runway is considered a branch because it serves a single function (allowing aircraft to take off and land). Taxiways, aprons, and T-hangars are also separate branches.

Each branch was further divided into sections. Traditionally, sections are defined as parts of the branch that share common attributes, such as cross-section, date of last construction, traffic level, and performance. Using this approach, if a runway was built in 1968 and then extended in 1984, it would contain two separate sections.

To estimate the overall condition of a pavement section, each section was subdivided into sample units. Portions of these sample units were evaluated during the pavement inspection, and the collected information was extrapolated to predict the overall section condition and quantities of distress.

Approximately 1,826,700 square feet of pavement were evaluated at Davenport Municipal Airport, as illustrated in Figure 2. This figure also shows the area-weighted age, in years, of the pavements at the time of the inspection. Figure 3 provides a map that details how the pavement network was divided into management units and identifies the sample units that were evaluated during the pavement inspection at Davenport Municipal Airport.

Figure 2. Pavement area by branch use at Davenport Municipal Airport.





FIGURE 3. NETWORK DEFINITION MAP.



NETWORK DEFINITION LEGEND

	BRANCH IDENTIFIER
	SECTION IDENTIFIER
	PCI VALUE
	SAMPLE UNIT BREAK LINE
	SLAB JOINT
	SAMPLE UNIT NUMBER
	SAMPLE UNIT INSPECTED
	ADDITIONAL SAMPLE UNIT

applied pavement TECHNOLOGY
 115 W. Main Street, Suite 400
 Urbana, IL 61801
 Tel: 217-398-3977
 Fax: 217-398-4027

AGENCY: Iowa Department of Transportation
 Modal Transportation Bureau

LOCATION: Davenport Municipal Airport
 Davenport, Iowa

PAGE TITLE: Network Definition Map

PROJECT DATE: OCT. 2022	CREATION DATE: OCT. 2022	PROJECT MANAGER: LJR	JOB NUMBER: 2021-125-AM01
DRAWING SCALE: 1"=200'	LAST MODIFIED DATE: JAN. 2023	REVISED BY: DMS	DRAWN BY: KEW
FILENAME: Davenport.dwg	LAYOUT NAME/NUMBER: NET. DEF.	PAGE NUMBER: 5	

PAVEMENT EVALUATION


Pavement Evaluation Procedure

APTech inspected the pavements at Davenport Municipal Airport using the PCI procedure described in:

- FAA Advisory Circular 150/5380-6C, [Guidelines and Procedures for Maintenance of Airport Pavements](#).
- FAA Advisory Circular 150/5380-7B, [Airport Pavement Management Program \(PMP\)](#).
- ASTM D5340-20, *Standard Test Method for Airport Pavement Condition Index Surveys*.

The PCI provides a numerical indication of overall pavement condition, as illustrated in Figure 4. The types and amounts of deterioration are used to calculate the PCI of the section. The PCI ranges from a value of 0, which represents a pavement in a failed condition, to a value of 100, which represents a pavement in excellent condition. It is important to note that factors other than overall PCI need to be considered when identifying the appropriate type of repair, including types of distress present and rate of deterioration. Also, since the PCI does not assess the structural integrity or capacity of the pavement structure, further testing may be needed to validate and refine the treatment strategy.

Figure 4. Visual representation of PCI scale on typical pavement surfaces.



Note: Photographs shown are not specific to Davenport Municipal Airport.

Generally, pavements with relatively high PCIs that are not exhibiting significant load-related distress will benefit from preventive maintenance actions, such as crack sealing or joint resealing. As the PCI drops, the pavements may require major rehabilitation, such as an overlay or whitetopping. In some situations where the PCI has dropped low enough, reconstruction may be the only viable alternative due to the substantial damage to the pavement structure. Figure 5 illustrates how the appropriate repair type varies with the PCI of a pavement section and provides the corresponding colors used for the maps and charts in this report for each range of PCIs.

Figure 5. PCI versus repair type.

PCI Range	Repair
86-100	Preventive Maintenance
71-85	
56-70	
41-55	Major Rehabilitation
26-40	Reconstruction
11-25	
0-10	

The types of distress identified during the PCI inspection provide insight into the cause of pavement deterioration, which is useful when selecting M&R strategies. Understanding the cause of distress helps in selecting a rehabilitation alternative that corrects the cause and thus eliminates or delays its recurrence. PCI distress types are characterized as:

- Load-related—These distress types are defined as being caused by aircraft or vehicular traffic and may indicate a structural deficiency. Examples of load-related distress include alligator cracking on asphalt-surfaced pavements and corner breaks on portland cement concrete (PCC) pavements.
- Climate/durability-related—These distress types often signify the presence of aged or environmentally susceptible (or both) material and include durability-related issues. Examples of climate/durability-related distress include weathering on asphalt-surfaced pavements, which is climate-related, and durability cracking on PCC pavements, which is durability-related.
- Other—Distress types that fall into this category cannot be attributed solely to load or climate/durability. Examples of this type of distress include depressions on asphalt-surfaced pavements and shrinkage cracking on PCC pavements.

Appendix A identifies the distress types considered during a PCI inspection and describes the likely cause of each distress type. It should be noted that a PCI is based on visual signs of pavement deterioration and does not provide a measure of structural capacity.

Pavement Evaluation Results

The pavements at Davenport Municipal Airport were inspected in February 2023. The 2022 area-weighted condition of Davenport Municipal Airport is 78, with conditions ranging from 6 to 98 (on a scale of 0 [failed] to 100 [excellent]). During the previous pavement inspection in 2019, the area-weighted PCI of the airport was 74.

Figure 6 summarizes the overall condition of the pavements at Davenport Municipal Airport, and Figure 7 presents area-weighted condition (average PCI adjusted to account for the relative size of the pavement sections) by branch use. Figure 8 is a map that displays the condition of the evaluated pavements. Table 1 summarizes the results of the pavement evaluation. Appendix B presents photographs taken during the PCI inspection, and Appendix C contains detailed information on the distress types observed during the visual survey. Appendix D includes detailed work history information that was collected during the record review process.

Figure 6. Pavement area by PCI range at Davenport Municipal Airport.




Figure 7. Area-weighted PCI by branch use at Davenport Municipal Airport.
(Values on chart are area-weighted)





FIGURE 8. PCI MAP.



LEGEND

- BRANCH IDENTIFIER
- SECTION IDENTIFIER
- PCI VALUE
- SECTION BREAK LINE

PAVEMENT CONDITION INDEX

PCI
86-100
71-85
56-70
41-55
26-40
11-25
0-10

applied pavement TECHNOLOGY
 115 W. Main Street, Suite 400
 Urbana, IL 61801
 Tel: 217-398-3977
 Fax: 217-398-4027

Robinson Engineering Company
 Consulting Engineers
 819 Second Street NE
 Independence, Iowa 50644
 319-334-7211

AGENCY: Iowa Department of Transportation
 Modal Transportation Bureau

LOCATION: Davenport Municipal Airport
 Davenport, Iowa

PAGE TITLE: 2022 Pavement Condition Index Map

PROJECT DATE: OCT. 2022	CREATION DATE: OCT. 2022	PROJECT MANAGER: LJR	JOB NUMBER: 2021-125-AM01
DRAWING SCALE: 1"=200'	LAST MODIFIED DATE: MAR. 2023	REVISED BY: DMS	DRAWN BY: KEW
FILENAME: Davenport.dwg	LAYOUT NAME/NUMBER: PCI	PAGE NUMBER: 10	

Table 1. 2022 pavement evaluation results.

Branch	Section	Surface Type	Section Area (sf)	LCD	2022 PCI	% Distress Due to Load	% Distress Due to Climate/Durability	% Distress Due to Other	Type of Distress
A01DA	01	PCC	45,000	6/2/1949	40	39	12	49	ASR, Corner Break, Corner Spalling, Joint Spalling, Joint Seal Damage, LTD Cracking, Popouts, Pumping, Shrinkage Cracking, Small Patch
A02DA	01	PCC	61,421	6/1/2001	59	53	10	37	ASR, Corner Break, Corner Spalling, Faulting, Joint Spalling, Joint Seal Damage, LTD Cracking, Scaling, Shattered Slab, Shrinkage Cracking, Small Patch
A02DA	02	PCC	17,878	8/1/1996	83	24	71	5	Corner Break, Corner Spalling, Joint Spalling, Joint Seal Damage, LTD Cracking
A03DA	01	PCC	28,137	6/2/1949	6	78	7	15	Corner Break, Corner Spalling, Joint Spalling, Joint Seal Damage, LTD Cracking, Shattered Slab
A04DA	01	PCC	63,183	6/2/1949	35	81	12	7	Corner Break, Corner Spalling, Joint Spalling, Joint Seal Damage, LTD Cracking, Shattered Slab, Shrinkage Cracking
R03DA	01	PCC	389,389	6/3/2015	95	0	90	10	Faulting, Joint Seal Damage
R15DA	01	PCC	270,860	4/3/2019	96	0	100	0	Joint Seal Damage
R15DA	02	PCC	125,500	6/30/1994	92	0	85	15	Corner Spalling, Faulting, Joint Seal Damage, Popouts, Small Patch
R15DA	03	PCC	157,200	6/3/2015	96	0	100	0	Joint Seal Damage
T01DA	01	PCC	55,043	6/2/1949	83	13	25	62	ASR, Faulting, Joint Spalling, Joint Seal Damage, LTD Cracking, Scaling, Shrinkage Cracking

Table 1. 2022 pavement evaluation results (continued).

Branch	Section	Surface Type	Section Area (sf)	LCD	2022 PCI	% Distress Due to Load	% Distress Due to Climate/Durability	% Distress Due to Other	Type of Distress
T01DA	02	PCC	78,251	6/1/1949	56	7	25	68	ASR, Corner Break, Corner Spalling, Joint Spalling, Joint Seal Damage, Large Patch, LTD Cracking, Popouts, Shrinkage Cracking, Small Patch
T01DA	03	PCC	22,277	6/2/1949	25	35	11	54	ASR, Corner Break, Joint Spalling, Joint Seal Damage, Large Patch, LTD Cracking, Small Patch
T01DA	04	PCC	57,742	6/2/1949	88	0	13	87	ASR, Corner Spalling, Joint Spalling, Joint Seal Damage, Large Patch, Popouts, Scaling, Shrinkage Cracking, Small Patch
T01DA	05	PCC	23,533	6/3/2015	93	77	23	0	Corner Break, Joint Seal Damage, LTD Cracking
T01DA	06	PCC	40,715	4/3/2019	98	35	65	0	Joint Seal Damage, LTD Cracking
T02DA	01	PCC	3,040	6/1/1979	35	25	13	62	ASR, Corner Break, Faulting, Joint Seal Damage, LTD Cracking, Popouts, Shattered Slab
T02DA	02	PCC	10,494	1/1/2005	85	27	8	65	ASR, Corner Break, Corner Spalling, Joint Spalling, Joint Seal Damage, LTD Cracking, Popouts
T02DA	03	PCC	62,872	6/1/1979	41	75	12	13	ASR, Corner Spalling, Faulting, Joint Spalling, Joint Seal Damage, LTD Cracking, Shattered Slab
T02DA	04	PCC	10,542	6/3/2015	98	0	100	0	Joint Seal Damage
T03DA	01	PCC	62,394	6/2/1949	25	78	12	10	Corner Break, Corner Spalling, Joint Spalling, Joint Seal Damage, LTD Cracking, Shattered Slab, Shrinkage Cracking

Table 1. 2022 pavement evaluation results (continued).

Branch	Section	Surface Type	Section Area (sf)	LCD	2022 PCI	% Distress Due to Load	% Distress Due to Climate/Durability	% Distress Due to Other	Type of Distress
T03DA	02	PCC	17,612	6/1/1947	60	3	4	93	ASR, Joint Spalling, Joint Seal Damage, Large Patch, LTD Cracking, Shrinkage Cracking, Small Patch
T03DA	03	PCC	16,547	4/3/2019	98	0	100	0	Joint Seal Damage
T04DA	01	PCC	7,628	6/1/1948	12	42	8	50	ASR, Joint Seal Damage, Large Patch, LTD Cracking, Popouts, Shattered Slab, Small Patch
T05DA	01	PCC	7,628	6/1/1948	18	44	8	48	ASR, Corner Break, Faulting, Joint Seal Damage, Large Patch, LTD Cracking, Popouts, Shattered Slab
T06DA	01	PCC	13,887	8/1/1996	84	24	68	8	Corner Spalling, Joint Spalling, Joint Seal Damage, LTD Cracking
T07DA	01	PCC	62,407	6/30/1994	88	0	71	29	ASR, Faulting, Joint Spalling, Joint Seal Damage
TH01DA	01	AAC	10,915	6/1/2008	26	56	44	0	Alligator Cracking, L&T Cracking, Weathering
TH01DA	02	AC	42,929	1/2/1949	16	52	42	6	Alligator Cracking, Block Cracking, L&T Cracking, Patching, Raveling, Rutting, Swelling, Weathering
TH01DA	03	PCC	42,763	10/1/2010	95	17	31	52	Faulting, Joint Seal Damage, Large Patch, LTD Cracking
TH01DA	04	PCC	18,886	10/2/2005	91	20	65	15	Corner Break, Corner Spalling, Joint Spalling, Joint Seal Damage, LTD Cracking

Table Notes:

1. See Figure 3 for the location of the branch and section.
2. Surface Type: AC = asphalt cement concrete; AAC = asphalt overlay on AC; PCC = portland cement concrete; APC = asphalt overlay on PCC.

Table 1. 2022 pavement evaluation results (continued).

3. LCD = last construction date.
4. Distress due to load includes distress types that are attributed to a structural deficiency in the pavement, such as alligator cracking or rutting on asphalt-surfaced pavements or shattered slabs on PCC pavements.
5. Distress due to climate or durability includes distress types that are attributed to either the aging of the pavement and the effects of the environment (such as weathering, raveling, or block cracking on asphalt-surfaced pavements) or to a materials-related problem (such as durability cracking or alkali-silica reaction [ASR] on PCC pavements). If materials-related distresses were recorded during the inspection, further laboratory testing is required to definitively determine the type present.
6. Distress due to other refers to distress types that are not attributed to one factor but rather may be caused by a combination of factors.
7. Distress types are defined by ASTM D5340-20. L&T Cracking = Longitudinal and Transverse Cracking; LTD Cracking = Longitudinal, Transverse, and Diagonal Cracking; ASR = Alkali-Silica Reaction.

Inspection Comments

Davenport Municipal Airport was inspected on February 21, 2023. There were thirty pavement sections defined during the inspection. Suspected alkali-silica reaction (ASR) was recorded at this airport in accordance with ASTM D5340-20. It should be noted that laboratory testing in the form of petrographic analysis is the only definitive way to validate the presence of ASR; however, the formation of a precipitate is evidence of a reaction consistent with this type of materials-related distress.

Runways

Runway 03/21 was defined by one section in excellent condition with areas of low-severity faulting and low- and medium-severity joint seal damage identified.

Runway 15/33 consisted of three sections. Sections 01 and 03 were both in excellent condition with low- and medium-severity joint seal damage noted throughout. Areas of low- and medium-severity corner spalling, low-severity faulting and small patching, all severities of joint seal damage, and popouts were observed in Section 02.

Taxiways

Taxiway 01 was defined by six sections. Section 01 contained areas of low- and medium-severity ASR and joint seal damage; low-severity faulting, scaling, and joint spalling; and shrinkage cracking. An atypical area of medium-severity longitudinal, transverse, and diagonal (LTD) cracking was observed and recorded as an additional sample unit in accordance with ASTM D5340-20. All severities of ASR and joint seal damage; medium-severity corner break and joint spalling; low-severity corner spalling, small patching, and large patching; low- and medium-severity LTD cracking; popouts; and shrinkage cracking were identified in Section 02. Section 03 was in poor condition with areas of low- and medium-severity ASR and large patching, low-severity corner break; low- and high-severity joint seal damage and small patching; medium-severity joint spalling; and all severities of LTD cracking recorded. Section 04 contained low-severity ASR, joint seal damage, joint spalling, and large patching; low- and medium-severity corner spalling; popouts; medium-severity scaling; shrinkage cracking; and low- and high-severity small patching throughout. Areas of low-severity corner break, joint seal damage, and LTD cracking were identified in Section 05. Section 06 was in excellent condition with low-severity joint seal damage noted throughout. An atypical area of low-severity LTD cracking was observed and recorded as an additional sample unit in accordance with ASTM D5340-20.

Taxiway 02 contained four sections. Section 01 was in poor condition with areas of low-severity corner break, LTD cracking, shattered slab, and faulting; low- and medium-severity ASR; high-severity joint seal damage; and popouts noted. Section 02 contained areas of low-severity corner break, corner spalling, and joint seal damage; low- and medium-severity joint spalling, ASR, and LTD cracking; and popouts. Low- and medium-severity ASR and corner spalling; low-severity faulting; high-severity joint seal damage; and all severities of joint spalling, LTD cracking, and shattered slab were identified in Section 03. Section 04 was in excellent condition with low-severity joint seal damage observed throughout.

Taxiway 03 consisted of three sections. Section 01 was in poor condition with areas of medium-severity corner break, low- and medium-severity joint spalling and corner spalling, medium- and high-severity joint seal damage, all severities of LTD cracking and shattered slab, and shrinkage

cracking noted. Low-severity joint seal damage, joint spalling, large patching, small patching, and LTD cracking; low- and medium-severity ASR; and shrinkage cracking were identified in Section 02. Section 03 was in excellent condition with only low-severity joint seal damage recorded throughout.

Taxiway 04 was defined by one section in poor condition, with areas of low- and medium-severity ASR and LTD cracking, high-severity joint seal damage, low-severity small patching and large patching, popouts, and medium-severity shattered slab.

Taxiway 05 contained one section in poor condition. Areas of low-severity corner break, faulting, large patching, and shattered slab; low- and medium-severity ASR and LTD cracking; high-severity joint seal damage; and popouts were observed in Section 01.

Taxiway 06 was defined by one section that contained areas of low-severity corner spalling and LTD cracking, high-severity joint seal damage, and medium-severity joint spalling.

Taxiway 07 consisted of one section. Low-severity ASR and faulting, all severities of joint seal damage, and low- and medium-severity joint spalling were recorded in Section 01.

Aprons

Apron 01 contained one section in poor condition with areas of low- and medium-severity ASR, corner break, corner spalling, joint spalling, and LTD cracking; high-severity joint seal damage; popouts; pumping; shrinkage cracking; and low-severity small patching identified.

Apron 02 consisted of two sections. Low- and medium-severity ASR, LTD cracking, shattered slab, joint spalling, corner spalling, and joint seal damage; low-severity faulting, scaling, and small patching; medium-severity corner break; and shrinkage cracking were identified in Section 01. Section 02 contained areas of low-severity corner break, corner spalling, and joint spalling; medium- and high-severity joint seal damage; and low- and medium-severity LTD cracking.

Apron 03 was defined by one section in poor condition, with areas of all severities of shattered slab and joint spalling, low- and medium-severity LTD cracking and corner spalling, low-severity corner break, and high-severity joint seal damage observed throughout.

Apron 04 contained one section in poor condition, with areas of low- and medium-severity corner spalling, joint spalling, LTD cracking, and shattered slab; medium-severity corner break; high-severity joint seal damage; and shrinkage cracking noted.

T-Hangar

The T-hangar area consisted of four sections. Section 01 was in poor condition with areas of low- and medium-severity alligator cracking and longitudinal and transverse (L&T) cracking, and medium-severity weathering identified throughout. The low-severity cracking was unsealed, and the medium-severity cracking was due to either unsealed crack widths that exceeded $\frac{1}{4}$ in, unsatisfactory crack sealant, or the development of secondary cracking. Section 02 was also in poor condition with areas of low- and medium-severity alligator cracking, L&T cracking, patching, rutting, and swelling; low-severity block cracking; high-severity raveling; and medium-severity weathering recorded. Most of low-severity cracking was unsealed, and the medium-severity cracking was due to either unsealed crack widths greater than $\frac{1}{4}$ in, unsatisfactory crack sealant, or the development of secondary cracking. Section 03 was in

excellent condition with areas of medium-severity faulting and low-severity joint seal damage, large patching, and LTD cracking. Low-severity corner break, joint spalling, and LTD cracking and low- and medium-severity corner spalling and joint seal damage were identified in Section 04.

PAVEMENT MAINTENANCE AND REHABILITATION PROGRAM

Using the information collected during the pavement inspection, the PAVER pavement management software was used to develop a 5-year M&R program for Davenport Municipal Airport. In addition, a 1-year plan for localized preventive maintenance (such as crack sealing and patching) was prepared.

Analysis Parameters

Critical PCIs

PAVER uses critical PCIs to determine whether localized preventive maintenance or major rehabilitation is the appropriate repair action. Above the critical PCI, localized preventive maintenance activities are recommended. Below the critical PCI, major rehabilitation actions, such as an overlay or reconstruction, are recommended. The Iowa DOT set the critical PCIs at 65 for runways, 60 for taxiways, and 55 for aprons and T-hangars.

Localized Preventive Maintenance Policies and Unit Costs

Localized preventive maintenance policies were developed for asphalt-surfaced and PCC pavements. These policies, shown in Appendix E, identify the localized preventive maintenance actions that the Iowa DOT considered appropriate to correct the different distress types and severities. The Iowa DOT provided unit costs for each of the localized preventive maintenance actions included in these policies, and these costs are detailed in Appendix E. Please note that this information is of a general nature for the entire state. The localized preventive maintenance policies and unit costs may require adjustment to reflect specific conditions at Davenport Municipal Airport.

Major Rehabilitation Unit Costs

PAVER estimates the cost of major rehabilitation based on the predicted PCI of the pavement section. The Iowa DOT provided the costs for major rehabilitation, and they are presented in Appendix E. If major rehabilitation is recommended in the 5-year program, further engineering investigation will be needed to identify the most appropriate rehabilitation action and to estimate the cost of such work more accurately.

Budget and Inflation Rate

An unlimited budget with a start date of July 1, 2023 and an inflation rate of 4.0 percent was used during the analysis.

Analysis Approach

The 5-year M&R program was prepared with the goal of maintaining the pavements above established critical PCIs. During this analysis, major rehabilitation was recommended for pavements in the year they dropped below their critical PCI. For the first year (2023) of the analysis only, a localized preventive maintenance plan was developed for those pavement sections that were above their critical PCI. If major rehabilitation was triggered for a section in 2024 or 2025, then localized preventive maintenance was not recommended for 2023. While localized preventive maintenance should be an annual undertaking at Davenport Municipal Airport, it is not possible to accurately predict the propagation of cracking and other distress types. Therefore, the airport should budget for maintenance every year and can use the 2023

localized preventive maintenance plan as a baseline for that work. As the pavements age, it can be assumed that the amount of localized preventive maintenance required will increase.

Analysis Results

A summary of the M&R program for Davenport Municipal Airport is presented in Table 2. Detailed information on the recommended localized preventive maintenance plan for 2023 is provided in Appendix F.

Table 2. 5-year M&R program under an unlimited funding analysis scenario.

Year	Branch	Section	Surface Type	Type of Repair	Estimated Cost
2023	A01DA	01	PCC	Major Rehabilitation	\$813,594
2023	A02DA	01	PCC	Major Rehabilitation	\$525,141
2023	A02DA	02	PCC	Preventive Maintenance	\$9,762
2023	A03DA	01	PCC	Major Rehabilitation	\$508,713
2023	A04DA	01	PCC	Major Rehabilitation	\$1,142,340
2023	R03DA	01	PCC	Preventive Maintenance	\$75,815
2023	R15DA	01	PCC	Preventive Maintenance	\$51,519
2023	R15DA	02	PCC	Preventive Maintenance	\$26,535
2023	R15DA	03	PCC	Preventive Maintenance	\$33,573
2023	T01DA	01	PCC	Preventive Maintenance	\$38,231
2023	T01DA	02	PCC	Major Rehabilitation	\$669,036
2023	T01DA	03	PCC	Major Rehabilitation	\$402,765
2023	T01DA	04	PCC	Preventive Maintenance	\$4,145
2023	T01DA	05	PCC	Preventive Maintenance	\$33
2023	T02DA	01	PCC	Major Rehabilitation	\$54,963
2023	T02DA	02	PCC	Preventive Maintenance	\$4,518
2023	T02DA	03	PCC	Major Rehabilitation	\$1,092,978
2023	T03DA	01	PCC	Major Rehabilitation	\$1,128,075
2023	T03DA	02	PCC	Major Rehabilitation	\$150,580
2023	T04DA	01	PCC	Major Rehabilitation	\$137,913
2023	T05DA	01	PCC	Major Rehabilitation	\$137,913
2023	T06DA	01	PCC	Preventive Maintenance	\$6,944
2023	T07DA	01	PCC	Preventive Maintenance	\$11,645
2023	TH01DA	01	AAC	Major Rehabilitation	\$118,105
2023	TH01DA	02	AC	Major Rehabilitation	\$464,510
2023	TH01DA	03	PCC	Preventive Maintenance	\$9
2023	TH01DA	04	PCC	Preventive Maintenance	\$5,666

Total Estimated Cost: \$7,616,000

Table 2. 5-year M&R program under an unlimited funding analysis scenario (continued).

Table Notes:

1. See Figure 3 for the location of the branch and section.
2. Surface Type: AC = asphalt cement concrete; AAC = asphalt overlay on AC; PCC = portland cement concrete; APC = asphalt overlay on PCC.
3. Type of Repair: Major Rehabilitation such as pavement reconstruction or an overlay; Localized Preventive Maintenance such as crack sealing or patching.
4. The estimated costs provided are of a general nature for the entire state and may require adjustment to reflect specific conditions at Davenport Municipal Airport.

The recommendations made in this report are based on a broad network-level analysis and meant to provide Davenport Municipal Airport with an indication of the type of pavement-related work required during the next 5 years. Further engineering investigation may be necessary to identify which repair action is most appropriate. In addition, the cost estimates provided are based on overall unit costs for the entire state, and Davenport Municipal Airport should adjust the plan to reflect local costs.

Because an unlimited budget was used in the analysis, it is possible that the pavement repair program may need to be adjusted to consider economic or operational constraints. The identification of a project need does not necessarily mean that state or federal funding will be available in the year it is indicated. It is important to remember that regardless of the recommendations presented within this report, Davenport Municipal Airport is responsible for repairing pavements where existing conditions pose a hazard to safe operations.

General Maintenance Recommendations

In addition to the specific maintenance actions presented in Appendix F, it is recommended that the following strategies be considered for prolonging pavement life:

1. Regularly inspect all safety areas of the airport and document all inspection activity. A sample form that can be used to perform these inspections is provided in Table 3 of this report.
2. Provide a method of tracking all maintenance activities that occur as a result of inspections. These need to be reported to the FAA and the Iowa DOT. This information is used to update the APMS records and is required to remain in compliance with Public Law 103-305 (see the next section of this report for further information on this law).
3. Conduct an aggressive campaign against weed growth through timely herbicide applications and mowing programs of the safety areas. Vegetation growth in pavement cracks is destructive and significantly increases the rate of pavement deterioration.
4. Implement a periodic crack and joint sealing program. Keeping water and debris out of the pavement system by sealing cracks and joints is a proven and cost-effective method of extending the life of the pavement system.
5. Ensure that dirt does not build up along the edges of the pavements. This can create a “bathtub” effect, reducing the ability of water to drain away from the pavement system.
6. Closely monitor the movement of heavy equipment (particularly farming, construction, and fueling equipment) to make sure it is only operating on pavements that are designed to accommodate heavy loads. Failure to restrict heavy equipment to appropriate areas may result in the premature failure of airport pavements.

FAA Requirements (Public Law 103-305)

Because Davenport Municipal Airport is in the National Plan of Integrated Airport Systems (NPIAS), the airport sponsor is required to keep the airport in a viable operating condition. This includes maintaining airport pavements in accordance with Public Law 103-305. Public Law 103-305 states that after January 1, 1995, NPIAS airport sponsors must provide assurances or certifications that an airport has implemented an effective airport pavement maintenance management system (PMMS) before the airport will be considered for federal funding of pavement replacement or reconstruction projects. To be in full compliance with the federal law, the PMMS must include the following components at minimum: pavement inventory, pavement inspections, record keeping, information retrieval, and program funding.

This report serves as a complete pavement inventory and detailed inspection. To remain in compliance with the law, Davenport Municipal Airport will also need to undertake monthly drive-by inspections of pavement conditions and track pavement-related maintenance activities.

FAA Advisory Circular 150/5380-7B provides detailed guidance pertaining to the requirements for an acceptable pavement management program (PMP). Appendix A of the FAA Advisory Circular 150/5380-7B outlines what needs to be included in a PMP to remain in compliance with this law and Grant Assurance #11. The following is a copy of this Appendix, along with instructions for supplementing this report so that all requirements are met. Note that the italicized words are direct quotations from the FAA Advisory Circular.

FAA Advisory Circular 150/5830-7B, Appendix A. Pavement Management Program (PMP)

A-1.0. An effective PMP specifies the procedures to follow to assure that proper preventative and remedial pavement maintenance is performed. The program should identify funding or anticipated funding and other resources available to provide remedial and preventive maintenance activities. An airport sponsor may use any format deemed appropriate, but the program needs to, as a minimum, include the following:

A-1.1. Pavement Inventory. The following must be depicted:

- a. Identification of all runways, taxiways, and aprons with pavement broken down into sections each having similar properties.*

The network definition map provided in Figure 3 of this report shows the location of all runways, taxiways, aprons, and T-hangars at Davenport Municipal Airport. If any new pavements are constructed or any pavement areas are permanently closed, this map must be updated. Project plans should be submitted to the Iowa DOT after project completion.

- b. Dimensions of pavement sections.*

The dimensions of all runways, taxiways, aprons, and T-hangars are stored in the PAVER database. Appendix C provides information on length, width, and area. In addition, the network definition map provided in Figure 3 is drawn to scale. Any changes to pavement dimensions must be recorded.

- c. Type of pavement surface.*

The type of pavement for each section at Davenport Municipal Airport is listed in Table 1 of this report and is also stored in the PAVER database. Any changes to the pavement type (through an overlay or reconstruction) must be recorded.

- d. *Year of construction and/or most recent major rehabilitation.*

Dates for pavement construction, rehabilitation, or reconstruction must be recorded. The current pavement history for Davenport Municipal Airport is provided in Appendix D of this report.

- e. *Whether AIP [Airport Improvement Program] or PFC [Passenger Facility Charge] funds were used to construct, reconstruct, or repair the pavement.*

Funding sources for all pavement projects should be recorded.

A-1.2. PMP Pavement Inspection Schedule. *Airports must perform a detailed inspection of airfield pavements at least once a year for the PMP. If a pavement condition index (PCI) survey is performed, as set forth in ASTM D5340, Standard Test Method for Airport Pavement Condition Index Surveys, the frequency of the detailed inspection by PCI surveys may be extended to three years. Less comprehensive routine daily, weekly, and monthly maintenance inspections required for operations should be addressed.*

This report consists of a detailed inspection that will extend the inspection period to 3 years. It is the airport sponsor's responsibility to perform monthly drive-by inspections. A sample pavement inspection report form is provided in Table 3 of this report.

A-1.3. Record Keeping. *The airport must record and keep on file complete information about all detailed inspections and maintenance performed until the pavement system is replaced. The types of distress, their locations, and remedial action, scheduled or performed, must be documented. The minimum information recorded includes:*

- a. *Inspection date*
- b. *Location*
- c. *Distress types*
- d. *Maintenance scheduled or performed*

Items a through c are satisfied by this inspection report. Item d is the responsibility of the airport, as is record keeping of the monthly drive-by inspections.

A-1.4. Information Retrieval. *An airport sponsor may use any form of record keeping it deems appropriate so long as the information and records from the pavement survey can generate required reports, as necessary.*

Keep this report, monthly drive-by inspection reports, construction updates, and all records of maintenance activities in a readily accessible location so that they can be easily retrieved as requested by the FAA.

Table 3. Pavement inspection report.

Inspected By: _____

Date Inspected: _____

Branch	Section	Distress Description/Dimensions/Severity/ Recommended Action	Description of Repair	Date Performed	Cost	Funding Source
A01DA	01					
A02DA	01					
A02DA	02					
A03DA	01					
A04DA	01					
R03DA	01					

Table 3. Pavement inspection report (continued).

Inspected By: _____

Date Inspected: _____

Branch	Section	Distress Description/Dimensions/Severity/ Recommended Action	Description of Repair	Date Performed	Cost	Funding Source
R15DA	01					
R15DA	02					
R15DA	03					
T01DA	01					
T01DA	02					
T01DA	03					

Table 3. Pavement inspection report (continued).

Inspected By: _____

Date Inspected: _____

Branch	Section	Distress Description/Dimensions/Severity/ Recommended Action	Description of Repair	Date Performed	Cost	Funding Source
T01DA	04					
T01DA	05					
T01DA	06					
T02DA	01					
T02DA	02					
T02DA	03					

Table 3. Pavement inspection report (continued).

Inspected By: _____

Date Inspected: _____

Branch	Section	Distress Description/Dimensions/Severity/ Recommended Action	Description of Repair	Date Performed	Cost	Funding Source
T02DA	04					
T03DA	01					
T03DA	02					
T03DA	03					
T04DA	01					
T05DA	01					

Table 3. Pavement inspection report (continued).

Inspected By: _____

Date Inspected: _____

Branch	Section	Distress Description/Dimensions/Severity/ Recommended Action	Description of Repair	Date Performed	Cost	Funding Source
T06DA	01					
T07DA	01					
TH01DA	01					
TH01DA	02					
TH01DA	03					
TH01DA	04					

Table Note: See Figure 3 for the location of the branch and section.

SUMMARY

This report documents the results of the pavement evaluation conducted at Davenport Municipal Airport. A visual inspection of the pavements in 2022 found that the overall condition of the pavement network is a PCI of 78. A 5-year pavement repair program, shown in Table 2, was generated for Davenport Municipal Airport, which revealed that approximately \$7,616,000 needs to be expended on M&R. Davenport Municipal Airport should utilize these study results to assist in planning for future maintenance needs as part of the airport CIP planning process.

APPENDIX A

CAUSE OF DISTRESS TABLES

Table A-1. Cause of pavement distress, asphalt-surfaced pavements.

Distress Type	Probable Cause of Distress
Alligator Cracking	Fatigue failure of the asphalt surface under repeated traffic loading.
Bleeding	Excessive amounts of asphalt cement or tars in the mix or low air void content, or both.
Block Cracking	Shrinkage of the asphalt and daily temperature cycling; it is not load associated.
Corrugation	Traffic action combined with an unstable pavement layer.
Depression	Settlement of the foundation soil or can be “built up” during construction.
Jet-Blast Erosion	Bituminous binder has been burned or carbonized.
Joint Reflection Cracking	Movement of the concrete slab beneath the asphalt surface due to thermal and moisture changes.
L&T Cracking	Cracks may be caused by (1) a poorly constructed paving lane joint, (2) shrinkage of the asphalt surface due to low temperatures or hardening of the asphalt, or (3) reflective cracking caused by cracks in an underlying PCC slab.
Oil Spillage	Deterioration or softening of the pavement surface caused by the spilling of oil, fuel, or other solvents.
Patching	N/A
Polished Aggregate	Repeated traffic applications.
Raveling	Asphalt binder may have hardened significantly, causing coarse aggregate pieces to dislodge.
Rutting	Usually caused by consolidation or lateral movement of the materials due to traffic loads.
Shoving	Where PCC pavements adjoin flexible pavements, PCC “growth” may shove the asphalt pavement.
Slippage Cracking	Low strength surface mix or poor bond between the surface and the next layer of the pavement structure.
Swelling	Usually caused by frost action or by swelling soil.
Weathering	Asphalt binder and/or fine aggregate may wear away as the pavement ages and hardens.

Table A-2. Cause of pavement distress, PCC pavements.

Distress Type	Probable Cause of Distress
ASR	Chemical reaction of alkalis in the portland cement with certain reactive silica minerals. ASR may be accelerated by the use of chemical pavement deicers.
Blowup	Incompressible materials in the joints.
Corner Break	Load repetition combined with loss of support and curling stresses.
Durability Cracking	Concrete's inability to withstand environmental factors such as freeze-thaw cycles.
Faulting	Upheaval or consolidation.
Joint Seal Damage	Stripping of joint sealant, extrusion of joint sealant, weed growth, hardening of the filler (oxidation), loss of bond to the slab edges, or absence of sealant in the joint.
LTD Cracking	Combination of load repetition, curling stresses, and shrinkage stresses.
Patching (Small and Large)	N/A
Popouts	Freeze-thaw action in combination with expansive aggregates.
Pumping	Poor drainage, poor joint sealant.
Scaling	Over finishing of concrete, deicing salts, improper construction, freeze-thaw cycles, and poor aggregate.
Shattered Slab	Load repetition.
Shrinkage Cracking	Setting and curing of the concrete.
Spalling (Joint and Corner)	Excessive stresses at the joint caused by infiltration of incompressible materials or traffic loads; weak concrete at the joint combined with traffic loads.

APPENDIX B

INSPECTION PHOTOGRAPHS

A01DA-01. Overview.



A01DA-01. LTD Cracking (Sample Unit No. 07).



A02DA-01. Overview.



A02DA-01. Shattered Slab (Sample Unit No. 07).



A02DA-02. Overview.



A02DA-02. Joint Spalling (Sample Unit No. 04).



A03DA-01. Overview.



A03DA-01. Shattered Slab (Sample Unit No. 04).



A04DA-01. Overview.



A04DA-01. Shattered Slab (Sample Unit No. 05).



R03DA-01. Overview.



R03DA-01. Faulting (Sample Unit No. 07).



R15DA-01. Overview.



R15DA-01. Joint Seal Damage (Sample Unit No. 05).



R15DA-02. Overview.



R15DA-02. Corner Spalling (Sample Unit No. 01).



R15DA-03. Overview.



R15DA-03. Joint Seal Damage (Sample Unit No. 06).



T01DA-01. Overview.



T01DA-01. ASR (Sample Unit No. 08).



T01DA-01. LTD Cracking (Additional Sample Unit No. 04).



T01DA-02. Overview.



T01DA-02. ASR (Sample Unit No. 15).



T01DA-02. Small Patching (Sample Unit No. 15).



T01DA-03. Overview.



T01DA-03. LTD Cracking (Sample Unit No. 03).



T01DA-04. Overview.



T01DA-04. ASR (Sample Unit No. 07).



T01DA-05. Overview.




T01DA-05. Corner Break (Sample Unit No. 08).



T01DA-06. Overview.



T01DA-06. Joint Seal Damage (Sample Unit No. 09).



T01DA-06. LTD Cracking (Additional Sample Unit No. 08).



T02DA-01. Overview.



T02DA-01. ASR (Sample Unit No. 01).



T02DA-02. Overview.



T02DA-02. ASR (Sample Unit No. 01).



T02DA-02. LTD Cracking (Additional Sample Unit No. 04).



T02DA-03. Overview.




T02DA-03. LTD Cracking (Sample Unit No. 02).



T02DA-04. Overview.



T02DA-04. Joint Seal Damage (Sample Unit No. 03).




T03DA-01. Overview.




T03DA-01. Shattered Slab (Sample Unit No. 02).



T03DA-02. Overview.




T03DA-02. ASR (Sample Unit No. 02).



T03DA-03. Overview.



T03DA-03. Joint Seal Damage (Sample Unit No. 05).



T04DA-01. Overview.



T04DA-01. LTD Cracking (Sample Unit No. 01).



T05DA-01. Overview.




T05DA-01. ASR (Sample Unit No. 01).



T06DA-01. Overview.



T06DA-01. LTD Cracking (Sample Unit No. 02).



T07DA-01. Overview.



T07DA-01. ASR (Sample Unit No. 12) (1).



T07DA-01. ASR (Sample Unit No. 12) (2).



T07DA-01. Joint Spalling (Sample Unit No. 02).



TH01DA-01. Overview.



TH01DA-01. Alligator Cracking (Sample Unit No. 02).



TH01DA-02. Overview.



TH01DA-02. Alligator Cracking (Sample Unit No. 07).



TH01DA-03. Overview.



TH01DA-03. LTD Cracking (Sample Unit No. 07).



TH01DA-04. Overview.



TH01DA-04. Corner Spalling (Sample Unit No. 09).



APPENDIX C

INSPECTION REPORT

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 1

Branch - Section ID: A01DA - 001

Branch Name: APRON 01

Use: APRON

LCD: 6/2/1949

PCI Family: IowaPCCAPNCE_Enhanced

Surface Type: PCC

Rank: P

Section Area (sf): 45,000.00

Length (ft): 300.00

Width (ft): 150.00

From: TERMINAL

To: TAXIWAYS 04 & 05

Slabs: 183

Section Comments:

Slab Length (ft): 20.00

Slab Width (ft): 12.27

Joint Length (ft): 5,467.48

Last Insp Date: 2/21/2023

Inspection Comments:

PCI: 40

Total Samples: 9

Surveyed: 5

Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 48

Sample Area (Slabs): 20.00

63 LINEAR CRACKING	M	4.00 Slabs
65 JOINT SEAL DAMAGE	H	20.00 Slabs
74 JOINT SPALL	M	1.00 Slabs
75 CORNER SPALL	L	2.00 Slabs
76 ASR	L	3.00 Slabs
76 ASR	M	1.00 Slabs

Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 22

Sample Area (Slabs): 20.00

62 CORNER BREAK	L	1.00 Slabs
62 CORNER BREAK	M	1.00 Slabs
63 LINEAR CRACKING	M	12.00 Slabs
65 JOINT SEAL DAMAGE	H	20.00 Slabs
68 POPOUTS	N	2.00 Slabs
74 JOINT SPALL	L	1.00 Slabs
74 JOINT SPALL	M	1.00 Slabs
75 CORNER SPALL	L	2.00 Slabs
76 ASR	L	4.00 Slabs
76 ASR	M	2.00 Slabs

Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 56

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	H	20.00 Slabs
68 POPOUTS	N	2.00 Slabs
73 SHRINKAGE CRACKING	N	2.00 Slabs
76 ASR	M	4.00 Slabs

RE-INSPECTION REPORT

DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 2

Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 52

Sample Area (Slabs): 20.00

63 LINEAR CRACKING	L	1.00 Slabs
63 LINEAR CRACKING	M	2.00 Slabs
65 JOINT SEAL DAMAGE	H	20.00 Slabs
69 PUMPING	N	3.00 Slabs
73 SHRINKAGE CRACKING	N	1.00 Slabs
74 JOINT SPALL	L	1.00 Slabs
75 CORNER SPALL	M	1.00 Slabs
76 ASR	L	3.00 Slabs

Sample Number: 07

Sample Type: R

Sample Comments:

Sample PCI: 20

Sample Area (Slabs): 20.00

63 LINEAR CRACKING	L	1.00 Slabs
63 LINEAR CRACKING	M	11.00 Slabs
65 JOINT SEAL DAMAGE	H	20.00 Slabs
66 SMALL PATCH	L	2.00 Slabs
68 POPOUTS	N	5.00 Slabs
74 JOINT SPALL	L	1.00 Slabs
75 CORNER SPALL	L	2.00 Slabs
76 ASR	L	3.00 Slabs
76 ASR	M	3.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 3

Branch - Section ID: A02DA - 001

Branch Name: APRON 02

Use: APRON

LCD: 6/1/2001

PCI Family: IowaPCCAPNCE_Enhanced

Surface Type: PCC

Rank: P

Section Area (sf): 61,421.00

Length (ft): 300.00

Width (ft): 200.00

From: BUILDINGS

To: TAXIWAY 06

Slabs: 246

Section Comments:

Slab Length (ft): 20.00

Slab Width (ft): 12.50

Joint Length (ft): 7,472.89

Last Insp Date: 2/21/2023

Inspection Comments:

PCI: 59

Total Samples: 12

Surveyed: 6

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 18

Sample Area (Slabs): 20.00

63 LINEAR CRACKING	L	1.00 Slabs
63 LINEAR CRACKING	M	7.00 Slabs
66 SMALL PATCH	L	3.00 Slabs
70 SCALING	L	1.00 Slabs
72 SHATTERED SLAB	M	4.00 Slabs
73 SHRINKAGE CRACKING	N	1.00 Slabs
75 CORNER SPALL	L	1.00 Slabs
76 ASR	L	14.00 Slabs
76 ASR	M	1.00 Slabs

Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 43

Sample Area (Slabs): 20.00

62 CORNER BREAK	M	1.00 Slabs
65 JOINT SEAL DAMAGE	M	20.00 Slabs
72 SHATTERED SLAB	L	1.00 Slabs
76 ASR	L	7.00 Slabs
76 ASR	M	6.00 Slabs

Sample Number: 07

Sample Type: R

Sample Comments:

Sample PCI: 31

Sample Area (Slabs): 20.00

63 LINEAR CRACKING	M	6.00 Slabs
65 JOINT SEAL DAMAGE	L	20.00 Slabs
70 SCALING	L	1.00 Slabs
72 SHATTERED SLAB	M	4.00 Slabs
74 JOINT SPALL	M	1.00 Slabs

RE-INSPECTION REPORT

DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 4

Sample Number: 09

Sample Type: R

Sample Comments:

Sample PCI: 82

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	L	20.00 Slabs
71 FAULTING	L	3.00 Slabs
75 CORNER SPALL	M	1.00 Slabs

Sample Number: 11

Sample Type: R

Sample Comments:

Sample PCI: 88

Sample Area (Slabs): 20.00

63 LINEAR CRACKING	L	2.00 Slabs
65 JOINT SEAL DAMAGE	L	20.00 Slabs
70 SCALING	L	1.00 Slabs

Sample Number: 12

Sample Type: R

Sample Comments:

Sample PCI: 94

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	L	20.00 Slabs
74 JOINT SPALL	L	1.00 Slabs
75 CORNER SPALL	L	1.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 5

Branch - Section ID: A02DA - 002

Branch Name: APRON 02

Use: APRON

LCD: 8/1/1996

PCI Family: IowaPCCAPNCE_Enhanced

Surface Type: PCC

Rank: P

Section Area (sf): 17,878.00

Length (ft): 145.00

Width (ft): 120.00

From: WISE AVIATION

To:

Slabs: 155

Section Comments:

Slab Length (ft): 11.00

Slab Width (ft): 10.50

Joint Length (ft): 3,055.66

Last Insp Date: 2/21/2023

Inspection Comments:

PCI: 83

Total Samples: 7

Surveyed: 4

Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 88

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	H	20.00 Slabs
----------------------	---	-------------

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 80

Sample Area (Slabs): 24.00

62 CORNER BREAK	L	1.00 Slabs
63 LINEAR CRACKING	M	1.00 Slabs
65 JOINT SEAL DAMAGE	H	24.00 Slabs

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 77

Sample Area (Slabs): 20.00

62 CORNER BREAK	L	1.00 Slabs
63 LINEAR CRACKING	L	1.00 Slabs
65 JOINT SEAL DAMAGE	H	20.00 Slabs
74 JOINT SPALL	L	1.00 Slabs

Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 88

Sample Area (Slabs): 15.00

65 JOINT SEAL DAMAGE	M	15.00 Slabs
74 JOINT SPALL	L	1.00 Slabs
75 CORNER SPALL	L	1.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 6

Branch - Section ID: A03DA - 001

Branch Name: APRON 03

Use: APRON

LCD: 6/2/1949
 Surface Type: PCC
 Rank: P
 Section Area (sf): 28,137.00
 Length (ft): 200.00
 Width (ft): 140.00
 From: HANGER
 To: TAXIWAY 03
 Slabs: 113
 Slab Length (ft): 20.00
 Slab Width (ft): 12.50
 Joint Length (ft): 3,316.15
 Last Insp Date: 2/21/2023
 PCI: 6
 Total Samples: 5
 Surveyed: 4

PCI Family: IowaPCCAPNCE_Enhanced

Section Comments:

Inspection Comments:

Sample Number: 02

Sample Type: R
 Sample PCI: 3
 Sample Area (Slabs): 21.00

Sample Comments:

63 LINEAR CRACKING	M	14.00 Slabs
65 JOINT SEAL DAMAGE	H	21.00 Slabs
72 SHATTERED SLAB	L	1.00 Slabs
72 SHATTERED SLAB	M	6.00 Slabs
74 JOINT SPALL	L	8.00 Slabs
74 JOINT SPALL	M	6.00 Slabs
75 CORNER SPALL	L	6.00 Slabs
75 CORNER SPALL	M	2.00 Slabs

Sample Number: 03

Sample Type: R
 Sample PCI: 10
 Sample Area (Slabs): 21.00

Sample Comments:

62 CORNER BREAK	L	1.00 Slabs
63 LINEAR CRACKING	L	2.00 Slabs
63 LINEAR CRACKING	M	14.00 Slabs
65 JOINT SEAL DAMAGE	H	21.00 Slabs
72 SHATTERED SLAB	L	1.00 Slabs
72 SHATTERED SLAB	M	4.00 Slabs
74 JOINT SPALL	H	1.00 Slabs
74 JOINT SPALL	M	4.00 Slabs

RE-INSPECTION REPORT

DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 7

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 2

Sample Area (Slabs): 21.00

63 LINEAR CRACKING	L	3.00 Slabs
63 LINEAR CRACKING	M	13.00 Slabs
65 JOINT SEAL DAMAGE	H	21.00 Slabs
72 SHATTERED SLAB	H	1.00 Slabs
72 SHATTERED SLAB	L	1.00 Slabs
72 SHATTERED SLAB	M	3.00 Slabs
74 JOINT SPALL	M	8.00 Slabs
75 CORNER SPALL	L	2.00 Slabs

Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 9

Sample Area (Slabs): 28.00

63 LINEAR CRACKING	L	9.00 Slabs
63 LINEAR CRACKING	M	5.00 Slabs
65 JOINT SEAL DAMAGE	H	28.00 Slabs
72 SHATTERED SLAB	H	3.00 Slabs
72 SHATTERED SLAB	L	8.00 Slabs
72 SHATTERED SLAB	M	3.00 Slabs
74 JOINT SPALL	M	2.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 8

Branch - Section ID: A04DA - 001

Branch Name: APRON 04

Use: APRON

LCD: 6/2/1949

PCI Family: IowaPCCAPNCE_Enhanced

Surface Type: PCC

Rank: P

Section Area (sf): 63,183.00

Length (ft): 295.00

Width (ft): 200.00

From: MIDWEST AVIATION

To:

Slabs: 253

Section Comments:

Slab Length (ft): 20.00

Slab Width (ft): 12.50

Joint Length (ft): 7,683.70

Last Insp Date: 2/21/2023

Inspection Comments:

PCI: 35

Total Samples: 13

Surveyed: 6

Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 43

Sample Area (Slabs): 20.00

63 LINEAR CRACKING	L	5.00 Slabs
63 LINEAR CRACKING	M	11.00 Slabs
65 JOINT SEAL DAMAGE	H	20.00 Slabs

Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 50

Sample Area (Slabs): 20.00

62 CORNER BREAK	M	1.00 Slabs
63 LINEAR CRACKING	M	5.00 Slabs
65 JOINT SEAL DAMAGE	H	20.00 Slabs
74 JOINT SPALL	M	1.00 Slabs
75 CORNER SPALL	M	1.00 Slabs

Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 23

Sample Area (Slabs): 20.00

63 LINEAR CRACKING	L	7.00 Slabs
63 LINEAR CRACKING	M	9.00 Slabs
65 JOINT SEAL DAMAGE	H	20.00 Slabs
72 SHATTERED SLAB	L	3.00 Slabs
72 SHATTERED SLAB	M	1.00 Slabs
74 JOINT SPALL	L	1.00 Slabs
74 JOINT SPALL	M	3.00 Slabs
75 CORNER SPALL	L	1.00 Slabs

RE-INSPECTION REPORT

DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 9

Sample Number: 07

Sample Type: R

Sample Comments:

Sample PCI: 35

Sample Area (Slabs): 20.00

63 LINEAR CRACKING	L	4.00 Slabs
63 LINEAR CRACKING	M	9.00 Slabs
65 JOINT SEAL DAMAGE	H	20.00 Slabs
72 SHATTERED SLAB	L	1.00 Slabs
72 SHATTERED SLAB	M	1.00 Slabs

Sample Number: 09

Sample Type: R

Sample Comments:

Sample PCI: 36

Sample Area (Slabs): 20.00

63 LINEAR CRACKING	L	4.00 Slabs
63 LINEAR CRACKING	M	9.00 Slabs
65 JOINT SEAL DAMAGE	H	20.00 Slabs
73 SHRINKAGE CRACKING	N	1.00 Slabs
74 JOINT SPALL	M	1.00 Slabs
75 CORNER SPALL	L	1.00 Slabs
75 CORNER SPALL	M	2.00 Slabs

Sample Number: 11

Sample Type: R

Sample Comments:

Sample PCI: 25

Sample Area (Slabs): 20.00

63 LINEAR CRACKING	M	13.00 Slabs
65 JOINT SEAL DAMAGE	H	20.00 Slabs
72 SHATTERED SLAB	L	1.00 Slabs
72 SHATTERED SLAB	M	2.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 10

Branch - Section ID: R03DA - 001

Branch Name: RUNWAY 03/21

Use: RUNWAY

LCD: 6/3/2015

PCI Family: IowaPCCRWNCE_Enhanced

Surface Type: PCC

Rank: S

Section Area (sf): 389,389.00

Length (ft): 4,000.00

Width (ft): 100.00

From: SEE MAP

To: SEE MAP

Slabs: 2,077

Section Comments:

Slab Length (ft): 15.00

Slab Width (ft): 12.50

Joint Length (ft): 53,119.15

Last Insp Date: 2/21/2023

Inspection Comments:

PCI: 95

Total Samples: 104

Surveyed: 11

Sample Number: 07

Sample Type: R

Sample Comments:

Sample PCI: 88

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

M

20.00 Slabs

71 FAULTING

L

1.00 Slabs

Sample Number: 22

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 25

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 40

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 43

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 58

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

RE-INSPECTION REPORT

DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 11

Sample Number: 61

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 78

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

M

20.00 Slabs

Sample Number: 81

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

M

20.00 Slabs

Sample Number: 96

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

M

20.00 Slabs

Sample Number: 99

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

M

20.00 Slabs

RE-INSPECTION REPORT

DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 12

Branch - Section ID: R15DA - 001

Branch Name: RUNWAY 15/33

Use: RUNWAY

LCD: 4/3/2019

PCI Family: IowaPCCRWNCE_Enhanced

Surface Type: PCC

Rank: P

Section Area (sf): 270,860.00

Length (ft): 2,693.00

Width (ft): 100.00

From: RUNWAY END 15

To: RUNWAY END 33

Slabs: 1,445

Section Comments:

Slab Length (ft): 15.00

Slab Width (ft): 12.50

Joint Length (ft): 36,916.95

Last Insp Date: 2/21/2023

Inspection Comments:

PCI: 96

Total Samples: 71

Surveyed: 9

Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

M

20.00 Slabs

Sample Number: 14

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

M

20.00 Slabs

Sample Number: 27

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

M

20.00 Slabs

Sample Number: 34

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

M

20.00 Slabs

Sample Number: 42

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 49

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 13

Sample Number: 54

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 61

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 66

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 14

Branch - Section ID: R15DA - 002

Branch Name: RUNWAY 15/33

Use: RUNWAY

LCD: 6/30/1994 PCI Family: IowaPCCRWNCE_Enhanced

Surface Type: PCC

Rank: P

Section Area (sf): 125,500.00

Length (ft): 1,255.00

Width (ft): 100.00

From: SOUTH END OF R15-01

To: SOUTN END OF THE RWY

Slabs: 669

Section Comments:

Slab Length (ft): 15.00

Slab Width (ft): 12.50

Joint Length (ft): 17,051.67

Last Insp Date: 2/21/2023

Inspection Comments:

PCI: 92

Total Samples: 34

Surveyed: 8

Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 90

Sample Area (Slabs): 16.00

65 JOINT SEAL DAMAGE	M	16.00 Slabs
75 CORNER SPALL	L	1.00 Slabs

Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	M	20.00 Slabs
----------------------	---	-------------

Sample Number: 08

Sample Type: R

Sample Comments:

Sample PCI: 94

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	L	20.00 Slabs
75 CORNER SPALL	M	1.00 Slabs

Sample Number: 11

Sample Type: R

Sample Comments:

Sample PCI: 89

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	L	20.00 Slabs
68 POPOUTS	N	1.00 Slabs
71 FAULTING	L	1.00 Slabs

Sample Number: 15

Sample Type: R

Sample Comments:

Sample PCI: 88

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	M	20.00 Slabs
66 SMALL PATCH	L	1.00 Slabs
68 POPOUTS	N	1.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 15

Sample Number: 20

Sample Type: R

Sample Comments:

Sample PCI: 88

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

H

20.00 Slabs

Sample Number: 24

Sample Type: R

Sample Comments:

Sample PCI: 97

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

66 SMALL PATCH

L

1.00 Slabs

Sample Number: 25

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

RE-INSPECTION REPORT

DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 16

Branch - Section ID: R15DA - 003

Branch Name: RUNWAY 15/33

Use: RUNWAY

LCD: 6/3/2015

PCI Family: IowaPCCRWNCE_Enhanced

Surface Type: PCC

Rank: P

Section Area (sf): 157,200.00

Length (ft): 1,572.00

Width (ft): 100.00

From: SEE MAP

To: SEE MAP

Slabs: 838

Section Comments:

Slab Length (ft): 15.00

Slab Width (ft): 12.50

Joint Length (ft): 21,384.00

Last Insp Date: 2/21/2023

Inspection Comments:

PCI: 96

Total Samples: 42

Surveyed: 8

Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

M

20.00 Slabs

Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

M

20.00 Slabs

Sample Number: 11

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

M

20.00 Slabs

Sample Number: 18

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 23

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 30

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 17

Sample Number: 35

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 40

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

M

20.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 18

Branch - Section ID: T01DA - 001

Branch Name: TAXIWAY 01

Use: TAXIWAY

LCD: 6/2/1949

PCI Family: IowaPCCTWNCE_Enhanced

Surface Type: PCC

Rank: P

Section Area (sf): 55,043.00

Length (ft): 1,100.00

Width (ft): 50.00

From: RUNWAY END 15

To: SEE MAP

Slabs: 220

Section Comments:

Slab Length (ft): 20.00

Slab Width (ft): 12.50

Joint Length (ft): 6,004.69

Last Insp Date: 2/21/2023

Inspection Comments:

PCI: 83

Total Samples: 11

Surveyed: 7

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 55

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	L	20.00 Slabs
70 SCALING	L	1.00 Slabs
71 FAULTING	L	1.00 Slabs
76 ASR	L	5.00 Slabs
76 ASR	M	4.00 Slabs

Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 77

Sample Area (Slabs): 20.00

76 ASR	L	6.00 Slabs
76 ASR	M	1.00 Slabs

Sample Number: 04

Sample Type: A

Sample Comments:

Sample PCI: 60

Sample Area (Slabs): 20.00

63 LINEAR CRACKING	M	4.00 Slabs
65 JOINT SEAL DAMAGE	M	20.00 Slabs
74 JOINT SPALL	L	1.00 Slabs
76 ASR	L	2.00 Slabs

Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	L	20.00 Slabs
----------------------	---	-------------

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 19

Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

76 ASR

L

1.00 Slabs

Sample Number: 08

Sample Type: R

Sample Comments:

Sample PCI: 92

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

70 SCALING

L

1.00 Slabs

76 ASR

L

1.00 Slabs

Sample Number: 09

Sample Type: R

Sample Comments:

Sample PCI: 97

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

73 SHRINKAGE CRACKING

N

1.00 Slabs

RE-INSPECTION REPORT

DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 20

Branch - Section ID: T01DA - 002

Branch Name: TAXIWAY 01

Use: TAXIWAY

LCD: 6/1/1949

PCI Family: IowaPCCTWNCE_Enhanced

Surface Type: PCC

Rank: P

Section Area (sf): 78,251.00

Length (ft): 1,560.00

Width (ft): 50.00

From: SEE MAP

To: TAXIWAY 01 SECT 03

Slabs: 313

Section Comments:

Slab Length (ft): 20.00

Slab Width (ft): 12.50

Joint Length (ft): 8,557.45

Last Insp Date: 2/21/2023

Inspection Comments:

PCI: 56

Total Samples: 17

Surveyed: 7

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 62

Sample Area (Slabs): 20.00

63 LINEAR CRACKING	L	1.00 Slabs
65 JOINT SEAL DAMAGE	M	20.00 Slabs
67 LARGE PATCH	L	2.00 Slabs
68 POPOUTS	N	4.00 Slabs
74 JOINT SPALL	M	1.00 Slabs
75 CORNER SPALL	L	1.00 Slabs
76 ASR	L	4.00 Slabs

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 39

Sample Area (Slabs): 20.00

62 CORNER BREAK	M	1.00 Slabs
63 LINEAR CRACKING	L	1.00 Slabs
63 LINEAR CRACKING	M	1.00 Slabs
65 JOINT SEAL DAMAGE	H	20.00 Slabs
67 LARGE PATCH	L	2.00 Slabs
68 POPOUTS	N	8.00 Slabs
73 SHRINKAGE CRACKING	N	1.00 Slabs
76 ASR	L	1.00 Slabs
76 ASR	M	2.00 Slabs

Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 70

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	L	20.00 Slabs
68 POPOUTS	N	6.00 Slabs
76 ASR	L	2.00 Slabs
76 ASR	M	1.00 Slabs

RE-INSPECTION REPORT

DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 21

Sample Number: 08

Sample Type: R

Sample Comments:

Sample PCI: 32

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	M	20.00 Slabs
67 LARGE PATCH	L	3.00 Slabs
68 POPOUTS	N	2.00 Slabs
74 JOINT SPALL	M	1.00 Slabs
76 ASR	H	1.00 Slabs
76 ASR	L	5.00 Slabs
76 ASR	M	4.00 Slabs

Sample Number: 10

Sample Type: R

Sample Comments:

Sample PCI: 44

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	H	20.00 Slabs
66 SMALL PATCH	L	1.00 Slabs
67 LARGE PATCH	L	5.00 Slabs
68 POPOUTS	N	6.00 Slabs
76 ASR	L	2.00 Slabs
76 ASR	M	5.00 Slabs

Sample Number: 13

Sample Type: R

Sample Comments:

Sample PCI: 67

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	M	20.00 Slabs
66 SMALL PATCH	L	1.00 Slabs
67 LARGE PATCH	L	1.00 Slabs
68 POPOUTS	N	2.00 Slabs
76 ASR	L	1.00 Slabs
76 ASR	M	1.00 Slabs

Sample Number: 15

Sample Type: R

Sample Comments:

Sample PCI: 79

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	M	20.00 Slabs
66 SMALL PATCH	L	1.00 Slabs
68 POPOUTS	N	3.00 Slabs
76 ASR	L	1.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 22

Branch - Section ID: T01DA - 003

Branch Name: TAXIWAY 01

Use: TAXIWAY

LCD: 6/2/1949

PCI Family: IowaPCCTWNCE_Enhanced

Surface Type: PCC

Rank: P

Section Area (sf): 22,277.00

Length (ft): 158.00

Width (ft): 150.00

From: TAXIWAY 01 SECT 02

To: TAXIWAY 01 SECT 04

Slabs: 89

Section Comments:

Slab Length (ft): 20.00

Slab Width (ft): 12.50

Joint Length (ft): 2,606.50

Last Insp Date: 2/21/2023

Inspection Comments:

PCI: 25

Total Samples: 4

Surveyed: 3

Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 18

Sample Area (Slabs): 24.00

62 CORNER BREAK	L	3.00 Slabs
63 LINEAR CRACKING	H	2.00 Slabs
63 LINEAR CRACKING	L	1.00 Slabs
63 LINEAR CRACKING	M	5.00 Slabs
65 JOINT SEAL DAMAGE	H	24.00 Slabs
66 SMALL PATCH	L	7.00 Slabs
67 LARGE PATCH	L	6.00 Slabs
76 ASR	L	3.00 Slabs
76 ASR	M	5.00 Slabs

Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 34

Sample Area (Slabs): 18.00

62 CORNER BREAK	L	1.00 Slabs
63 LINEAR CRACKING	M	4.00 Slabs
65 JOINT SEAL DAMAGE	H	18.00 Slabs
66 SMALL PATCH	H	1.00 Slabs
66 SMALL PATCH	L	2.00 Slabs
67 LARGE PATCH	L	4.00 Slabs
67 LARGE PATCH	M	2.00 Slabs
74 JOINT SPALL	M	1.00 Slabs
76 ASR	L	2.00 Slabs
76 ASR	M	1.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 23

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 25

Sample Area (Slabs): 24.00

63 LINEAR CRACKING	L	2.00 Slabs
63 LINEAR CRACKING	M	4.00 Slabs
65 JOINT SEAL DAMAGE	L	24.00 Slabs
66 SMALL PATCH	L	3.00 Slabs
67 LARGE PATCH	L	1.00 Slabs
67 LARGE PATCH	M	4.00 Slabs
74 JOINT SPALL	M	1.00 Slabs
76 ASR	L	3.00 Slabs
76 ASR	M	5.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 24

Branch - Section ID: T01DA - 004

Branch Name: TAXIWAY 01

Use: TAXIWAY

LCD: 6/2/1949

PCI Family: IowaPCCTWNCE_Enhanced

Surface Type: PCC

Rank: P

Section Area (sf): 57,742.00

Length (ft): 1,085.00

Width (ft): 50.00

From: TAXIWAY 01 SECT 03

To: RUNWAY END 33

Slabs: 231

Section Comments:

Slab Length (ft): 20.00

Slab Width (ft): 12.50

Joint Length (ft): 6,298.40

Last Insp Date: 2/21/2023

Inspection Comments:

PCI: 88

Total Samples: 12

Surveyed: 6

Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 81

Sample Area (Slabs): 20.00

66 SMALL PATCH	H	1.00 Slabs
66 SMALL PATCH	L	2.00 Slabs
68 POPOUTS	N	3.00 Slabs
75 CORNER SPALL	L	1.00 Slabs

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 95

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	L	20.00 Slabs
73 SHRINKAGE CRACKING	N	3.00 Slabs

Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 86

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	L	20.00 Slabs
66 SMALL PATCH	L	2.00 Slabs
68 POPOUTS	N	1.00 Slabs
75 CORNER SPALL	L	1.00 Slabs
75 CORNER SPALL	M	1.00 Slabs

Sample Number: 07

Sample Type: R

Sample Comments:

Sample PCI: 80

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	L	20.00 Slabs
67 LARGE PATCH	L	1.00 Slabs
70 SCALING	M	1.00 Slabs
76 ASR	L	3.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 25

Sample Number: 10

Sample Type: R

Sample Comments:

Sample PCI: 92

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	L	20.00 Slabs
67 LARGE PATCH	L	1.00 Slabs
75 CORNER SPALL	L	1.00 Slabs

Sample Number: 11

Sample Type: R

Sample Comments:

Sample PCI: 94

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	L	20.00 Slabs
66 SMALL PATCH	L	1.00 Slabs
74 JOINT SPALL	L	2.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 26

Branch - Section ID: T01DA - 005

Branch Name: TAXIWAY 01

Use: TAXIWAY

LCD: 6/3/2015

PCI Family: IowaPCCTWNCE_Enhanced

Surface Type: PCC

Rank: P

Section Area (sf): 23,533.00

Length (ft): 330.00

Width (ft): 50.00

From: SEE MAP

To: SEE MAP

Slabs: 142

Section Comments:

Slab Length (ft): 13.30

Slab Width (ft): 12.50

Joint Length (ft): 3,110.07

Last Insp Date: 2/21/2023

Inspection Comments:

PCI: 93

Total Samples: 8

Surveyed: 5

Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 86

Sample Area (Slabs): 23.00

63 LINEAR CRACKING

L

4.00 Slabs

65 JOINT SEAL DAMAGE

L

23.00 Slabs

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 87

Sample Area (Slabs): 20.00

63 LINEAR CRACKING

L

3.00 Slabs

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 24.00

65 JOINT SEAL DAMAGE

L

24.00 Slabs

Sample Number: 07

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 21.00

65 JOINT SEAL DAMAGE

L

21.00 Slabs

Sample Number: 08

Sample Type: R

Sample Comments:

Sample PCI: 94

Sample Area (Slabs): 23.00

62 CORNER BREAK

L

1.00 Slabs

65 JOINT SEAL DAMAGE

L

23.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 27

Branch - Section ID: T01DA - 006

Branch Name: TAXIWAY 01

Use: TAXIWAY

LCD: 4/3/2019

PCI Family: IowaPCCTWNCE_Enhanced

Surface Type: PCC

Rank: P

Section Area (sf): 40,715.00

Length (ft): 750.00

Width (ft): 50.00

From: .

To: .

Slabs: 261

Section Comments:

Slab Length (ft): 12.50

Slab Width (ft): 12.50

Joint Length (ft): 5,645.81

Last Insp Date: 2/21/2023

Inspection Comments:

PCI: 98

Total Samples: 12

Surveyed: 7

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 25.00

65 JOINT SEAL DAMAGE

L

25.00 Slabs

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 23.00

65 JOINT SEAL DAMAGE

L

23.00 Slabs

Sample Number: 08

Sample Type: A

Sample Comments:

Sample PCI: 94

Sample Area (Slabs): 25.00

63 LINEAR CRACKING

L

1.00 Slabs

65 JOINT SEAL DAMAGE

L

25.00 Slabs

Sample Number: 09

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 27.00

65 JOINT SEAL DAMAGE

L

27.00 Slabs

Sample Number: 10

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 25.00

65 JOINT SEAL DAMAGE

L

25.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 28

Sample Number: 11

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 25.00

65 JOINT SEAL DAMAGE

L

25.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 29

Branch - Section ID: T02DA - 001

Branch Name: TAXIWAY 02

Use: TAXIWAY

LCD: 6/1/1979

PCI Family: IowaPCCTWNCE_Enhanced

Surface Type: PCC

Rank: P

Section Area (sf): 3,040.00

Length (ft): 75.00

Width (ft): 40.00

From: SEE MAP

To: SEE MAP

Slabs: 24

Section Comments:

Slab Length (ft): 12.50

Slab Width (ft): 10.00

Joint Length (ft): 430.67

Last Insp Date: 2/21/2023

Inspection Comments:

PCI: 35

Total Samples: 1

Surveyed: 1

Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 35

Sample Area (Slabs): 24.00

62 CORNER BREAK	L	2.00 Slabs
63 LINEAR CRACKING	L	2.00 Slabs
65 JOINT SEAL DAMAGE	H	24.00 Slabs
68 POPOUTS	N	2.00 Slabs
71 FAULTING	L	1.00 Slabs
72 SHATTERED SLAB	L	1.00 Slabs
76 ASR	L	20.00 Slabs
76 ASR	M	3.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 31

Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 88

Sample Area (Slabs): 16.00

65 JOINT SEAL DAMAGE

L

16.00 Slabs

68 POPOUTS

N

1.00 Slabs

74 JOINT SPALL

L

1.00 Slabs

75 CORNER SPALL

L

1.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 32

Branch - Section ID: T02DA - 003

Branch Name: TAXIWAY 02

Use: TAXIWAY

LCD: 6/1/1979
 Surface Type: PCC
 Rank: P
 Section Area (sf): 62,872.00
 Length (ft): 2,020.00
 Width (ft): 30.00
 From: TAXIWAY 02 SECT 02
 To: TAXIWAY 01 SECT 02

PCI Family: IowaPCCTWNCE_Enhanced

Slabs: 507
 Slab Length (ft): 12.40
 Slab Width (ft): 10.00
 Joint Length (ft): 9,230.66
 Last Insp Date: 2/21/2023
 PCI: 41
 Total Samples: 25
 Surveyed: 7

Section Comments: AVERAGE SLAB LENGTH ENTERED AND DRAWN

Inspection Comments:

Sample Number: 02

Sample Type: R
 Sample PCI: 32
 Sample Area (Slabs): 21.00

Sample Comments:

63 LINEAR CRACKING	H	1.00 Slabs
63 LINEAR CRACKING	L	5.00 Slabs
63 LINEAR CRACKING	M	9.00 Slabs
65 JOINT SEAL DAMAGE	H	21.00 Slabs
76 ASR	L	3.00 Slabs
76 ASR	M	1.00 Slabs

Sample Number: 05

Sample Type: R
 Sample PCI: 70
 Sample Area (Slabs): 21.00

Sample Comments:

63 LINEAR CRACKING	L	1.00 Slabs
63 LINEAR CRACKING	M	2.00 Slabs
65 JOINT SEAL DAMAGE	H	21.00 Slabs
74 JOINT SPALL	L	1.00 Slabs

Sample Number: 08

Sample Type: R
 Sample PCI: 76
 Sample Area (Slabs): 21.00

Sample Comments:

63 LINEAR CRACKING	M	2.00 Slabs
65 JOINT SEAL DAMAGE	H	21.00 Slabs

RE-INSPECTION REPORT

DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 33

Sample Number: 11

Sample Type: R

Sample Comments:

Sample PCI: 27

Sample Area (Slabs): 21.00

63 LINEAR CRACKING	H	1.00 Slabs
63 LINEAR CRACKING	L	2.00 Slabs
63 LINEAR CRACKING	M	10.00 Slabs
65 JOINT SEAL DAMAGE	H	21.00 Slabs
71 FAULTING	L	2.00 Slabs
72 SHATTERED SLAB	M	1.00 Slabs
74 JOINT SPALL	H	1.00 Slabs

Sample Number: 17

Sample Type: R

Sample Comments:

Sample PCI: 25

Sample Area (Slabs): 21.00

63 LINEAR CRACKING	L	2.00 Slabs
63 LINEAR CRACKING	M	8.00 Slabs
65 JOINT SEAL DAMAGE	H	21.00 Slabs
72 SHATTERED SLAB	H	1.00 Slabs
72 SHATTERED SLAB	M	1.00 Slabs

Sample Number: 20

Sample Type: R

Sample Comments:

Sample PCI: 35

Sample Area (Slabs): 21.00

63 LINEAR CRACKING	L	4.00 Slabs
63 LINEAR CRACKING	M	12.00 Slabs
65 JOINT SEAL DAMAGE	H	21.00 Slabs
74 JOINT SPALL	M	1.00 Slabs
75 CORNER SPALL	M	1.00 Slabs

Sample Number: 23

Sample Type: R

Sample Comments:

Sample PCI: 27

Sample Area (Slabs): 22.00

63 LINEAR CRACKING	L	3.00 Slabs
63 LINEAR CRACKING	M	5.00 Slabs
65 JOINT SEAL DAMAGE	H	22.00 Slabs
72 SHATTERED SLAB	H	1.00 Slabs
72 SHATTERED SLAB	L	3.00 Slabs
74 JOINT SPALL	M	2.00 Slabs
75 CORNER SPALL	L	1.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 34

Branch - Section ID: T02DA - 004

Branch Name: TAXIWAY 02

Use: TAXIWAY

LCD: 6/3/2015

PCI Family: IowaPCCTWNCE_Enhanced

Surface Type: PCC

Rank: P

Section Area (sf): 10,542.00

Length (ft): 290.00

Width (ft): 35.00

From: SEE MAP

To: SEE MAP

Slabs: 120

Section Comments:

Slab Length (ft): 10.00

Slab Width (ft): 8.75

Joint Length (ft): 1,921.45

Last Insp Date: 2/21/2023

Inspection Comments:

PCI: 98

Total Samples: 6

Surveyed: 4

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 35

Branch - Section ID: T03DA - 001

Branch Name: TAXIWAY 03

Use: TAXIWAY

LCD: 6/2/1949
 Surface Type: PCC
 Rank: P
 Section Area (sf): 62,394.00
 Length (ft): 1,200.00
 Width (ft): 50.00
 From: APRON 03
 To: TAXIWAY 01 SECT 02

PCI Family: IowaPCCTWNCE_Enhanced

Slabs: 253
 Slab Length (ft): 19.70
 Slab Width (ft): 12.50
 Joint Length (ft): 6,858.85

Section Comments:

Last Insp Date: 2/21/2023
 PCI: 25
 Total Samples: 13
 Surveyed: 6

Inspection Comments:

Sample Number: 02

Sample Type: R
 Sample PCI: 29
 Sample Area (Slabs): 20.00

Sample Comments:

62 CORNER BREAK	M	1.00 Slabs
63 LINEAR CRACKING	H	1.00 Slabs
63 LINEAR CRACKING	L	3.00 Slabs
63 LINEAR CRACKING	M	4.00 Slabs
65 JOINT SEAL DAMAGE	M	20.00 Slabs
72 SHATTERED SLAB	L	1.00 Slabs
72 SHATTERED SLAB	M	1.00 Slabs
73 SHRINKAGE CRACKING	N	1.00 Slabs
74 JOINT SPALL	L	1.00 Slabs
74 JOINT SPALL	M	6.00 Slabs
75 CORNER SPALL	L	1.00 Slabs
75 CORNER SPALL	M	2.00 Slabs

Sample Number: 03

Sample Type: R
 Sample PCI: 38
 Sample Area (Slabs): 20.00

Sample Comments:

63 LINEAR CRACKING	L	2.00 Slabs
63 LINEAR CRACKING	M	8.00 Slabs
65 JOINT SEAL DAMAGE	M	20.00 Slabs
74 JOINT SPALL	L	2.00 Slabs
74 JOINT SPALL	M	1.00 Slabs
75 CORNER SPALL	L	3.00 Slabs

RE-INSPECTION REPORT

DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 36

Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 40

Sample Area (Slabs): 20.00

63 LINEAR CRACKING	L	2.00 Slabs
63 LINEAR CRACKING	M	7.00 Slabs
65 JOINT SEAL DAMAGE	M	20.00 Slabs
72 SHATTERED SLAB	L	1.00 Slabs
73 SHRINKAGE CRACKING	N	1.00 Slabs
74 JOINT SPALL	L	1.00 Slabs
74 JOINT SPALL	M	1.00 Slabs
75 CORNER SPALL	L	1.00 Slabs

Sample Number: 07

Sample Type: R

Sample Comments:

Sample PCI: 7

Sample Area (Slabs): 20.00

63 LINEAR CRACKING	L	1.00 Slabs
63 LINEAR CRACKING	M	3.00 Slabs
65 JOINT SEAL DAMAGE	H	20.00 Slabs
72 SHATTERED SLAB	H	3.00 Slabs
72 SHATTERED SLAB	L	3.00 Slabs
72 SHATTERED SLAB	M	6.00 Slabs
74 JOINT SPALL	L	1.00 Slabs
74 JOINT SPALL	M	2.00 Slabs
75 CORNER SPALL	M	2.00 Slabs

Sample Number: 08

Sample Type: R

Sample Comments:

Sample PCI: 29

Sample Area (Slabs): 20.00

63 LINEAR CRACKING	L	7.00 Slabs
63 LINEAR CRACKING	M	4.00 Slabs
65 JOINT SEAL DAMAGE	M	20.00 Slabs
72 SHATTERED SLAB	L	3.00 Slabs
72 SHATTERED SLAB	M	2.00 Slabs
74 JOINT SPALL	L	1.00 Slabs
74 JOINT SPALL	M	1.00 Slabs

Sample Number: 10

Sample Type: R

Sample Comments:

Sample PCI: 4

Sample Area (Slabs): 20.00

63 LINEAR CRACKING	L	2.00 Slabs
63 LINEAR CRACKING	M	10.00 Slabs
72 SHATTERED SLAB	H	1.00 Slabs
72 SHATTERED SLAB	L	4.00 Slabs
72 SHATTERED SLAB	M	3.00 Slabs
74 JOINT SPALL	M	1.00 Slabs
75 CORNER SPALL	L	3.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 37

Branch - Section ID: T03DA - 002

Branch Name: TAXIWAY 03

Use: TAXIWAY

LCD: 6/1/1947

PCI Family: IowaPCCTWNCE_Enhanced

Surface Type: PCC

Rank: P

Section Area (sf): 17,612.00

Length (ft): 340.00

Width (ft): 50.00

From: TAXIWAY 01 SECT 02

To: RUNWAY 15/33

Slabs: 70

Section Comments:

Slab Length (ft): 20.00

Slab Width (ft): 12.50

Joint Length (ft): 1,885.52

Last Insp Date: 2/21/2023

Inspection Comments:

PCI: 60

Total Samples: 4

Surveyed: 3

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 48

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	L	20.00 Slabs
66 SMALL PATCH	L	2.00 Slabs
67 LARGE PATCH	L	5.00 Slabs
74 JOINT SPALL	L	2.00 Slabs
76 ASR	L	7.00 Slabs
76 ASR	M	5.00 Slabs

Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 58

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE	L	20.00 Slabs
66 SMALL PATCH	L	2.00 Slabs
67 LARGE PATCH	L	3.00 Slabs
76 ASR	L	5.00 Slabs
76 ASR	M	3.00 Slabs

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 78

Sample Area (Slabs): 16.00

63 LINEAR CRACKING	L	1.00 Slabs
65 JOINT SEAL DAMAGE	L	16.00 Slabs
67 LARGE PATCH	L	1.00 Slabs
73 SHRINKAGE CRACKING	N	1.00 Slabs
76 ASR	L	2.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 38

Branch - Section ID: T03DA - 003

Branch Name: TAXIWAY 03

Use: TAXIWAY

LCD: 4/3/2019

PCI Family: IowaPCCTWNCE_Enhanced

Surface Type: PCC

Rank: P

Section Area (sf): 16,547.00

Length (ft): 300.00

Width (ft): 50.00

From: .

To: .

Slabs: 106

Section Comments:

Slab Length (ft): 12.50

Slab Width (ft): 12.50

Joint Length (ft): 2,261.42

Last Insp Date: 2/21/2023

Inspection Comments:

PCI: 98

Total Samples: 5

Surveyed: 4

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 22.00

65 JOINT SEAL DAMAGE

L

22.00 Slabs

Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

RE-INSPECTION REPORT

DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 39

Branch - Section ID: T04DA - 001

Branch Name: TAXIWAY 04

Use: TAXIWAY

LCD: 6/1/1948

PCI Family: IowaPCCTWNCE_Enhanced

Surface Type: PCC

Rank: P

Section Area (sf): 7,628.00

Length (ft): 95.00

Width (ft): 50.00

From: APRON 01

To: TAXIWAY 01 SECT 02

Slabs: 34

Section Comments:

Slab Length (ft): 18.00

Slab Width (ft): 12.50

Joint Length (ft): 801.16

Last Insp Date: 2/21/2023

Inspection Comments:

PCI: 12

Total Samples: 2

Surveyed: 2

Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 8

Sample Area (Slabs): 14.00

63 LINEAR CRACKING	L	2.00 Slabs
63 LINEAR CRACKING	M	6.00 Slabs
65 JOINT SEAL DAMAGE	H	14.00 Slabs
66 SMALL PATCH	L	1.00 Slabs
67 LARGE PATCH	L	2.00 Slabs
68 POPOUTS	N	6.00 Slabs
72 SHATTERED SLAB	M	1.00 Slabs
76 ASR	L	2.00 Slabs
76 ASR	M	7.00 Slabs

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 14

Sample Area (Slabs): 20.00

63 LINEAR CRACKING	L	3.00 Slabs
63 LINEAR CRACKING	M	7.00 Slabs
65 JOINT SEAL DAMAGE	H	20.00 Slabs
66 SMALL PATCH	L	1.00 Slabs
67 LARGE PATCH	L	3.00 Slabs
76 ASR	L	5.00 Slabs
76 ASR	M	11.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 40

Branch - Section ID: T05DA - 001

Branch Name: TAXIWAY 05

Use: TAXIWAY

LCD: 6/1/1948

PCI Family: IowaPCCTWNCE_Enhanced

Surface Type: PCC

Rank: P

Section Area (sf): 7,628.00

Length (ft): 95.00

Width (ft): 50.00

From: APRON 01

To: TAXIWAY 01 SECT 02

Slabs: 33

Section Comments:

Slab Length (ft): 18.50

Slab Width (ft): 12.50

Joint Length (ft): 789.71

Last Insp Date: 2/21/2023

Inspection Comments:

PCI: 18

Total Samples: 2

Surveyed: 2

Sample Number: 002

Sample Type: R

Sample Comments:

Sample PCI: 25

Sample Area (Slabs): 20.00

62 CORNER BREAK	L	1.00 Slabs
63 LINEAR CRACKING	L	4.00 Slabs
63 LINEAR CRACKING	M	8.00 Slabs
65 JOINT SEAL DAMAGE	H	20.00 Slabs
67 LARGE PATCH	L	1.00 Slabs
68 POPOUTS	N	4.00 Slabs
71 FAULTING	L	2.00 Slabs
76 ASR	L	5.00 Slabs
76 ASR	M	2.00 Slabs

Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 7

Sample Area (Slabs): 13.00

63 LINEAR CRACKING	L	3.00 Slabs
63 LINEAR CRACKING	M	9.00 Slabs
65 JOINT SEAL DAMAGE	H	13.00 Slabs
67 LARGE PATCH	L	4.00 Slabs
68 POPOUTS	N	5.00 Slabs
72 SHATTERED SLAB	L	1.00 Slabs
76 ASR	L	2.00 Slabs
76 ASR	M	5.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 41

Branch - Section ID: T06DA - 001

Branch Name: TAXIWAY 06

Use: TAXIWAY

LCD: 8/1/1996 PCI Family: IowaPCCTWNCE_Enhanced
 Surface Type: PCC
 Rank: P
 Section Area (sf): 13,887.00
 Length (ft): 208.00
 Width (ft): 40.00
 From: APRON 02
 To: TAXIWAY 02 SECT 03
 Slabs: 115 Section Comments: AVERAGE
 Slab Length (ft): 11.00
 Slab Width (ft): 11.00
 Joint Length (ft): 2,110.97
 Last Insp Date: 2/21/2023 Inspection Comments:
 PCI: 84
 Total Samples: 5
 Surveyed: 4

Sample Number: 01

Sample Type: R Sample Comments:
 Sample PCI: 88
 Sample Area (Slabs): 28.00
 65 JOINT SEAL DAMAGE H 28.00 Slabs

Sample Number: 02

Sample Type: R Sample Comments:
 Sample PCI: 83
 Sample Area (Slabs): 23.00
 63 LINEAR CRACKING L 2.00 Slabs
 65 JOINT SEAL DAMAGE H 23.00 Slabs

Sample Number: 03

Sample Type: R Sample Comments:
 Sample PCI: 83
 Sample Area (Slabs): 18.00
 63 LINEAR CRACKING L 2.00 Slabs
 65 JOINT SEAL DAMAGE H 18.00 Slabs

Sample Number: 04

Sample Type: R Sample Comments:
 Sample PCI: 83
 Sample Area (Slabs): 23.00
 65 JOINT SEAL DAMAGE H 23.00 Slabs
 74 JOINT SPALL M 1.00 Slabs
 75 CORNER SPALL L 1.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 42

Branch - Section ID: T07DA - 001

Branch Name: TAXIWAY 07

Use: TAXIWAY

LCD: 6/30/1994

PCI Family: IowaPCCTWNCE_Enhanced

Surface Type: PCC

Rank: P

Section Area (sf): 62,407.00

Length (ft): 1,526.00

Width (ft): 35.00

From: TAXIWAY 04

To: SOUTH END OF 15/33

Slabs: 369

Section Comments:

Slab Length (ft): 13.00

Slab Width (ft): 13.00

Joint Length (ft): 7,777.12

Last Insp Date: 2/21/2023

Inspection Comments:

PCI: 88

Total Samples: 19

Surveyed: 7

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 86

Sample Area (Slabs): 21.00

65 JOINT SEAL DAMAGE

H

21.00 Slabs

74 JOINT SPALL

L

1.00 Slabs

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 84

Sample Area (Slabs): 21.00

65 JOINT SEAL DAMAGE

H

21.00 Slabs

74 JOINT SPALL

L

3.00 Slabs

Sample Number: 07

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 21.00

65 JOINT SEAL DAMAGE

L

21.00 Slabs

Sample Number: 10

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 21.00

65 JOINT SEAL DAMAGE

L

21.00 Slabs

Sample Number: 12

Sample Type: R

Sample Comments:

Sample PCI: 82

Sample Area (Slabs): 21.00

71 FAULTING

L

1.00 Slabs

74 JOINT SPALL

M

1.00 Slabs

76 ASR

L

3.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 43

Sample Number: 14

Sample Type: R

Sample Comments:

Sample PCI: 84

Sample Area (Slabs): 21.00

65 JOINT SEAL DAMAGE

L

21.00 Slabs

71 FAULTING

L

4.00 Slabs

Sample Number: 17

Sample Type: R

Sample Comments:

Sample PCI: 83

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

M

20.00 Slabs

71 FAULTING

L

2.00 Slabs

74 JOINT SPALL

M

1.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 44

Branch - Section ID: TH01DA - 001

Branch Name: T-HANGAR 01

Use: T-HANGAR

LCD: 6/1/2008

PCI Family: IowaASPHALTTHNorthern

Surface Type: AAC

Rank: P

Section Area (sf): 10,915.00

Length (ft): 530.00

Width (ft): 20.00

From: .

To: .

Slabs:

Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 2/21/2023

Inspection Comments:

PCI: 26

Total Samples: 2

Surveyed: 2

Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 29

Sample Area (SF): 5,215.00

41 ALLIGATOR CRACKING	M	450.00 SF	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	240.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	485.00 Ft	2NDY, FS, W
57 WEATHERING	M	5,215.00 SF	

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 24

Sample Area (SF): 5,700.00

41 ALLIGATOR CRACKING	L	215.00 SF	
41 ALLIGATOR CRACKING	M	620.00 SF	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	315.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	240.00 Ft	W
57 WEATHERING	M	5,700.00 SF	

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 45

Branch - Section ID: TH01DA - 002

Branch Name: T-HANGAR 01

Use: T-HANGAR

LCD: 1/2/1949 PCI Family: IowaASPHALTTHNorthern

Surface Type: AC

Rank: P

Section Area (sf): 42,929.00

Length (ft): 2,090.00

Width (ft): 20.00

From: .

To: .

Slabs:

Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 2/21/2023

Inspection Comments:

PCI: 16

Total Samples: 8

Surveyed: 4

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 21

Sample Area (SF): 5,000.00

41 ALLIGATOR CRACKING	L	85.00 SF	
41 ALLIGATOR CRACKING	M	520.00 SF	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	135.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	L	20.00 Ft	LS
48 LONGITUDINAL/TRANSVERSE CRACKING	M	220.00 Ft	2NDY, FS, W
50 PATCHING	L	400.00 SF	PCC
50 PATCHING	L	160.00 SF	
50 PATCHING	M	40.00 SF	
57 WEATHERING	M	4,400.00 SF	

Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 21

Sample Area (SF): 6,000.00

41 ALLIGATOR CRACKING	L	110.00 SF	
41 ALLIGATOR CRACKING	M	610.00 SF	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	20.00 Ft	LS
48 LONGITUDINAL/TRANSVERSE CRACKING	L	110.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	130.00 Ft	2NDY, FS, W
50 PATCHING	L	90.00 SF	
50 PATCHING	L	500.00 SF	PCC
50 PATCHING	M	60.00 SF	
53 RUTTING	L	44.00 SF	
57 WEATHERING	M	5,350.00 SF	

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 46

Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 11

Sample Area (SF): 6,320.00

41 ALLIGATOR CRACKING	M	2,500.00 SF	
43 BLOCK CRACKING	L	1,000.00 SF	LU/LS TYP. 5X5
48 LONGITUDINAL/TRANSVERSE CRACKING	L	740.00 Ft	LU
50 PATCHING	L	160.00 SF	
52 RAVELING	H	15.00 SF	MISSING SURFACE LAYER
57 WEATHERING	M	6,145.00 SF	

Sample Number: 07

Sample Type: R

Sample Comments:

Sample PCI: 11

Sample Area (SF): 4,000.00

41 ALLIGATOR CRACKING	M	2,400.00 SF	
48 LONGITUDINAL/TRANSVERSE CRACKING	L	135.00 Ft	LU
48 LONGITUDINAL/TRANSVERSE CRACKING	M	225.00 Ft	2NDY, FS, W
50 PATCHING	L	357.00 SF	PCC
50 PATCHING	M	80.00 SF	
53 RUTTING	L	76.00 SF	
53 RUTTING	M	54.00 SF	
56 SWELLING	L	120.00 SF	
56 SWELLING	M	120.00 SF	
57 WEATHERING	M	3,563.00 SF	

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 47

Branch - Section ID: TH01DA - 003

Branch Name: T-HANGAR 01

Use: T-HANGAR

LCD: 10/1/2010 PCI Family: IOWA PCCTH NE NCE

Surface Type: PCC

Rank: P

Section Area (sf): 42,763.00

Length (ft): 1,175.00

Width (ft): 35.00

From: .

To: .

Slabs: 391

Section Comments:

Slab Length (ft): 12.50

Slab Width (ft): 8.75

Joint Length (ft): 7,050.05

Last Insp Date: 2/21/2023

Inspection Comments:

PCI: 95

Total Samples: 20

Surveyed: 7

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 07

Sample Type: R

Sample Comments:

Sample PCI: 82

Sample Area (Slabs): 20.00

63 LINEAR CRACKING

L

1.00 Slabs

65 JOINT SEAL DAMAGE

L

20.00 Slabs

67 LARGE PATCH

L

1.00 Slabs

71 FAULTING

M

1.00 Slabs

AT BREAK WITH BUILDING PA

Sample Number: 10

Sample Type: R

Sample Comments:

Sample PCI: 92

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

67 LARGE PATCH

L

2.00 Slabs

Sample Number: 12

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 48

Sample Number: 15

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 17

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

RE-INSPECTION REPORT DAVENPORT MUNICIPAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: DVN

Page 49

Branch - Section ID: TH01DA - 004

Branch Name: T-HANGAR 01

Use: T-HANGAR

LCD: 10/2/2005
 Surface Type: PCC
 Rank: P
 Section Area (sf): 18,886.00
 Length (ft): 800.00
 Width (ft): 20.00
 From: .
 To: .
 Slabs: 189
 Slab Length (ft): 10.00
 Slab Width (ft): 10.00
 Joint Length (ft): 2,809.29
 Last Insp Date: 2/21/2023
 PCI: 91
 Total Samples: 10
 Surveyed: 5

PCI Family: IowaPCCTH NE NCE

Section Comments:

Inspection Comments:

Sample Number: 03

Sample Type: R
 Sample PCI: 90
 Sample Area (Slabs): 24.00

Sample Comments:

62 CORNER BREAK	L	1.00 Slabs
65 JOINT SEAL DAMAGE	M	24.00 Slabs

Sample Number: 05

Sample Type: R
 Sample PCI: 91
 Sample Area (Slabs): 20.00

Sample Comments:

65 JOINT SEAL DAMAGE	M	20.00 Slabs
75 CORNER SPALL	L	1.00 Slabs

Sample Number: 06

Sample Type: R
 Sample PCI: 91
 Sample Area (Slabs): 20.00

Sample Comments:

65 JOINT SEAL DAMAGE	M	20.00 Slabs
74 JOINT SPALL	L	1.00 Slabs

Sample Number: 08

Sample Type: R
 Sample PCI: 90
 Sample Area (Slabs): 20.00

Sample Comments:

63 LINEAR CRACKING	L	2.00 Slabs
65 JOINT SEAL DAMAGE	L	20.00 Slabs

Sample Number: 09

Sample Type: R
 Sample PCI: 92
 Sample Area (Slabs): 20.00

Sample Comments:

65 JOINT SEAL DAMAGE	L	20.00 Slabs
75 CORNER SPALL	L	1.00 Slabs
75 CORNER SPALL	M	1.00 Slabs

APPENDIX D

WORK HISTORY REPORT

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: DVN

Page 1

Network: DAVENPORT MUNICIPAL AIRPORT

Branch - Section ID: A01DA - 001

LCD: 6/2/1949
Use: APRON
Rank: P
Surface: PCC

Length (ft): 300.00
Width (ft): 150.00
True Area (sf): 45,000.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-02-1949	NC-PC	New Construction - PCC	\$0.00	10.00	True	10" P-501 PCC CONSTRUCTION
06-01-1949	SB-AG	Subbase - Aggregate	\$0.00	7.00	False	7" P-154 SUBBASE

Branch - Section ID: A02DA - 001

LCD: 6/1/2001
Use: APRON
Rank: P
Surface: PCC

Length (ft): 300.00
Width (ft): 200.00
True Area (sf): 61,421.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
01-02-2016	SL-PC	Slab Replacement - PCC	\$0.00	0.00	False	EST; SLAB REPLACEMENT
01-01-2016	JS-SI	Joint Seal - Silicon	\$0.00	0.00	False	EST; JOINT SEAL REPAIR
06-01-2001	CR-PC	Complete Reconstruction - PCC	\$0.00	0.00	True	PCC COMPLETE RECONSTRUCTION
06-02-1949	NC-PC	New Construction - PCC	\$0.00	10.00	True	10" P-501 PCC CONSTRUCTION
06-01-1949	SB-AG	Subbase - Aggregate	\$0.00	7.00	False	7" P-154 SUBBASE

Branch - Section ID: A02DA - 002

LCD: 8/1/1996
Use: APRON
Rank: P
Surface: PCC

Length (ft): 145.00
Width (ft): 120.00
True Area (sf): 17,878.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2019	SL-PC	Slab Replacement - PCC	\$0.00	0.00	False	EST; SLAB REPLACEMENT
08-01-1996	CR-PC	Complete Reconstruction - PCC	\$0.00	0.00	True	PCC RECONSTRUCTION
06-01-1950	NC-AC	New Construction - AC	\$0.00	0.00	True	AC CONSTRUCTION

Branch - Section ID: A03DA - 001

LCD: 6/2/1949
Use: APRON
Rank: P
Surface: PCC

Length (ft): 200.00
Width (ft): 140.00
True Area (sf): 28,137.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-02-1949	NC-PC	New Construction - PCC	\$0.00	10.00	True	10" P-501 PCC CONSTRUCTION
06-01-1949	SB-AG	Subbase - Aggregate	\$0.00	7.00	False	7" P-154 SUBBASE

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: DVN

Page 2

Branch - Section ID: A04DA - 001

LCD: 6/2/1949
 Use: APRON
 Rank: P
 Surface: PCC

Length (ft): 295.00
 Width (ft): 200.00
 True Area (sf): 63,183.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-02-1949	NC-PC	New Construction - PCC	\$0.00	10.00	True	10" P-501 PCC CONSTRUCTION
06-01-1949	SB-AG	Subbase - Aggregate	\$0.00	7.00	False	7" P-154 SUBBASE

Branch - Section ID: R03DA - 001

LCD: 6/3/2015
 Use: RUNWAY
 Rank: S
 Surface: PCC

Length (ft): 4,000.00
 Width (ft): 100.00
 True Area (sf): 389,389.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-03-2015	CR-PC	Complete Reconstruction - PCC	\$0.00	8.00	True	8" P-501 PCC RECONSTRUCTION
06-02-2015	BA-AG	Base Course - Aggregate	\$0.00	8.00	False	8" P-209 CAB
06-01-2015	SG-ST	Subgrade - Stabilized	\$0.00	12.00	False	12" P-158 FLY ASH TREATED SUBGRADE
06-01-2009	PA-PP	Patching - PCC Partial Depth	\$0.00	0.00	False	EST; PCC PARTIAL DEPTH PATCHING
06-01-2004	PA-PF	Patching - PCC Full Depth	\$0.00	0.00	False	PCC FULL DEPTH PATCHING
06-01-2003	PA-PF	Patching - PCC Full Depth	\$0.00	0.00	False	PCC FULL DEPTH PATCHING
06-01-1994	JS-LC	Joint Seal (Localized)	\$0.00	0.00	False	JOINT SEAL REPAIR
06-01-1994	CS-PC	Crack Sealing - PCC	\$0.00	0.00	False	CRACK SEAL REPAIR
06-02-1947	NC-PC	New Construction - PCC	\$0.00	9.00	True	9" P-501 PC CONSTRUCTION
06-01-1947	SB-AG	Subbase - Aggregate	\$0.00	7.00	False	7" P-154 SUBBASE

Branch - Section ID: R15DA - 001

LCD: 4/3/2019
 Use: RUNWAY
 Rank: P
 Surface: PCC

Length (ft): 2,693.00
 Width (ft): 100.00
 True Area (sf): 270,860.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
04-03-2019	CR-PC	Complete Reconstruction - PCC	\$0.00	10.00	True	10" P-501 COMPLETE RECONSTRUCTION
04-02-2019	BA-AG	Base Course - Aggregate	\$0.00	12.00	False	12" P-219 RECYCLED CONCRETE AGGREGATE BASE COURSE
04-01-2019	SG-ST	Subgrade - Stabilized	\$0.00	9.00	False	9" P-157 CEMENT TREATED SUBGRADE
06-01-2015	PA-PP	Patching - PCC Partial Depth	\$0.00	0.00	False	2013-2015; PCC PARTIAL DEPTH PATCHING
06-01-2015	SL-PC	Slab Replacement - PCC	\$0.00	0.00	False	2013-2015; SLAB REPLACEMENT
06-01-2004	PA-PF	Patching - PCC Full Depth	\$0.00	0.00	False	PCC FULL DEPTH PATCHING
06-01-2003	PA-PF	Patching - PCC Full Depth	\$0.00	0.00	False	PCC FULL DEPTH PATCHING
06-01-1997	JS-LC	Joint Seal (Localized)	\$0.00	0.00	False	JOINT SEAL REPAIR
06-01-1997	CS-PC	Crack Sealing - PCC	\$0.00	0.00	False	CRACK SEAL REPAIR
06-02-1947	NC-PC	New Construction - PCC	\$0.00	9.00	True	9" P-501 PCC CONSTRUCTION
06-01-1947	SB-AG	Subbase - Aggregate	\$0.00	7.00	False	7" P-154 SUBBASE

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: DVN

Page 3

Branch - Section ID: R15DA - 002

LCD: 6/30/1994
 Use: RUNWAY
 Rank: P
 Surface: PCC

Length (ft): 1,255.00
 Width (ft): 100.00
 True Area (sf): 125,500.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
04-01-2019	JS-LC	Joint Seal (Localized)	\$0.00	0.00	False	JOINT SEAL REPAIR
06-01-2015	PA-PP	Patching - PCC Partial Depth	\$0.00	0.00	False	PCC PARTIAL DEPTH PATCHING
06-01-2004	PA-PF	Patching - PCC Full Depth	\$0.00	0.00	False	PCC FULL DEPTH PATCHING
06-01-2003	PA-PF	Patching - PCC Full Depth	\$0.00	0.00	False	PCC FULL DEPTH PATCHING
06-01-1997	JS-LC	Joint Seal (Localized)	\$0.00	0.00	False	JOINT SEAL REPAIR
06-01-1997	CS-PC	Crack Sealing - PCC	\$0.00	0.00	False	CRACK SEAL REPAIR
06-30-1994	NC-PC	New Construction - PCC	\$0.00	10.00	True	10" P-501 PCC CONSTRUCTION
06-29-1994	BA-AG	Base Course - Aggregate	\$0.00	4.00	False	4" P-209 AGG BASE COURSE
06-28-1994	SB-AG	Subbase - Aggregate	\$0.00	4.00	False	4" P-154 SUBBASE
06-27-1994	SG-CO	Subgrade - Compacted	\$0.00	12.00	False	12" COMPACTED SUBGRADE

Branch - Section ID: R15DA - 003

LCD: 6/3/2015
 Use: RUNWAY
 Rank: P
 Surface: PCC

Length (ft): 1,572.00
 Width (ft): 100.00
 True Area (sf): 157,200.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-03-2015	CR-PC	Complete Reconstruction - PCC	\$0.00	10.00	True	10" P-501 PCC RECONSTRUCTION
06-02-2015	BA-AG	Base Course - Aggregate	\$0.00	6.00	False	6" P-209 CAB
06-01-2015	SG-ST	Subgrade - Stabilized	\$0.00	12.00	False	12" P-158 FLY ASH TREATED SUBGRADE
06-01-1947	NC-PC	New Construction - PCC	\$0.00	0.00	True	PCC CONSTRUCTION

Branch - Section ID: T01DA - 001

LCD: 6/2/1949
 Use: TAXIWAY
 Rank: P
 Surface: PCC

Length (ft): 1,100.00
 Width (ft): 50.00
 True Area (sf): 55,043.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
04-02-2019	JS-LC	Joint Seal (Localized)	\$0.00	0.00	False	JOINT SEAL REPAIR. PARTIAL ONLY, UP TO HOLD LINE
04-01-2019	SL-PC	Slab Replacement - PCC	\$0.00	0.00	False	SLAB REPLACEMENT
06-01-2013	PA-PP	Patching - PCC Partial Depth	\$0.00	0.00	False	PCC PARTIAL DEPTH PATCHING
06-02-1949	NC-PC	New Construction - PCC	\$0.00	10.00	True	10" P-501 PCC CONSTRUCTION
06-01-1949	SB-AG	Subbase - Aggregate	\$0.00	7.00	False	7" P-154 SUBBASE

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: DVN

Page 4

Branch - Section ID: T01DA - 002

LCD: 6/1/1949
Use: TAXIWAY
Rank: P
Surface: PCC

Length (ft): 1,560.00
Width (ft): 50.00
True Area (sf): 78,251.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2021	PA-PP	Patching - PCC Partial Depth	\$0.00	0.00	False	PCC PATCHING; FIELD ESTIMATE
01-01-2016	PA-PP	Patching - PCC Partial Depth	\$0.00	0.00	False	EST; PCC PARTIAL DEPTH PATCHING
08-01-2014	PA-PP	Patching - PCC Partial Depth	\$0.00	0.00	False	PCC PARTIAL DEPTH PATCHING
06-01-1949	NC-PC	New Construction - PCC	\$0.00	10.00	True	10" P-501 PCC CONSTRUCTION
06-01-1949	SB-AG	Subbase - Aggregate	\$0.00	7.00	False	7" P-154 SUBBASE

Branch - Section ID: T01DA - 003

LCD: 6/2/1949
Use: TAXIWAY
Rank: P
Surface: PCC

Length (ft): 158.00
Width (ft): 150.00
True Area (sf): 22,277.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
03-01-2015	JS-LC	Joint Seal (Localized)	\$0.00	0.00	False	JOINT SEAL REPAIR
08-01-2014	SL-PC	Slab Replacement - PCC	\$0.00	0.00	False	SLAB REPLACEMENT
08-01-2014	PA-PP	Patching - PCC Partial Depth	\$0.00	0.00	False	PCC PARTIAL DEPTH PATCHING
06-02-1949	NC-PC	New Construction - PCC	\$0.00	10.00	True	10" P-501 PCC CONSTRUCTION
06-01-1949	SB-AG	Subbase - Aggregate	\$0.00	7.00	False	7" P-154 SUBBASE

Branch - Section ID: T01DA - 004

LCD: 6/2/1949
Use: TAXIWAY
Rank: P
Surface: PCC

Length (ft): 1,085.00
Width (ft): 50.00
True Area (sf): 57,742.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2021	PA-PP	Patching - PCC Partial Depth	\$0.00	0.00	False	PCC PATCHING; FIELD ESTIMATE
04-02-2019	JS-LC	Joint Seal (Localized)	\$0.00	0.00	False	JOINT SEAL REPAIR. PARTIAL, UP TO HOLD LINES
04-01-2019	SL-PC	Slab Replacement - PCC	\$0.00	0.00	False	SLAB REPLACEMENT
03-01-2015	JS-LC	Joint Seal (Localized)	\$0.00	0.00	False	JOINT SEAL REPAIR
06-02-1949	NC-PC	New Construction - PCC	\$0.00	10.00	True	10" P-501 PCC CONSTRUCTION
06-01-1949	SB-AG	Subbase - Aggregate	\$0.00	7.00	False	7" P-154 SUBBASE

Branch - Section ID: T01DA - 005

LCD: 6/3/2015
Use: TAXIWAY
Rank: P
Surface: PCC

Length (ft): 330.00
Width (ft): 50.00
True Area (sf): 23,533.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-03-2015	CR-PC	Complete Reconstruction - PCC	\$0.00	10.00	True	10" P-501 PCC CONSTRUCTION
06-02-2015	BA-AG	Base Course - Aggregate	\$0.00	6.00	False	6" P-209 CAB
06-01-2015	SG-ST	Subgrade - Stabilized	\$0.00	12.00	False	12" FLY ASH TREATED SUBGRADE
06-02-1949	NC-PC	New Construction - PCC	\$0.00	10.00	True	10" P-501 PCC CONSTRUCTION

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: DVN

Page 5

Branch - Section ID: T01DA - 006

LCD: 4/3/2019
 Use: TAXIWAY
 Rank: P
 Surface: PCC

Length (ft): 750.00
 Width (ft): 50.00
 True Area (sf): 40,715.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
04-03-2019	CR-PC	Complete Reconstruction - PCC	\$0.00	10.00	True	10" P-501 COMPELTE RECONSTRUCTION
04-02-2019	BA-AG	Base Course - Aggregate	\$0.00	12.00	False	12" P-219 RECYCLED CONCRETE AGGREGATE BASE COURSE
04-01-2019	SG-ST	Subgrade - Stabilized	\$0.00	9.00	False	9" P-157 CEMENT TREATED SUBGRADE
06-02-1949	NC-PC	New Construction - PCC	\$0.00	10.00	True	10" P-501 PCC CONSTRUCTION

Branch - Section ID: T02DA - 001

LCD: 6/1/1979
 Use: TAXIWAY
 Rank: P
 Surface: PCC

Length (ft): 75.00
 Width (ft): 40.00
 True Area (sf): 3,040.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-1979	NC-PC	New Construction - PCC	\$0.00	0.00	True	PCC CONSTRUCTION

Branch - Section ID: T02DA - 002

LCD: 1/1/2005
 Use: TAXIWAY
 Rank: P
 Surface: PCC

Length (ft): 230.00
 Width (ft): 40.00
 True Area (sf): 10,494.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
01-01-2005	CR-PC	Complete Reconstruction - PCC	\$0.00	0.00	True	PCC RECONSTRUCTION
06-01-1972	NC-PC	New Construction - PCC	\$0.00	0.00	True	PCC CONSTRUCTION

Branch - Section ID: T02DA - 003

LCD: 6/1/1979
 Use: TAXIWAY
 Rank: P
 Surface: PCC

Length (ft): 2,020.00
 Width (ft): 30.00
 True Area (sf): 62,872.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2021	CS-PC	Crack Sealing - PCC	\$0.00	0.00	False	ROUTE AND FILL CRACK SEAL, FIELD ESTIMATE
01-01-2016	SL-PC	Slab Replacement - PCC	\$0.00	0.00	False	EST; PCC SLAB REPLACEMENT
06-01-2005	CS-PC	Crack Sealing - PCC	\$0.00	0.00	False	CRACK SEAL REPAIR
06-01-1979	NC-PC	New Construction - PCC	\$0.00	0.00	True	PCC CONSTRUCTION

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: DVN

Page 6

Branch - Section ID: T02DA - 004

LCD: 6/3/2015
 Use: TAXIWAY
 Rank: P
 Surface: PCC

Length (ft): 290.00
 Width (ft): 35.00
 True Area (sf): 10,542.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-03-2015	CR-PC	Complete Reconstruction - PCC	\$0.00	8.00	True	8" P-501 PCC RECONSTRUCTION
06-02-2015	BA-AG	Base Course - Aggregate	\$0.00	8.00	False	8" P-209 CAB
06-01-2015	SG-ST	Subgrade - Stabilized	\$0.00	12.00	False	12" P-158 FLY ASH TREATED SUBGRADE
06-01-1979	NC-PC	New Construction - PCC	\$0.00	0.00	True	PCC CONSTRUCTION

Branch - Section ID: T03DA - 001

LCD: 6/2/1949
 Use: TAXIWAY
 Rank: P
 Surface: PCC

Length (ft): 1,200.00
 Width (ft): 50.00
 True Area (sf): 62,394.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
01-01-2017	JS-SI	Joint Seal - Silicon	\$0.00	0.00	False	EST; JOINT SEAL REPAIR
01-01-2017	CS-PC	Crack Sealing - PCC	\$0.00	0.00	False	EST; CRACK SEAL REPAIR
06-02-1949	NC-PC	New Construction - PCC	\$0.00	10.00	True	10" P-501 PCC CONSTRUCTION
06-01-1949	SB-AG	Subbase - Aggregate	\$0.00	7.00	False	7" P-154 SUBBASE

Branch - Section ID: T03DA - 002

LCD: 6/1/1947
 Use: TAXIWAY
 Rank: P
 Surface: PCC

Length (ft): 340.00
 Width (ft): 50.00
 True Area (sf): 17,612.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2019	PA-PP	Patching - PCC Partial Depth	\$0.00	0.00	False	EST; PCC PARTIAL DEPTH PATCHING
03-01-2015	JS-LC	Joint Seal (Localized)	\$0.00	0.00	False	JOINT SEAL REPAIR
08-01-2014	PA-PP	Patching - PCC Partial Depth	\$0.00	0.00	False	PCC PARTIAL DEPTH PATCHING
06-01-1947	NC-PC	New Construction - PCC	\$0.00	0.00	True	PCC CONSTRUCTION

Branch - Section ID: T03DA - 003

LCD: 4/3/2019
 Use: TAXIWAY
 Rank: P
 Surface: PCC

Length (ft): 300.00
 Width (ft): 50.00
 True Area (sf): 16,547.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
04-03-2019	CR-PC	Complete Reconstruction - PCC	\$0.00	10.00	True	10" P-501 COMPLETE RECONSTRUCTION
04-02-2019	BA-AG	Base Course - Aggregate	\$0.00	12.00	False	12" P-219 RECYCLE CONCRETE AGGREGATE BASE COURSE
04-01-2019	SG-ST	Subgrade - Stabilized	\$0.00	9.00	False	9" P-157 CEMENT TREATED SUBGRADE
06-01-1947	NC-PC	New Construction - PCC	\$0.00	0.00	True	PCC CONSTRUCTION

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: DVN

Page 7

Branch - Section ID: T04DA - 001

LCD: 6/1/1948
 Use: TAXIWAY
 Rank: P
 Surface: PCC

Length (ft): 95.00
 Width (ft): 50.00
 True Area (sf): 7,628.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2014	PA-PP	Patching - PCC Partial Depth	\$0.00	0.00	False	PCC PARTIAL DEPTH PATCHING
06-01-2009	CS-PC	Crack Sealing - PCC	\$0.00	0.00	False	CRACK SEAL REPAIR
06-01-1948	NC-PC	New Construction - PCC	\$0.00	0.00	True	PCC CONSTRUCTION

Branch - Section ID: T05DA - 001

LCD: 6/1/1948
 Use: TAXIWAY
 Rank: P
 Surface: PCC

Length (ft): 95.00
 Width (ft): 50.00
 True Area (sf): 7,628.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-1948	NC-PC	New Construction - PCC	\$0.00	0.00	True	PCC CONSTRUCTION

Branch - Section ID: T06DA - 001

LCD: 8/1/1996
 Use: TAXIWAY
 Rank: P
 Surface: PCC

Length (ft): 208.00
 Width (ft): 40.00
 True Area (sf): 13,887.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
08-01-1996	CR-PC	Complete Reconstruction - PCC	\$0.00	0.00	True	PCC RECONSTRUCTION
06-01-1950	NC-AC	New Construction - AC	\$0.00	0.00	True	AC CONSTRUCTION

Branch - Section ID: T07DA - 001

LCD: 6/30/1994
 Use: TAXIWAY
 Rank: P
 Surface: PCC

Length (ft): 1,526.00
 Width (ft): 35.00
 True Area (sf): 62,407.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
04-01-2019	JS-LC	Joint Seal (Localized)	\$0.00	0.00	False	JOINT SEAL REPAIR. PARTIAL, UP TO HOLD LINE
03-01-2015	JS-LC	Joint Seal (Localized)	\$0.00	0.00	False	JOINT SEAL REPAIR
06-01-2005	PA-PF	Patching - PCC Full Depth	\$0.00	0.00	False	PCC PARTIAL DEPTH PATCHING
06-30-1994	NC-PC	New Construction - PCC	\$0.00	10.00	True	10" P-501 PCC CONSTRUCTION
06-29-1994	BA-AG	Base Course - Aggregate	\$0.00	4.00	False	4" P-209 CRUSHED AGGREGATE BASE COURSE
06-28-1994	SB-AG	Subbase - Aggregate	\$0.00	4.00	False	4" P-154 SUBBASE
06-27-1994	SG-CO	Subgrade - Compacted	\$0.00	12.00	False	12" COMPACTED SUBGRADE

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: DVN

Page 8

Branch - Section ID: TH01DA - 001

LCD: 6/1/2008
 Use: T-HANGAR
 Rank: P
 Surface: AAC

Length (ft): 530.00
 Width (ft): 20.00
 True Area (sf): 10,915.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-01-2008	OL-AC	Overlay - AC	\$0.00	0.00	True	AC OVERLAY
06-01-1994	NC-AC	New Construction - AC	\$0.00	0.00	True	UNKNOWN, PRE 1994; AC CONSTRUCTION

Branch - Section ID: TH01DA - 002

LCD: 1/2/1949
 Use: T-HANGAR
 Rank: P
 Surface: AC

Length (ft): 2,090.00
 Width (ft): 20.00
 True Area (sf): 42,929.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
01-03-1949	ST-SC	Surface Treatment - Seal Coat	\$0.00	0.00	False	P-609 CHIP SEAL COAT
01-02-1949	NU-IN	New Construction - Initial	\$0.00	0.00	True	AC CONSTRUCTION
01-01-1949	BA-AG	Base Course - Aggregate	\$0.00	8.00	False	8" P-208 CAB

Branch - Section ID: TH01DA - 003

LCD: 10/1/2010
 Use: T-HANGAR
 Rank: P
 Surface: PCC

Length (ft): 1,175.00
 Width (ft): 35.00
 True Area (sf): 42,763.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
06-02-2021	JS-LC	Joint Seal (Localized)	\$0.00	0.00	False	JOINT SEAL REPAIR; FIELD ETIMATE
06-01-2021	PA-PP	Patching - PCC Partial Depth	\$0.00	0.00	False	PCC PATCHING; FIELD ESTIMATE
06-01-2021	SL-PC	Slab Replacement - PCC	\$0.00	0.00	False	SLAB REPLACEMENT; FIELD ESTIMATE
10-01-2010	NU-IN	New Construction - Initial	\$0.00	0.00	True	PCC CONSTRUCTION

Branch - Section ID: TH01DA - 004

LCD: 10/2/2005
 Use: T-HANGAR
 Rank: P
 Surface: PCC

Length (ft): 800.00
 Width (ft): 20.00
 True Area (sf): 18,886.00

Work Date	Work Code	Work Description	Cost	Thickness (in)	Major MR	Comments
10-02-2005	NU-IN	New Construction - Initial	\$0.00	5.00	True	5" P-501 PCC CONSTRUCTION
10-01-2005	SB-AG	Subbase - Aggregate	\$0.00	4.00	False	4" P-154 SUBBASE

APPENDIX E

LOCALIZED PREVENTIVE MAINTENANCE POLICIES AND UNIT COST TABLES

Table E-1. Localized preventive maintenance policy, asphalt-surfaced pavements.

Distress Type	Severity Level	Maintenance Action
Alligator Cracking	Low	Monitor
Alligator Cracking	Medium	Asphalt Patch
Alligator Cracking	High	Asphalt Patch
Bleeding	N/A	Monitor
Block Cracking	Low	Monitor
Block Cracking	Medium	Crack Seal—Asphalt
Block Cracking	High	Crack Seal—Asphalt
Corrugation	Low	Monitor
Corrugation	Medium	Asphalt Patch
Corrugation	High	Asphalt Patch
Depression	Low	Monitor
Depression	Medium	Monitor
Depression	High	Asphalt Patch
Jet-Blast Erosion	N/A	Asphalt Patch
Joint Reflection Cracking	Low	Monitor
Joint Reflection Cracking	Medium	Crack Seal—Asphalt
Joint Reflection Cracking	High	Crack Seal—Asphalt
L&T Cracking	Low	Monitor
L&T Cracking	Medium	Crack Seal—Asphalt
L&T Cracking	High	Crack Seal—Asphalt
Oil Spillage	N/A	Asphalt Patch
Patching	Low	Monitor
Patching	Medium	Asphalt Patch
Patching	High	Asphalt Patch
Polished Aggregate	N/A	Monitor
Raveling	Low	Monitor
Raveling	Medium	Asphalt Patch
Raveling	High	Asphalt Patch
Rutting	Low	Monitor
Rutting	Medium	Monitor
Rutting	High	Asphalt Patch
Shoving	Low	Monitor
Shoving	Medium	Asphalt Patch
Shoving	High	Asphalt Patch
Slippage Cracking	N/A	Asphalt Patch
Swelling	Low	Monitor
Swelling	Medium	Monitor
Swelling	High	Asphalt Patch
Weathering	Low	Monitor
Weathering	Medium	Monitor
Weathering	High	Asphalt Patch

Table E-2. Localized preventive maintenance policy, PCC pavements.

Distress Type	Severity Level	Maintenance Action
ASR	Low	Monitor
ASR	Medium	Slab Replacement
ASR	High	Slab Replacement
Blowup	Low	Slab Replacement
Blowup	Medium	Slab Replacement
Blowup	High	Slab Replacement
Corner Break	Low	Crack Seal—PCC
Corner Break	Medium	Full Depth PCC Patch
Corner Break	High	Full Depth PCC Patch
Durability Cracking	Low	Monitor
Durability Cracking	Medium	Full Depth Patch
Durability Cracking	High	Slab Replacement
Faulting	Low	Monitor
Faulting	Medium	Grinding
Faulting	High	Slab Replacement
Joint Seal Damage	Low	Monitor
Joint Seal Damage	Medium	Joint Seal
Joint Seal Damage	High	Joint Seal
LTD Cracking	Low	Monitor
LTD Cracking	Medium	Crack Seal—PCC
LTD Cracking	High	Slab Replacement
Patching (Small and Large)	Low	Monitor
Patching (Small and Large)	Medium	Full Depth PCC Patch
Patching (Small and Large)	High	Full Depth PCC Patch
Popouts	N/A	Monitor
Pumping	N/A	Monitor
Scaling	Low	Monitor
Scaling	Medium	Partial Depth PCC Patch
Scaling	High	Slab Replacement
Shattered Slab	Low	Crack Seal—PCC
Shattered Slab	Medium	Slab Replacement
Shattered Slab	High	Slab Replacement
Shrinkage Cracking	N/A	Monitor
Spalling (Joint and Corner)	Low	Monitor
Spalling (Joint and Corner)	Medium	Partial Depth PCC Patch
Spalling (Joint and Corner)	High	Partial Depth PCC Patch

Table E-3. 2023 unit costs for localized preventive maintenance actions.

Maintenance Action	Unit Cost
Asphalt Patch—Asphalt-Surfaced Pavement	\$15.24/sf
Crack Sealing—Asphalt-Surfaced Pavement	\$2.61/lf
Partial Depth PCC Patch—PCC Pavement	\$39.04/sf
Full Depth PCC Patch—PCC Pavement	\$17.43/sf
Crack Sealing—PCC Pavement	\$3.14/lf
Joint Sealing—PCC Pavement	\$3.14/lf
Grinding—PCC Pavement	\$0.37/sf
Slab Replacement—PCC Pavement	\$17.43/sf

Table Note: The unit cost estimates are based on broad statewide numbers and should be adjusted to reflect local costs.

Table E-4. 2023 unit costs (per square foot) based on pavement type and PCI ranges.

Pavement Type	PCI Range 0–40	PCI Range 40–50	PCI Range 50–60	PCI Range 60–70	PCI Range 70–80	PCI Range 80–90	PCI Range 90–100
AC	\$10.82	\$5.12	\$5.12	\$5.12	\$0.00	\$0.00	\$0.00
PCC	\$18.08	\$8.55	\$8.55	\$8.55	\$0.00	\$0.00	\$0.00

Table Note: The unit cost estimates are based on broad statewide numbers and should be adjusted to reflect local costs.

APPENDIX F

YEAR 2023 LOCALIZED PREVENTIVE MAINTENANCE DETAILS

Table F-1. Year 2023 localized preventive maintenance details.

Branch	Section	Distress Type	Severity	Distress Quantity	Distress Unit	Maintenance Action	Unit Cost	2023 Estimated Cost
A02DA	02	Corner Break	Low	4	Slabs	Crack Sealing - PCC	\$3.14	\$101
A02DA	02	Joint Seal Damage	Medium	29	Slabs	Joint Seal (Localized)	\$3.14	\$1,822
A02DA	02	Joint Seal Damage	High	126	Slabs	Joint Seal (Localized)	\$3.14	\$7,773
A02DA	02	LTD Cracking	Medium	2	Slabs	Crack Sealing - PCC	\$3.14	\$66
R03DA	01	Joint Seal Damage	Medium	944	Slabs	Joint Seal (Localized)	\$3.14	\$75,815
R15DA	01	Joint Seal Damage	Medium	642	Slabs	Joint Seal (Localized)	\$3.14	\$51,519
R15DA	02	Corner Spalling	Medium	4	Slabs	Patching - PCC Partial Depth	\$39.04	\$451
R15DA	02	Joint Seal Damage	Medium	240	Slabs	Joint Seal (Localized)	\$3.14	\$19,220
R15DA	02	Joint Seal Damage	High	86	Slabs	Joint Seal (Localized)	\$3.14	\$6,864
R15DA	03	Joint Seal Damage	Medium	419	Slabs	Joint Seal (Localized)	\$3.14	\$33,573
T01DA	01	ASR	Medium	8	Slabs	Slab Replacement - PCC	\$17.43	\$36,313
T01DA	01	Joint Seal Damage	Medium	20	Slabs	Joint Seal (Localized)	\$3.14	\$1,714
T01DA	01	LTD Cracking	Medium	4	Slabs	Crack Sealing - PCC	\$3.14	\$204
T01DA	04	Corner Spalling	Medium	2	Slabs	Patching - PCC Partial Depth	\$39.04	\$202
T01DA	04	Scaling	Medium	2	Slabs	Patching - PCC Partial Depth	\$39.04	\$3,853
T01DA	04	Small Patch	High	2	Slabs	Patching - PCC Full Depth	\$17.43	\$90
T01DA	05	Corner Break	Low	1	Slabs	Crack Sealing - PCC	\$3.14	\$33
T02DA	02	ASR	Medium	2	Slabs	Slab Replacement - PCC	\$17.43	\$4,180
T02DA	02	Corner Break	Low	2	Slabs	Crack Sealing - PCC	\$3.14	\$52
T02DA	02	Joint Spalling	Medium	1	Slabs	Patching - PCC Partial Depth	\$39.04	\$252
T02DA	02	LTD Cracking	Medium	1	Slabs	Crack Sealing - PCC	\$3.14	\$34

Table F-1. Year 2023 localized preventive maintenance details (continued).

Branch	Section	Distress Type	Severity	Distress Quantity	Distress Unit	Maintenance Action	Unit Cost	2023 Estimated Cost
T06DA	01	Joint Seal Damage	High	115	Slabs	Joint Seal (Localized)	\$3.14	\$6,628
T06DA	01	Joint Spalling	Medium	1	Slabs	Patching - PCC Partial Depth	\$39.04	\$315
T07DA	01	Joint Seal Damage	Medium	51	Slabs	Joint Seal (Localized)	\$3.14	\$3,345
T07DA	01	Joint Seal Damage	High	106	Slabs	Joint Seal (Localized)	\$3.14	\$7,025
T07DA	01	Joint Spalling	Medium	5	Slabs	Patching - PCC Partial Depth	\$39.04	\$1,274
TH01DA	03	Faulting	Medium	3	Slabs	Grinding (Localized)	\$0.37	\$9
TH01DA	04	Corner Break	Low	2	Slabs	Crack Sealing - PCC	\$3.14	\$47
TH01DA	04	Corner Spalling	Medium	2	Slabs	Patching - PCC Partial Depth	\$39.04	\$191
TH01DA	04	Joint Seal Damage	Medium	116	Slabs	Joint Seal (Localized)	\$3.14	\$5,428

Table Notes:

1. See Figure 3 for the location of the branch and section.
2. Distress types are defined by ASTM D5340-20. L&T Cracking = Longitudinal and Transverse Cracking; LTD Cracking = Longitudinal, Transverse, and Diagonal Cracking; ASR = Alkali-Silica Reaction.
3. The costs provided are of a general nature for the entire state and may require adjustment to reflect specific conditions at Davenport Municipal Airport.



PREPARED FOR

Iowa Department of Transportation
Modal Transportation Bureau
800 Lincoln Way
Ames, Iowa 50010
515-239-1691
<https://iowadot.gov/aviation>

JULY 2023