

Fort Dodge Regional Airport



Pavement Management Report

PREPARED BY

Applied Pavement Technology, Inc.
115 West Main Street, Suite 400
Urbana, Illinois 61801
(217) 398-3977
www.appliedpavement.com

JULY 2023



The preparation of this document was financed in part through an Airport Improvement Program grant from the Federal Aviation Administration (Project Number 3-19-0000-030-2022) as provided under Section 505 of the Airport and Airway Improvement Act of 1982, as amended. The contents do not necessarily reflect the DOT's official views or the policy of the FAA. Acceptance of this report by the FAA does not in any way constitute a commitment on the part of the United States to participate in any development depicted therein nor does it indicate the proposed development is environmentally acceptable in accordance with appropriate public laws.

FORT DODGE REGIONAL AIRPORT PAVEMENT MANAGEMENT REPORT

Prepared For:



Iowa Department of Transportation
Modal Transportation Bureau
800 Lincoln Way
Ames, Iowa 50010
515-239-1691
<https://iowadot.gov/aviation/>

Prepared By:



Applied Pavement Technology, Inc.
115 West Main Street, Suite 400
Urbana, Illinois 61801
217-398-3977
<https://www.appliedpavement.com>

In Association With:



Robinson Engineering Company
Consulting Engineers
819 Second Street NE
Independence, Iowa 50644
319-334-7211

TABLE OF CONTENTS

| | |
|---|----|
| INTRODUCTION | 1 |
| PAVEMENT INVENTORY | 3 |
| PAVEMENT EVALUATION..... | 6 |
| Pavement Evaluation Procedure | 6 |
| Pavement Evaluation Results..... | 7 |
| Inspection Comments..... | 13 |
| Runways..... | 13 |
| Taxiways..... | 13 |
| Aprons..... | 14 |
| T-Hangar | 14 |
| PAVEMENT MAINTENANCE AND REHABILITATION PROGRAM | 15 |
| Analysis Parameters..... | 15 |
| Critical PCIs..... | 15 |
| Localized Preventive Maintenance Policies and Unit Costs..... | 15 |
| Major Rehabilitation Unit Costs | 15 |
| Budget and Inflation Rate | 15 |
| Analysis Approach..... | 15 |
| Analysis Results..... | 16 |
| General Maintenance Recommendations | 17 |
| FAA Requirements (Public Law 103-305)..... | 17 |
| FAA Advisory Circular 150/5830-7B, Appendix A. Pavement Management Program (PMP) | 18 |
| SUMMARY | 25 |

LIST OF FIGURES

| | |
|--|----|
| Figure 1. Pavement condition versus cost of repair..... | 1 |
| Figure 2. Pavement area by branch use at Fort Dodge Regional Airport..... | 4 |
| Figure 3. Fort Dodge Regional Airport network definition map..... | 5 |
| Figure 4. Visual representation of PCI scale on typical pavement surfaces..... | 6 |
| Figure 5. PCI versus repair type..... | 7 |
| Figure 6. Pavement area by PCI range at Fort Dodge Regional Airport..... | 8 |
| Figure 7. Area-weighted PCI by branch use at Fort Dodge Regional Airport..... | 9 |
| Figure 8. Fort Dodge Regional Airport PCI map..... | 10 |

LIST OF TABLES

| | |
|---|----|
| Table 1. 2022 pavement evaluation results..... | 11 |
| Table 2. 5-year M&R program under an unlimited funding analysis scenario..... | 16 |
| Table 3. Pavement inspection report..... | 20 |

APPENDIXES

Appendix A. Cause of Distress Tables A-1
Appendix B. Inspection PhotographsB-1
Appendix C. Inspection Report.....C-1
Appendix D. Work History Report..... D-1
Appendix E. Localized Preventive Maintenance Policies and Unit Cost TablesE-1
Appendix F. Year 2023 Localized Preventive Maintenance Details F-1


INTRODUCTION

Applied Pavement Technology, Inc. (APTech), with assistance from Robinson Engineering Company Consulting Engineers (Robinson), updated the Airport Pavement Management System (APMS) for the Iowa Department of Transportation, Modal Transportation Bureau (Iowa DOT). The APMS provides a means to monitor the condition of the pavements within the state of Iowa and to proactively plan for their preservation.

As part of this project, pavement conditions at Fort Dodge Regional Airport were assessed in November 2022 using the Pavement Condition Index (PCI) procedure. During a PCI inspection, the types, severities, and amounts of distress present in a pavement are quantified. This information is then used to develop a composite index that represents the overall condition of the pavement in numerical terms, ranging from 0 (failed) to 100 (excellent). The PCI provides an overall measure of condition and an indication of the level of work that will be required to maintain or repair a pavement. The distress information also provides insight into what is causing the pavement to deteriorate, which is the first step in selecting the appropriate repair action to correct the problem.

Programmed into an APMS, PCI information is used to determine when preventive maintenance actions (such as crack or joint sealing) are advisable and to identify the most cost-effective time to perform major rehabilitation (such as an overlay or whitetopping). Delaying maintenance and rehabilitation (M&R) until a pavement structure has seriously degraded can cost many times more than if M&R was applied earlier in a pavement's life cycle, as shown in Figure 1. From a safety perspective, pavement distresses, such as cracks and loose debris, may pose risks in terms of the potential for aircraft tire damage and the ability of a pilot to safely control aircraft.

Figure 1. Pavement condition versus cost of repair.



The pavement evaluation results for Fort Dodge Regional Airport are presented within this report and can be used by Fort Dodge Regional Airport, the Iowa DOT, and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement M&R actions at the airport. In addition to this report, the web-based interactive pavement data visualization tool IDEA, containing the information collected during this project, was updated and may be accessed from the [Iowa DOT's website](#) or directly ([Iowa APMS IDEA](#)).

PAVEMENT INVENTORY

The project began with a review of the existing inventory information pertaining to the pavements at Fort Dodge Regional Airport. The date of original construction, along with the date of any subsequent rehabilitation; the location of completed work; and the type of work undertaken were gathered. The information was used to update the pavement management database and associated maps, as necessary, to account for pavement-related work that had been undertaken since the last time the airport was evaluated in 2019.

The pavement network at Fort Dodge Regional Airport was then divided into branches, sections, and sample units. A branch is a single entity that serves a distinct function. For example, a runway is considered a branch because it serves a single function (allowing aircraft to take off and land). Taxiways, aprons, and T-hangars are also separate branches.

Each branch was further divided into sections. Traditionally, sections are defined as parts of the branch that share common attributes, such as cross-section, date of last construction, traffic level, and performance. Using this approach, if a runway was built in 1968 and then extended in 1984, it would contain two separate sections.

To estimate the overall condition of a pavement section, each section was subdivided into sample units. Portions of these sample units were evaluated during the pavement inspection, and the collected information was extrapolated to predict the overall section condition and quantities of distress.

Approximately 2,479,300 square feet of pavement were evaluated at Fort Dodge Regional Airport, as illustrated in Figure 2. This figure also shows the area-weighted age, in years, of the pavements at the time of the inspection. Figure 3 provides a map that details how the pavement network was divided into management units and identifies the sample units that were evaluated during the pavement inspection at Fort Dodge Regional Airport.

Figure 2. Pavement area by branch use at Fort Dodge Regional Airport.





FIGURE 3. NETWORK DEFINITION MAP.



NETWORK DEFINITION LEGEND

| | |
|--|------------------------|
| | BRANCH IDENTIFIER |
| | SECTION IDENTIFIER |
| | PCI VALUE |
| | SECTION BREAK LINE |
| | SAMPLE UNIT BREAK LINE |
| | SLAB JOINT |
| | SAMPLE UNIT NUMBER |
| | SAMPLE UNIT INSPECTED |
| | ADDITIONAL SAMPLE UNIT |

applied pavement
TECHNOLOGY

115 W. Main Street, Suite 400
Urbana, IL 61801
Tel: 217-398-3977
Fax: 217-398-4027

| | | | |
|---|-------------------------------|----------------------|---------------------------|
| AGENCY: Iowa Department of Transportation | | | |
| Modal Transportation Bureau | | | |
| LOCATION: Fort Dodge Regional Airport | | | |
| Fort Dodge, Iowa | | | |
| PAGE TITLE: Network Definition Map | | | |
| PROJECT DATE: OCT. 2022 | CREATION DATE: OCT. 2022 | PROJECT MANAGER: LJR | JOB NUMBER: 2021-125-AM01 |
| DRAWING SCALE: 1"=300' | LAST MODIFIED DATE: MAY 2023 | REVISED BY: DMS | DRAWN BY: KEW |
| FILENAME: Fort Dodge.dwg | LAYOUT NAME/NUMBER: NET. DEF. | PAGE NUMBER: 5 | |

PAVEMENT EVALUATION

Pavement Evaluation Procedure

APTech inspected the pavements at Fort Dodge Regional Airport using the PCI procedure described in:

- FAA Advisory Circular 150/5380-6C, [Guidelines and Procedures for Maintenance of Airport Pavements](#).
- FAA Advisory Circular 150/5380-7B, [Airport Pavement Management Program \(PMP\)](#).
- ASTM D5340-20, *Standard Test Method for Airport Pavement Condition Index Surveys*.

The PCI provides a numerical indication of overall pavement condition, as illustrated in Figure 4. The types and amounts of deterioration are used to calculate the PCI of the section. The PCI ranges from a value of 0, which represents a pavement in a failed condition, to a value of 100, which represents a pavement in excellent condition. It is important to note that factors other than overall PCI need to be considered when identifying the appropriate type of repair, including types of distress present and rate of deterioration. Also, since the PCI does not assess the structural integrity or capacity of the pavement structure, further testing may be needed to validate and refine the treatment strategy.

Figure 4. Visual representation of PCI scale on typical pavement surfaces.



Note: Photographs shown are not specific to Fort Dodge Regional Airport.

Generally, pavements with relatively high PCIs that are not exhibiting significant load-related distress will benefit from preventive maintenance actions, such as crack sealing or joint resealing. As the PCI drops, the pavements may require major rehabilitation, such as an overlay or whitetopping. In some situations where the PCI has dropped low enough, reconstruction may be the only viable alternative due to the substantial damage to the pavement structure. Figure 5 illustrates how the appropriate repair type varies with the PCI of a pavement section and provides the corresponding colors used for the maps and charts in this report for each range of PCIs.

Figure 5. PCI versus repair type.

| PCI Range | Repair |
|-----------|------------------------|
| 86-100 | Preventive Maintenance |
| 71-85 | |
| 56-70 | |
| 41-55 | Major Rehabilitation |
| 26-40 | Reconstruction |
| 11-25 | |
| 0-10 | |

The types of distress identified during the PCI inspection provide insight into the cause of pavement deterioration, which is useful when selecting M&R strategies. Understanding the cause of distress helps in selecting a rehabilitation alternative that corrects the cause and thus eliminates or delays its recurrence. PCI distress types are characterized as:

- Load-related—These distress types are defined as being caused by aircraft or vehicular traffic and may indicate a structural deficiency. Examples of load-related distress include alligator cracking on asphalt-surfaced pavements and corner breaks on portland cement concrete (PCC) pavements.
- Climate/durability-related—These distress types often signify the presence of aged or environmentally susceptible (or both) material and include durability-related issues. Examples of climate/durability-related distress include weathering on asphalt-surfaced pavements, which is climate-related, and durability cracking on PCC pavements, which is durability-related.
- Other—Distress types that fall into this category cannot be attributed solely to load or climate/durability. Examples of this type of distress include depressions on asphalt-surfaced pavements and shrinkage cracking on PCC pavements.

Appendix A identifies the distress types considered during a PCI inspection and describes the likely cause of each distress type. It should be noted that a PCI is based on visual signs of pavement deterioration and does not provide a measure of structural capacity.

Pavement Evaluation Results

The pavements at Fort Dodge Regional Airport were inspected in November 2022. The 2022 area-weighted condition of Fort Dodge Regional Airport is 77, with conditions ranging from 30 to 100 (on a scale of 0 [failed] to 100 [excellent]). During the previous pavement inspection in 2019, the area-weighted PCI of the airport was 83.

Figure 6 summarizes the overall condition of the pavements at Fort Dodge Regional Airport, and Figure 7 presents area-weighted condition (average PCI adjusted to account for the relative size of the pavement sections) by branch use. Figure 8 is a map that displays the condition of the evaluated pavements. Table 1 summarizes the results of the pavement evaluation. Appendix B presents photographs taken during the PCI inspection, and Appendix C contains detailed information on the distress types observed during the visual survey. Appendix D includes detailed work history information that was collected during the record review process.

Figure 6. Pavement area by PCI range at Fort Dodge Regional Airport.




Figure 7. Area-weighted PCI by branch use at Fort Dodge Regional Airport.
(Values on chart are area-weighted)





FIGURE 8. PCI MAP.



| LEGEND | |
|--------|--------------------|
| | BRANCH IDENTIFIER |
| | SECTION IDENTIFIER |
| | PCI VALUE |
| | SECTION BREAK LINE |

| PAVEMENT CONDITION INDEX | |
|--------------------------|--------|
| PCI | |
| | 86-100 |
| | 71-85 |
| | 56-70 |
| | 41-55 |
| | 26-40 |
| | 11-25 |
| | 0-10 |

| | | | |
|--|---------------------------------|---|------------------------------|
| | | 115 W. Main Street, Suite 400 Urbana, IL 61801 Tel: 217-398-3977 Fax: 217-398-4027 | |
| Robinson Engineering Company Consulting Engineers | | 819 Second Street NE Independence, Iowa 50644 319-319-7211 | |
| AGENCY: Iowa Department of Transportation Modal Transportation Bureau | | | |
| LOCATION: Fort Dodge Regional Airport Fort Dodge, Iowa | | | |
| PAGE TITLE: 2022 Pavement Condition Index Map | | | |
| PROJECT DATE: OCT. 2022 | CREATION DATE: OCT. 2022 | PROJECT MANAGER: LJR | JOB NUMBER: 2021-125-AM01 |
| DRAWING SCALE: 1"=300' | LAST MODIFIED DATE: MAY 2023 | REVISED BY: DMS | DRAWN BY: KEW |
| FILENAME: Fort Dodge.dwg | | LAYOUT NAME/NUMBER: PCI | PAGE NUMBER: 10 |

Table 1. 2022 pavement evaluation results.

| Branch | Section | Surface Type | Section Area (sf) | LCD | 2022 PCI | % Distress Due to Load | % Distress Due to Climate/Durability | % Distress Due to Other | Type of Distress |
|--------|---------|--------------|-------------------|-----------|----------|------------------------|--------------------------------------|-------------------------|--|
| A01FD | 01 | PCC | 102,275 | 6/3/2019 | 98 | 0 | 100 | 0 | Joint Seal Damage |
| A01FD | 02 | PCC | 53,202 | 6/3/2019 | 98 | 0 | 70 | 30 | Corner Spalling, Joint Seal Damage |
| A02FD | 01 | PCC | 76,791 | 6/3/2019 | 93 | 12 | 80 | 8 | Corner Spalling, Joint Seal Damage, LTD Cracking, Shrinkage Cracking |
| A02FD | 02 | PCC | 21,688 | 7/3/2012 | 88 | 9 | 56 | 35 | Corner Spalling, Joint Spalling, Joint Seal Damage, LTD Cracking, Shrinkage Cracking |
| R06FD | 01 | AAC | 877,200 | 6/3/2015 | 78 | 0 | 100 | 0 | L&T Cracking, Weathering |
| R06FD | 02 | AAC | 105,000 | 6/1/2012 | 78 | 22 | 78 | 0 | Alligator Cracking, L&T Cracking, Weathering |
| R12FD | 01 | APC | 147,855 | 6/1/2012 | 72 | 0 | 100 | 0 | L&T Cracking, Raveling, Weathering |
| R12FD | 02 | APC | 291,412 | 6/1/2012 | 72 | 0 | 100 | 0 | L&T Cracking, Raveling, Weathering |
| R12FD | 03 | PCC | 10,869 | 5/1/2004 | 84 | 85 | 8 | 7 | Corner Break, Corner Spalling, Joint Spalling, Joint Seal Damage, LTD Cracking, Shattered Slab |
| R12FD | 04 | PCC | 70,952 | 5/1/2004 | 97 | 31 | 0 | 69 | Corner Spalling, Faulting, Joint Spalling, LTD Cracking |
| TAFD | 01 | PCC | 25,248 | 8/16/2001 | 85 | 25 | 67 | 8 | Corner Break, Joint Spalling, Joint Seal Damage, LTD Cracking |
| TBFD | 01 | AAC | 65,568 | 6/3/2015 | 64 | 0 | 100 | 0 | L&T Cracking, Raveling, Weathering |
| TBFD | 02 | AAC | 162,730 | 6/1/2007 | 59 | 0 | 100 | 0 | L&T Cracking, Weathering |
| TBFD | 03 | AC | 111,503 | 6/3/2022 | 100 | 0 | 0 | 0 | No distress |
| TBFD | 04 | AAC | 14,250 | 6/1/2012 | 76 | 0 | 100 | 0 | L&T Cracking, Weathering |
| TBFD | 05 | AAC | 17,528 | 6/1/2015 | 70 | 0 | 100 | 0 | L&T Cracking, Raveling, Weathering |
| TBFD | 06 | AC | 3,245 | 6/3/2019 | 83 | 0 | 100 | 0 | Raveling, Weathering |

Table 1. 2022 pavement evaluation results (continued).

| Branch | Section | Surface Type | Section Area (sf) | LCD | 2022 PCI | % Distress Due to Load | % Distress Due to Climate/Durability | % Distress Due to Other | Type of Distress |
|--------|---------|--------------|-------------------|----------|----------|------------------------|--------------------------------------|-------------------------|--|
| TCFD | 01 | PCC | 34,299 | 8/1/2001 | 84 | 4 | 67 | 29 | Corner Break, Corner Spalling, Faulting, Joint Spalling, Joint Seal Damage |
| TDFD | 01 | AAC | 87,990 | 6/1/2007 | 55 | 0 | 100 | 0 | L&T Cracking, Raveling, Weathering |
| TDFD | 02 | AAC | 32,689 | 6/1/2015 | 71 | 0 | 100 | 0 | L&T Cracking, Raveling, Weathering |
| TDFD | 03 | PCC | 13,390 | 6/3/2007 | 80 | 42 | 49 | 9 | Corner Break, Joint Spalling, Joint Seal Damage, LTD Cracking |
| TFFD | 01 | AC | 39,481 | 6/5/1991 | 66 | 0 | 100 | 0 | L&T Cracking, Weathering |
| TFFD | 02 | PCC | 38,600 | 6/3/2007 | 75 | 58 | 38 | 4 | Corner Break, Corner Spalling, Joint Seal Damage, LTD Cracking |
| TH01FD | 01 | AC | 44,195 | 6/4/1995 | 30 | 34 | 65 | 1 | Alligator Cracking, Depression, L&T Cracking, Raveling, Swelling, Weathering |
| TH01FD | 02 | PCC | 2,495 | 3/3/2018 | 100 | 0 | 0 | 0 | No distress |
| TH01FD | 03 | PCC | 28,809 | 6/3/2021 | 95 | 91 | 0 | 9 | Corner Break, Corner Spalling, LTD Cracking |

Table Notes:

- See Figure 3 for the location of the branch and section.
- Surface Type: AC = asphalt cement concrete; AAC = asphalt overlay on AC; PCC = portland cement concrete; APC = asphalt overlay on PCC.
- LCD = last construction date.
- Distress due to load includes distress types that are attributed to a structural deficiency in the pavement, such as alligator cracking or rutting on asphalt-surfaced pavements or shattered slabs on PCC pavements.
- Distress due to climate or durability includes distress types that are attributed to either the aging of the pavement and the effects of the environment (such as weathering, raveling, or block cracking on asphalt-surfaced pavements) or to a materials-related problem (such as durability cracking or alkali-silica reaction [ASR] on PCC pavements). If materials-related distresses were recorded during the inspection, further laboratory testing is required to definitively determine the type present.
- Distress due to other refers to distress types that are not attributed to one factor but rather may be caused by a combination of factors.
- Distress types are defined by ASTM D5340-20. L&T Cracking = Longitudinal and Transverse Cracking; LTD Cracking = Longitudinal, Transverse, and Diagonal Cracking; ASR = Alkali-Silica Reaction.

Inspection Comments

Fort Dodge Regional Airport was inspected on November 9-10, 2022. There were twenty-six pavement sections defined during the inspection.

Runways

Runway 06/24 was defined by two sections. Section 01 contained areas of low- and medium-severity longitudinal and transverse (L&T) cracking and all severities of weathering. Low- and medium-severity L&T cracking and low-severity alligator cracking and weathering were recorded in Section 02. The low-severity L&T cracking in Sections 01 and 02 was either sealed or unsealed, and the medium-severity L&T cracking was primarily due to crack sealant that was no longer performing satisfactorily.

Runway 12/30 consisted of four sections. Section 01 contained low-severity L&T cracking, raveling, and weathering. Areas of low- and medium-severity L&T cracking and low-severity raveling and weathering were recorded in Section 02. Most of the low-severity L&T cracking in Sections 01 and 02 was sealed, and the medium-severity L&T cracking was due to unsatisfactory crack sealant. Section 03 contained areas of low-severity corner break, corner spalling, joint seal damage, and joint spalling; low- and medium-severity longitudinal, transverse, and diagonal (LTD) cracking; and medium-severity shattered slab. Section 04 was in excellent condition with small amounts of low-severity corner spalling, faulting, joint spalling, and LTD cracking noted.

Taxiways

Taxiway A contained one section that had areas of high-severity joint seal damage and medium-severity corner break, joint spalling, and LTD cracking.

Taxiway B was defined by six sections. Section 01 contained low-severity L&T cracking, raveling, and weathering. Areas of low- and medium-severity L&T cracking and weathering were noted in Section 02. Section 03 was in excellent condition with no distress noted at the time of inspection. Section 04 contained areas low-severity L&T cracking and weathering. Low-severity raveling and low- and medium-severity L&T cracking and weathering were observed in Section 05. The low-severity L&T cracking in Sections 01, 02, 04, and 05 was sealed and unsealed, and the medium-severity L&T cracking was due to either unsatisfactory crack sealant or unsealed crack widths that exceeded $\frac{1}{4}$ in. Section 06 contained low-severity raveling and weathering.

Taxiway C consisted of one section. Section 01 contained areas of high-severity joint seal damage and low-severity corner break, corner spalling, faulting, and joint spalling.

Taxiway D was defined by three sections. All severities of weathering and low- and medium-severity L&T cracking and raveling were recorded in Section 01. Areas of low-severity L&T cracking, raveling, and weathering were identified in Section 02. The low-severity L&T cracking in Sections 01 and 02 was sealed and unsealed, and the medium-severity L&T cracking in Section 01 was due to either unsatisfactory crack sealant or unsealed crack widths greater than $\frac{1}{4}$ in. Section 03 contained areas of low- and medium-severity corner break, high-severity joint seal damage, and medium-severity joint spalling and LTD cracking.

Taxiway F contained two sections. Section 01 contained all severities of L&T cracking and medium-severity weathering. The low-severity L&T cracking was sealed and unsealed, and the medium-severity L&T cracking was due unsatisfactory crack sealant. Low-severity corner break,

medium-severity corner spalling, high-severity joint seal damage, and low- and medium-severity LTD cracking were observed in Section 02.

Aprons

Apron 01 contained two sections. Section 01 was in excellent condition with low-severity joint seal damage recorded throughout. Section 02 was also in excellent condition with low-severity joint seal damage noted. An atypical area of medium-severity corner spalling was observed and recorded as an additional sample unit in accordance with ASTM D5340-20.

Apron 02 was defined by two sections. Section 01 contained medium-severity joint seal damage throughout. An atypical area of shrinkage cracking and low-severity corner spalling and LTD cracking was observed and recorded as an additional sample unit in accordance with ASTM D5340-20. Medium-severity corner spalling, joint seal damage, and joint spalling; low-severity LTD cracking; and shrinkage cracking were observed in Section 02.

T-Hangar

The T-hangar area consisted of three sections. Section 01 was in poor condition with low-severity raveling, swelling, and depression; medium-severity weathering and alligator cracking; and all severities of L&T cracking observed. The low-severity L&T cracking was unsealed, and the medium-severity L&T cracking was due to either the development of secondary cracking, unsatisfactory crack sealant, or unsealed crack widths that exceeded $\frac{1}{4}$ in. Section 02 was in excellent condition with no distress noted at the time of inspection. Section 03 was also in excellent condition with areas of low-severity corner break, corner spalling, and LTD cracking identified during the inspection.

PAVEMENT MAINTENANCE AND REHABILITATION PROGRAM

Using the information collected during the pavement inspection, the PAVER pavement management software was used to develop a 5-year M&R program for Fort Dodge Regional Airport. In addition, a 1-year plan for localized preventive maintenance (such as crack sealing and patching) was prepared.

Analysis Parameters

Critical PCIs

PAVER uses critical PCIs to determine whether localized preventive maintenance or major rehabilitation is the appropriate repair action. Above the critical PCI, localized preventive maintenance activities are recommended. Below the critical PCI, major rehabilitation actions, such as an overlay or reconstruction, are recommended. The Iowa DOT set the critical PCIs at 65 for runways, 60 for taxiways, and 55 for aprons and T-hangars.

Localized Preventive Maintenance Policies and Unit Costs

Localized preventive maintenance policies were developed for asphalt-surfaced and PCC pavements. These policies, shown in Appendix E, identify the localized preventive maintenance actions that the Iowa DOT considered appropriate to correct the different distress types and severities. The Iowa DOT provided unit costs for each of the localized preventive maintenance actions included in these policies, and these costs are detailed in Appendix E. Please note that this information is of a general nature for the entire state. The localized preventive maintenance policies and unit costs may require adjustment to reflect specific conditions at Fort Dodge Regional Airport.

Major Rehabilitation Unit Costs

PAVER estimates the cost of major rehabilitation based on the predicted PCI of the pavement section. The Iowa DOT provided the costs for major rehabilitation, and they are presented in Appendix E. If major rehabilitation is recommended in the 5-year program, further engineering investigation will be needed to identify the most appropriate rehabilitation action and to estimate the cost of such work more accurately.

Budget and Inflation Rate

An unlimited budget with a start date of July 1, 2023 and an inflation rate of 4.0 percent was used during the analysis.

Analysis Approach

The 5-year M&R program was prepared with the goal of maintaining the pavements above established critical PCIs. During this analysis, major rehabilitation was recommended for pavements in the year they dropped below their critical PCI. For the first year (2023) of the analysis only, a localized preventive maintenance plan was developed for those pavement sections that were above their critical PCI. If major rehabilitation was triggered for a section in 2024 or 2025, then localized preventive maintenance was not recommended for 2023. While localized preventive maintenance should be an annual undertaking at Fort Dodge Regional Airport, it is not possible to accurately predict the propagation of cracking and other distress types. Therefore, the airport should budget for maintenance every year and can use the 2023

localized preventive maintenance plan as a baseline for that work. As the pavements age, it can be assumed that the amount of localized preventive maintenance required will increase.

Analysis Results

A summary of the M&R program for Fort Dodge Regional Airport is presented in Table 2. Detailed information on the recommended localized preventive maintenance plan for 2023 is provided in Appendix F.

Table 2. 5-year M&R program under an unlimited funding analysis scenario.

| Year | Branch | Section | Surface Type | Type of Repair | Estimated Cost |
|------|--------|---------|--------------|------------------------|----------------|
| 2023 | A01FD | 02 | PCC | Preventive Maintenance | \$105 |
| 2023 | A02FD | 01 | PCC | Preventive Maintenance | \$36,490 |
| 2023 | A02FD | 02 | PCC | Preventive Maintenance | \$11,421 |
| 2023 | R06FD | 01 | AAC | Preventive Maintenance | \$26,796 |
| 2023 | R06FD | 02 | AAC | Preventive Maintenance | \$468 |
| 2023 | R12FD | 02 | APC | Preventive Maintenance | \$761 |
| 2023 | R12FD | 03 | PCC | Preventive Maintenance | \$3,181 |
| 2023 | TAFD | 01 | PCC | Preventive Maintenance | \$14,764 |
| 2023 | TBFD | 02 | AAC | Major Rehabilitation | \$833,159 |
| 2023 | TBFD | 05 | AAC | Preventive Maintenance | \$952 |
| 2023 | TCFD | 01 | PCC | Preventive Maintenance | \$17,339 |
| 2023 | TDFD | 01 | AAC | Major Rehabilitation | \$450,499 |
| 2023 | TDFD | 03 | PCC | Preventive Maintenance | \$7,436 |
| 2023 | TFFD | 01 | AC | Preventive Maintenance | \$2,326 |
| 2023 | TFFD | 02 | PCC | Preventive Maintenance | \$17,844 |
| 2023 | TH01FD | 01 | AC | Major Rehabilitation | \$478,208 |
| 2023 | TH01FD | 03 | PCC | Preventive Maintenance | \$178 |
| 2025 | TBFD | 01 | AAC | Major Rehabilitation | \$363,094 |
| 2026 | R12FD | 01 | APC | Major Rehabilitation | \$851,523 |
| 2026 | R12FD | 02 | APC | Major Rehabilitation | \$1,678,293 |
| 2026 | TFFD | 01 | AC | Major Rehabilitation | \$227,378 |
| 2027 | TBFD | 05 | AAC | Major Rehabilitation | \$104,985 |
| 2027 | TDFD | 02 | AAC | Major Rehabilitation | \$195,792 |

Total Estimated Cost: \$5,323,000

Table Notes:

1. See Figure 3 for the location of the branch and section.
2. Surface Type: AC = asphalt cement concrete; AAC = asphalt overlay on AC; PCC = portland cement concrete; APC = asphalt overlay on PCC.
3. Type of Repair: Major Rehabilitation such as pavement reconstruction or an overlay; Localized Preventive Maintenance such as crack sealing or patching.
4. The estimated costs provided are of a general nature for the entire state and may require adjustment to reflect specific conditions at Fort Dodge Regional Airport.

The recommendations made in this report are based on a broad network-level analysis and meant to provide Fort Dodge Regional Airport with an indication of the type of pavement-related work required during the next 5 years. Further engineering investigation may be necessary to identify which repair action is most appropriate. In addition, the cost estimates provided are based on overall unit costs for the entire state, and Fort Dodge Regional Airport should adjust the plan to reflect local costs.

Because an unlimited budget was used in the analysis, it is possible that the pavement repair program may need to be adjusted to consider economic or operational constraints. The identification of a project need does not necessarily mean that state or federal funding will be available in the year it is indicated. It is important to remember that regardless of the recommendations presented within this report, Fort Dodge Regional Airport is responsible for repairing pavements where existing conditions pose a hazard to safe operations.

General Maintenance Recommendations

In addition to the specific maintenance actions presented in Appendix F, it is recommended that the following strategies be considered for prolonging pavement life:

1. Regularly inspect all safety areas of the airport and document all inspection activity. A sample form that can be used to perform these inspections is provided in Table 3 of this report.
2. Provide a method of tracking all maintenance activities that occur as a result of inspections. These need to be reported to the FAA and the Iowa DOT. This information is used to update the APMS records and is required to remain in compliance with Public Law 103-305 (see the next section of this report for further information on this law).
3. Conduct an aggressive campaign against weed growth through timely herbicide applications and mowing programs of the safety areas. Vegetation growth in pavement cracks is destructive and significantly increases the rate of pavement deterioration.
4. Implement a periodic crack and joint sealing program. Keeping water and debris out of the pavement system by sealing cracks and joints is a proven and cost-effective method of extending the life of the pavement system.
5. Ensure that dirt does not build up along the edges of the pavements. This can create a “bathtub” effect, reducing the ability of water to drain away from the pavement system.
6. Closely monitor the movement of heavy equipment (particularly farming, construction, and fueling equipment) to make sure it is only operating on pavements that are designed to accommodate heavy loads. Failure to restrict heavy equipment to appropriate areas may result in the premature failure of airport pavements.

FAA Requirements (Public Law 103-305)

Because Fort Dodge Regional Airport is in the National Plan of Integrated Airport Systems (NPIAS), the airport sponsor is required to keep the airport in a viable operating condition. This includes maintaining airport pavements in accordance with Public Law 103-305. Public Law 103-305 states that after January 1, 1995, NPIAS airport sponsors must provide assurances or certifications that an airport has implemented an effective airport pavement maintenance management system (PMMS) before the airport will be considered for federal funding of pavement replacement or reconstruction projects. To be in full compliance with the federal law,

the PMMS must include the following components at minimum: pavement inventory, pavement inspections, record keeping, information retrieval, and program funding.

This report serves as a complete pavement inventory and detailed inspection. To remain in compliance with the law, Fort Dodge Regional Airport will also need to undertake monthly drive-by inspections of pavement conditions and track pavement-related maintenance activities.

FAA Advisory Circular 150/5380-7B provides detailed guidance pertaining to the requirements for an acceptable pavement management program (PMP). Appendix A of the FAA Advisory Circular 150/5380-7B outlines what needs to be included in a PMP to remain in compliance with this law and Grant Assurance #11. The following is a copy of this Appendix, along with instructions for supplementing this report so that all requirements are met. Note that the italicized words are direct quotations from the FAA Advisory Circular.

FAA Advisory Circular 150/5830-7B, Appendix A. Pavement Management Program (PMP)

A-1.0. An effective PMP specifies the procedures to follow to assure that proper preventative and remedial pavement maintenance is performed. The program should identify funding or anticipated funding and other resources available to provide remedial and preventive maintenance activities. An airport sponsor may use any format deemed appropriate, but the program needs to, as a minimum, include the following:

A-1.1. Pavement Inventory. The following must be depicted:

- a. *Identification of all runways, taxiways, and aprons with pavement broken down into sections each having similar properties.*

The network definition map provided in Figure 3 of this report shows the location of all runways, taxiways, aprons, and T-hangars at Fort Dodge Regional Airport. If any new pavements are constructed or any pavement areas are permanently closed, this map must be updated. Project plans should be submitted to the Iowa DOT after project completion.

- b. *Dimensions of pavement sections.*

The dimensions of all runways, taxiways, aprons, and T-hangars are stored in the PAVER database. Appendix C provides information on length, width, and area. In addition, the network definition map provided in Figure 3 is drawn to scale. Any changes to pavement dimensions must be recorded.

- c. *Type of pavement surface.*

The type of pavement for each section at Fort Dodge Regional Airport is listed in Table 1 of this report and is also stored in the PAVER database. Any changes to the pavement type (through an overlay or reconstruction) must be recorded.

- d. *Year of construction and/or most recent major rehabilitation.*

Dates for pavement construction, rehabilitation, or reconstruction must be recorded. The current pavement history for Fort Dodge Regional Airport is provided in Appendix D of this report.

- e. *Whether AIP [Airport Improvement Program] or PFC [Passenger Facility Charge] funds were used to construct, reconstruct, or repair the pavement.*

Funding sources for all pavement projects should be recorded.

A-1.2. PMP Pavement Inspection Schedule. *Airports must perform a detailed inspection of airfield pavements at least once a year for the PMP. If a pavement condition index (PCI) survey is performed, as set forth in ASTM D5340, Standard Test Method for Airport Pavement Condition Index Surveys, the frequency of the detailed inspection by PCI surveys may be extended to three years. Less comprehensive routine daily, weekly, and monthly maintenance inspections required for operations should be addressed.*

This report consists of a detailed inspection that will extend the inspection period to 3 years. It is the airport sponsor's responsibility to perform monthly drive-by inspections. A sample pavement inspection report form is provided in Table 3 of this report.

A-1.3. Record Keeping. *The airport must record and keep on file complete information about all detailed inspections and maintenance performed until the pavement system is replaced. The types of distress, their locations, and remedial action, scheduled or performed, must be documented. The minimum information recorded includes:*

- a. *Inspection date*
- b. *Location*
- c. *Distress types*
- d. *Maintenance scheduled or performed*

Items a through c are satisfied by this inspection report. Item d is the responsibility of the airport, as is record keeping of the monthly drive-by inspections.

A-1.4. Information Retrieval. *An airport sponsor may use any form of record keeping it deems appropriate so long as the information and records from the pavement survey can generate required reports, as necessary.*

Keep this report, monthly drive-by inspection reports, construction updates, and all records of maintenance activities in a readily accessible location so that they can be easily retrieved as requested by the FAA.

Table 3. Pavement inspection report.

Inspected By: _____

Date Inspected: _____

| Branch | Section | Distress Description/Dimensions/Severity/ Recommended Action | Description of Repair | Date Performed | Cost | Funding Source |
|---------------|----------------|---|----------------------------------|---------------------------|-------------|---------------------------|
| A01FD | 01 | | | | | |
| A01FD | 02 | | | | | |
| A02FD | 01 | | | | | |
| A02FD | 02 | | | | | |
| R06FD | 01 | | | | | |
| R06FD | 02 | | | | | |

Table 3. Pavement inspection report (continued).

Inspected By: _____

Date Inspected: _____

| Branch | Section | Distress Description/Dimensions/Severity/ Recommended Action | Description of Repair | Date Performed | Cost | Funding Source |
|---------------|----------------|---|----------------------------------|---------------------------|-------------|---------------------------|
| R12FD | 01 | | | | | |
| R12FD | 02 | | | | | |
| R12FD | 03 | | | | | |
| R12FD | 04 | | | | | |
| TAFD | 01 | | | | | |
| TBFD | 01 | | | | | |

Table 3. Pavement inspection report (continued).

Inspected By: _____

Date Inspected: _____

| Branch | Section | Distress Description/Dimensions/Severity/ Recommended Action | Description of Repair | Date Performed | Cost | Funding Source |
|---------------|----------------|---|----------------------------------|---------------------------|-------------|---------------------------|
| TBFD | 02 | | | | | |
| TBFD | 03 | | | | | |
| TBFD | 04 | | | | | |
| TBFD | 05 | | | | | |
| TBFD | 06 | | | | | |
| TCFD | 01 | | | | | |

Table 3. Pavement inspection report (continued).

Inspected By: _____

Date Inspected: _____

| Branch | Section | Distress Description/Dimensions/Severity/ Recommended Action | Description of Repair | Date Performed | Cost | Funding Source |
|---------------|----------------|---|----------------------------------|---------------------------|-------------|---------------------------|
| TDFD | 01 | | | | | |
| TDFD | 02 | | | | | |
| TDFD | 03 | | | | | |
| TFFD | 01 | | | | | |
| TFFD | 02 | | | | | |
| TH01FD | 01 | | | | | |

Table 3. Pavement inspection report (continued).

Inspected By: _____

Date Inspected: _____

| Branch | Section | Distress Description/Dimensions/Severity/ Recommended Action | Description of Repair | Date Performed | Cost | Funding Source |
|---------------|----------------|---|----------------------------------|---------------------------|-------------|---------------------------|
| TH01FD | 02 | | | | | |
| TH01FD | 03 | | | | | |

Table Note: See Figure 3 for the location of the branch and section.

SUMMARY

This report documents the results of the pavement evaluation conducted at Fort Dodge Regional Airport. A visual inspection of the pavements in 2022 found that the overall condition of the pavement network is a PCI of 77. A 5-year pavement repair program, shown in Table 2, was generated for Fort Dodge Regional Airport, which revealed that approximately \$5,323,000 needs to be expended on M&R. Fort Dodge Regional Airport should utilize these study results to assist in planning for future maintenance needs as part of the airport CIP planning process.

APPENDIX A

CAUSE OF DISTRESS TABLES

Table A-1. Cause of pavement distress, asphalt-surfaced pavements.

| Distress Type | Probable Cause of Distress |
|---------------------------|--|
| Alligator Cracking | Fatigue failure of the asphalt surface under repeated traffic loading. |
| Bleeding | Excessive amounts of asphalt cement or tars in the mix or low air void content, or both. |
| Block Cracking | Shrinkage of the asphalt and daily temperature cycling; it is not load associated. |
| Corrugation | Traffic action combined with an unstable pavement layer. |
| Depression | Settlement of the foundation soil or can be “built up” during construction. |
| Jet-Blast Erosion | Bituminous binder has been burned or carbonized. |
| Joint Reflection Cracking | Movement of the concrete slab beneath the asphalt surface due to thermal and moisture changes. |
| L&T Cracking | Cracks may be caused by (1) a poorly constructed paving lane joint, (2) shrinkage of the asphalt surface due to low temperatures or hardening of the asphalt, or (3) reflective cracking caused by cracks in an underlying PCC slab. |
| Oil Spillage | Deterioration or softening of the pavement surface caused by the spilling of oil, fuel, or other solvents. |
| Patching | N/A |
| Polished Aggregate | Repeated traffic applications. |
| Raveling | Asphalt binder may have hardened significantly, causing coarse aggregate pieces to dislodge. |
| Rutting | Usually caused by consolidation or lateral movement of the materials due to traffic loads. |
| Shoving | Where PCC pavements adjoin flexible pavements, PCC “growth” may shove the asphalt pavement. |
| Slippage Cracking | Low strength surface mix or poor bond between the surface and the next layer of the pavement structure. |
| Swelling | Usually caused by frost action or by swelling soil. |
| Weathering | Asphalt binder and/or fine aggregate may wear away as the pavement ages and hardens. |

Table A-2. Cause of pavement distress, PCC pavements.

| Distress Type | Probable Cause of Distress |
|-----------------------------|---|
| ASR | Chemical reaction of alkalis in the portland cement with certain reactive silica minerals. ASR may be accelerated by the use of chemical pavement deicers. |
| Blowup | Incompressible materials in the joints. |
| Corner Break | Load repetition combined with loss of support and curling stresses. |
| Durability Cracking | Concrete's inability to withstand environmental factors such as freeze-thaw cycles. |
| Faulting | Upheaval or consolidation. |
| Joint Seal Damage | Stripping of joint sealant, extrusion of joint sealant, weed growth, hardening of the filler (oxidation), loss of bond to the slab edges, or absence of sealant in the joint. |
| LTD Cracking | Combination of load repetition, curling stresses, and shrinkage stresses. |
| Patching (Small and Large) | N/A |
| Popouts | Freeze-thaw action in combination with expansive aggregates. |
| Pumping | Poor drainage, poor joint sealant. |
| Scaling | Over finishing of concrete, deicing salts, improper construction, freeze-thaw cycles, and poor aggregate. |
| Shattered Slab | Load repetition. |
| Shrinkage Cracking | Setting and curing of the concrete. |
| Spalling (Joint and Corner) | Excessive stresses at the joint caused by infiltration of incompressible materials or traffic loads; weak concrete at the joint combined with traffic loads. |

APPENDIX B

INSPECTION PHOTOGRAPHS

A01FD-01. Overview.



A01FD-02. Overview.



A01FD-02. Corner Spalling (Additional Sample Unit No. 15).



A02FD-01. Overview.



A02FD-01. Joint Seal Damage (Sample Unit No. 07).



A02FD-01. LTD Cracking (Additional Sample Unit No. 14).



A02FD-02. Overview.



A02FD-02. Joint Spalling (Sample Unit No. 04).



A02FD-02. LTD Cracking (Sample Unit No. 04).



A02FD-02. Shrinkage Cracking (Sample Unit No. 04).



R06FD-01. Overview.



R06FD-01. L&T Cracking (Sample Unit No. 155).



R06FD-01. L&T Cracking (Sample Unit No. 96).




R06FD-01. Weathering (Sample Unit No. 155).




R06FD-02. Overview.



R06FD-02. L&T Cracking (Sample Unit No. 18).




R06FD-02. Weathering (Sample Unit No. 18).



R12FD-01. Overview.




R12FD-01. L&T Cracking (Sample Unit No. 24).



R12FD-02. Overview.



R12FD-02. L&T Cracking (Sample Unit No. 53).



R12FD-03. Overview.



R12FD-03. LTD Cracking (Sample Unit No. 02).



R12FD-04. Overview.



R12FD-04. Corner Spalling (Sample Unit No. 12).



TAFD-01. Overview.



TAFD-01. LTD Cracking (Sample Unit No. 10).



TBFD-01. Overview.



TBFD-01. L&T Cracking (Sample Unit No. 11).



TBFD-01. Weathering (Sample Unit No. 11).



TBFD-02. Overview.



TBFD-02. L&T Cracking (Sample Unit No. 09).



TBFD-02. Weathering (Sample Unit No. 09).



TBFD-03. Overview (1).



TBFD-03. Overview (2).



TBFD-04. Overview.



TBFD-04. L&T Cracking (Sample Unit No. 03).



TBFD-05. Overview.



TBFD-05. L&T Cracking (Sample Unit No. 03).



TBFD-05. Weathering (Sample Unit No. 03).



TBFD-06. Overview.



TBFD-06. Weathering (Sample Unit No. 01).



TCFD-01. Overview.



TCFD-01. Joint Seal Damage (Sample Unit No. 12).



TDFD-01. Overview.



TDFD-01. L&T Cracking (Sample Unit No. 05).



TDFD-01. Weathering (Sample Unit No. 05).



TDFD-02. Overview.



TDFD-02. L&T Cracking (Sample Unit No. 04).



TDFD-02. Weathering (Sample Unit No. 04).



TDFD-03. Overview.



TDFD-03. Joint Seal Damage (Sample Unit No. 03).



TDFD-03. LTD Cracking (Sample Unit No. 03).



TFFD-01. Overview.



TFFD-01. L&T Cracking (Sample Unit. 05).



TFFD-01. Weathering (Sample Unit. 05).



TFFD-02. Overview.



TFFD-02. Corner Break (Sample Unit No. 03).



TFFD-02. LTD Cracking (Sample Unit No. 12).



TH01FD-01. Overview.



TH01FD-01. Alligator Cracking (Sample Unit No. 07).



TH01FD-01. L&T Cracking (Sample Unit No. 09).




TH01FD-02. Overview.



TH01FD-03. Overview.



TH01FD-03. Corner Break (Sample Unit No. 04).



APPENDIX C

INSPECTION REPORT

RE-INSPECTION REPORT

FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 1

Branch - Section ID: A01FD - 001

Branch Name: TERMINAL APRON

Use: APRON

LCD: 6/3/2019

PCI Family: IowaPCCAPNC_CommEnh

Surface Type: PCC

Rank: P

Section Area (sf): 102,275.00

Length (ft): 390.00

Width (ft): 225.00

From: TAXIWAY A

To: TAXIWAY C

Slabs: 455

Section Comments: avg slab width entered

Slab Length (ft): 15.00

Slab Width (ft): 15.00

Joint Length (ft): 12,919.87

Last Insp Date: 11/10/2022

Inspection Comments:

PCI: 98

Total Samples: 22

Surveyed: 7

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 24.00

65 JOINT SEAL DAMAGE

L

24.00 Slabs

Sample Number: 07

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 24.00

65 JOINT SEAL DAMAGE

L

24.00 Slabs

Sample Number: 09

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 24.00

65 JOINT SEAL DAMAGE

L

24.00 Slabs

Sample Number: 11

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 14

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 24.00

65 JOINT SEAL DAMAGE

L

24.00 Slabs

Sample Number: 17

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 25.00

65 JOINT SEAL DAMAGE

L

25.00 Slabs

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 2

Sample Number: 19

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 3

Branch - Section ID: A01FD - 002

Branch Name: TERMINAL APRON

Use: APRON

LCD: 6/3/2019

PCI Family: IowaPCCAPNC_CommEnh

Surface Type: PCC

Rank: P

Section Area (sf): 53,202.00

Length (ft): 225.00

Width (ft): 250.00

From: .

To: .

Slabs: 340

Section Comments:

Slab Length (ft): 12.50

Slab Width (ft): 12.50

Joint Length (ft): 8,063.06

Last Insp Date: 11/10/2022

Inspection Comments:

PCI: 98

Total Samples: 16

Surveyed: 7

Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

Sample Number: 08

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 26.00

65 JOINT SEAL DAMAGE

L

26.00 Slabs

Sample Number: 09

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 14.00

65 JOINT SEAL DAMAGE

L

14.00 Slabs

Sample Number: 11

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

65 JOINT SEAL DAMAGE

L

20.00 Slabs

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 4

Sample Number: 15

Sample Type: A

Sample Comments:

Sample PCI: 95

Sample Area (Slabs): 28.00

65 JOINT SEAL DAMAGE

L

28.00 Slabs

75 CORNER SPALL

M

1.00 Slabs

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 5

Branch - Section ID: A02FD - 001

Branch Name: GENERAL AVIATION A

Use: APRON

LCD: 6/3/2019

PCI Family: IowaPCCAPNC_CommEnh

Surface Type: PCC

Rank: P

Section Area (sf): 76,791.00

Length (ft): 500.00

Width (ft): 150.00

From: TERMINAL APRON

To: SEE MAP

Slabs: 491

Section Comments: Slurry seal in '88

Slab Length (ft): 12.50

Slab Width (ft): 12.50

Joint Length (ft): 11,621.04

Last Insp Date: 11/10/2022

Inspection Comments:

PCI: 93

Total Samples: 24

Surveyed: 8

Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 24.00

65 JOINT SEAL DAMAGE

M

24.00 Slabs

Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 24.00

65 JOINT SEAL DAMAGE

M

24.00 Slabs

Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 24.00

65 JOINT SEAL DAMAGE

M

24.00 Slabs

Sample Number: 07

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 24.00

65 JOINT SEAL DAMAGE

M

24.00 Slabs

Sample Number: 12

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 24.00

65 JOINT SEAL DAMAGE

M

24.00 Slabs

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 6

Sample Number: 14

Sample Type: A

Sample Comments:

Sample PCI: 86

Sample Area (Slabs): 24.00

| | | |
|-----------------------|---|-------------|
| 63 LINEAR CRACKING | L | 1.00 Slabs |
| 65 JOINT SEAL DAMAGE | M | 24.00 Slabs |
| 73 SHRINKAGE CRACKING | N | 1.00 Slabs |
| 75 CORNER SPALL | L | 1.00 Slabs |

Sample Number: 15

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 24.00

| | | |
|----------------------|---|-------------|
| 65 JOINT SEAL DAMAGE | M | 24.00 Slabs |
|----------------------|---|-------------|

Sample Number: 17

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 24.00

| | | |
|----------------------|---|-------------|
| 65 JOINT SEAL DAMAGE | M | 24.00 Slabs |
|----------------------|---|-------------|

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 7

Branch - Section ID: A02FD - 002

Branch Name: GENERAL AVIATION A

Use: APRON

LCD: 7/3/2012
 Surface Type: PCC
 Rank: P
 Section Area (sf): 21,688.00
 Length (ft): 370.00
 Width (ft): 62.50
 From: SEE MAP
 To: SEE MAP
 Slabs: 167
 Slab Length (ft): 10.70
 Slab Width (ft): 12.50
 Joint Length (ft): 3,447.33
 Last Insp Date: 11/10/2022
 PCI: 88
 Total Samples: 8
 Surveyed: 5

PCI Family: IowaPCCAPNC_CommEnh

Section Comments: avg slab length entered

Inspection Comments:

Sample Number: 002

Sample Type: R
 Sample PCI: 89
 Sample Area (Slabs): 20.00

Sample Comments:

| | | |
|-----------------------|---|-------------|
| 65 JOINT SEAL DAMAGE | M | 20.00 Slabs |
| 73 SHRINKAGE CRACKING | N | 5.00 Slabs |

Sample Number: 003

Sample Type: R
 Sample PCI: 90
 Sample Area (Slabs): 20.00

Sample Comments:

| | | |
|-----------------------|---|-------------|
| 65 JOINT SEAL DAMAGE | M | 20.00 Slabs |
| 73 SHRINKAGE CRACKING | N | 3.00 Slabs |

Sample Number: 004

Sample Type: R
 Sample PCI: 81
 Sample Area (Slabs): 20.00

Sample Comments:

| | | |
|-----------------------|---|-------------|
| 63 LINEAR CRACKING | L | 1.00 Slabs |
| 65 JOINT SEAL DAMAGE | M | 20.00 Slabs |
| 73 SHRINKAGE CRACKING | N | 4.00 Slabs |
| 74 JOINT SPALL | M | 1.00 Slabs |

Sample Number: 005

Sample Type: R
 Sample PCI: 93
 Sample Area (Slabs): 20.00

Sample Comments:

| | | |
|----------------------|---|-------------|
| 65 JOINT SEAL DAMAGE | M | 20.00 Slabs |
|----------------------|---|-------------|

Sample Number: 006

Sample Type: R
 Sample PCI: 86
 Sample Area (Slabs): 20.00

Sample Comments:

| | | |
|-----------------------|---|-------------|
| 65 JOINT SEAL DAMAGE | M | 20.00 Slabs |
| 73 SHRINKAGE CRACKING | N | 4.00 Slabs |
| 75 CORNER SPALL | M | 1.00 Slabs |

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 8

Branch - Section ID: R06FD - 001

Branch Name: RUNWAY 06/24

Use: RUNWAY

LCD: 6/3/2015
 Surface Type: AAC
 Rank: P
 Section Area (sf): 877,200.00
 Length (ft): 5,868.00
 Width (ft): 150.00
 From: 06 APPROACH
 To: 24 APPROACH

PCI Family: IowaAACRWNC&NCW

Slabs:
 Slab Length (ft):
 Slab Width (ft):
 Joint Length (ft):

Section Comments:

Last Insp Date: 11/9/2022
 PCI: 78
 Total Samples: 158
 Surveyed: 16

Inspection Comments:

Sample Number: 005

Sample Type: R
 Sample PCI: 76
 Sample Area (SF): 5,625.00

Sample Comments:

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 41.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 120.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 100.00 Ft | FS |
| 57 WEATHERING | L | 2,625.00 SF | |

Sample Number: 016

Sample Type: R
 Sample PCI: 81
 Sample Area (SF): 5,625.00

Sample Comments:

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 10.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 15.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 75.00 Ft | FS |
| 57 WEATHERING | L | 2,625.00 SF | |

Sample Number: 025

Sample Type: R
 Sample PCI: 78
 Sample Area (SF): 5,625.00

Sample Comments:

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 62.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 150.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 75.00 Ft | FS |
| 57 WEATHERING | L | 2,625.00 SF | |

Sample Number: 036

Sample Type: R
 Sample PCI: 77
 Sample Area (SF): 5,625.00

Sample Comments:

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 75.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 83.00 Ft | FS |
| 57 WEATHERING | L | 2,625.00 SF | |

RE-INSPECTION REPORT

FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 9

Sample Number: 045

Sample Type: R

Sample Comments:

Sample PCI: 78

Sample Area (SF): 5,625.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 150.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 200.00 Ft | LS |
| 57 WEATHERING | L | 2,625.00 SF | |

Sample Number: 056

Sample Type: R

Sample Comments:

Sample PCI: 71

Sample Area (SF): 5,625.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 10.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 61.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 75.00 Ft | FS |
| 57 WEATHERING | H | 10.00 SF | PR |
| 57 WEATHERING | L | 2,525.00 SF | |
| 57 WEATHERING | M | 95.00 SF | PR |

Sample Number: 065

Sample Type: R

Sample Comments:

Sample PCI: 78

Sample Area (SF): 5,625.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 150.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 75.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 75.00 Ft | FS |
| 57 WEATHERING | L | 2,625.00 SF | |

Sample Number: 076

Sample Type: R

Sample Comments:

Sample PCI: 83

Sample Area (SF): 5,625.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 27.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 75.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 20.00 Ft | FS |
| 57 WEATHERING | L | 2,625.00 SF | |

Sample Number: 085

Sample Type: R

Sample Comments:

Sample PCI: 78

Sample Area (SF): 5,625.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 75.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 75.00 Ft | FS |
| 57 WEATHERING | L | 2,625.00 SF | |

Sample Number: 096

Sample Type: R

Sample Comments:

Sample PCI: 82

Sample Area (SF): 5,625.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 40.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 4.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 35.00 Ft | FS |
| 57 WEATHERING | L | 2,625.00 SF | |

RE-INSPECTION REPORT

FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 10

Sample Number: 103

Sample Type: R

Sample Comments:

Sample PCI: 76

Sample Area (SF): 5,625.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 160.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 50.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 100.00 Ft | FS |
| 57 WEATHERING | L | 2,625.00 SF | |

Sample Number: 115

Sample Type: R

Sample Comments:

Sample PCI: 80

Sample Area (SF): 5,625.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 150.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 50.00 Ft | W |
| 57 WEATHERING | L | 2,625.00 SF | |

Sample Number: 126

Sample Type: R

Sample Comments:

Sample PCI: 80

Sample Area (SF): 5,625.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 43.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 100.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 50.00 Ft | FS |
| 57 WEATHERING | L | 2,625.00 SF | |

Sample Number: 135

Sample Type: R

Sample Comments:

Sample PCI: 84

Sample Area (SF): 5,625.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 100.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 10.00 Ft | FS |
| 57 WEATHERING | L | 2,625.00 SF | |

Sample Number: 146

Sample Type: R

Sample Comments:

Sample PCI: 76

Sample Area (SF): 5,625.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 50.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 85.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 100.00 Ft | FS |
| 57 WEATHERING | L | 2,625.00 SF | |

Sample Number: 155

Sample Type: R

Sample Comments:

Sample PCI: 76

Sample Area (SF): 3,750.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 125.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 50.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 50.00 Ft | FS |
| 57 WEATHERING | L | 1,750.00 SF | |

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 11

Branch - Section ID: R06FD - 002

Branch Name: RUNWAY 06/24

Use: RUNWAY

LCD: 6/1/2012

PCI Family: IowaAACRWNC&NCW

Surface Type: AAC

Rank: P

Section Area (sf): 105,000.00

Length (ft): 700.00

Width (ft): 150.00

From: SEE MAP

To: SEE MAP

Slabs:

Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/9/2022

Inspection Comments:

PCI: 78

Total Samples: 19

Surveyed: 5

Sample Number: 003

Sample Type: R

Sample Comments:

Sample PCI: 84

Sample Area (SF): 5,625.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 41.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 180.00 Ft | LS |
| 57 WEATHERING | L | 1,625.00 SF | |

Sample Number: 006

Sample Type: R

Sample Comments:

Sample PCI: 73

Sample Area (SF): 5,625.00

| | | | |
|-------------------------------------|---|-------------|----|
| 41 ALLIGATOR CRACKING | L | 10.00 SF | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 75.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 175.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 48.00 Ft | FS |
| 57 WEATHERING | L | 1,625.00 SF | |

Sample Number: 012

Sample Type: R

Sample Comments:

Sample PCI: 72

Sample Area (SF): 5,625.00

| | | | |
|-------------------------------------|---|-------------|----|
| 41 ALLIGATOR CRACKING | L | 20.00 SF | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 126.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 300.00 Ft | LS |
| 57 WEATHERING | L | 1,625.00 SF | |

Sample Number: 013

Sample Type: R

Sample Comments:

Sample PCI: 78

Sample Area (SF): 5,625.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 300.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 75.00 Ft | LU |
| 57 WEATHERING | L | 1,625.00 SF | |

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 12

Sample Number: 018

Sample Type: R

Sample Comments:

Sample PCI: 81

Sample Area (SF): 5,625.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 285.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 23.00 Ft | LU |
| 57 WEATHERING | L | 1,625.00 SF | |

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 13

Branch - Section ID: R12FD - 001

Branch Name: RUNWAY 12/30

Use: RUNWAY

LCD: 6/1/2012

PCI Family: IowaAPCRWNorthern

Surface Type: APC

Rank: S

Section Area (sf): 147,855.00

Length (ft): 1,432.00

Width (ft): 100.00

From: 12 APPROACH

To: RUNWAY 06/24

Slabs:

Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/9/2022

Inspection Comments:

PCI: 72

Total Samples: 29

Surveyed: 6

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 68

Sample Area (SF): 5,000.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 34.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 497.00 Ft | LS |
| 52 RAVELING | L | 500.00 SF | |
| 57 WEATHERING | L | 1,000.00 SF | |

Sample Number: 08

Sample Type: R

Sample Comments:

Sample PCI: 72

Sample Area (SF): 5,000.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 16.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 390.00 Ft | LS |
| 52 RAVELING | L | 500.00 SF | |
| 57 WEATHERING | L | 1,000.00 SF | |

Sample Number: 12

Sample Type: R

Sample Comments:

Sample PCI: 69

Sample Area (SF): 5,000.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 71.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 420.00 Ft | LS |
| 52 RAVELING | L | 500.00 SF | |
| 57 WEATHERING | L | 1,000.00 SF | |

Sample Number: 16

Sample Type: R

Sample Comments:

Sample PCI: 74

Sample Area (SF): 5,000.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 51.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 300.00 Ft | LS |
| 52 RAVELING | L | 500.00 SF | |
| 57 WEATHERING | L | 1,000.00 SF | |

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 14

Sample Number: 20

Sample Type: R

Sample Comments:

Sample PCI: 76

Sample Area (SF): 5,000.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 55.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 225.00 Ft | LS |
| 52 RAVELING | L | 500.00 SF | |
| 57 WEATHERING | L | 1,000.00 SF | |

Sample Number: 24

Sample Type: R

Sample Comments:

Sample PCI: 75

Sample Area (SF): 5,000.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 275.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 30.00 Ft | LU |
| 52 RAVELING | L | 500.00 SF | |
| 57 WEATHERING | L | 1,000.00 SF | |

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 15

Branch - Section ID: R12FD - 002

Branch Name: RUNWAY 12/30

Use: RUNWAY

LCD: 6/1/2012

PCI Family: IowaAPCRWNorthern

Surface Type: APC

Rank: S

Section Area (sf): 291,412.00

Length (ft): 2,890.00

Width (ft): 100.00

From: RUNWAY 06/24

To: 30 APPROACH

Slabs:

Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/9/2022

Inspection Comments:

PCI: 72

Total Samples: 58

Surveyed: 7

Sample Number: 13

Sample Type: R

Sample Comments:

Sample PCI: 72

Sample Area (SF): 5,000.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 82.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 327.00 Ft | LS |
| 52 RAVELING | L | 200.00 SF | |
| 57 WEATHERING | L | 1,000.00 SF | |

Sample Number: 21

Sample Type: R

Sample Comments:

Sample PCI: 71

Sample Area (SF): 5,000.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 111.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 318.00 Ft | LS |
| 52 RAVELING | L | 200.00 SF | |
| 57 WEATHERING | L | 1,000.00 SF | |

Sample Number: 29

Sample Type: R

Sample Comments:

Sample PCI: 74

Sample Area (SF): 5,000.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 102.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 222.00 Ft | LS |
| 52 RAVELING | L | 200.00 SF | |
| 57 WEATHERING | L | 1,000.00 SF | |

Sample Number: 33

Sample Type: R

Sample Comments:

Sample PCI: 70

Sample Area (SF): 5,000.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 116.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 350.00 Ft | LS |
| 52 RAVELING | L | 200.00 SF | |
| 57 WEATHERING | L | 1,000.00 SF | |

RE-INSPECTION REPORT

FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 16

Sample Number: 38

Sample Type: R

Sample Comments:

Sample PCI: 73

Sample Area (SF): 5,000.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 273.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 100.00 Ft | LS |
| 52 RAVELING | L | 200.00 SF | |
| 57 WEATHERING | L | 1,000.00 SF | |

Sample Number: 46

Sample Type: R

Sample Comments:

Sample PCI: 70

Sample Area (SF): 5,000.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 12.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 310.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 35.00 Ft | FS |
| 52 RAVELING | L | 200.00 SF | |
| 57 WEATHERING | L | 1,000.00 SF | |

Sample Number: 53

Sample Type: R

Sample Comments:

Sample PCI: 74

Sample Area (SF): 5,000.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 300.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 44.00 Ft | LU |
| 52 RAVELING | L | 200.00 SF | |
| 57 WEATHERING | L | 1,000.00 SF | |

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 17

Branch - Section ID: R12FD - 003

Branch Name: RUNWAY 12/30

Use: RUNWAY

LCD: 5/1/2004

PCI Family: IowaPCCRWNC_CommEnhanced

Surface Type: PCC

Rank: S

Section Area (sf): 10,869.00

Length (ft): 100.00

Width (ft): 100.00

From: RW12FO-01

To: ..

Slabs: 72

Section Comments:

Slab Length (ft): 12.50

Slab Width (ft): 12.50

Joint Length (ft): 1,573.18

Last Insp Date: 11/9/2022

Inspection Comments:

PCI: 84

Total Samples: 5

Surveyed: 4

Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 95

Sample Area (Slabs): 16.00

62 CORNER BREAK

L

1.00 Slabs

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 80

Sample Area (Slabs): 16.00

63 LINEAR CRACKING

L

1.00 Slabs

63 LINEAR CRACKING

M

1.00 Slabs

74 JOINT SPALL

L

1.00 Slabs

Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 16.00

65 JOINT SEAL DAMAGE

L

16.00 Slabs

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 63

Sample Area (Slabs): 16.00

63 LINEAR CRACKING

L

2.00 Slabs

63 LINEAR CRACKING

M

1.00 Slabs

72 SHATTERED SLAB

M

1.00 Slabs

75 CORNER SPALL

L

2.00 Slabs

RE-INSPECTION REPORT

FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 18

Branch - Section ID: R12FD - 004

Branch Name: RUNWAY 12/30

Use: RUNWAY

LCD: 5/1/2004

PCI Family: IowaPCCRWNC_CommEnhanced

Surface Type: PCC

Rank: S

Section Area (sf): 70,952.00

Length (ft): 700.00

Width (ft): 100.00

From: RW12FO-02

To: ..

Slabs: 465

Section Comments:

Slab Length (ft): 12.20

Slab Width (ft): 12.50

Joint Length (ft): 10,681.02

Last Insp Date: 11/9/2022

Inspection Comments:

PCI: 97

Total Samples: 24

Surveyed: 7

Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 20.00

NO DISTRESS

Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 20.00

NO DISTRESS

Sample Number: 09

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20.00

75 CORNER SPALL

L

1.00 Slabs

Sample Number: 12

Sample Type: R

Sample Comments:

Sample PCI: 91

Sample Area (Slabs): 20.00

63 LINEAR CRACKING

L

1.00 Slabs

74 JOINT SPALL

L

1.00 Slabs

75 CORNER SPALL

L

1.00 Slabs

Sample Number: 15

Sample Type: R

Sample Comments:

Sample PCI: 92

Sample Area (Slabs): 20.00

71 FAULTING

L

2.00 Slabs

Sample Number: 18

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 20.00

NO DISTRESS

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 19

Sample Number: 22

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 20.00

NO DISTRESS

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 20

Branch - Section ID: TAFD - 001

Branch Name: TAXIWAY A

Use: TAXIWAY

LCD: 8/16/2001

PCI Family: IowaPCCTWNC_CommEnhanced

Surface Type: PCC

Rank: P

Section Area (sf): 25,248.00

Length (ft): 690.00

Width (ft): 35.00

From: 24 APPROACH

To: TERMINAL APRON

Slabs: 223

Section Comments:

Slab Length (ft): 9.70

Slab Width (ft): 11.66

Joint Length (ft): 4,010.28

Last Insp Date: 11/9/2022

Inspection Comments:

PCI: 85

Total Samples: 10

Surveyed: 5

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 88

Sample Area (Slabs): 23.00

65 JOINT SEAL DAMAGE

H

23.00 Slabs

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 88

Sample Area (Slabs): 21.00

65 JOINT SEAL DAMAGE

H

21.00 Slabs

Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 88

Sample Area (Slabs): 21.00

65 JOINT SEAL DAMAGE

H

21.00 Slabs

Sample Number: 08

Sample Type: R

Sample Comments:

Sample PCI: 83

Sample Area (Slabs): 21.00

65 JOINT SEAL DAMAGE

H

21.00 Slabs

74 JOINT SPALL

M

2.00 Slabs

Sample Number: 10

Sample Type: R

Sample Comments:

Sample PCI: 78

Sample Area (Slabs): 27.00

62 CORNER BREAK

M

1.00 Slabs

63 LINEAR CRACKING

M

1.00 Slabs

65 JOINT SEAL DAMAGE

H

27.00 Slabs

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 21

Branch - Section ID: TBFD - 001

Branch Name: TAXIWAY B

Use: TAXIWAY

LCD: 6/3/2015
 Surface Type: AAC
 Rank: P
 Section Area (sf): 65,568.00
 Length (ft): 1,230.00
 Width (ft): 50.00
 From: TERMINAL APRON
 To: TBFD-04

PCI Family: IowaAACTWNC&NCW

Slabs:
 Slab Length (ft):
 Slab Width (ft):
 Joint Length (ft):

Section Comments:

Last Insp Date: 11/10/2022
 PCI: 64
 Total Samples: 13
 Surveyed: 5

Inspection Comments:

Sample Number: 03

Sample Type: R
 Sample PCI: 64
 Sample Area (SF): 5,000.00

Sample Comments:

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 165.00 Ft | LU |
| 52 RAVELING | L | 5,000.00 SF | |
| 57 WEATHERING | L | 5,000.00 SF | |

Sample Number: 05

Sample Type: R
 Sample PCI: 64
 Sample Area (SF): 5,000.00

Sample Comments:

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 142.00 Ft | LU |
| 52 RAVELING | L | 5,000.00 SF | |
| 57 WEATHERING | L | 5,000.00 SF | |

Sample Number: 07

Sample Type: R
 Sample PCI: 64
 Sample Area (SF): 5,000.00

Sample Comments:

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 115.00 Ft | LU |
| 52 RAVELING | L | 5,000.00 SF | |
| 57 WEATHERING | L | 5,000.00 SF | |

Sample Number: 09

Sample Type: R
 Sample PCI: 64
 Sample Area (SF): 5,000.00

Sample Comments:

| | | | |
|-------------------------------------|---|-------------|--|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 183.00 Ft | |
| 52 RAVELING | L | 5,000.00 SF | |
| 57 WEATHERING | L | 5,000.00 SF | |

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 22

Sample Number: 11

Sample Type: R

Sample Comments:

Sample PCI: 64

Sample Area (SF): 5,000.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 318.00 Ft | LU |
| 52 RAVELING | L | 5,000.00 SF | |
| 57 WEATHERING | L | 5,000.00 SF | |

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 23

Branch - Section ID: TBFD - 002

Branch Name: TAXIWAY B

Use: TAXIWAY

LCD: 6/1/2007

PCI Family: IowaAACTWNC&NCW

Surface Type: AAC

Rank: P

Section Area (sf): 162,730.00

Length (ft): 2,500.00

Width (ft): 50.00

From: TAXIWAY E

To: RUNWAY 12/30

Slabs:

Section Comments: Slurry seal '93

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/9/2022

Inspection Comments:

PCI: 59

Total Samples: 33

Surveyed: 7

Sample Number: 09

Sample Type: R

Sample Comments:

Sample PCI: 57

Sample Area (SF): 6,050.00

| | | | |
|-------------------------------------|---|-------------|------|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 224.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 350.00 Ft | W FS |
| 57 WEATHERING | L | 3,050.00 SF | |
| 57 WEATHERING | M | 2,800.00 SF | |
| 57 WEATHERING | M | 200.00 SF | PR |

Sample Number: 12

Sample Type: R

Sample Comments:

Sample PCI: 55

Sample Area (SF): 5,000.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 355.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 350.00 Ft | W |
| 57 WEATHERING | L | 2,500.00 SF | |
| 57 WEATHERING | M | 2,500.00 SF | |

Sample Number: 16

Sample Type: R

Sample Comments:

Sample PCI: 56

Sample Area (SF): 5,000.00

| | | | |
|-------------------------------------|---|-------------|------|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 262.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 314.00 Ft | W FS |
| 57 WEATHERING | L | 2,500.00 SF | |
| 57 WEATHERING | M | 2,500.00 SF | |

Sample Number: 20

Sample Type: R

Sample Comments:

Sample PCI: 59

Sample Area (SF): 5,000.00

| | | | |
|-------------------------------------|---|-------------|------|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 311.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 252.00 Ft | W FS |
| 57 WEATHERING | L | 2,500.00 SF | |
| 57 WEATHERING | M | 2,500.00 SF | |

RE-INSPECTION REPORT

FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 24

Sample Number: 24

Sample Type: R

Sample Comments:

Sample PCI: 61

Sample Area (SF): 5,000.00

| | | | |
|-------------------------------------|---|-------------|------|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 447.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 200.00 Ft | W FS |
| 57 WEATHERING | L | 2,500.00 SF | |
| 57 WEATHERING | M | 2,500.00 SF | |

Sample Number: 28

Sample Type: R

Sample Comments:

Sample PCI: 60

Sample Area (SF): 5,000.00

| | | | |
|-------------------------------------|---|-------------|------|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 236.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 250.00 Ft | W FS |
| 57 WEATHERING | L | 2,500.00 SF | |
| 57 WEATHERING | M | 2,500.00 SF | |

Sample Number: 30

Sample Type: R

Sample Comments:

Sample PCI: 64

Sample Area (SF): 5,000.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 54.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 232.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 200.00 Ft | FS |
| 57 WEATHERING | L | 1,250.00 SF | |
| 57 WEATHERING | M | 1,250.00 SF | |

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 25

Branch - Section ID: TBFD - 003

Branch Name: TAXIWAY B

Use: TAXIWAY

LCD: 6/3/2022

PCI Family: IowaACTWNC_NotEnhanced

Surface Type: AC

Rank: P

Section Area (sf): 111,503.00

Length (ft): 1,930.00

Width (ft): 50.00

From: 06 APPROACH

To: TAXIWAY E

Slabs:

Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/9/2022

Inspection Comments:

PCI: 100

Total Samples: 22

Surveyed: 6

Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (SF): 5,000.00

NO DISTRESS

Sample Number: 08

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (SF): 5,000.00

NO DISTRESS

Sample Number: 11

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (SF): 5,000.00

NO DISTRESS

Sample Number: 14

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (SF): 5,000.00

NO DISTRESS

Sample Number: 17

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (SF): 5,000.00

NO DISTRESS

Sample Number: 20

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (SF): 5,000.00

NO DISTRESS

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 26

Branch - Section ID: TBFD - 004

Branch Name: TAXIWAY B

Use: TAXIWAY

LCD: 6/1/2012
 Surface Type: AAC
 Rank: P
 Section Area (sf): 14,250.00
 Length (ft): 250.00
 Width (ft): 50.00
 From: SEE MAP
 To: SEE MAP

PCI Family: IowaAACTWNC&NCW

Slabs:
 Slab Length (ft):
 Slab Width (ft):
 Joint Length (ft):

Section Comments:

Last Insp Date: 11/10/2022
 PCI: 76
 Total Samples: 3
 Surveyed: 3

Inspection Comments:

Sample Number: 001

Sample Type: R
 Sample PCI: 80
 Sample Area (SF): 5,500.00

Sample Comments:

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 25.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 311.00 Ft | LS |
| 57 WEATHERING | L | 1,500.00 SF | |

Sample Number: 002

Sample Type: R
 Sample PCI: 71
 Sample Area (SF): 3,750.00

Sample Comments:

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 32.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 375.00 Ft | LS |
| 57 WEATHERING | L | 1,750.00 SF | |

Sample Number: 003

Sample Type: R
 Sample PCI: 76
 Sample Area (SF): 5,000.00

Sample Comments:

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 111.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 302.00 Ft | LS |
| 57 WEATHERING | L | 1,500.00 SF | |

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 27

Branch - Section ID: TBFD - 005

Branch Name: TAXIWAY B

Use: TAXIWAY

LCD: 6/1/2015
 Surface Type: AAC
 Rank: P
 Section Area (sf): 17,528.00
 Length (ft): 150.00
 Width (ft): 65.00
 From: 06 APPROACH
 To: .

PCI Family: IowaAACTWNC&NCW

Slabs:
 Slab Length (ft):
 Slab Width (ft):
 Joint Length (ft):

Section Comments:

Last Insp Date: 11/9/2022
 PCI: 70
 Total Samples: 4
 Surveyed: 3

Inspection Comments:

Sample Number: 01

Sample Type: R
 Sample PCI: 65
 Sample Area (SF): 3,695.00

Sample Comments:

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 50.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 80.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 130.00 Ft | FS |
| 52 RAVELING | L | 700.00 SF | |
| 57 WEATHERING | L | 1,000.00 SF | |

Sample Number: 03

Sample Type: R
 Sample PCI: 68
 Sample Area (SF): 5,525.00

Sample Comments:

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 50.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 50.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 85.00 Ft | FS |
| 52 RAVELING | L | 1,000.00 SF | |
| 57 WEATHERING | L | 1,500.00 SF | |
| 57 WEATHERING | M | 400.00 SF | PR |

Sample Number: 04

Sample Type: R
 Sample PCI: 74
 Sample Area (SF): 5,678.00

Sample Comments:

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 83.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 95.00 Ft | FS |
| 57 WEATHERING | L | 2,000.00 SF | |
| 57 WEATHERING | M | 190.00 SF | PR |

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 28

Branch - Section ID: TBFD - 006

Branch Name: TAXIWAY B

Use: TAXIWAY

LCD: 6/3/2019

PCI Family: IowaACTWNC_NotEnhanced

Surface Type: AC

Rank: P

Section Area (sf): 3,245.00

Length (ft): 125.00

Width (ft): 25.00

From: .

To: .

Slabs:

Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/10/2022

Inspection Comments:

PCI: 83

Total Samples: 1

Surveyed: 1

Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 83

Sample Area (SF): 3,245.00

52 RAVELING

L

500.00 SF

57 WEATHERING

L

3,245.00 SF

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 29

Branch - Section ID: TCFD - 001

Branch Name: TAXIWAY C

Use: TAXIWAY

LCD: 8/1/2001

PCI Family: IowaPCCTWNC_CommEnhanced

Surface Type: PCC

Rank: P

Section Area (sf): 34,299.00

Length (ft): 752.00

Width (ft): 35.00

From: TERMINAL APRON

To: RUNWAY 12/30

Slabs: 309

Section Comments:

Slab Length (ft): 9.40

Slab Width (ft): 11.66

Joint Length (ft): 5,501.73

Last Insp Date: 11/9/2022

Inspection Comments:

PCI: 84

Total Samples: 15

Surveyed: 6

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 78

Sample Area (Slabs): 21.00

| | | |
|----------------------|---|-------------|
| 65 JOINT SEAL DAMAGE | H | 21.00 Slabs |
| 71 FAULTING | L | 3.00 Slabs |
| 74 JOINT SPALL | L | 1.00 Slabs |
| 75 CORNER SPALL | L | 1.00 Slabs |

Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 79

Sample Area (Slabs): 21.00

| | | |
|----------------------|---|-------------|
| 62 CORNER BREAK | L | 1.00 Slabs |
| 65 JOINT SEAL DAMAGE | H | 21.00 Slabs |
| 71 FAULTING | L | 2.00 Slabs |

Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 88

Sample Area (Slabs): 21.00

| | | |
|----------------------|---|-------------|
| 65 JOINT SEAL DAMAGE | H | 21.00 Slabs |
|----------------------|---|-------------|

Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 84

Sample Area (Slabs): 21.00

| | | |
|----------------------|---|-------------|
| 65 JOINT SEAL DAMAGE | H | 21.00 Slabs |
| 71 FAULTING | L | 1.00 Slabs |

Sample Number: 12

Sample Type: R

Sample Comments:

Sample PCI: 88

Sample Area (Slabs): 21.00

| | | |
|----------------------|---|-------------|
| 65 JOINT SEAL DAMAGE | H | 21.00 Slabs |
|----------------------|---|-------------|

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 30

Sample Number: 13

Sample Type: R

Sample Comments:

Sample PCI: 88

Sample Area (Slabs): 21.00

65 JOINT SEAL DAMAGE

H

21.00 Slabs

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 31

Branch - Section ID: TDFD - 001

Branch Name: TAXIWAY D

Use: TAXIWAY

LCD: 6/1/2007

PCI Family: IowaAACTWNC&NCW

Surface Type: AAC

Rank: P

Section Area (sf): 87,990.00

Length (ft): 1,870.00

Width (ft): 40.00

From: 12 APPROACH

To: RUNWAY 06/24

Slabs:

Section Comments: Slurry seal '93

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/9/2022

Inspection Comments:

PCI: 55

Total Samples: 18

Surveyed: 5

Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 52

Sample Area (SF): 5,000.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 106.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 215.00 Ft | FS |
| 52 RAVELING | M | 30.00 SF | |
| 57 WEATHERING | H | 150.00 SF | PR |
| 57 WEATHERING | L | 2,320.00 SF | |
| 57 WEATHERING | M | 2,500.00 SF | |

Sample Number: 08

Sample Type: R

Sample Comments:

Sample PCI: 59

Sample Area (SF): 5,000.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 65.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 197.00 Ft | FS |
| 52 RAVELING | L | 300.00 SF | |
| 57 WEATHERING | L | 2,500.00 SF | |
| 57 WEATHERING | M | 2,500.00 SF | |

Sample Number: 10

Sample Type: R

Sample Comments:

Sample PCI: 57

Sample Area (SF): 5,000.00

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 126.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 215.00 Ft | FS |
| 52 RAVELING | L | 300.00 SF | |
| 57 WEATHERING | L | 2,500.00 SF | |
| 57 WEATHERING | M | 2,500.00 SF | |

RE-INSPECTION REPORT

FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 32

Sample Number: 12

Sample Type: R

Sample Comments:

Sample PCI: 53

Sample Area (SF): 5,000.00

| | | | |
|-------------------------------------|---|-------------|------|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 88.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 305.00 Ft | FS W |
| 52 RAVELING | L | 300.00 SF | |
| 57 WEATHERING | L | 2,500.00 SF | |
| 57 WEATHERING | M | 2,500.00 SF | |

Sample Number: 14

Sample Type: R

Sample Comments:

Sample PCI: 53

Sample Area (SF): 5,000.00

| | | | |
|-------------------------------------|---|-------------|------|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 82.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 307.00 Ft | FS W |
| 52 RAVELING | L | 300.00 SF | |
| 57 WEATHERING | L | 2,500.00 SF | |
| 57 WEATHERING | M | 2,500.00 SF | |

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 33

Branch - Section ID: TDFD - 002

Branch Name: TAXIWAY D

Use: TAXIWAY

LCD: 6/1/2015
 Surface Type: AAC
 Rank: P
 Section Area (sf): 32,689.00
 Length (ft): 330.00
 Width (ft): 65.00
 From: TAXIWAY B
 To: RUNWAY 06/24

PCI Family: IowaAACTWNC&NCW

Slabs:
 Slab Length (ft):
 Slab Width (ft):
 Joint Length (ft):

Section Comments:

Last Insp Date: 11/10/2022
 PCI: 71
 Total Samples: 5
 Surveyed: 4

Inspection Comments:

Sample Number: 02

Sample Type: R
 Sample PCI: 75
 Sample Area (SF): 5,860.00

Sample Comments:

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 251.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 109.00 Ft | LU |
| 52 RAVELING | L | 1,500.00 SF | |
| 57 WEATHERING | L | 1,500.00 SF | |

Sample Number: 03

Sample Type: R
 Sample PCI: 71
 Sample Area (SF): 6,500.00

Sample Comments:

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 405.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 153.00 Ft | LU |
| 52 RAVELING | L | 1,500.00 SF | |
| 57 WEATHERING | L | 1,500.00 SF | |

Sample Number: 04

Sample Type: R
 Sample PCI: 67
 Sample Area (SF): 6,500.00

Sample Comments:

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 311.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 336.00 Ft | LS |
| 52 RAVELING | L | 2,000.00 SF | |
| 57 WEATHERING | L | 6,500.00 SF | |

Sample Number: 05

Sample Type: R
 Sample PCI: 74
 Sample Area (SF): 7,100.00

Sample Comments:

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 211.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 200.00 Ft | LU |
| 52 RAVELING | L | 2,000.00 SF | |
| 57 WEATHERING | L | 7,100.00 SF | |

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 34

Branch - Section ID: TDFD - 003

Branch Name: TAXIWAY D

Use: TAXIWAY

LCD: 6/3/2007

PCI Family: IowaPCCTWNC_CommEnhanced

Surface Type: PCC

Rank: P

Section Area (sf): 13,390.00

Length (ft): 330.00

Width (ft): 35.00

From: .

To: .

Slabs: 98

Section Comments:

Slab Length (ft): 11.70

Slab Width (ft): 11.66

Joint Length (ft): 1,869.67

Last Insp Date: 11/9/2022

Inspection Comments:

PCI: 80

Total Samples: 4

Surveyed: 3

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 88

Sample Area (Slabs): 21.00

65 JOINT SEAL DAMAGE

H

21.00 Slabs

Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 77

Sample Area (Slabs): 28.00

62 CORNER BREAK

L

1.00 Slabs

63 LINEAR CRACKING

M

1.00 Slabs

65 JOINT SEAL DAMAGE

H

28.00 Slabs

74 JOINT SPALL

M

1.00 Slabs

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 75

Sample Area (Slabs): 24.00

62 CORNER BREAK

M

1.00 Slabs

63 LINEAR CRACKING

M

1.00 Slabs

65 JOINT SEAL DAMAGE

H

24.00 Slabs

74 JOINT SPALL

M

1.00 Slabs

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 35

Branch - Section ID: TFFD - 001

Branch Name: TAXIWAY F

Use: TAXIWAY

LCD: 6/5/1991
 Surface Type: AC
 Rank: P
 Section Area (sf): 39,481.00
 Length (ft): 860.00
 Width (ft): 40.00
 From: TAXIWAY C
 To: 30 APPROACH

PCI Family: IowaACTWNC_NotEnhanced

Slabs:
 Slab Length (ft):
 Slab Width (ft):
 Joint Length (ft):

Section Comments:

Last Insp Date: 11/9/2022
 PCI: 66
 Total Samples: 8
 Surveyed: 4

Inspection Comments:

Sample Number: 05

Sample Type: R
 Sample PCI: 63
 Sample Area (SF): 5,000.00

Sample Comments:

| | | | |
|-------------------------------------|---|-------------|----------------|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | H | 40.00 Ft | 1FT TRANSVERSE |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 300.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 200.00 Ft | LS |
| 57 WEATHERING | M | 5,000.00 SF | |

Sample Number: 06

Sample Type: R
 Sample PCI: 70
 Sample Area (SF): 5,000.00

Sample Comments:

| | | | |
|-------------------------------------|---|-------------|----------------|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | H | 40.00 Ft | 1FT TRANSVERSE |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 87.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 125.00 Ft | LU |
| 57 WEATHERING | M | 5,000.00 SF | |

Sample Number: 07

Sample Type: R
 Sample PCI: 59
 Sample Area (SF): 5,000.00

Sample Comments:

| | | | |
|-------------------------------------|---|-------------|----------------|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | H | 40.00 Ft | 1FT TRANSVERSE |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 60.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 245.00 Ft | FS |
| 57 WEATHERING | M | 5,000.00 SF | |

Sample Number: 08

Sample Type: R
 Sample PCI: 70
 Sample Area (SF): 5,600.00

Sample Comments:

| | | | |
|-------------------------------------|---|-------------|----|
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 239.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 100.00 Ft | LS |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 100.00 Ft | FS |
| 57 WEATHERING | M | 5,600.00 SF | |

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 36

Branch - Section ID: TFFD - 002

Branch Name: TAXIWAY F

Use: TAXIWAY

LCD: 6/3/2007

PCI Family: IowaPCCTWNC_CommEnhanced

Surface Type: PCC

Rank: P

Section Area (sf): 38,600.00

Length (ft): 1,033.00

Width (ft): 35.00

From: .

To: .

Slabs: 283

Section Comments:

Slab Length (ft): 11.70

Slab Width (ft): 11.66

Joint Length (ft): 5,469.38

Last Insp Date: 11/9/2022

Inspection Comments:

PCI: 75

Total Samples: 14

Surveyed: 6

Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 76

Sample Area (Slabs): 21.00

| | | |
|----------------------|---|-------------|
| 62 CORNER BREAK | L | 1.00 Slabs |
| 63 LINEAR CRACKING | L | 1.00 Slabs |
| 65 JOINT SEAL DAMAGE | H | 21.00 Slabs |
| 75 CORNER SPALL | M | 1.00 Slabs |

Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 83

Sample Area (Slabs): 21.00

| | | |
|----------------------|---|-------------|
| 63 LINEAR CRACKING | L | 1.00 Slabs |
| 65 JOINT SEAL DAMAGE | H | 21.00 Slabs |

Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 75

Sample Area (Slabs): 21.00

| | | |
|----------------------|---|-------------|
| 63 LINEAR CRACKING | L | 8.00 Slabs |
| 65 JOINT SEAL DAMAGE | H | 21.00 Slabs |

Sample Number: 08

Sample Type: R

Sample Comments:

Sample PCI: 76

Sample Area (Slabs): 21.00

| | | |
|----------------------|---|-------------|
| 63 LINEAR CRACKING | L | 7.00 Slabs |
| 65 JOINT SEAL DAMAGE | H | 21.00 Slabs |

Sample Number: 09

Sample Type: R

Sample Comments:

Sample PCI: 71

Sample Area (Slabs): 21.00

| | | |
|----------------------|---|-------------|
| 63 LINEAR CRACKING | L | 6.00 Slabs |
| 63 LINEAR CRACKING | M | 1.00 Slabs |
| 65 JOINT SEAL DAMAGE | H | 21.00 Slabs |

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 37

Sample Number: 12

Sample Type: R

Sample Comments:

Sample PCI: 72

Sample Area (Slabs): 21.00

| | | |
|----------------------|---|-------------|
| 62 CORNER BREAK | L | 1.00 Slabs |
| 63 LINEAR CRACKING | L | 5.00 Slabs |
| 65 JOINT SEAL DAMAGE | H | 21.00 Slabs |
| 75 CORNER SPALL | M | 1.00 Slabs |

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 38

Branch - Section ID: TH01FD - 001

Branch Name: T-HANGAR 01

Use: T-HANGAR

LCD: 6/4/1995

PCI Family: IowaASPHALTTHNorthern

Surface Type: AC

Rank: P

Section Area (sf): 44,195.00

Length (ft): 1,760.00

Width (ft): 25.00

From: .

To: .

Slabs:

Section Comments:

Slab Length (ft):

Slab Width (ft):

Joint Length (ft):

Last Insp Date: 11/9/2022

Inspection Comments:

PCI: 30

Total Samples: 9

Surveyed: 4

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 31

Sample Area (SF): 5,250.00

| | | | |
|-------------------------------------|---|-------------|----------|
| 41 ALLIGATOR CRACKING | M | 160.00 SF | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | H | 10.00 Ft | OVER 1FT |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 656.00 Ft | 2NDY FS |
| 52 RAVELING | L | 1,500.00 SF | |
| 57 WEATHERING | M | 5,250.00 SF | |

Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 28

Sample Area (SF): 3,750.00

| | | | |
|-------------------------------------|---|-------------|--|
| 41 ALLIGATOR CRACKING | M | 300.00 SF | |
| 45 DEPRESSION | L | 20.00 SF | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 68.00 Ft | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 266.00 Ft | |
| 52 RAVELING | L | 1,000.00 SF | |
| 56 SWELLING | L | 5.00 SF | |
| 57 WEATHERING | M | 3,750.00 SF | |

Sample Number: 07

Sample Type: R

Sample Comments:

Sample PCI: 32

Sample Area (SF): 5,000.00

| | | | |
|-------------------------------------|---|-------------|----------------|
| 41 ALLIGATOR CRACKING | M | 200.00 SF | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | H | 10.00 Ft | 1FT TRANSVERSE |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 55.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 425.00 Ft | W 2NDY FS |
| 52 RAVELING | L | 1,000.00 SF | |
| 57 WEATHERING | M | 5,000.00 SF | |

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 39

Sample Number: 09

Sample Type: R

Sample Comments:

Sample PCI: 31

Sample Area (SF): 4,950.00

| | | | |
|-------------------------------------|---|-------------|----|
| 41 ALLIGATOR CRACKING | M | 150.00 SF | |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | L | 135.00 Ft | LU |
| 48 LONGITUDINAL/TRANSVERSE CRACKING | M | 716.00 Ft | FS |
| 52 RAVELING | L | 1,500.00 SF | |
| 57 WEATHERING | M | 4,950.00 SF | |

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 40

Branch - Section ID: TH01FD - 002

Branch Name: T-HANGAR 01

Use: T-HANGAR

LCD: 3/3/2018

PCI Family: IowaPCCTH NC NCW

Surface Type: PCC

Rank: P

Section Area (sf): 2,495.00

Length (ft): 75.00

Width (ft): 33.00

From: .

To: .

Slabs: 24

Section Comments:

Slab Length (ft): 10.00

Slab Width (ft): 10.50

Joint Length (ft): 378.25

Last Insp Date: 11/9/2022

Inspection Comments:

PCI: 100

Total Samples: 1

Surveyed: 1

Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 24.00

NO DISTRESS

RE-INSPECTION REPORT FORT DODGE REGIONAL AIRPORT

Pavement Database: IA 2022

Generate Date: 6/14/2023

Network ID: FOD

Page 41

Branch - Section ID: TH01FD - 003

Branch Name: T-HANGAR 01

Use: T-HANGAR

LCD: 6/3/2021

PCI Family: IowaPCCTH NC NCW

Surface Type: PCC

Rank: P

Section Area (sf): 28,809.00

Length (ft): 516.00

Width (ft): 49.00

From: .

To: .

Slabs: 288

Section Comments:

Slab Length (ft): 10.00

Slab Width (ft): 10.00

Joint Length (ft): 5,118.03

Last Insp Date: 11/9/2022

Inspection Comments:

PCI: 95

Total Samples: 13

Surveyed: 6

Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 20.00

NO DISTRESS

Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 83

Sample Area (Slabs): 20.00

62 CORNER BREAK

L

3.00 Slabs

63 LINEAR CRACKING

L

1.00 Slabs

Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 95

Sample Area (Slabs): 20.00

63 LINEAR CRACKING

L

1.00 Slabs

Sample Number: 08

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 20.00

63 LINEAR CRACKING

L

1.00 Slabs

75 CORNER SPALL

L

1.00 Slabs

Sample Number: 10

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 20.00

NO DISTRESS

Sample Number: 12

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 25.00

NO DISTRESS

APPENDIX D

WORK HISTORY REPORT

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: FOD

Page 1

Network: FORT DODGE REGIONAL AIRPORT

Branch - Section ID: A01FD - 001

LCD: 6/3/2019
 Use: APRON
 Rank: P
 Surface: PCC

Length (ft): 390.00
 Width (ft): 225.00
 True Area (sf): 102,275.00

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major MR | Comments |
|------------|-----------|------------------------------------|--------|----------------|----------|--|
| 06-03-2019 | CR-PC | Complete Reconstruction - PCC | \$0.00 | 12.00 | True | 12" P-501 |
| 06-02-2019 | BA-ST | Base Course - Stabilized (non-Bi.) | \$0.00 | 6.00 | False | 6" P-307 Cement Drainable Treated Base |
| 06-01-2019 | SG-ST | Subgrade - Stabilized | \$0.00 | 12.00 | False | 12" P-157 Cement Treated Subgrade |
| 06-01-2007 | SL-PC | Slab Replacement - PCC | \$0.00 | 0.00 | False | - |
| 06-01-2007 | CS-PC | Crack Sealing - PCC | \$0.00 | 0.00 | False | - |
| 06-01-2007 | JS-LC | Joint Seal (Localized) | \$0.00 | 0.00 | False | - |
| 06-01-2007 | PA-PP | Patching - PCC Partial Depth | \$0.00 | 0.00 | False | - |
| 11-01-1994 | CS-PC | Crack Sealing - PCC | \$0.00 | 0.00 | False | - |
| 06-01-1990 | CS-PC | Crack Sealing - PCC | \$0.00 | 0.00 | False | P-626 |
| 06-01-1972 | OL-PF | Overlay - PCC Fully Bonded | \$0.00 | 6.00 | True | 6" P-501 PCC OVERLAY |
| 06-02-1949 | NC-PC | New Construction - PCC | \$0.00 | 8.00 | True | 8" P-501 |
| 06-01-1949 | SB-AG | Subbase - Aggregate | \$0.00 | 6.00 | False | 6" P-154 Subbase |

Branch - Section ID: A01FD - 002

LCD: 6/3/2019
 Use: APRON
 Rank: P
 Surface: PCC

Length (ft): 225.00
 Width (ft): 250.00
 True Area (sf): 53,202.00

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major MR | Comments |
|------------|-----------|-------------------------------|--------|----------------|----------|-------------------------------|
| 06-03-2019 | CR-PC | Complete Reconstruction - PCC | \$0.00 | 8.00 | True | 8" P-501 |
| 06-02-2019 | BA-AG | Base Course - Aggregate | \$0.00 | 6.00 | False | 6" P-219 Recycled Agg Base |
| 06-01-2019 | SG-ST | Subgrade - Stabilized | \$0.00 | 12.00 | False | 12" P-157 Cement Treated Base |
| 06-01-1972 | OL-PF | Overlay - PCC Fully Bonded | \$0.00 | 6.00 | True | 6" P-501 PCC OVERLAY |
| 06-02-1949 | NC-PC | New Construction - PCC | \$0.00 | 8.00 | True | 8" P-501 |
| 06-01-1949 | SB-AG | Subbase - Aggregate | \$0.00 | 6.00 | False | 6" P-154 Subbase |

Branch - Section ID: A02FD - 001

LCD: 6/3/2019
 Use: APRON
 Rank: P
 Surface: PCC

Length (ft): 500.00
 Width (ft): 150.00
 True Area (sf): 76,791.00

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major MR | Comments |
|------------|-----------|---------------------------------|--------|----------------|----------|---|
| 06-03-2019 | CR-PC | Complete Reconstruction - PCC | \$0.00 | 7.00 | True | 7" P-501 |
| 06-02-2019 | BA-AG | Base Course - Aggregate | \$0.00 | 6.00 | False | 6" P-209 |
| 06-01-2019 | SG-ST | Subgrade - Stabilized | \$0.00 | 12.00 | False | 12" P-158 Fly Ash Treated Subgrade |
| 07-01-2001 | PA-AD | Patching - AC Deep | \$0.00 | 0.00 | False | MILLED AND AC OVERLAY SMALL AREA NEAR TAXIWAY |
| 06-01-1990 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | P-626 |
| 06-01-1988 | ST-SS | Surface Treatment - Slurry Seal | \$0.00 | 0.00 | False | P626 Slurry Seal |
| 06-01-1974 | OL-AS | Overlay - AC Structural | \$0.00 | 2.00 | True | 2" P-401 |
| 06-04-1972 | NC-AC | New Construction - AC | \$0.00 | 2.00 | True | 2" P-401 |
| 06-03-1972 | BA-BI | Base Course - Bituminous | \$0.00 | 4.00 | False | 4" P-201 |
| 06-02-1972 | SB-AG | Subbase - Aggregate | \$0.00 | 8.00 | False | 8" P-154 |
| 06-01-1972 | SG-ST | Subgrade - Stabilized | \$0.00 | 6.00 | False | 6" P-155 Lime Treated Subgrade |

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: FOD

Page 2

Branch - Section ID: A02FD - 002

LCD: 7/3/2012
 Use: APRON
 Rank: P
 Surface: PCC

Length (ft): 370.00
 Width (ft): 62.50
 True Area (sf): 21,688.00

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major MR | Comments |
|------------|-----------|------------------------|--------|----------------|----------|---------------------------------|
| 07-03-2012 | NC-PC | New Construction - PCC | \$0.00 | 7.00 | True | 7" PCC |
| 07-02-2012 | SB-AG | Subbase - Aggregate | \$0.00 | 6.00 | False | 6" GRANULAR SUBBASE (IDOT 2111) |
| 07-01-2012 | SG-ST | Subgrade - Stabilized | \$0.00 | 12.00 | False | 12" FLY-ASH TREATED SUBGRADE |

Branch - Section ID: R06FD - 001

LCD: 6/3/2015
 Use: RUNWAY
 Rank: P
 Surface: AAC

Length (ft): 5,868.00
 Width (ft): 150.00
 True Area (sf): 877,200.00

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major MR | Comments |
|------------|-----------|-------------------------------|--------|----------------|----------|------------------------------------|
| 08-01-2020 | ST-SC | Surface Treatment - Seal Coat | \$0.00 | 0.00 | False | P-608 EMULSIFIED ASPHALT SEAL COAT |
| 08-01-2020 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | CRACK SEAL |
| 06-03-2015 | OL-AS | Overlay - AC Structural | \$0.00 | 3.00 | True | 0-3" MILL/3" AC OVERLAY |
| 06-02-2015 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | PRE-OVERLAY CRACK SEAL |
| 06-01-2015 | PA-AD | Patching - AC Deep | \$0.00 | 0.00 | False | PRE-OVERLAY FULL DEPTH PATCHING |
| 06-01-2007 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 06-01-2001 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 06-01-1999 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 06-01-1994 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 12-01-1993 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 06-01-1991 | OL-AS | Overlay - AC Structural | \$0.00 | 3.00 | True | 3" P-401 |
| 06-01-1988 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | P-626 |
| 06-01-1982 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | P-626 |
| 06-01-1977 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | P-626 |
| 01-07-1972 | NC-AC | New Construction - AC | \$0.00 | 4.00 | True | 4" P-401 |
| 01-06-1972 | BA-BI | Base Course - Bituminous | \$0.00 | 6.00 | False | 6" P-201 BASE |
| 01-05-1972 | SB-AG | Subbase - Aggregate | \$0.00 | 15.00 | False | 15" P-154 SUBBASE |
| 01-04-1972 | SG-ST | Subgrade - Stabilized | \$0.00 | 6.00 | False | 6" P-155 SUBGRADE |

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: FOD

Page 3

Branch - Section ID: R06FD - 002

LCD: 6/1/2012
 Use: RUNWAY
 Rank: P
 Surface: AAC

Length (ft): 700.00
 Width (ft): 150.00
 True Area (sf): 105,000.00

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major MR | Comments |
|------------|-----------|-------------------------------|--------|----------------|----------|--|
| 08-02-2020 | ST-SC | Surface Treatment - Seal Coat | \$0.00 | 0.00 | False | P-608R EMULSIFIED ASPHALT SEAL COAT RAPID CURE |
| 08-02-2020 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | CRACK SEAL |
| 06-01-2015 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 06-01-2012 | OL-AS | Overlay - AC Structural | \$0.00 | 6.00 | True | 6" MILL & OVERLAY |
| 06-01-2007 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 06-01-2001 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 06-01-1999 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 06-01-1994 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 12-01-1993 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 06-01-1991 | OL-AS | Overlay - AC Structural | \$0.00 | 3.00 | True | 3" P-401 |
| 06-01-1988 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | P-626 |
| 06-01-1982 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | P-626 |
| 06-01-1977 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | P-626 |
| 01-07-1972 | NC-AC | New Construction - AC | \$0.00 | 4.00 | True | 4" P-401 |
| 01-06-1972 | BA-BI | Base Course - Bituminous | \$0.00 | 6.00 | False | 6" P-201 BASE |
| 01-05-1972 | SB-AG | Subbase - Aggregate | \$0.00 | 15.00 | False | 15" P-154 SUBBASE |
| 01-04-1972 | SG-ST | Subgrade - Stabilized | \$0.00 | 6.00 | False | 6" P-155 SUBGRADE |

Branch - Section ID: R12FD - 001

LCD: 6/1/2012
 Use: RUNWAY
 Rank: S
 Surface: APC

Length (ft): 1,432.00
 Width (ft): 100.00
 True Area (sf): 147,855.00

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major MR | Comments |
|------------|-----------|---------------------------------|--------|----------------|----------|---|
| 08-02-2020 | ST-SC | Surface Treatment - Seal Coat | \$0.00 | 0.00 | False | P-608 EMULSIFIED ASPHALT SEAL COAT, P-608R EMULSIFIED ASPHALT SEAL COAT RAPID CURE AROUND RUNWAYS' INTERSECTION |
| 08-01-2020 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | CRACK SEAL |
| 06-01-2012 | OL-AS | Overlay - AC Structural | \$0.00 | 6.00 | True | 6" MILL & OVERLAY |
| 06-01-2005 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 07-01-2001 | PA-AD | Patching - AC Deep | \$0.00 | 0.00 | False | - |
| 06-01-2001 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 06-01-1999 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 07-10-1996 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 03-01-1994 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 06-01-1993 | OL-AS | Overlay - AC Structural | \$0.00 | 3.00 | True | 3" P-401 |
| 06-01-1984 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | P-626 |
| 06-01-1984 | ST-SS | Surface Treatment - Slurry Seal | \$0.00 | 0.00 | False | P-626 |
| 06-02-1972 | OL-AS | Overlay - AC Structural | \$0.00 | 3.00 | True | 3" P-401 |
| 06-01-1972 | BA-BI | Base Course - Bituminous | \$0.00 | 1.00 | False | 1" P-201 VARIABLE BASE |
| 06-03-1949 | NC-PC | New Construction - PCC | \$0.00 | 7.00 | True | 7" P-501 |
| 06-02-1949 | SB-AG | Subbase - Aggregate | \$0.00 | 4.00 | False | 4" P-154 SUBBASE |
| 06-01-1949 | SG-CO | Subgrade - Compacted | \$0.00 | 12.00 | False | 12" P-152 SUBGRADE |

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: FOD

Page 4

Branch - Section ID: R12FD - 002

LCD: 6/1/2012
 Use: RUNWAY
 Rank: S
 Surface: APC

Length (ft): 2,890.00
 Width (ft): 100.00
 True Area (sf): 291,412.00

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major MR | Comments |
|------------|-----------|---------------------------------|--------|----------------|----------|---|
| 08-02-2020 | ST-SC | Surface Treatment - Seal Coat | \$0.00 | 0.00 | False | P-608 EMULSIFIED ASPHALT SEAL COAT, P-608R EMULSIFIED ASPHALT SEAL COAT RAPID CURE AROUND RUNWAYS' INTERSECTION |
| 08-01-2020 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | CRACK SEAL |
| 06-01-2012 | OL-AS | Overlay - AC Structural | \$0.00 | 6.00 | True | 6" MILL & OVERLAY |
| 06-01-2007 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 06-01-2001 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 06-01-1999 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 07-08-1996 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 03-08-1994 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 06-30-1993 | OL-AS | Overlay - AC Structural | \$0.00 | 3.00 | True | 3" P-401 |
| 06-01-1984 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | P-626 |
| 06-01-1984 | ST-SS | Surface Treatment - Slurry Seal | \$0.00 | 0.00 | False | P-626 |
| 06-02-1972 | OL-AS | Overlay - AC Structural | \$0.00 | 3.00 | True | 3" P-401 |
| 06-01-1972 | BA-BI | Base Course - Bituminous | \$0.00 | 1.00 | False | 1" VARIABLE P-201 BASE |
| 06-03-1949 | NC-PC | New Construction - PCC | \$0.00 | 7.00 | True | 7" P-501 PCC |
| 06-02-1949 | SB-AG | Subbase - Aggregate | \$0.00 | 4.00 | False | 4" P-154 SUBBASE |
| 06-01-1949 | SG-CO | Subgrade - Compacted | \$0.00 | 12.00 | False | 12" P-152 SUBGRADE |

Branch - Section ID: R12FD - 003

LCD: 5/1/2004
 Use: RUNWAY
 Rank: S
 Surface: PCC

Length (ft): 100.00
 Width (ft): 100.00
 True Area (sf): 10,869.00

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major MR | Comments |
|------------|-----------|------------------------|--------|----------------|----------|------------------|
| 08-01-2020 | JS-LC | Joint Seal (Localized) | \$0.00 | 0.00 | False | JOINT RESEALING |
| 08-01-2020 | SL-PC | Slab Replacement - PCC | \$0.00 | 0.00 | False | SLAB REPLACEMENT |
| 08-01-2020 | CS-PC | Crack Sealing - PCC | \$0.00 | 0.00 | False | CRACK SEAL |
| 05-01-2004 | NC-PC | New Construction - PCC | \$0.00 | 0.00 | True | - |

Branch - Section ID: R12FD - 004

LCD: 5/1/2004
 Use: RUNWAY
 Rank: S
 Surface: PCC

Length (ft): 700.00
 Width (ft): 100.00
 True Area (sf): 70,952.00

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major MR | Comments |
|------------|-----------|------------------------|--------|----------------|----------|------------------|
| 08-01-2020 | JS-LC | Joint Seal (Localized) | \$0.00 | 0.00 | False | JOINTS RESEALING |
| 05-01-2004 | NC-PC | New Construction - PCC | \$0.00 | 0.00 | True | - |

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: FOD

Page 5

Branch - Section ID: TAFD - 001

LCD: 8/16/2001
 Use: TAXIWAY
 Rank: P
 Surface: PCC

Length (ft): 690.00
 Width (ft): 35.00
 True Area (sf): 25,248.00

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major MR | Comments |
|------------|-----------|-------------------------------|--------|----------------|----------|---|
| 06-01-2015 | CS-PC | Crack Sealing - PCC | \$0.00 | 0.00 | False | ONLY ON THE PORTION ADJACENT TO RW 6/24 |
| 08-16-2001 | CR-PC | Complete Reconstruction - PCC | \$0.00 | 11.00 | True | 11" P-501 PCC |
| 11-07-1994 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 06-30-1972 | NC-AC | New Construction - AC | \$0.00 | 0.00 | True | - |

Branch - Section ID: TBFD - 001

LCD: 6/3/2015
 Use: TAXIWAY
 Rank: P
 Surface: AAC

Length (ft): 1,230.00
 Width (ft): 50.00
 True Area (sf): 65,568.00

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major MR | Comments |
|------------|-----------|-------------------------|--------|----------------|----------|---------------------------------|
| 06-03-2015 | OL-AS | Overlay - AC Structural | \$0.00 | 3.00 | True | 3" MILL/3" AC OVERLAY |
| 06-02-2015 | PA-AD | Patching - AC Deep | \$0.00 | 0.00 | False | PRE-OVERLAY FULL DEPTH PATCHING |
| 06-01-2015 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | PRE-OVERLAY CRACK SEAL |
| 06-01-2007 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 11-08-1994 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 06-30-1977 | OL-AS | Overlay - AC Structural | \$0.00 | 0.00 | True | 14" TOTAL OF ASPHALT |
| 06-02-1972 | NC-AC | New Construction - AC | \$0.00 | 0.00 | True | - |
| 06-01-1972 | BA-AG | Base Course - Aggregate | \$0.00 | 6.00 | False | - |

Branch - Section ID: TBFD - 002

LCD: 6/1/2007
 Use: TAXIWAY
 Rank: P
 Surface: AAC

Length (ft): 2,500.00
 Width (ft): 50.00
 True Area (sf): 162,730.00

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major MR | Comments |
|------------|-----------|---------------------------------|--------|----------------|----------|---|
| 06-01-2015 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | ONLY ON THE PORTION ADJACENT TO RW 6/24 |
| 06-01-2007 | OL-AS | Overlay - AC Structural | \$0.00 | 0.00 | True | EST |
| 06-01-2001 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | ONLY ON A PORTION OF THE SECTION |
| 11-08-1994 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 06-01-1993 | ST-SS | Surface Treatment - Slurry Seal | \$0.00 | 0.00 | False | - |
| 06-30-1977 | NC-AC | New Construction - AC | \$0.00 | 0.00 | True | - |

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: FOD

Page 6

Branch - Section ID: TBFD - 003

LCD: 6/3/2022
 Use: TAXIWAY
 Rank: P
 Surface: AC

Length (ft): 1,930.00
 Width (ft): 50.00
 True Area (sf): 111,503.00

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major MR | Comments |
|------------|-----------|------------------------------|--------------|----------------|----------|-----------------------------------|
| 06-03-2022 | CR-AC | Complete Reconstruction - AC | \$448,775.00 | 8.00 | True | 8" P-401 AC RECONSTRUCTION |
| 06-02-2022 | BA-AG | Base Course - Aggregate | \$0.00 | 15.00 | False | 15" P-209 CAB |
| 06-01-2022 | SG-ST | Subgrade - Stabilized | \$0.00 | 12.00 | False | 12" P-156 CEMENT TREATED SUBGRADE |
| 06-01-2015 | PA-AD | Patching - AC Deep | \$0.00 | 0.00 | False | - |
| 06-01-2007 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 06-01-2001 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 10-01-1997 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 06-05-1991 | NC-AC | New Construction - AC | \$0.00 | 4.00 | True | 4" P-401 AC |
| 06-04-1991 | BA-BI | Base Course - Bituminous | \$0.00 | 6.00 | False | 6" P-401 Bit Base |
| 06-03-1991 | SB-AG | Subbase - Aggregate | \$0.00 | 9.00 | False | 9" P-154 Subbase |
| 06-02-1991 | SG-ST | Subgrade - Stabilized | \$0.00 | 6.00 | False | 6" P-155 Fly Ash Treated SG |
| 06-01-1991 | SG-CO | Subgrade - Compacted | \$0.00 | 6.00 | False | 6" P-152 Compacted SG |

Branch - Section ID: TBFD - 004

LCD: 6/1/2012
 Use: TAXIWAY
 Rank: P
 Surface: AAC

Length (ft): 250.00
 Width (ft): 50.00
 True Area (sf): 14,250.00

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major MR | Comments |
|------------|-----------|-------------------------------|--------|----------------|----------|--|
| 08-02-2020 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | CRACK SEAL |
| 08-02-2020 | ST-SC | Surface Treatment - Seal Coat | \$0.00 | 0.00 | False | P-608R EMULSIFIED ASPHALT SEAL COAT RAPID CURE |
| 06-01-2012 | OL-AS | Overlay - AC Structural | \$0.00 | 6.00 | True | 6" MILL & OVERLAY |
| 06-01-2007 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 11-08-1994 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 12-01-1993 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 06-30-1977 | OL-AS | Overlay - AC Structural | \$0.00 | 0.00 | True | 14" TOTAL OF ASPHALT |
| 06-02-1972 | NC-AC | New Construction - AC | \$0.00 | 0.00 | True | - |
| 06-01-1972 | SB-AG | Subbase - Aggregate | \$0.00 | 6.00 | False | - |

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: FOD

Page 7

Branch - Section ID: TBFD - 005

LCD: 6/1/2015
 Use: TAXIWAY
 Rank: P
 Surface: AAC

Length (ft): 150.00
 Width (ft): 65.00
 True Area (sf): 17,528.00

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major MR | Comments |
|------------|-----------|-------------------------------|--------|----------------|----------|---|
| 08-02-2020 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | CRACK SEAL |
| 08-02-2020 | ST-SC | Surface Treatment - Seal Coat | \$0.00 | 0.00 | False | P-608 EMULSIFIED ASPHALT SEAL COAT; PARTIAL |
| 06-01-2015 | OL-AS | Overlay - AC Structural | \$0.00 | 3.00 | True | 0-3" MILL/3" AC OVERLAY |
| 06-01-2007 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 06-01-2001 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 10-01-1997 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 06-05-1991 | NC-AC | New Construction - AC | \$0.00 | 4.00 | True | 4" P-401 AC |
| 06-04-1991 | BA-BI | Base Course - Bituminous | \$0.00 | 6.00 | False | 6" P-401 Bit Base |
| 06-03-1991 | SB-AG | Subbase - Aggregate | \$0.00 | 9.00 | False | 9" P-154 Subbase |
| 06-02-1991 | SG-ST | Subgrade - Stabilized | \$0.00 | 6.00 | False | 6" P-155 Fly Ash Treated SG |
| 06-01-1991 | SG-CO | Subgrade - Compacted | \$0.00 | 6.00 | False | 6" P-152 Compacted SG |

Branch - Section ID: TBFD - 006

LCD: 6/3/2019
 Use: TAXIWAY
 Rank: P
 Surface: AC

Length (ft): 125.00
 Width (ft): 25.00
 True Area (sf): 3,245.00

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major MR | Comments |
|------------|-----------|----------------------------|--------|----------------|----------|-----------------------------------|
| 06-03-2019 | NU-IN | New Construction - Initial | \$0.00 | 9.00 | True | 9" P-401 |
| 06-02-2019 | BA-AG | Base Course - Aggregate | \$0.00 | 6.00 | False | 6" P-219 Recycled Agg Base |
| 06-01-2019 | SG-ST | Subgrade - Stabilized | \$0.00 | 12.00 | False | 12" P-157 Cement Treated Subgrade |

Branch - Section ID: TCFD - 001

LCD: 8/1/2001
 Use: TAXIWAY
 Rank: P
 Surface: PCC

Length (ft): 752.00
 Width (ft): 35.00
 True Area (sf): 34,299.00

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major MR | Comments |
|------------|-----------|-------------------------------|--------|----------------|----------|----------|
| 08-01-2001 | CR-PC | Complete Reconstruction - PCC | \$0.00 | 7.00 | True | - |
| 06-01-1997 | PA-AD | Patching - AC Deep | \$0.00 | 0.00 | False | - |
| 06-30-1977 | NC-AC | New Construction - AC | \$0.00 | 0.00 | True | - |

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: FOD

Page 8

Branch - Section ID: TDFD - 001

LCD: 6/1/2007
 Use: TAXIWAY
 Rank: P
 Surface: AAC

Length (ft): 1,870.00
 Width (ft): 40.00
 True Area (sf): 87,990.00

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major MR | Comments |
|------------|-----------|---------------------------------|--------|----------------|----------|---|
| 06-01-2015 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | ONLY ON THE PORTION ADJACENT TO RW 6/24 |
| 06-01-2007 | OL-AS | Overlay - AC Structural | \$0.00 | 0.00 | True | - |
| 11-01-1994 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 06-01-1993 | ST-SS | Surface Treatment - Slurry Seal | \$0.00 | 0.00 | False | - |
| 06-30-1982 | NC-AC | New Construction - AC | \$0.00 | 4.00 | True | 4" P-401 AC |
| 06-29-1982 | BA-BI | Base Course - Bituminous | \$0.00 | 4.00 | False | 4" P-201 Bit Base |
| 06-28-1982 | SB-AG | Subbase - Aggregate | \$0.00 | 9.00 | False | 9" P-154 Subbase |
| 06-27-1982 | SG-ST | Subgrade - Stabilized | \$0.00 | 6.00 | False | 6" P-155 Fly Ash Treated SG |
| 06-26-1982 | SG-CO | Subgrade - Compacted | \$0.00 | 6.00 | False | 6" P-152 Compacted SG |

Branch - Section ID: TDFD - 002

LCD: 6/1/2015
 Use: TAXIWAY
 Rank: P
 Surface: AAC

Length (ft): 330.00
 Width (ft): 65.00
 True Area (sf): 32,689.00

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major MR | Comments |
|------------|-----------|-------------------------------|--------|----------------|----------|--|
| 08-02-2020 | ST-SC | Surface Treatment - Seal Coat | \$0.00 | 0.00 | False | P-608R EMULSIFIED ASPHALT SEAL COAT RAPID CURE |
| 08-01-2020 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | CRACK SEAL |
| 06-01-2015 | OL-AS | Overlay - AC Structural | \$0.00 | 3.00 | True | 0-3" MILL/3" AC OVERLAY |
| 06-01-2007 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 06-30-1972 | OL-AS | Overlay - AC Structural | \$0.00 | 0.00 | True | - |
| 06-01-1965 | NC-AC | New Construction - AC | \$0.00 | 0.00 | True | ESTIMATED |

Branch - Section ID: TDFD - 003

LCD: 6/3/2007
 Use: TAXIWAY
 Rank: P
 Surface: PCC

Length (ft): 330.00
 Width (ft): 35.00
 True Area (sf): 13,390.00

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major MR | Comments |
|------------|-----------|-------------------------|--------|----------------|----------|----------|
| 06-03-2007 | NC-PC | New Construction - PCC | \$0.00 | 7.00 | True | - |
| 06-02-2007 | BA-AG | Base Course - Aggregate | \$0.00 | 4.00 | False | - |
| 06-01-2007 | SB-AG | Subbase - Aggregate | \$0.00 | 12.00 | False | - |

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: FOD

Page 9

Branch - Section ID: TFFD - 001

LCD: 6/5/1991
 Use: TAXIWAY
 Rank: P
 Surface: AC

Length (ft): 860.00
 Width (ft): 40.00
 True Area (sf): 39,481.00

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major MR | Comments |
|------------|-----------|--------------------------|--------|----------------|----------|-----------------------------|
| 06-01-2019 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 03-01-1994 | CS-AC | Crack Sealing - AC | \$0.00 | 0.00 | False | - |
| 06-05-1991 | NC-AC | New Construction - AC | \$0.00 | 4.00 | True | 4" P-401 AC |
| 06-04-1991 | BA-BI | Base Course - Bituminous | \$0.00 | 6.00 | False | 6" P-401 Bit Base |
| 06-03-1991 | SB-AG | Subbase - Aggregate | \$0.00 | 9.00 | False | 9" P-154 Subbase |
| 06-02-1991 | SG-ST | Subgrade - Stabilized | \$0.00 | 6.00 | False | 6" P-155 Fly ash Treated SG |
| 06-01-1991 | SG-CO | Subgrade - Compacted | \$0.00 | 6.00 | False | 6" P-152 Compacted SG |

Branch - Section ID: TFFD - 002

LCD: 6/3/2007
 Use: TAXIWAY
 Rank: P
 Surface: PCC

Length (ft): 1,033.00
 Width (ft): 35.00
 True Area (sf): 38,600.00

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major MR | Comments |
|------------|-----------|--------------------------|--------|----------------|----------|----------|
| 06-01-2019 | CS-PC | Crack Sealing - PCC | \$0.00 | 0.00 | False | - |
| 06-03-2007 | NC-PC | New Construction - PCC | \$0.00 | 7.00 | True | - |
| 06-02-2007 | BA-BI | Base Course - Bituminous | \$0.00 | 4.00 | False | - |
| 06-01-2007 | SB-AG | Subbase - Aggregate | \$0.00 | 21.00 | False | - |

Branch - Section ID: TH01FD - 001

LCD: 6/4/1995
 Use: T-HANGAR
 Rank: P
 Surface: AC

Length (ft): 1,760.00
 Width (ft): 25.00
 True Area (sf): 44,195.00

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major MR | Comments |
|------------|-----------|----------------------------|--------|----------------|----------|-----------------------|
| 06-04-1995 | NU-IN | New Construction - Initial | \$0.00 | 4.00 | True | 4" P401 |
| 06-03-1995 | BA-AG | Base Course - Aggregate | \$0.00 | 6.00 | False | 6" P209 AGG BASE |
| 06-02-1995 | SG-ST | Subgrade - Stabilized | \$0.00 | 6.00 | False | 6" FLY ASH SUBGRADE |
| 06-01-1995 | SG-CO | Subgrade - Compacted | \$0.00 | 6.00 | False | 6" COMPACTED SUBGRADE |

Branch - Section ID: TH01FD - 002

LCD: 3/3/2018
 Use: T-HANGAR
 Rank: P
 Surface: PCC

Length (ft): 75.00
 Width (ft): 33.00
 True Area (sf): 2,495.00

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major MR | Comments |
|------------|-----------|----------------------------|--------|----------------|----------|------------------------|
| 03-03-2018 | NU-IN | New Construction - Initial | \$0.00 | 7.00 | True | 7" P-501 |
| 03-02-2018 | BA-AG | Base Course - Aggregate | \$0.00 | 6.00 | False | 6" P-219 AGG BASE |
| 03-01-2018 | SG-CO | Subgrade - Compacted | \$0.00 | 12.00 | False | 12" COMPACTED SUBGRADE |

WORK HISTORY

Pavement Database: IA 2022

Generate Date: 6/25/2023

Network ID: FOD

Page 10

Branch - Section ID: TH01FD - 003

LCD: 6/3/2021
Use: T-HANGAR
Rank: P
Surface: PCC

Length (ft): 516.00
Width (ft): 49.00
True Area (sf): 28,809.00

| Work Date | Work Code | Work Description | Cost | Thickness (in) | Major MR | Comments |
|------------|-----------|-------------------------------|--------|----------------|----------|------------------------------|
| 06-03-2021 | CR-PC | Complete Reconstruction - PCC | \$0.00 | 7.00 | True | 7" P-505 PCC PAVEMENT |
| 06-02-2021 | BA-AG | Base Course - Aggregate | \$0.00 | 6.00 | False | 6" IDOT 2115 BASE COURSE |
| 06-01-2021 | SG-CO | Subgrade - Compacted | \$0.00 | 12.00 | False | 12" P-152 COMPACTED SUBGRADE |
| 06-05-1995 | NC-AC | New Construction - AC | \$0.00 | 4.00 | True | 4" P401 |
| 06-03-1995 | BA-AG | Base Course - Aggregate | \$0.00 | 6.00 | False | 6" P209 AGG BASE |
| 06-02-1995 | SG-ST | Subgrade - Stabilized | \$0.00 | 6.00 | False | 6" FLY ASH SUBGRADE |
| 06-01-1995 | SG-CO | Subgrade - Compacted | \$0.00 | 6.00 | False | 6" COMPACTED SUBGRADE |

APPENDIX E

LOCALIZED PREVENTIVE MAINTENANCE POLICIES AND UNIT COST TABLES

Table E-1. Localized preventive maintenance policy, asphalt-surfaced pavements.

| Distress Type | Severity Level | Maintenance Action |
|---------------------------|-----------------------|---------------------------|
| Alligator Cracking | Low | Monitor |
| Alligator Cracking | Medium | Asphalt Patch |
| Alligator Cracking | High | Asphalt Patch |
| Bleeding | N/A | Monitor |
| Block Cracking | Low | Monitor |
| Block Cracking | Medium | Crack Seal—Asphalt |
| Block Cracking | High | Crack Seal—Asphalt |
| Corrugation | Low | Monitor |
| Corrugation | Medium | Asphalt Patch |
| Corrugation | High | Asphalt Patch |
| Depression | Low | Monitor |
| Depression | Medium | Monitor |
| Depression | High | Asphalt Patch |
| Jet-Blast Erosion | N/A | Asphalt Patch |
| Joint Reflection Cracking | Low | Monitor |
| Joint Reflection Cracking | Medium | Crack Seal—Asphalt |
| Joint Reflection Cracking | High | Crack Seal—Asphalt |
| L&T Cracking | Low | Monitor |
| L&T Cracking | Medium | Crack Seal—Asphalt |
| L&T Cracking | High | Crack Seal—Asphalt |
| Oil Spillage | N/A | Asphalt Patch |
| Patching | Low | Monitor |
| Patching | Medium | Asphalt Patch |
| Patching | High | Asphalt Patch |
| Polished Aggregate | N/A | Monitor |
| Raveling | Low | Monitor |
| Raveling | Medium | Asphalt Patch |
| Raveling | High | Asphalt Patch |
| Rutting | Low | Monitor |
| Rutting | Medium | Monitor |
| Rutting | High | Asphalt Patch |
| Shoving | Low | Monitor |
| Shoving | Medium | Asphalt Patch |
| Shoving | High | Asphalt Patch |
| Slippage Cracking | N/A | Asphalt Patch |
| Swelling | Low | Monitor |
| Swelling | Medium | Monitor |
| Swelling | High | Asphalt Patch |
| Weathering | Low | Monitor |
| Weathering | Medium | Monitor |
| Weathering | High | Asphalt Patch |

Table E-2. Localized preventive maintenance policy, PCC pavements.

| Distress Type | Severity Level | Maintenance Action |
|-----------------------------|-----------------------|---------------------------|
| ASR | Low | Monitor |
| ASR | Medium | Slab Replacement |
| ASR | High | Slab Replacement |
| Blowup | Low | Slab Replacement |
| Blowup | Medium | Slab Replacement |
| Blowup | High | Slab Replacement |
| Corner Break | Low | Crack Seal—PCC |
| Corner Break | Medium | Full Depth PCC Patch |
| Corner Break | High | Full Depth PCC Patch |
| Durability Cracking | Low | Monitor |
| Durability Cracking | Medium | Full Depth Patch |
| Durability Cracking | High | Slab Replacement |
| Faulting | Low | Monitor |
| Faulting | Medium | Grinding |
| Faulting | High | Slab Replacement |
| Joint Seal Damage | Low | Monitor |
| Joint Seal Damage | Medium | Joint Seal |
| Joint Seal Damage | High | Joint Seal |
| LTD Cracking | Low | Monitor |
| LTD Cracking | Medium | Crack Seal—PCC |
| LTD Cracking | High | Slab Replacement |
| Patching (Small and Large) | Low | Monitor |
| Patching (Small and Large) | Medium | Full Depth PCC Patch |
| Patching (Small and Large) | High | Full Depth PCC Patch |
| Popouts | N/A | Monitor |
| Pumping | N/A | Monitor |
| Scaling | Low | Monitor |
| Scaling | Medium | Partial Depth PCC Patch |
| Scaling | High | Slab Replacement |
| Shattered Slab | Low | Crack Seal—PCC |
| Shattered Slab | Medium | Slab Replacement |
| Shattered Slab | High | Slab Replacement |
| Shrinkage Cracking | N/A | Monitor |
| Spalling (Joint and Corner) | Low | Monitor |
| Spalling (Joint and Corner) | Medium | Partial Depth PCC Patch |
| Spalling (Joint and Corner) | High | Partial Depth PCC Patch |

Table E-3. 2023 unit costs for localized preventive maintenance actions.

| Maintenance Action | Unit Cost |
|---|------------|
| Asphalt Patch—Asphalt-Surfaced Pavement | \$15.24/sf |
| Crack Sealing—Asphalt-Surfaced Pavement | \$2.61/lf |
| Partial Depth PCC Patch—PCC Pavement | \$39.04/sf |
| Full Depth PCC Patch—PCC Pavement | \$17.43/sf |
| Crack Sealing—PCC Pavement | \$3.14/lf |
| Joint Sealing—PCC Pavement | \$3.14/lf |
| Grinding—PCC Pavement | \$0.37/sf |
| Slab Replacement—PCC Pavement | \$17.43/sf |

Table Note: The unit cost estimates are based on broad statewide numbers and should be adjusted to reflect local costs.

Table E-4. 2023 unit costs (per square foot) based on pavement type and PCI ranges.

| Pavement Type | PCI Range 0–40 | PCI Range 40–50 | PCI Range 50–60 | PCI Range 60–70 | PCI Range 70–80 | PCI Range 80–90 | PCI Range 90–100 |
|---------------|----------------|-----------------|-----------------|-----------------|-----------------|-----------------|------------------|
| AC | \$10.82 | \$5.12 | \$5.12 | \$5.12 | \$0.00 | \$0.00 | \$0.00 |
| PCC | \$18.08 | \$8.55 | \$8.55 | \$8.55 | \$0.00 | \$0.00 | \$0.00 |

Table Note: The unit cost estimates are based on broad statewide numbers and should be adjusted to reflect local costs.

APPENDIX F

YEAR 2023 LOCALIZED PREVENTIVE MAINTENANCE DETAILS

Table F-1. Year 2023 localized preventive maintenance details.

| Branch | Section | Distress Type | Severity | Distress Quantity | Distress Unit | Maintenance Action | Unit Cost | 2023 Estimated Cost |
|--------|---------|-------------------|----------|-------------------|---------------|------------------------------|-----------|---------------------|
| A01FD | 02 | Corner Spalling | Medium | 1 | Slabs | Patching - PCC Partial Depth | \$39.04 | \$105 |
| A02FD | 01 | Joint Seal Damage | Medium | 491 | Slabs | Joint Seal (Localized) | \$3.14 | \$36,490 |
| A02FD | 02 | Corner Spalling | Medium | 2 | Slabs | Patching - PCC Partial Depth | \$39.04 | \$175 |
| A02FD | 02 | Joint Seal Damage | Medium | 167 | Slabs | Joint Seal (Localized) | \$3.14 | \$10,825 |
| A02FD | 02 | Joint Spalling | Medium | 2 | Slabs | Patching - PCC Partial Depth | \$39.04 | \$421 |
| R06FD | 01 | L&T Cracking | Medium | 9,685 | Ft | Crack Sealing - AC | \$2.61 | \$25,279 |
| R06FD | 01 | Weathering | High | 100 | SqFt | Patching - AC Deep | \$15.24 | \$1,517 |
| R06FD | 02 | L&T Cracking | Medium | 179 | Ft | Crack Sealing - AC | \$2.61 | \$468 |
| R12FD | 02 | L&T Cracking | Medium | 291 | Ft | Crack Sealing - AC | \$2.61 | \$761 |
| R12FD | 03 | Corner Break | Low | 1 | Slabs | Crack Sealing - PCC | \$3.14 | \$29 |
| R12FD | 03 | LTD Cracking | Medium | 2 | Slabs | Crack Sealing - PCC | \$3.14 | \$88 |
| R12FD | 03 | Shattered Slab | Medium | 1 | Slabs | Slab Replacement - PCC | \$17.43 | \$3,064 |
| TAFD | 01 | Corner Break | Medium | 2 | Slabs | Patching - PCC Full Depth | \$17.43 | \$1,111 |
| TAFD | 01 | Joint Seal Damage | High | 223 | Slabs | Joint Seal (Localized) | \$3.14 | \$12,592 |
| TAFD | 01 | Joint Spalling | Medium | 4 | Slabs | Patching - PCC Partial Depth | \$39.04 | \$995 |
| TAFD | 01 | LTD Cracking | Medium | 2 | Slabs | Crack Sealing - PCC | \$3.14 | \$66 |
| TBFD | 05 | L&T Cracking | Medium | 365 | Ft | Crack Sealing - AC | \$2.61 | \$952 |
| TCFD | 01 | Corner Break | Low | 2 | Slabs | Crack Sealing - PCC | \$3.14 | \$63 |
| TCFD | 01 | Joint Seal Damage | High | 309 | Slabs | Joint Seal (Localized) | \$3.14 | \$17,275 |
| TDFD | 03 | Corner Break | Low | 1 | Slabs | Crack Sealing - PCC | \$3.14 | \$35 |
| TDFD | 03 | Corner Break | Medium | 1 | Slabs | Patching - PCC Full Depth | \$17.43 | \$756 |

Table F-1. Year 2023 localized preventive maintenance details (continued).

| Branch | Section | Distress Type | Severity | Distress Quantity | Distress Unit | Maintenance Action | Unit Cost | 2023 Estimated Cost |
|--------|---------|-------------------|----------|-------------------|---------------|------------------------------|-----------|---------------------|
| TDFD | 03 | Joint Seal Damage | High | 98 | Slabs | Joint Seal (Localized) | \$3.14 | \$5,871 |
| TDFD | 03 | Joint Spalling | Medium | 3 | Slabs | Patching - PCC Partial Depth | \$39.04 | \$677 |
| TDFD | 03 | LTD Cracking | Medium | 3 | Slabs | Crack Sealing - PCC | \$3.14 | \$98 |
| TFFD | 01 | L&T Cracking | Medium | 661 | Ft | Crack Sealing - AC | \$2.61 | \$1,726 |
| TFFD | 01 | L&T Cracking | High | 230 | Ft | Crack Sealing - AC | \$2.61 | \$600 |
| TFFD | 02 | Corner Break | Low | 4 | Slabs | Crack Sealing - PCC | \$3.14 | \$116 |
| TFFD | 02 | Corner Spalling | Medium | 4 | Slabs | Patching - PCC Partial Depth | \$39.04 | \$472 |
| TFFD | 02 | Joint Seal Damage | High | 283 | Slabs | Joint Seal (Localized) | \$3.14 | \$17,174 |
| TFFD | 02 | LTD Cracking | Medium | 2 | Slabs | Crack Sealing - PCC | \$3.14 | \$82 |
| TH01FD | 03 | Corner Break | Low | 7 | Slabs | Crack Sealing - PCC | \$3.14 | \$178 |

Table Notes:

1. See Figure 3 for the location of the branch and section.
2. Distress types are defined by ASTM D5340-20. L&T Cracking = Longitudinal and Transverse Cracking; LTD Cracking = Longitudinal, Transverse, and Diagonal Cracking; ASR = Alkali-Silica Reaction.
3. The costs provided are of a general nature for the entire state and may require adjustment to reflect specific conditions at Fort Dodge Regional Airport.



PREPARED FOR

Iowa Department of Transportation
Modal Transportation Bureau
800 Lincoln Way
Ames, Iowa 50010
515-239-1691
<https://iowadot.gov/aviation>

JULY 2023