

# Knoxville Municipal Airport

## PAVEMENT MANAGEMENT REPORT



### PREPARED BY

Applied Pavement Technology, Inc.  
115 West Main Street, Suite 400  
Urbana, Illinois 61801  
(217) 398-3977  
[www.appliedpavement.com](http://www.appliedpavement.com)

**JULY 2022**



The preparation of this document was financed in part through an Airport Improvement Program grant from the Federal Aviation Administration (Project Number 3-19-0000-028-2021) as provided under Section 505 of the Airport and Airway Improvement Act of 1982, as amended. The contents do not necessarily reflect the DOT's official views or the policy of the FAA. Acceptance of this report by the FAA does not in any way constitute a commitment on the part of the United States to participate in any development depicted therein nor does it indicate the proposed development is environmentally acceptable in accordance with appropriate public laws.

# KNOXVILLE MUNICIPAL AIRPORT PAVEMENT MANAGEMENT REPORT

## Prepared For:



Iowa Department of Transportation  
Modal Transportation Bureau – Aviation  
800 Lincoln Way  
Ames, Iowa 50010  
515-239-1691  
<https://iowadot.gov/aviation/>

## Prepared By:



Applied Pavement Technology, Inc.  
115 West Main Street, Suite 400  
Urbana, Illinois 61801  
217-398-3977  
<https://www.appliedpavement.com>

## In Association With:



Robinson Engineering Company  
Consulting Engineers  
819 Second Street NE  
Independence, Iowa 50644  
319-334-7211

## TABLE OF CONTENTS

|   |    |
|---|----|
| INTRODUCTION .....  | 1  |
| PAVEMENT INVENTORY .....  | 3  |
| PAVEMENT EVALUATION.....  | 6  |
| Pavement Evaluation Procedure .....   | 6  |
| Pavement Evaluation Results.....  | 7  |
| Inspection Comments.....  | 12 |
| Runway .....  | 12 |
| Taxiways.....   | 12 |
| Aprons.....   | 12 |
| T-Hangar.....   | 12 |
| PAVEMENT MAINTENANCE AND REHABILITATION PROGRAM .....                                     | 13 |
| Analysis Parameters.....  | 13 |
| Critical PCIs.....  | 13 |
| Localized Preventive Maintenance Policies and Unit Costs.....                             | 13 |
| Major Rehabilitation Unit Costs .....   | 13 |
| Budget and Inflation Rate .....   | 13 |
| Analysis Approach.....  | 13 |
| Analysis Results.....   | 14 |
| General Maintenance Recommendations .....   | 15 |
| FAA Requirements (Public Law 103-305).....  | 15 |
| FAA Advisory Circular 150/5830-7B, Appendix A. Pavement Management Program<br>(PMP) ..... | 16 |
| SUMMARY .....   | 21 |

## LIST OF FIGURES

|   |   |
|---|---|
| Figure 1. Pavement condition versus cost of repair.....                         | 1 |
| Figure 2. Pavement area by branch use at Knoxville Municipal Airport. ....      | 4 |
| Figure 3. Knoxville Municipal Airport network definition map. ....              | 5 |
| Figure 4. Visual representation of PCI scale on typical pavement surfaces ..... | 6 |
| Figure 5. PCI versus repair type. ....  | 7 |
| Figure 6. Pavement area by PCI range at Knoxville Municipal Airport. ....       | 8 |
| Figure 7. Area-weighted PCI by branch use at Knoxville Municipal Airport.....   | 8 |
| Figure 8. Knoxville Municipal Airport PCI map.....                              | 9 |

## LIST OF TABLES

|  |    |
|--|----|
| Table 1. 2021 pavement evaluation results.....                                 | 10 |
| Table 2. 5-year M&R program under an unlimited funding analysis scenario. .... | 14 |
| Table 3. Pavement inspection report.....                                       | 18 |

## APPENDIXES

|  |     |
|--|-----|
| Appendix A. Cause of Distress Tables .....                                       | A-1 |
| Appendix B. Inspection Photographs .....   | B-1 |
| Appendix C. Inspection Report.....   | C-1 |
| Appendix D. Work History Report.....   | D-1 |
| Appendix E. Localized Preventive Maintenance Policies and Unit Cost Tables ..... | E-1 |
| Appendix F. Year 2022 Localized Preventive Maintenance Details .....             | F-1 |


## INTRODUCTION

Applied Pavement Technology, Inc. (APTech), with assistance from Robinson Engineering Company, updated the Airport Pavement Management System (APMS) for the Iowa Department of Transportation, Modal Transportation Bureau – Aviation (Iowa DOT). The APMS provides a means to monitor the condition of the pavements within the state of Iowa and to proactively plan for their preservation.

As part of this project, pavement conditions at Knoxville Municipal Airport were assessed in November 2021 using the Pavement Condition Index (PCI) procedure. During a PCI inspection, the types, severities, and amounts of distress present in a pavement are quantified. This information is then used to develop a composite index that represents the overall condition of the pavement in numerical terms, ranging from 0 (failed) to 100 (excellent). The PCI provides an overall measure of condition and an indication of the level of work that will be required to maintain or repair a pavement. The distress information also provides insight into what is causing the pavement to deteriorate, which is the first step in selecting the appropriate repair action to correct the problem.

Programmed into an APMS, PCI information is used to determine when preventive maintenance actions (such as crack or joint sealing) are advisable and to identify the most cost-effective time to perform major rehabilitation (such as an overlay or whitetopping). Delaying maintenance and rehabilitation (M&R) until a pavement structure has seriously degraded can cost many times more than if M&R was applied earlier in a pavement’s life cycle, as shown in Figure 1. From a safety perspective, pavement distresses, such as cracks and loose debris, may pose risks in terms of the potential for aircraft tire damage and the ability of a pilot to safely control aircraft.

Figure 1. Pavement condition versus cost of repair.



The pavement evaluation results for Knoxville Municipal Airport are presented within this report and can be used by Knoxville Municipal Airport, the Iowa DOT, and the Federal Aviation Administration (FAA) to identify, prioritize, and schedule pavement M&R actions at the airport. In addition to this report, the interactive pavement management data visualization tool IDEA, containing the pavement management information collected during this project, was updated and may be accessed from the Iowa DOT's website (<https://iowadot.gov/aviation>).

## PAVEMENT INVENTORY

The project began with a review of the existing inventory information pertaining to the pavements at Knoxville Municipal Airport. The date of original construction, along with the date of any subsequent rehabilitation; the location of completed work; and the type of work undertaken were gathered. The information was used to update the pavement management database and associated maps as necessary to account for pavement-related work that had been undertaken since the last time the airport was evaluated in 2018.

The pavement network at Knoxville Municipal Airport was then divided into branches, sections, and sample units. A branch is a single entity that serves a distinct function. For example, a runway is considered a branch because it serves a single function (allowing aircraft to take off and land). Taxiways, aprons, and T-hangars are also separate branches.

Each branch was further divided into sections. Traditionally, sections are defined as parts of the branch that share common attributes, such as cross-section, date of last construction, traffic level, and performance. Using this approach, if a runway was built in 1968 and then extended in 1984, it would contain two separate sections.

To estimate the overall condition of a pavement section, each section was subdivided into sample units. Portions of these sample units were evaluated during the pavement inspection, and the collected information was extrapolated to predict the overall section condition and quantities of distress.

Approximately 632,100 square feet of pavement were evaluated at Knoxville Municipal Airport, as illustrated in Figure 2. This figure also shows the area-weighted age, in years, of the pavements at the time of the inspection. Figure 3 provides a map that details how the pavement network was divided into management units and identifies the sample units that were evaluated during the pavement inspection at Knoxville Municipal Airport.



Figure 2. Pavement area by branch use at Knoxville Municipal Airport.





FIGURE 3. NETWORK DEFINITION MAP.



**NETWORK DEFINITION LEGEND**

|  |                        |
|--|------------------------|
|  | BRANCH IDENTIFIER      |
|  | SECTION IDENTIFIER     |
|  | PCI VALUE              |
|  | SECTION BREAK LINE     |
|  | SAMPLE UNIT BREAK LINE |
|  | SLAB JOINT             |
|  | SAMPLE UNIT NUMBER     |
|  | SAMPLE UNIT INSPECTED  |
|  | ADDITIONAL SAMPLE UNIT |

|   |                                  |                                  |                            |
|---|----------------------------------|----------------------------------|----------------------------|
|   |                                  |                                  |                            |
| AGENCY: Iowa Department of Transportation<br>Modal Transportation Bureau - Aviation |                                  |                                  |                            |
| LOCATION: Knoxville Municipal Airport<br>Knoxville, Iowa                            |                                  |                                  |                            |
| PAGE TITLE: Network Definition Map  |                                  |                                  |                            |
| PROJECT DATE:<br>SEP. 2021  | CREATION DATE:<br>SEP. 2021      | PROJECT MANAGER:<br>LJR          | JOB NUMBER:<br>17-020-AM05 |
| DRAWING SCALE:<br>1"=300'   | LAST MODIFIED DATE:<br>JAN. 2022 | REVISED BY:<br>DMS               | DRAWN BY:<br>DSP           |
| FILENAME:<br>Knoxville.dwg  |                                  | LAYOUT NAME/NUMBER:<br>NET. DEF. | PAGE NUMBER:<br>5          |

115 W. Main Street, Suite 400  
 Urbana, IL 61801  
 Tel: (217) 398-3977  
 Fax: (217) 398-4027

## PAVEMENT EVALUATION

### Pavement Evaluation Procedure

APTech inspected the pavements at Knoxville Municipal Airport using the PCI procedure described in:

- FAA Advisory Circular 150/5380-6C, *Guidelines and Procedures for Maintenance of Airport Pavements* ([https://www.faa.gov/documentLibrary/media/Advisory\\_Circular/150-5380-6C.pdf](https://www.faa.gov/documentLibrary/media/Advisory_Circular/150-5380-6C.pdf)).
- FAA Advisory Circular 150/5380-7B, *Airport Pavement Management Program (PMP)* ([https://www.faa.gov/documentLibrary/media/Advisory\\_Circular/150-5380-7B.pdf](https://www.faa.gov/documentLibrary/media/Advisory_Circular/150-5380-7B.pdf)).
- ASTM D5340-20, *Standard Test Method for Airport Pavement Condition Index Surveys*.

The PCI provides a numerical indication of overall pavement condition, as illustrated in Figure 4. The types and amounts of deterioration are used to calculate the PCI of the section. The PCI ranges from a value of 0, which represents a pavement in a failed condition, to a value of 100, which represents a pavement in excellent condition. It is important to note that factors other than overall PCI need to be considered when identifying the appropriate type of repair, including types of distress present and rate of deterioration. Also, since the PCI does not assess the structural integrity or capacity of the pavement structure, further testing may be needed to validate and refine the treatment strategy.

Figure 4. Visual representation of PCI scale on typical pavement surfaces<sup>1</sup>.



<sup>1</sup>Photographs shown are not specific to Knoxville Municipal Airport.

Generally, pavements with relatively high PCIs that are not exhibiting significant load-related distress will benefit from preventive maintenance actions, such as crack sealing or joint resealing. As the PCI drops, the pavements may require major rehabilitation, such as an overlay or whitetopping. In some situations where the PCI has dropped low enough, reconstruction may be the only viable alternative due to the substantial damage to the pavement structure. Figure 5 illustrates how the appropriate repair type varies with the PCI of a pavement section and provides the corresponding colors used for the maps and charts in this report for each range of PCIs.

Figure 5. PCI versus repair type.

| PCI Range | Repair                 |
|-----------|------------------------|
| 86-100    | Preventive Maintenance |
| 71-85     |                        |
| 56-70     |                        |
| 41-55     | Major Rehabilitation   |
| 26-40     | Reconstruction         |
| 11-25     |                        |
| 0-10      |                        |

The types of distress identified during the PCI inspection provide insight into the cause of pavement deterioration, which in turn helps in selecting a rehabilitation alternative that corrects the cause, thus eliminating or delaying its recurrence. PCI distress types are characterized as load-related (such as alligator cracking on asphalt-surfaced pavements or shattered slabs on portland cement concrete [PCC] pavements), climate/durability-related (such as weathering [a climate-related distress type on asphalt-surfaced pavements] and durability cracking [a durability-related distress type on PCC pavements]), and other (distress types that cannot be attributed solely to load or climate/durability).

Appendix A identifies the distress types considered during a PCI inspection and describes the likely cause of each distress type. It should be noted that a PCI is based on visual signs of pavement deterioration and does not provide a measure of structural capacity.

### Pavement Evaluation Results

The pavements at Knoxville Municipal Airport were inspected in November 2021. The 2021 area-weighted condition of Knoxville Municipal Airport is 89, with conditions ranging from 10 to 100 (on a scale of 0 [failed] to 100 [excellent]). During the previous pavement inspection in 2018, the area-weighted PCI of the airport was 72.

Figure 6 summarizes the overall condition of the pavements at Knoxville Municipal Airport, and Figure 7 presents area-weighted condition (average PCI adjusted to account for the relative size of the pavement sections) by branch use. Figure 8 is a map that displays the condition of the evaluated pavements. Table 1 summarizes the results of the pavement evaluation. Appendix B presents photographs taken during the PCI inspection, and Appendix C contains detailed information on the distress types observed during the visual survey. Appendix D includes detailed work history information that was collected during the record review process.

Figure 6. Pavement area by PCI range at Knoxville Municipal Airport.




Figure 7. Area-weighted PCI by branch use at Knoxville Municipal Airport.

(Values on chart are area-weighted)






FIGURE 8. PCI MAP.



| LEGEND |                    |
|--------|--------------------|
|        | BRANCH IDENTIFIER  |
|        | SECTION IDENTIFIER |
|        | PCI VALUE          |
|        | SECTION BREAK LINE |

| PAVEMENT CONDITION INDEX |        |
|--------------------------|--------|
| PCI                      |        |
|                          | 86-100 |
|                          | 71-85  |
|                          | 56-70  |
|                          | 41-55  |
|                          | 26-40  |
|                          | 11-25  |
|                          | 0-10   |

|   |                                  |   |                            |
|---|----------------------------------|---|----------------------------|
|   |                                  | 115 W. Main Street, Suite 400<br>Urbana, IL 61801<br>Tel: (217) 398-3977<br>Fax: (217) 398-4027 |                            |
|   |                                  | 322 1st Street East<br>Independence, IA 50644<br>Tel: (319) 334-7211                            |                            |
| AGENCY: Iowa Department of Transportation<br>Modal Transportation Bureau - Aviation |                                  |   |                            |
| LOCATION: Knoxville Municipal Airport<br>Knoxville, Iowa                            |                                  |   |                            |
| PAGE TITLE: 2021 Pavement Condition Index Map                                       |                                  |   |                            |
| PROJECT DATE:<br>SEP. 2021  | CREATION DATE:<br>SEP. 2021      | PROJECT MANAGER:<br>LJR   | JOB NUMBER:<br>17-020-AM05 |
| DRAWING SCALE:<br>1"=300'   | LAST MODIFIED DATE:<br>APR. 2022 | REVISED BY:<br>DMS  | DRAWN BY:<br>DSP           |
| FILENAME:<br>Knoxville.dwg  |                                  | LAYOUT NAME/NUMBER:<br>PCI  | PAGE NUMBER:<br>9          |

Table 1. 2021 pavement evaluation results.

| Branch | Section | Surface Type | Section Area (sf) | LCD       | 2021 PCI | % Distress Due to Load | % Distress Due to Climate/<br>Durability | % Distress Due to Other | Type of Distress  |
|--------|---------|--------------|-------------------|-----------|----------|------------------------|--|-------------------------|---|
| A01KN  | 01      | PCC          | 30,703            | 3/3/2015  | 98       | 76                     | 0  | 24                      | Joint Spalling, LTD Cracking, Shrinkage Cracking  |
| A02KN  | 01      | PCC          | 37,012            | 6/1/1991  | 85       | 14                     | 44                                       | 42                      | Corner Spalling, Faulting, Joint Spalling, Joint Seal Damage, LTD Cracking, Shrinkage Cracking    |
| A02KN  | 02      | PCC          | 16,055            | 1/3/2012  | 82       | 67                     | 30                                       | 3                       | Corner Break, Joint Spalling, Joint Seal Damage, LTD Cracking, Shattered Slab, Shrinkage Cracking |
| R15KN  | 01      | PCC          | 244,244           | 3/3/2020  | 100      | 0                      | 0  | 0                       | No Distresses   |
| R15KN  | 02      | PCC          | 69,339            | 6/30/1990 | 82       | 9                      | 0  | 91                      | Corner Spalling, Faulting, Joint Spalling, LTD Cracking, Shrinkage Cracking, Small Patch          |
| T01KN  | 01      | PCC          | 26,202            | 3/3/2015  | 89       | 64                     | 15                                       | 21                      | Joint Spalling, Joint Seal Damage, LTD Cracking, Shrinkage Cracking, Small Patch                  |
| T02KN  | 01      | PCC          | 12,433            | 6/30/1990 | 93       | 0                      | 0  | 100                     | ASR, Faulting, Small Patch  |
| T03KN  | 01      | PCC          | 56,546            | 6/4/1991  | 84       | 47                     | 34                                       | 19                      | ASR, Corner Break, Corner Spalling, Joint Spalling, Joint Seal Damage, LTD Cracking               |
| T03KN  | 02      | PCC          | 83,867            | 6/3/1994  | 88       | 0                      | 49                                       | 51                      | ASR, Corner Spalling, Faulting, Joint Seal Damage, Small Patch                                    |
| T03KN  | 03      | PCC          | 5,570             | 6/30/1991 | 82       | 0                      | 78                                       | 22                      | Durability Cracking, Faulting, Joint Seal Damage, Large Patch                                     |
| T03KN  | 04      | PCC          | 2,585             | 6/1/1991  | 88       | 0                      | 100                                      | 0                       | Durability Cracking, Joint Seal Damage  |
| T03KN  | 05      | PCC          | 7,323             | 3/3/2020  | 100      | 0                      | 0  | 0                       | No Distresses   |
| TH01KN | 01      | PCC          | 24,950            | 1/1/1967  | 10       | 41                     | 9  | 50                      | ASR, Corner Break, Joint Spalling, Joint Seal Damage, Large Patch, LTD Cracking, Shattered Slab   |

Table 1. 2021 pavement evaluation results (continued).

| Branch | Section | Surface Type | Section Area (sf) | LCD      | 2021 PCI | % Distress Due to Load | % Distress Due to Climate/Durability | % Distress Due to Other | Type of Distress                              |
|--------|---------|--------------|-------------------|----------|----------|------------------------|--------------------------------------|-------------------------|---|
| TH01KN | 02      | PCC          | 15,227            | 1/1/2016 | 89       | 50                     | 50                                   | 0                       | Corner Break, Joint Seal Damage, LTD Cracking |

## Table Notes:

1. See Figure 3 for the location of the branch and section.
2. Surface Type: AC = asphalt cement concrete; AAC = asphalt overlay on AC; PCC = portland cement concrete; APC = asphalt overlay on PCC.
3. LCD = last construction date.
4. Distress due to load includes distress types that are attributed to a structural deficiency in the pavement, such as alligator cracking or rutting on asphalt-surfaced pavements or shattered slabs on PCC pavements.
5. Distress due to climate or durability includes distress types that are attributed to either the aging of the pavement and the effects of the environment (such as weathering, raveling, or block cracking on asphalt-surfaced pavements) or to a materials-related problem (such as durability cracking or alkali-silica reaction [ASR] on PCC pavements). If materials-related distresses were recorded during the inspection, further laboratory testing is required to definitively determine the type present.
6. Distress due to other refers to distress types that are not attributed to one factor but rather may be caused by a combination of factors.
7. Distress types are defined by ASTM D5340-20. L&T Cracking = Longitudinal and Transverse Cracking; LTD Cracking = Longitudinal, Transverse, and Diagonal Cracking; ASR = Alkali-Silica Reaction.



## Inspection Comments

Knoxville Municipal Airport was inspected on November 12, 2021. There were fourteen pavement sections defined during the inspection. Suspected alkali-silica reaction (ASR) was recorded at this airport in accordance with ASTM D5340-20. It should be noted that laboratory testing in the form of petrographic analysis is the only definitive way to validate the presence of ASR; however, the formation of a precipitate is evidence of a reaction consistent with this type of materials-related distress.

### *Runway*

Runway 15/33 was defined by two sections. Section 01 was in excellent condition with no distress noted at the time of inspection. Areas of low- and medium-severity corner spalling and joint spalling; shrinkage cracking; and low-severity faulting, small patching, and longitudinal, transverse and diagonal (LTD) cracking were observed in Section 02.

### *Taxiways*

Taxiway 01 connected Runway 15/33 to the apron area. This taxiway was defined by one section that contained medium-severity joint spalling; shrinkage cracking; and low-severity joint seal damage, LTD cracking, and small patching.

Taxiway 02 consisted of one section, adjacent to the Runway 33 approach. Low-severity ASR, faulting, and small patching were identified in Section 01.

Taxiway 03, the parallel taxiway to Runway 15/33, was defined by five sections. Section 01 had areas of low-severity ASR; medium-severity corner break and joint seal damage; and low- and medium-severity corner spalling, joint spalling, and LTD cracking noted during the inspection. Section 02 contained low- and medium-severity ASR, medium-severity corner spalling and joint seal damage, and low-severity faulting and small patching. Low- and medium-severity durability cracking, medium-severity joint seal damage, and low-severity faulting and large patching were identified in Section 03. Section 04 had low-severity durability cracking and medium-severity joint seal damage recorded during the inspection. Section 05 was in excellent condition with no distress identified at the time of inspection.

### *Aprons*

Apron 01 contained one section in excellent condition that had small amounts of shrinkage cracking and low-severity joint spalling and LTD cracking recorded during the inspection.

Apron 02 consisted of two sections. Section 01 contained low-severity corner spalling, faulting, and LTD cracking; medium-severity joint seal damage; low- and medium-severity joint spalling; and shrinkage cracking. Areas of low-severity corner break, shattered slab, and joint spalling; low- and medium-severity joint seal damage and LTD cracking; and shrinkage cracking were identified in Section 02.

### *T-Hangar*

The T-hangar area was defined by two sections. Section 01 was in poor condition with areas of all severities of ASR; low- and medium-severity corner break and LTD cracking; medium- and high-severity joint seal damage, joint spalling, and shattered slab; and low-severity large patching recorded throughout. Low- and medium-severity joint seal damage and low-severity LTD cracking and corner break were identified in Section 02.

## PAVEMENT MAINTENANCE AND REHABILITATION PROGRAM

Using the information collected during the pavement inspection, the PAVER pavement management software was used to develop a 5-year M&R program for Knoxville Municipal Airport. In addition, a 1-year plan for localized preventive maintenance (such as crack sealing and patching) was prepared.

### Analysis Parameters

#### *Critical PCIs*

PAVER uses critical PCIs to determine whether localized preventive maintenance or major rehabilitation is the appropriate repair action. Above the critical PCI, localized preventive maintenance activities are recommended. Below the critical PCI, major rehabilitation actions, such as an overlay or reconstruction, are recommended. The Iowa DOT set the critical PCIs at 65 for runways, 60 for taxiways, and 55 for aprons and T-hangars.

#### *Localized Preventive Maintenance Policies and Unit Costs*

Localized preventive maintenance policies were developed for asphalt-surfaced and PCC pavements. These policies, shown in Appendix E, identify the localized preventive maintenance actions that the Iowa DOT considered appropriate to correct for the different distress types and severities. The Iowa DOT provided unit costs for each of the localized preventive maintenance actions included in these policies, and these costs are detailed in Appendix E. Please note that this information is of a general nature for the entire state. The localized preventive maintenance policies and unit costs may require adjustment to reflect specific conditions at Knoxville Municipal Airport.

#### *Major Rehabilitation Unit Costs*

PAVER estimates the cost of major rehabilitation based on the predicted PCI of the pavement section. The Iowa DOT provided the costs for major rehabilitation, and they are presented in Appendix E. If major rehabilitation is recommended in the 5-year program, further engineering investigation will be needed to identify the most appropriate rehabilitation action and to estimate the cost of such work more accurately.

#### *Budget and Inflation Rate*

An unlimited budget with a start date of July 1, 2022 and an inflation rate of 4.0 percent was used during the analysis.

### Analysis Approach

The 5-year M&R program was prepared with the goal of maintaining the pavements above established critical PCIs. During this analysis, major rehabilitation was recommended for pavements in the year they dropped below their critical PCI. For the first year (2022) of the analysis only, a localized preventive maintenance plan was developed for those pavement sections that were above their critical PCI. If major rehabilitation was triggered for a section in 2023 or 2024, then localized preventive maintenance was not recommended for 2022. While localized preventive maintenance should be an annual undertaking at Knoxville Municipal Airport, it is not possible to accurately predict the propagation of cracking and other distress types. Therefore, the airport should budget for maintenance every year and can use the 2022

localized preventive maintenance plan as a baseline for that work. As the pavements age, it can be assumed that the amount of localized preventive maintenance required will increase.

## Analysis Results

A summary of the M&R program for Knoxville Municipal Airport is presented in Table 2. Detailed information on the recommended localized preventive maintenance plan for 2022 is provided in Appendix F.

Table 2. 5-year M&R program under an unlimited funding analysis scenario.

| Year | Branch | Section | Surface Type | Type of Repair         | Estimated Cost |
|------|--------|---------|--------------|------------------------|----------------|
| 2022 | A02KN  | 01      | PCC          | Preventive Maintenance | \$18,350       |
| 2022 | A02KN  | 02      | PCC          | Preventive Maintenance | \$1,948        |
| 2022 | R15KN  | 02      | PCC          | Preventive Maintenance | \$1,709        |
| 2022 | T01KN  | 01      | PCC          | Preventive Maintenance | \$466          |
| 2022 | T03KN  | 01      | PCC          | Preventive Maintenance | \$25,966       |
| 2022 | T03KN  | 02      | PCC          | Preventive Maintenance | \$43,186       |
| 2022 | T03KN  | 03      | PCC          | Preventive Maintenance | \$3,162        |
| 2022 | T03KN  | 04      | PCC          | Preventive Maintenance | \$1,057        |
| 2022 | TH01KN | 01      | PCC          | Major Rehabilitation   | \$433,685      |
| 2022 | TH01KN | 02      | PCC          | Preventive Maintenance | \$1,829        |

**Total Estimated Cost: \$531,000**

### Table Notes:

1. See Figure 3 for the location of the branch and section.
2. Surface Type: AC = asphalt cement concrete; AAC = asphalt overlay on AC; PCC = portland cement concrete; APC = asphalt overlay on PCC.
3. Type of Repair: Major Rehabilitation such as pavement reconstruction or an overlay; Localized Preventive Maintenance such as crack sealing or patching.
4. The estimated costs provided are of a general nature for the entire state and may require adjustment to reflect specific conditions at Knoxville Municipal Airport.

The recommendations made in this report are based on a broad network-level analysis and meant to provide Knoxville Municipal Airport with an indication of the type of pavement-related work required during the next 5 years. Further engineering investigation may be necessary to identify which repair action is most appropriate. In addition, the cost estimates provided are based on overall unit costs for the entire state, and Knoxville Municipal Airport should adjust the plan to reflect local costs.

Because an unlimited budget was used in the analysis, it is possible that the pavement repair program may need to be adjusted to consider economic or operational constraints. The identification of a project need does not necessarily mean that state or federal funding will be available in the year it is indicated. It is important to remember that regardless of the recommendations presented within this report, Knoxville Municipal Airport is responsible for repairing pavements where existing conditions pose a hazard to safe operations.

## General Maintenance Recommendations

In addition to the specific maintenance actions presented in Appendix F, it is recommended that the following strategies be considered for prolonging pavement life:

1. Regularly inspect all safety areas of the airport and document all inspection activity. A sample form that can be used to perform these inspections is provided in Table 3 of this report.
2. Provide a method of tracking all maintenance activities that occur as a result of inspections. These need to be reported to the FAA and the Iowa DOT. This information is used to update the APMS records and is required to remain in compliance with Public Law 103-305 (see the next section of this report for further information on this law).
3. Conduct an aggressive campaign against weed growth through timely herbicide applications and mowing programs of the safety areas. Vegetation growth in pavement cracks is destructive and significantly increases the rate of pavement deterioration.
4. Implement a periodic crack and joint sealing program. Keeping water and debris out of the pavement system by sealing cracks and joints is a proven and cost-effective method of extending the life of the pavement system.
5. Ensure that dirt does not build up along the edges of the pavements. This can create a “bathtub” effect, reducing the ability of water to drain away from the pavement system.
6. Closely monitor the movement of heavy equipment (particularly farming, construction, and fueling equipment) to make sure it is only operating on pavements that are designed to accommodate heavy loads. Failure to restrict heavy equipment to appropriate areas may result in the premature failure of airport pavements.

## FAA Requirements (Public Law 103-305)

Because Knoxville Municipal Airport is in the National Plan of Integrated Airport Systems (NPIAS), the airport sponsor is required to keep the airport in a viable operating condition. This includes maintaining airport pavements in accordance with Public Law 103-305. Public Law 103-305 states that after January 1, 1995, NPIAS airport sponsors must provide assurances or certifications that an airport has implemented an effective airport pavement maintenance management system (PMMS) before the airport will be considered for federal funding of pavement replacement or reconstruction projects. To be in full compliance with the federal law, the PMMS must include the following components at minimum: pavement inventory, pavement inspections, record keeping, information retrieval, and program funding.

This report serves as a complete pavement inventory and detailed inspection. To remain in compliance with the law, Knoxville Municipal Airport will also need to undertake monthly drive-by inspections of pavement conditions and track pavement-related maintenance activities.

FAA Advisory Circular 150/5380-7B provides detailed guidance pertaining to the requirements for an acceptable pavement management program (PMP). Appendix A of the FAA Advisory Circular 150/5380-7B outlines what needs to be included in a PMP to remain in compliance with this law and Grant Assurance #11. The following is a copy of this Appendix, along with instructions for supplementing this report so that all requirements are met. Note that the italicized words are direct quotations from the FAA Advisory Circular.

**FAA Advisory Circular 150/5830-7B, Appendix A. Pavement Management Program (PMP)**

**A-1.0.** *An effective PMP specifies the procedures to follow to assure that proper preventative and remedial pavement maintenance is performed. The program should identify funding or anticipated funding and other resources available to provide remedial and preventive maintenance activities. An airport sponsor may use any format deemed appropriate, but the program needs to, as a minimum, include the following:*

**A-1.1. Pavement Inventory.** *The following must be depicted:*

- a. *Identification of all runways, taxiways, and aprons with pavement broken down into sections each having similar properties.*

The network definition map provided in Figure 3 of this report shows the location of all runways, taxiways, aprons, and T-hangars at Knoxville Municipal Airport. If any new pavements are constructed or any pavement areas are permanently closed, this map must be updated. Project plans should be submitted to the Iowa DOT after project completion.

- b. *Dimensions of pavement sections.*

The dimensions of all runways, taxiways, aprons, and T-hangars are stored in the PAVER database. Appendix C provides information on length, width, and area. In addition, the network definition map (Figure 3) is drawn to scale. Any changes to pavement dimensions must be recorded.

- c. *Type of pavement surface.*

The type of pavement for each section at Knoxville Municipal Airport is listed in Table 1 of this report and is also stored in the PAVER database. Any changes to pavement type (through an overlay or reconstruction) must be recorded.

- d. *Year of construction and/or most recent major rehabilitation.*

Dates for pavement construction, rehabilitation, or reconstruction must be recorded. The current pavement history for Knoxville Municipal Airport is provided in Appendix D of this report.

- e. *Whether AIP [Airport Improvement Program] or PFC [Passenger Facility Charge] funds were used to construct, reconstruct, or repair the pavement.*

Funding sources for all pavement projects should be recorded.

**A-1.2. PMP Pavement Inspection Schedule.** *Airports must perform a detailed inspection of airfield pavements at least once a year for the PMP. If a pavement condition index (PCI) survey is performed, as set forth in ASTM D5340, Standard Test Method for Airport Pavement Condition Index Surveys, the frequency of the detailed inspection by PCI surveys may be extended to three years. Less comprehensive routine daily, weekly, and monthly maintenance inspections required for operations should be addressed.*

This report consists of a detailed inspection that will extend the inspection period to 3 years. It is the airport sponsor's responsibility to perform monthly drive-by inspections. A sample pavement inspection report form is provided in Table 3 of this report.

**A-1.3. Record Keeping.** *The airport must record and keep on file complete information about all detailed inspections and maintenance performed until the pavement system is replaced. The types of distress, their locations, and remedial action, scheduled or performed, must be documented. The minimum information recorded includes:*

- a. *Inspection date*
- b. *Location*
- c. *Distress types*
- d. *Maintenance scheduled or performed*

Items a through c are satisfied by this inspection report. Item d is the responsibility of the airport, as is record keeping of the monthly drive-by inspections.

**A-1.4. Information Retrieval.** *An airport sponsor may use any form of record keeping it deems appropriate so long as the information and records from the pavement survey can generate required reports, as necessary.*

Keep this report, monthly drive-by inspection reports, construction updates, and all records of maintenance activities in a readily accessible location so that they can be easily retrieved as requested by the FAA.

Table 3. Pavement inspection report.

Inspected By: \_\_\_\_\_

Date Inspected: \_\_\_\_\_

| <b>Branch</b> | <b>Section</b> | <b>Distress Description/Dimensions/Severity/<br/>Recommended Action</b> | <b>Description of<br/>Repair</b> | <b>Date<br/>Performed</b> | <b>Cost</b> | <b>Funding<br/>Source</b> |
|---------------|----------------|---|----------------------------------|---------------------------|-------------|---------------------------|
| A01KN         | 01             |   |                                  |                           |             |                           |
| A02KN         | 01             |   |                                  |                           |             |                           |
| A02KN         | 02             |   |                                  |                           |             |                           |
| R15KN         | 01             |   |                                  |                           |             |                           |
| R15KN         | 02             |   |                                  |                           |             |                           |
| T01KN         | 01             |   |                                  |                           |             |                           |

Table 3. Pavement inspection report (continued).

Inspected By: \_\_\_\_\_

Date Inspected: \_\_\_\_\_

| <b>Branch</b> | <b>Section</b> | <b>Distress Description/Dimensions/Severity/<br/>Recommended Action</b> | <b>Description of<br/>Repair</b> | <b>Date<br/>Performed</b> | <b>Cost</b> | <b>Funding<br/>Source</b> |
|---------------|----------------|---|----------------------------------|---------------------------|-------------|---------------------------|
| T02KN         | 01             |   |                                  |                           |             |                           |
| T03KN         | 01             |   |                                  |                           |             |                           |
| T03KN         | 02             |   |                                  |                           |             |                           |
| T03KN         | 03             |   |                                  |                           |             |                           |
| T03KN         | 04             |   |                                  |                           |             |                           |
| T03KN         | 05             |   |                                  |                           |             |                           |



Table 3. Pavement inspection report (continued).

Inspected By: \_\_\_\_\_

Date Inspected: \_\_\_\_\_

| <b>Branch</b> | <b>Section</b> | <b>Distress Description/Dimensions/Severity/<br/>Recommended Action</b> | <b>Description of<br/>Repair</b> | <b>Date<br/>Performed</b> | <b>Cost</b> | <b>Funding<br/>Source</b> |
|---------------|----------------|---|----------------------------------|---------------------------|-------------|---------------------------|
| TH01KN        | 01             |   |                                  |                           |             |                           |
| TH01KN        | 02             |   |                                  |                           |             |                           |

Table Notes:

1. See Figure 3 for the location of the branch and section.

## **SUMMARY**

This report documents the results of the pavement evaluation conducted at Knoxville Municipal Airport. A visual inspection of the pavements in 2021 found that the overall condition of the pavement network is a PCI of 89. A 5-year pavement repair program, shown in Table 2, was generated for Knoxville Municipal Airport, which revealed that approximately \$531,000 needs to be expended on M&R. Knoxville Municipal Airport should utilize these study results to assist in planning for future maintenance needs as part of the airport CIP planning process.

## **APPENDIX A**

### **CAUSE OF DISTRESS TABLES**

Table A-1. Cause of pavement distress, asphalt-surfaced pavements.

| <b>Distress Type</b>      | <b>Probable Cause of Distress</b>  |
|---------------------------|--|
| Alligator Cracking        | Fatigue failure of the asphalt surface under repeated traffic loading.   |
| Bleeding                  | Excessive amounts of asphalt cement or tars in the mix or low air void content, or both.   |
| Block Cracking            | Shrinkage of the asphalt and daily temperature cycling; it is not load associated.   |
| Corrugation               | Traffic action combined with an unstable pavement layer.   |
| Depression                | Settlement of the foundation soil or can be “built up” during construction.  |
| Jet-Blast Erosion         | Bituminous binder has been burned or carbonized.   |
| Joint Reflection Cracking | Movement of the concrete slab beneath the asphalt surface due to thermal and moisture changes.   |
| L&T Cracking              | Cracks may be caused by (1) a poorly constructed paving lane joint, (2) shrinkage of the asphalt surface due to low temperatures or hardening of the asphalt, or (3) reflective cracking caused by cracks in an underlying PCC slab. |
| Oil Spillage              | Deterioration or softening of the pavement surface caused by the spilling of oil, fuel, or other solvents.   |
| Patching                  | N/A  |
| Polished Aggregate        | Repeated traffic applications.   |
| Raveling                  | Asphalt binder may have hardened significantly, causing coarse aggregate pieces to dislodge.   |
| Rutting                   | Usually caused by consolidation or lateral movement of the materials due to traffic loads.   |
| Shoving                   | Where PCC pavements adjoin flexible pavements, PCC “growth” may shove the asphalt pavement.  |
| Slippage Cracking         | Low strength surface mix or poor bond between the surface and the next layer of the pavement structure.  |
| Swelling                  | Usually caused by frost action or by swelling soil.  |
| Weathering                | Asphalt binder and/or fine aggregate may wear away as the pavement ages and hardens.   |

Table A-2. Cause of pavement distress, PCC pavements.

| <b>Distress Type</b>        | <b>Probable Cause of Distress</b>   |
|-----------------------------|---|
| ASR                         | Chemical reaction of alkalis in the portland cement with certain reactive silica minerals. ASR may be accelerated by the use of chemical pavement deicers.                    |
| Blowup                      | Incompressible materials in the joints.   |
| Corner Break                | Load repetition combined with loss of support and curling stresses.   |
| Durability Cracking         | Concrete's inability to withstand environmental factors such as freeze-thaw cycles.   |
| Faulting                    | Upheaval or consolidation.  |
| Joint Seal Damage           | Stripping of joint sealant, extrusion of joint sealant, weed growth, hardening of the filler (oxidation), loss of bond to the slab edges, or absence of sealant in the joint. |
| LTD Cracking                | Combination of load repetition, curling stresses, and shrinkage stresses.   |
| Patching (Small and Large)  | N/A   |
| Popouts                     | Freeze-thaw action in combination with expansive aggregates.  |
| Pumping                     | Poor drainage, poor joint sealant.  |
| Scaling                     | Over finishing of concrete, deicing salts, improper construction, freeze-thaw cycles, and poor aggregate.   |
| Shattered Slab              | Load repetition.  |
| Shrinkage Cracking          | Setting and curing of the concrete.   |
| Spalling (Joint and Corner) | Excessive stresses at the joint caused by infiltration of incompressible materials or traffic loads; weak concrete at the joint combined with traffic loads.                  |

## **APPENDIX B**

### **INSPECTION PHOTOGRAPHS**

A01KN-01. Overview.



A01KN-01. LTD Cracking (Sample Unit No. 13).



A02KN-01. Overview.



A02KN-01. Corner Spalling (Sample Unit No. 10).





A02KN-01. LTD Cracking (Sample Unit No. 10).



A02KN-02. Overview.



A02KN-02. LTD Cracking (Sample Unit No. 03).



A02KN-02. Shattered Slab (Sample Unit No. 03).



R15KN-01. Overview.



R15KN-02. Overview.



R15KN-02. Joint Spalling (Sample Unit No. 14).



R15KN-02. LTD Cracking (Sample Unit No. 19).



R15KN-02. Small Patching (Sample Unit No. 14).



T01KN-01. Overview.



T01KN-01. LTD Cracking (Sample Unit No. 03).



T01KN-01. Shrinkage Cracking (Sample Unit No. 03).



T02KN-01. Overview.



T02KN-01. ASR (Sample Unit No. 06).



T02KN-01. Faulting (Sample Unit No. 02).



T02KN-01. Small Patching (Sample Unit No. 05).





T03KN-01. Overview.



T03KN-01. Joint Seal Damage (Sample Unit No. 02).



T03KN-01. LTD Cracking (Sample Unit No. 08).



T03KN-02. Overview.



T03KN-02. ASR (Sample Unit No. 05).



T03KN-02. ASR (Sample Unit No. 15).



T03KN-02. Joint Seal Damage (Sample Unit No. 20).



T03KN-03. Overview.



T03KN-03. Durability Cracking (Sample Unit No. 02).



T03KN-04. Overview.



T03KN-04. Durability Cracking (Sample Unit No. 01).



T03KN-05. Overview.



TH01KN-01. Overview.



TH01KN-01. ASR (Sample Unit No. 04) (1).



TH01KN-01. ASR (Sample Unit No. 04) (2).



TH01KN-02. Overview.





TH01KN-02. Corner Break (Sample Unit No. 01).



## **APPENDIX C**

### **INSPECTION REPORT**

# RE-INSPECTION REPORT KNOXVILLE MUNICIPAL AIRPORT

Pavement Database: IA 2021

Generate Date: 4/27/2022

Network ID: OXV

Page 1

## Branch - Section ID: A01KN - 01

Branch Name: APRON 01

Use: APRON

LCD: 3/3/2015

PCI Family: IowaPCCAPSE\_GeneralBasic

Surface Type: PCC

Rank: P

Section Area (sf): 30,703.00

Length (ft): 250.00

Width (ft): 120.00

From: HANGARS

To: TAXIWAY 01

Slabs: 196

Section Comments:

Slab Length (ft): 12.50

Slab Width (ft): 12.50

Joint Length (ft): 4,533.81

Last Insp Date: 11/12/2021

Inspection Comments:

PCI: 98

Total Samples: 13

Surveyed: 7

### Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 20

NO DISTRESS

### Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 97

Sample Area (Slabs): 20

74 JOINT SPALL

L

2 Slabs

### Sample Number: 07

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 20

NO DISTRESS

### Sample Number: 10

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 20

NO DISTRESS

### Sample Number: 11

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 12

NO DISTRESS

### Sample Number: 12

Sample Type: A

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 20

NO DISTRESS

# RE-INSPECTION REPORT KNOXVILLE MUNICIPAL AIRPORT

Pavement Database: IA 2021

Generate Date: 4/27/2022

Network ID: OXV

Page 2

## Sample Number: 13

Sample Type: R

Sample Comments:

Sample PCI: 86

Sample Area (Slabs): 16

63 LINEAR CR

L

3 Slabs

73 SHRINKAGE CR

N

1 Slabs

# RE-INSPECTION REPORT KNOXVILLE MUNICIPAL AIRPORT

Pavement Database: IA 2021

Generate Date: 4/27/2022

Network ID: OXV

Page 3

## Branch - Section ID: A02KN - 01

Branch Name: APRON 02

Use: APRON

LCD: 6/1/1991

PCI Family: IowaPCCAPSE\_GeneralBasic

Surface Type: PCC

Rank: P

Section Area (sf): 37,012.00

Length (ft): 120.00

Width (ft): 300.00

From: T01KN-01

To: A02KN-01

Slabs: 261

Section Comments:

Slab Length (ft): 11.80

Slab Width (ft): 12.00

Joint Length (ft): 5,789.14

Last Insp Date: 11/12/2021

Inspection Comments:

PCI: 85

Total Samples: 11

Surveyed: 6

### Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 91

Sample Area (Slabs): 21

65 JT SEAL DMG

M

21 Slabs

74 JOINT SPALL

L

1 Slabs

### Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 82

Sample Area (Slabs): 25

63 LINEAR CR

L

1 Slabs

65 JT SEAL DMG

M

25 Slabs

73 SHRINKAGE CR

N

2 Slabs

74 JOINT SPALL

L

3 Slabs

75 CORNER SPALL

L

1 Slabs

### Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 25

65 JT SEAL DMG

M

25 Slabs

### Sample Number: 07

Sample Type: R

Sample Comments:

Sample PCI: 82

Sample Area (Slabs): 25

65 JT SEAL DMG

M

25 Slabs

73 SHRINKAGE CR

N

1 Slabs

74 JOINT SPALL

L

1 Slabs

74 JOINT SPALL

M

2 Slabs

75 CORNER SPALL

L

2 Slabs

# RE-INSPECTION REPORT KNOXVILLE MUNICIPAL AIRPORT

Pavement Database: IA 2021

Generate Date: 4/27/2022

Network ID: OXV

Page 4

---

## Sample Number: 08

Sample Type: R

Sample Comments:

Sample PCI: 80

Sample Area (Slabs): 25

|                |   |          |
|----------------|---|----------|
| 63 LINEAR CR   | L | 1 Slabs  |
| 65 JT SEAL DMG | M | 25 Slabs |
| 71 FAULTING    | L | 3 Slabs  |
| 74 JOINT SPALL | L | 1 Slabs  |

---

## Sample Number: 10

Sample Type: R

Sample Comments:

Sample PCI: 85

Sample Area (Slabs): 25

|                 |   |          |
|-----------------|---|----------|
| 63 LINEAR CR    | L | 1 Slabs  |
| 65 JT SEAL DMG  | M | 25 Slabs |
| 73 SHRINKAGE CR | N | 1 Slabs  |
| 74 JOINT SPALL  | L | 1 Slabs  |
| 75 CORNER SPALL | L | 1 Slabs  |

# RE-INSPECTION REPORT KNOXVILLE MUNICIPAL AIRPORT

Pavement Database: IA 2021

Generate Date: 4/27/2022

Network ID: OXV

Page 5

## Branch - Section ID: A02KN - 02

Branch Name: APRON 02

Use: APRON

LCD: 1/3/2012  
 Surface Type: PCC  
 Rank: P  
 Section Area (sf): 16,055.00  
 Length (ft): 130.00  
 Width (ft): 120.00  
 From: SEE MAP  
 To: SEE MAP  
 Slabs: 113  
 Slab Length (ft): 11.80  
 Slab Width (ft): 12.00  
 Joint Length (ft): 2,441.22  
 Last Insp Date: 11/12/2021  
 PCI: 82  
 Total Samples: 5  
 Surveyed: 4

PCI Family: IowaPCCAPSE\_GeneralBasic

Section Comments:

Inspection Comments:

### Sample Number: 01

Sample Type: R  
 Sample PCI: 98  
 Sample Area (Slabs): 19  
 65 JT SEAL DMG

Sample Comments:

L 19 Slabs

### Sample Number: 02

Sample Type: R  
 Sample PCI: 93  
 Sample Area (Slabs): 20  
 65 JT SEAL DMG

Sample Comments:

M 20 Slabs

### Sample Number: 03

Sample Type: R  
 Sample PCI: 71  
 Sample Area (Slabs): 25  
 62 CORNER BREAK  
 63 LINEAR CR  
 65 JT SEAL DMG  
 72 SHAT. SLAB  
 73 SHRINKAGE CR

Sample Comments:

L 1 Slabs  
 L 8 Slabs  
 L 25 Slabs  
 L 1 Slabs  
 N 2 Slabs

### Sample Number: 04

Sample Type: R  
 Sample PCI: 72  
 Sample Area (Slabs): 25  
 62 CORNER BREAK  
 63 LINEAR CR  
 65 JT SEAL DMG  
 74 JOINT SPALL

Sample Comments:

L 1 Slabs  
 M 3 Slabs  
 L 25 Slabs  
 L 1 Slabs

# RE-INSPECTION REPORT KNOXVILLE MUNICIPAL AIRPORT

Pavement Database: IA 2021

Generate Date: 4/27/2022

Network ID: OXV

Page 6

## Branch - Section ID: R15KN - 01

Branch Name: RUNWAY 15/33

Use: RUNWAY

LCD: 3/3/2020

PCI Family: IowaPCCRWSE\_General

Surface Type: PCC

Rank: P

Section Area (sf): 244,244.00

Length (ft): 3,075.00

Width (ft): 75.00

From: RUNWAY END 33

To: RUNWAY END 15

Slabs: 1,303

Section Comments:

Slab Length (ft): 15.00

Slab Width (ft): 12.50

Joint Length (ft): 32,486.44

Last Insp Date: 11/12/2021

Inspection Comments:

PCI: 100

Total Samples: 59

Surveyed: 8

### Sample Number: 07

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 24

NO DISTRESS

### Sample Number: 14

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 24

NO DISTRESS

### Sample Number: 21

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 24

NO DISTRESS

### Sample Number: 28

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 24

NO DISTRESS

### Sample Number: 35

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 24

NO DISTRESS

### Sample Number: 42

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 24

NO DISTRESS



# RE-INSPECTION REPORT KNOXVILLE MUNICIPAL AIRPORT

Pavement Database: IA 2021

Generate Date: 4/27/2022

Network ID: OXV

Page 7

---

## Sample Number: 49

Sample Type: R  
Sample PCI: 100  
Sample Area (Slabs): 24  
NO DISTRESS

Sample Comments:

---

## Sample Number: 57

Sample Type: R  
Sample PCI: 100  
Sample Area (Slabs): 27  
NO DISTRESS

Sample Comments:

# RE-INSPECTION REPORT KNOXVILLE MUNICIPAL AIRPORT

Pavement Database: IA 2021

Generate Date: 4/27/2022

Network ID: OXV

Page 8

## Branch - Section ID: R15KN - 02

Branch Name: RUNWAY 15/33

Use: RUNWAY

LCD: 6/30/1990

PCI Family: IowaPCCRWSE\_General

Surface Type: PCC

Rank: P

Section Area (sf): 69,339.00

Length (ft): 923.00

Width (ft): 75.00

From: 33 END OF RWY 15/33

To: 1000 FEET SE

Slabs: 444

Section Comments:

Slab Length (ft): 12.50

Slab Width (ft): 12.50

Joint Length (ft): 10,094.60

Last Insp Date: 11/12/2021

Inspection Comments:

PCI: 82

Total Samples: 19

Surveyed: 7

### Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 81

Sample Area (Slabs): 24

|                 |   |          |
|-----------------|---|----------|
| 66 SMALL PATCH  | L | 11 Slabs |
| 71 FAULTING     | L | 4 Slabs  |
| 73 SHRINKAGE CR | N | 1 Slabs  |

### Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 71

Sample Area (Slabs): 24

|                 |   |         |
|-----------------|---|---------|
| 66 SMALL PATCH  | L | 9 Slabs |
| 71 FAULTING     | L | 3 Slabs |
| 73 SHRINKAGE CR | N | 1 Slabs |
| 74 JOINT SPALL  | M | 1 Slabs |
| 75 CORNER SPALL | L | 4 Slabs |
| 75 CORNER SPALL | M | 2 Slabs |

### Sample Number: 09

Sample Type: R

Sample Comments:

Sample PCI: 66

Sample Area (Slabs): 24

|                 |   |         |
|-----------------|---|---------|
| 63 LINEAR CR    | L | 2 Slabs |
| 66 SMALL PATCH  | L | 4 Slabs |
| 71 FAULTING     | L | 7 Slabs |
| 75 CORNER SPALL | L | 2 Slabs |
| 75 CORNER SPALL | M | 1 Slabs |

### Sample Number: 12

Sample Type: R

Sample Comments:

Sample PCI: 82

Sample Area (Slabs): 24

|                 |   |         |
|-----------------|---|---------|
| 66 SMALL PATCH  | L | 7 Slabs |
| 71 FAULTING     | L | 2 Slabs |
| 75 CORNER SPALL | L | 2 Slabs |
| 75 CORNER SPALL | M | 1 Slabs |

# RE-INSPECTION REPORT KNOXVILLE MUNICIPAL AIRPORT

Pavement Database: IA 2021

Generate Date: 4/27/2022

Network ID: OXV

Page 9

---

## Sample Number: 14

Sample Type: R

Sample Comments:

Sample PCI: 83

Sample Area (Slabs): 24

66 SMALL PATCH

L

9 Slabs

71 FAULTING

L

3 Slabs

74 JOINT SPALL

L

1 Slabs

---

## Sample Number: 16

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 24

71 FAULTING

L

2 Slabs

---

## Sample Number: 19

Sample Type: R

Sample Comments:

Sample PCI: 96

Sample Area (Slabs): 24

63 LINEAR CR

L

1 Slabs

# RE-INSPECTION REPORT KNOXVILLE MUNICIPAL AIRPORT

Pavement Database: IA 2021

Generate Date: 4/27/2022

Network ID: OXV

Page 10

## Branch - Section ID: T01KN - 01

Branch Name: TAXIWAY 01

Use: TAXIWAY

LCD: 3/3/2015

PCI Family: IowaPCCTWSE\_General

Surface Type: PCC

Rank: P

Section Area (sf): 26,202.00

Length (ft): 705.00

Width (ft): 35.00

From: APRON 01

To: RUNWAY 15/33

Slabs: 198

Section Comments:

Slab Length (ft): 12.00

Slab Width (ft): 11.00

Joint Length (ft): 3,779.71

Last Insp Date: 11/12/2021

Inspection Comments:

PCI: 89

Total Samples: 10

Surveyed: 5

### Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 92

Sample Area (Slabs): 21

63 LINEAR CR

L

1 Slabs

65 JT SEAL DMG

L

21 Slabs

73 SHRINKAGE CR

N

1 Slabs

### Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 21

65 JT SEAL DMG

L

21 Slabs

66 SMALL PATCH

L

2 Slabs

73 SHRINKAGE CR

N

5 Slabs

### Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 87

Sample Area (Slabs): 21

63 LINEAR CR

L

3 Slabs

65 JT SEAL DMG

L

21 Slabs

### Sample Number: 08

Sample Type: R

Sample Comments:

Sample PCI: 80

Sample Area (Slabs): 21

63 LINEAR CR

L

7 Slabs

65 JT SEAL DMG

L

21 Slabs

# RE-INSPECTION REPORT KNOXVILLE MUNICIPAL AIRPORT

Pavement Database: IA 2021

Generate Date: 4/27/2022

Network ID: OXV

Page 11

## Sample Number: 09

Sample Type: R

Sample Comments:

Sample PCI: 92

Sample Area (Slabs): 19

65 JT SEAL DMG

L

19 Slabs

73 SHRINKAGE CR

N

1 Slabs

73 SHRINKAGE CR

N

1 Slabs

74 JOINT SPALL

M

1 Slabs

# RE-INSPECTION REPORT KNOXVILLE MUNICIPAL AIRPORT

Pavement Database: IA 2021

Generate Date: 4/27/2022

Network ID: OXV

Page 12

## Branch - Section ID: T02KN - 01

Branch Name: TAXIWAY 02

Use: TAXIWAY

LCD: 6/30/1990

PCI Family: IowaPCCTWSE\_General

Surface Type: PCC

Rank: P

Section Area (sf): 12,433.00

Length (ft): 350.00

Width (ft): 46.00

From: RWY END 33

To: END OF T02KN-01

Slabs: 105

Section Comments:

Slab Length (ft): 11.80

Slab Width (ft): 10.00

Joint Length (ft): 1,990.14

Last Insp Date: 11/12/2021

Inspection Comments:

PCI: 93

Total Samples: 6

Surveyed: 4

### Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 86

Sample Area (Slabs): 16

71 FAULTING

L

3 Slabs

### Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 99

Sample Area (Slabs): 17

66 SMALL PATCH

L

1 Slabs

### Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 16

66 SMALL PATCH

L

1 Slabs

76 ASR

L

1 Slabs

### Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 92

Sample Area (Slabs): 16

66 SMALL PATCH

L

2 Slabs

76 ASR

L

1 Slabs

# RE-INSPECTION REPORT KNOXVILLE MUNICIPAL AIRPORT

Pavement Database: IA 2021

Generate Date: 4/27/2022

Network ID: OXV

Page 13

## Branch - Section ID: T03KN - 01

Branch Name: TAXIWAY 03

Use: TAXIWAY

LCD: 6/4/1991

PCI Family: IowaPCCTWSE\_General

Surface Type: PCC

Rank: P

Section Area (sf): 56,546.00

Length (ft): 1,600.00

Width (ft): 35.00

From: SW END OF T02KN-01

To: T01KN

Slabs: 385

Section Comments:

Slab Length (ft): 12.50

Slab Width (ft): 11.75

Joint Length (ft): 7,685.16

Last Insp Date: 11/12/2021

Inspection Comments:

PCI: 84

Total Samples: 16

Surveyed: 6

### Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 92

Sample Area (Slabs): 24

65 JT SEAL DMG

M

24 Slabs

74 JOINT SPALL

L

1 Slabs

### Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 90

Sample Area (Slabs): 24

65 JT SEAL DMG

M

24 Slabs

74 JOINT SPALL

L

1 Slabs

75 CORNER SPALL

L

1 Slabs

### Sample Number: 06

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 24

65 JT SEAL DMG

M

24 Slabs

### Sample Number: 08

Sample Type: R

Sample Comments:

Sample PCI: 81

Sample Area (Slabs): 24

62 CORNER BREAK

M

1 Slabs

63 LINEAR CR

M

1 Slabs

65 JT SEAL DMG

M

24 Slabs

### Sample Number: 12

Sample Type: R

Sample Comments:

Sample PCI: 66

Sample Area (Slabs): 24

63 LINEAR CR

L

1 Slabs

63 LINEAR CR

M

3 Slabs

65 JT SEAL DMG

M

24 Slabs

74 JOINT SPALL

M

1 Slabs

# RE-INSPECTION REPORT KNOXVILLE MUNICIPAL AIRPORT

Pavement Database: IA 2021

Generate Date: 4/27/2022

Network ID: OXV

Page 14

## Sample Number: 14

Sample Type: R

Sample Comments:

Sample PCI: 85

Sample Area (Slabs): 24

65 JT SEAL DMG

M

24 Slabs

75 CORNER SPALL

M

1 Slabs

76 ASR

L

1 Slabs



# RE-INSPECTION REPORT KNOXVILLE MUNICIPAL AIRPORT

Pavement Database: IA 2021

Generate Date: 4/27/2022

Network ID: OXV

Page 15

## Branch - Section ID: T03KN - 02

Branch Name: TAXIWAY 03

Use: TAXIWAY

LCD: 6/3/1994

PCI Family: IowaPCCTWSE\_General

Surface Type: PCC

Rank: P

Section Area (sf): 83,867.00

Length (ft): 2,400.00

Width (ft): 35.00

From: T01KN

To: T03KN

Slabs: 571

Section Comments:

Slab Length (ft): 12.50

Slab Width (ft): 11.75

Joint Length (ft): 11,415.83

Last Insp Date: 11/12/2021

Inspection Comments:

PCI: 88

Total Samples: 24

Surveyed: 7

### Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 84

Sample Area (Slabs): 24

|                 |   |          |
|-----------------|---|----------|
| 65 JT SEAL DMG  | M | 24 Slabs |
| 66 SMALL PATCH  | L | 3 Slabs  |
| 71 FAULTING     | L | 1 Slabs  |
| 75 CORNER SPALL | M | 1 Slabs  |

### Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 89

Sample Area (Slabs): 24

|                |   |          |
|----------------|---|----------|
| 65 JT SEAL DMG | M | 24 Slabs |
| 76 ASR         | L | 1 Slabs  |

### Sample Number: 10

Sample Type: R

Sample Comments:

Sample PCI: 83

Sample Area (Slabs): 24

|                |   |          |
|----------------|---|----------|
| 65 JT SEAL DMG | M | 24 Slabs |
| 76 ASR         | M | 1 Slabs  |

### Sample Number: 15

Sample Type: R

Sample Comments:

Sample PCI: 89

Sample Area (Slabs): 24

|                |   |          |
|----------------|---|----------|
| 65 JT SEAL DMG | M | 24 Slabs |
| 76 ASR         | L | 1 Slabs  |

### Sample Number: 17

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 24

|                |   |          |
|----------------|---|----------|
| 65 JT SEAL DMG | M | 24 Slabs |
|----------------|---|----------|

# RE-INSPECTION REPORT KNOXVILLE MUNICIPAL AIRPORT

Pavement Database: IA 2021

Generate Date: 4/27/2022

Network ID: OXV

Page 16

---

## Sample Number: 20

Sample Type: R

Sample Comments:

Sample PCI: 89

Sample Area (Slabs): 24

65 JT SEAL DMG

M

24 Slabs

71 FAULTING

L

1 Slabs

---

## Sample Number: 23

Sample Type: R

Sample Comments:

Sample PCI: 93

Sample Area (Slabs): 24

65 JT SEAL DMG

M

24 Slabs

# RE-INSPECTION REPORT KNOXVILLE MUNICIPAL AIRPORT

Pavement Database: IA 2021

Generate Date: 4/27/2022

Network ID: OXV

Page 17

## Branch - Section ID: T03KN - 03

Branch Name: TAXIWAY 03

Use: TAXIWAY

LCD: 6/30/1991 PCI Family: IowaPCCTWSE\_General  
 Surface Type: PCC  
 Rank: P  
 Section Area (sf): 5,570.00  
 Length (ft): 118.00  
 Width (ft): 35.00  
 From: R15KN-01  
 To: T03KN-03  
 Slabs: 47 Section Comments: avg slab width  
 Slab Length (ft): 11.80  
 Slab Width (ft): 10.10  
 Joint Length (ft): 817.17  
 Last Insp Date: 11/12/2021 Inspection Comments:  
 PCI: 82  
 Total Samples: 2  
 Surveyed: 2

### Sample Number: 01

Sample Type: R Sample Comments:  
 Sample PCI: 93  
 Sample Area (Slabs): 20  
 65 JT SEAL DMG M 20 Slabs

### Sample Number: 02

Sample Type: R Sample Comments:  
 Sample PCI: 73  
 Sample Area (Slabs): 27  
 64 DURABIL. CR L 4 Slabs  
 64 DURABIL. CR M 1 Slabs  
 65 JT SEAL DMG M 27 Slabs  
 67 LARGE PATCH L 2 Slabs  
 71 FAULTING L 1 Slabs

# RE-INSPECTION REPORT KNOXVILLE MUNICIPAL AIRPORT

Pavement Database: IA 2021

Generate Date: 4/27/2022

Network ID: OXV

Page 18

## Branch - Section ID: T03KN - 04

Branch Name: TAXIWAY 03

Use: TAXIWAY

LCD: 6/1/1991

PCI Family: IowaPCCTWSE\_General

Surface Type: PCC

Rank: P

Section Area (sf): 2,585.00

Length (ft): 50.00

Width (ft): 35.00

From: NORTH END OF R15KN-01

To: NORTH END OF T03KN-02

Slabs: 21

Section Comments: avg slab width

Slab Length (ft): 12.70

Slab Width (ft): 9.50

Joint Length (ft): 350.09

Last Insp Date: 11/12/2021

Inspection Comments:

PCI: 88

Total Samples: 1

Surveyed: 1

### Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 88

Sample Area (Slabs): 21

64 DURABIL. CR

L

2 Slabs

65 JT SEAL DMG

M

21 Slabs

# RE-INSPECTION REPORT KNOXVILLE MUNICIPAL AIRPORT

Pavement Database: IA 2021

Generate Date: 4/27/2022

Network ID: OXV

Page 19

## Branch - Section ID: T03KN - 05

Branch Name: TAXIWAY 03

Use: TAXIWAY

LCD: 3/3/2020

PCI Family: IowaPCCTWSE\_General

Surface Type: PCC

Rank: P

Section Area (sf): 7,323.00

Length (ft): 140.00

Width (ft): 35.00

From: NORTH END OF R15KN-01

To: NORTH END OF T03KN-04

Slabs: 89

Section Comments: avg slab width

Slab Length (ft): 10.00

Slab Width (ft): 8.20

Joint Length (ft): 1,363.81

Last Insp Date: 11/12/2021

Inspection Comments:

PCI: 100

Total Samples: 4

Surveyed: 3

### Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 20

NO DISTRESS

### Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 20

NO DISTRESS

### Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 100

Sample Area (Slabs): 29

NO DISTRESS

# RE-INSPECTION REPORT KNOXVILLE MUNICIPAL AIRPORT

Pavement Database: IA 2021

Generate Date: 4/27/2022

Network ID: OXV

Page 20

## Branch - Section ID: TH01KN - 01

Branch Name: T-HANGAR 01

Use: T-HANGAR

LCD: 1/1/1967

PCI Family: IowaPCCTH\_SE

Surface Type: PCC

Rank: P

Section Area (sf): 24,950.00

Length (ft): 1,010.00

Width (ft): 25.00

From: SEE MAP

To: SEE MAP

Slabs: 128

Section Comments: variable slabs

Slab Length (ft): 15.00

Slab Width (ft): 13.00

Joint Length (ft): 2,559.86

Last Insp Date: 11/12/2021

Inspection Comments:

PCI: 10

Total Samples: 6

Surveyed: 4

### Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 16

Sample Area (Slabs): 24

|                 |   |          |
|-----------------|---|----------|
| 62 CORNER BREAK | L | 1 Slabs  |
| 62 CORNER BREAK | M | 2 Slabs  |
| 63 LINEAR CR    | L | 1 Slabs  |
| 63 LINEAR CR    | L | 4 Slabs  |
| 65 JT SEAL DMG  | H | 24 Slabs |
| 74 JOINT SPALL  | M | 2 Slabs  |
| 74 JOINT SPALL  | M | 1 Slabs  |
| 76 ASR          | H | 7 Slabs  |
| 76 ASR          | L | 3 Slabs  |
| 76 ASR          | M | 4 Slabs  |

### Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 2

Sample Area (Slabs): 24

|                 |   |          |
|-----------------|---|----------|
| 62 CORNER BREAK | M | 2 Slabs  |
| 63 LINEAR CR    | L | 8 Slabs  |
| 63 LINEAR CR    | M | 8 Slabs  |
| 65 JT SEAL DMG  | H | 24 Slabs |
| 72 SHAT. SLAB   | H | 1 Slabs  |
| 74 JOINT SPALL  | M | 2 Slabs  |
| 76 ASR          | H | 10 Slabs |
| 76 ASR          | L | 4 Slabs  |
| 76 ASR          | M | 10 Slabs |

# RE-INSPECTION REPORT KNOXVILLE MUNICIPAL AIRPORT

Pavement Database: IA 2021

Generate Date: 4/27/2022

Network ID: OXV

Page 21

## Sample Number: 04

Sample Type: R

Sample Comments:

Sample PCI: 20

Sample Area (Slabs): 24

|                |   |          |
|----------------|---|----------|
| 63 LINEAR CR   | L | 2 Slabs  |
| 63 LINEAR CR   | M | 3 Slabs  |
| 65 JT SEAL DMG | M | 24 Slabs |
| 67 LARGE PATCH | L | 3 Slabs  |
| 74 JOINT SPALL | H | 1 Slabs  |
| 76 ASR         | H | 4 Slabs  |
| 76 ASR         | L | 2 Slabs  |
| 76 ASR         | M | 2 Slabs  |

## Sample Number: 05

Sample Type: R

Sample Comments:

Sample PCI: 0

Sample Area (Slabs): 15

|                 |   |          |
|-----------------|---|----------|
| 62 CORNER BREAK | M | 2 Slabs  |
| 63 LINEAR CR    | M | 9 Slabs  |
| 65 JT SEAL DMG  | H | 15 Slabs |
| 72 SHAT. SLAB   | M | 6 Slabs  |
| 74 JOINT SPALL  | M | 2 Slabs  |
| 76 ASR          | H | 3 Slabs  |
| 76 ASR          | L | 3 Slabs  |

# RE-INSPECTION REPORT KNOXVILLE MUNICIPAL AIRPORT

Pavement Database: IA 2021

Generate Date: 4/27/2022

Network ID: OXV

Page 22

## Branch - Section ID: TH01KN - 02

Branch Name: T-HANGAR 01

Use: T-HANGAR

LCD: 1/1/2016

PCI Family: IowaPCCTH\_SE

Surface Type: PCC

Rank: P

Section Area (sf): 15,227.00

Length (ft): 515.00

Width (ft): 30.00

From: SEE MAP

To: SEE MAP

Slabs: 85

Section Comments: avg slab length

Slab Length (ft): 12.00

Slab Width (ft): 15.00

Joint Length (ft): 1,746.92

Last Insp Date: 11/12/2021

Inspection Comments:

PCI: 89

Total Samples: 4

Surveyed: 3

### Sample Number: 01

Sample Type: R

Sample Comments:

Sample PCI: 82

Sample Area (Slabs): 20

62 CORNER BREAK

L

2 Slabs

63 LINEAR CR

L

1 Slabs

65 JT SEAL DMG

M

20 Slabs

### Sample Number: 02

Sample Type: R

Sample Comments:

Sample PCI: 87

Sample Area (Slabs): 20

63 LINEAR CR

L

3 Slabs

65 JT SEAL DMG

L

20 Slabs

### Sample Number: 03

Sample Type: R

Sample Comments:

Sample PCI: 98

Sample Area (Slabs): 20

65 JT SEAL DMG

L

20 Slabs



## **APPENDIX D**

### **WORK HISTORY REPORT**

## Network: KNOXVILLE MUNICIPAL AIRPORT

### Branch - Section ID:           A01KN - 01

LCD: 3/3/2015  
Use: APRON  
Rank: P  
Surface: PCC

Length (ft):                   250.00  
Width (ft):                   120.00  
True Area (sf):               30,703.00

| Work Date  | Work Code | Work Description              | Cost   | Thickness (in) | Major MR | Comments                          |
|------------|-----------|-------------------------------|--------|----------------|----------|-----------------------------------|
| 03-03-2015 | CR-PC     | Complete Reconstruction - PCC | \$0.00 | 6.00           | True     | 6" P505 PCC                       |
| 03-02-2015 | SB-AG     | Subbase - Aggregate           | \$0.00 | 6.00           | False    | 6" GRANULAR SUBBASE (IDOT 2111)   |
| 03-01-2015 | SG-ST     | Subgrade - Stabilized         | \$0.00 | 12.00          | False    | 12" P158 FLY ASH TREATED SUBGRADE |
| 06-01-2009 | PA-PP     | Patching - PCC Partial Depth  | \$0.00 | 0.00           | False    | EST                               |
| 06-01-2009 | SL-PC     | Slab Replacement - PCC        | \$0.00 | 0.00           | False    | EST                               |
| 06-01-1967 | NC-PC     | New Construction - PCC        | \$0.00 | 0.00           | True     | -                                 |

### Branch - Section ID:           A02KN - 01

LCD: 6/1/1991  
Use: APRON  
Rank: P  
Surface: PCC

Length (ft):                   120.00  
Width (ft):                   300.00  
True Area (sf):               37,012.00

| Work Date  | Work Code | Work Description       | Cost   | Thickness (in) | Major MR | Comments |
|------------|-----------|------------------------|--------|----------------|----------|----------|
| 10-01-2012 | JS-LC     | Joint Seal (Localized) | \$0.00 | 0.00           | False    | -        |
| 06-01-1991 | NC-PC     | New Construction - PCC | \$0.00 | 0.00           | True     | -        |

### Branch - Section ID:           A02KN - 02

LCD: 1/3/2012  
Use: APRON  
Rank: P  
Surface: PCC

Length (ft):                   130.00  
Width (ft):                   120.00  
True Area (sf):               16,055.00

| Work Date  | Work Code | Work Description       | Cost   | Thickness (in) | Major MR | Comments           |
|------------|-----------|------------------------|--------|----------------|----------|--------------------|
| 01-03-2012 | NC-PC     | New Construction - PCC | \$0.00 | 6.00           | True     | 6" P-505 SURFACE   |
| 01-02-2012 | SB-AG     | Subbase - Aggregate    | \$0.00 | 6.00           | False    | 6" SUBBASE         |
| 01-01-2012 | SG-ST     | Subgrade - Stabilized  | \$0.00 | 12.00          | False    | 12" P-158 SUBGRADE |

### Branch - Section ID:           R15KN - 01

LCD: 3/3/2020  
Use: RUNWAY  
Rank: P  
Surface: PCC

Length (ft):                   3,075.00  
Width (ft):                   75.00  
True Area (sf):               244,244.00

| Work Date  | Work Code | Work Description              | Cost        | Thickness (in) | Major MR | Comments                                   |
|------------|-----------|-------------------------------|-------------|----------------|----------|--|
| 03-03-2020 | CR-PC     | Complete Reconstruction - PCC | \$61,930.00 | 6.00           | True     | 6" PCC pavement                            |
| 03-02-2020 | BA-AG     | Base Course - Aggregate       | \$0.00      | 10.00          | False    | 10" recycled aggregate base course (P-219) |
| 03-01-2020 | SG-ST     | Subgrade - Stabilized         | \$0.00      | 12.00          | False    | 12" cement treated subgrade (P-157)        |
| 10-01-2012 | PA-AD     | Patching - AC Deep            | \$0.00      | 0.00           | False    | -  |
| 10-01-2012 | CS-AC     | Crack Sealing - AC            | \$0.00      | 0.00           | False    | -  |
| 06-01-2003 | OL-AC     | Overlay - AC                  | \$0.00      | 0.00           | True     | EST  |
| 06-03-1967 | NC-PC     | New Construction - PCC        | \$0.00      | 6.00           | True     | 6" P501 PCC (ASSUMED MAT. CODE)            |
| 06-02-1967 | SB-AG     | Subbase - Aggregate           | \$0.00      | 6.00           | False    | 6" P154 SUBBASE                            |
| 06-01-1967 | SG-CO     | Subgrade - Compacted          | \$0.00      | 6.00           | False    | 6" P152 COMPACTED SUBGRADE                 |

# Work History

Pavement Database: IA 2021

**Branch - Section ID: R15KN - 02**

LCD: 6/30/1990  
 Use: RUNWAY  
 Rank: P  
 Surface: PCC

Length (ft): 923.00  
 Width (ft): 75.00  
 True Area (sf): 69,339.00

| Work Date  | Work Code | Work Description             | Cost   | Thickness (in) | Major MR | Comments            |
|------------|-----------|------------------------------|--------|----------------|----------|---------------------|
| 03-02-2020 | JS-LC     | Joint Seal (Localized)       | \$0.00 | 0.00           | False    | PCC joint seal      |
| 03-01-2020 | PA-PP     | Patching - PCC Partial Depth | \$0.00 | 0.00           | False    | Partial depth patch |
| 10-01-2012 | GR-PP     | Grinding (Localized)         | \$0.00 | 0.00           | False    | -                   |
| 10-01-2012 | JS-LC     | Joint Seal (Localized)       | \$0.00 | 0.00           | False    | -                   |
| 06-30-1990 | NC-PC     | New Construction - PCC       | \$0.00 | 0.00           | True     | -                   |

**Branch - Section ID: T01KN - 01**

LCD: 3/3/2015  
 Use: TAXIWAY  
 Rank: P  
 Surface: PCC

Length (ft): 705.00  
 Width (ft): 35.00  
 True Area (sf): 26,202.00

| Work Date  | Work Code | Work Description              | Cost   | Thickness (in) | Major MR | Comments                          |
|------------|-----------|-------------------------------|--------|----------------|----------|-----------------------------------|
| 03-03-2015 | CR-PC     | Complete Reconstruction - PCC | \$0.00 | 6.00           | True     | 6" P505 PCC                       |
| 03-02-2015 | SB-AG     | Subbase - Aggregate           | \$0.00 | 6.00           | False    | 6" GRANULAR SUBBASE (IDOT 2111)   |
| 03-01-2015 | SG-ST     | Subgrade - Stabilized         | \$0.00 | 12.00          | False    | 12" P158 FLY ASH TREATED SUBGRADE |
| 06-01-2009 | PA-PP     | Patching - PCC Partial Depth  | \$0.00 | 0.00           | False    | EST                               |
| 06-01-2009 | SL-PC     | Slab Replacement - PCC        | \$0.00 | 0.00           | False    | EST                               |
| 06-01-1967 | NC-PC     | New Construction - PCC        | \$0.00 | 0.00           | True     | -                                 |

**Branch - Section ID: T02KN - 01**

LCD: 6/30/1990  
 Use: TAXIWAY  
 Rank: P  
 Surface: PCC

Length (ft): 350.00  
 Width (ft): 45.83  
 True Area (sf): 12,433.00

| Work Date  | Work Code | Work Description             | Cost   | Thickness (in) | Major MR | Comments            |
|------------|-----------|------------------------------|--------|----------------|----------|---------------------|
| 03-02-2020 | PA-PP     | Patching - PCC Partial Depth | \$0.00 | 0.00           | False    | Partial depth patch |
| 03-02-2020 | CS-PC     | Crack Sealing - PCC          | \$0.00 | 0.00           | False    | -                   |
| 03-01-2020 | JS-LC     | Joint Seal (Localized)       | \$0.00 | 0.00           | False    | -                   |
| 10-01-2012 | JS-LC     | Joint Seal (Localized)       | \$0.00 | 0.00           | False    | -                   |
| 06-30-1990 | NC-PC     | New Construction - PCC       | \$0.00 | 0.00           | True     | -                   |

**Branch - Section ID: T03KN - 01**

LCD: 6/4/1991  
 Use: TAXIWAY  
 Rank: P  
 Surface: PCC

Length (ft): 1,600.00  
 Width (ft): 35.00  
 True Area (sf): 56,546.00

| Work Date  | Work Code | Work Description       | Cost   | Thickness (in) | Major MR | Comments                         |
|------------|-----------|------------------------|--------|----------------|----------|----------------------------------|
| 10-01-2012 | JS-LC     | Joint Seal (Localized) | \$0.00 | 0.00           | False    | -                                |
| 06-04-1991 | NC-PC     | New Construction - PCC | \$0.00 | 6.00           | True     | 6" P501 PCC                      |
| 06-03-1991 | SB-AG     | Subbase - Aggregate    | \$0.00 | 6.00           | False    | 6" P154 SUBBASE                  |
| 06-02-1991 | SG-ST     | Subgrade - Stabilized  | \$0.00 | 6.00           | False    | 6" P155 FLY ASH TREATED SUBGRADE |
| 06-01-1991 | SG-CO     | Subgrade - Compacted   | \$0.00 | 6.00           | False    | 6" P152 COMPACTED SUBGRADE       |

# Work History

Pavement Database: IA 2021

**Branch - Section ID: T03KN - 02**

LCD: 6/3/1994  
 Use: TAXIWAY  
 Rank: P  
 Surface: PCC

Length (ft): 2,400.00  
 Width (ft): 35.00  
 True Area (sf): 83,867.00

| Work Date  | Work Code | Work Description       | Cost   | Thickness (in) | Major MR | Comments                            |
|------------|-----------|------------------------|--------|----------------|----------|-------------------------------------|
| 10-01-2012 | JS-LC     | Joint Seal (Localized) | \$0.00 | 0.00           | False    | -                                   |
| 06-03-1994 | NC-PC     | New Construction - PCC | \$0.00 | 6.00           | True     | 6" P501 PCC SURFACE                 |
| 06-02-1994 | SB-AG     | Subbase - Aggregate    | \$0.00 | 6.00           | False    | 6" P154 SUBBASE                     |
| 06-01-1994 | SG-ST     | Subgrade - Stabilized  | \$0.00 | 6.00           | False    | 6" P155 SUBRADE                     |
| 05-31-1994 | SG-CO     | Subgrade - Compacted   | \$0.00 | 6.00           | False    | 6" P152 SUBGRADE COMPACTED SUBGRADE |

**Branch - Section ID: T03KN - 03**

LCD: 6/30/1991  
 Use: TAXIWAY  
 Rank: P  
 Surface: PCC

Length (ft): 118.00  
 Width (ft): 35.00  
 True Area (sf): 5,570.00

| Work Date  | Work Code | Work Description       | Cost   | Thickness (in) | Major MR | Comments |
|------------|-----------|------------------------|--------|----------------|----------|----------|
| 10-01-2012 | JS-LC     | Joint Seal (Localized) | \$0.00 | 0.00           | False    | -        |
| 06-30-1991 | NC-PC     | New Construction - PCC | \$0.00 | 0.00           | True     | -        |

**Branch - Section ID: T03KN - 04**

LCD: 6/1/1991  
 Use: TAXIWAY  
 Rank: P  
 Surface: PCC

Length (ft): 50.00  
 Width (ft): 35.00  
 True Area (sf): 2,585.00

| Work Date  | Work Code | Work Description       | Cost   | Thickness (in) | Major MR | Comments |
|------------|-----------|------------------------|--------|----------------|----------|----------|
| 10-01-2012 | JS-LC     | Joint Seal (Localized) | \$0.00 | 0.00           | False    | -        |
| 06-01-1991 | NC-PC     | New Construction - PCC | \$0.00 | 0.00           | True     | -        |

**Branch - Section ID: T03KN - 05**

LCD: 3/3/2020  
 Use: TAXIWAY  
 Rank: P  
 Surface: PCC

Length (ft): 140.00  
 Width (ft): 35.00  
 True Area (sf): 7,323.00

| Work Date  | Work Code | Work Description              | Cost        | Thickness (in) | Major MR | Comments                                   |
|------------|-----------|-------------------------------|-------------|----------------|----------|--|
| 03-03-2020 | CR-PC     | Complete Reconstruction - PCC | \$61,930.00 | 6.00           | True     | 6" PCC pavement                            |
| 03-02-2020 | BA-AG     | Base Course - Aggregate       | \$0.00      | 10.00          | False    | 10" recycled aggregate base course (P-219) |
| 03-01-2020 | SG-ST     | Subgrade - Stabilized         | \$0.00      | 12.00          | False    | 12" cement treated subgrade (P-157)        |
| 10-01-2012 | JS-LC     | Joint Seal (Localized)        | \$0.00      | 0.00           | False    | -  |
| 06-01-1991 | NC-PC     | New Construction - PCC        | \$0.00      | 0.00           | True     | -  |

# Work History

Pavement Database: IA 2021

**Branch - Section ID: TH01KN - 01**

LCD: 1/1/1967  
 Use: T-HANGAR  
 Rank: P  
 Surface: PCC

Length (ft): 1,010.00  
 Width (ft): 25.00  
 True Area (sf): 24,950.00

| Work Date  | Work Code | Work Description       | Cost   | Thickness (in) | Major MR | Comments |
|------------|-----------|------------------------|--------|----------------|----------|----------|
| 01-01-1967 | NC-PC     | New Construction - PCC | \$0.00 | 0.00           | True     | UNKNOWN  |

**Branch - Section ID: TH01KN - 02**

LCD: 1/1/2016  
 Use: T-HANGAR  
 Rank: P  
 Surface: PCC

Length (ft): 515.00  
 Width (ft): 30.00  
 True Area (sf): 15,227.00

| Work Date  | Work Code | Work Description              | Cost   | Thickness (in) | Major MR | Comments         |
|------------|-----------|-------------------------------|--------|----------------|----------|------------------|
| 01-01-2016 | CR-PC     | Complete Reconstruction - PCC | \$0.00 | 0.00           | True     | PER GOOGLE EARTH |
| 06-01-2009 | PA-PP     | Patching - PCC Partial Depth  | \$0.00 | 0.00           | False    | EST              |
| 06-01-2009 | SL-PC     | Slab Replacement - PCC        | \$0.00 | 0.00           | False    | EST              |
| 06-01-1967 | NC-PC     | New Construction - PCC        | \$0.00 | 0.00           | True     | -                |

## **APPENDIX E**

### **LOCALIZED PREVENTIVE MAINTENANCE POLICIES AND UNIT COST TABLES**

Table E-1. Localized preventive maintenance policy, asphalt-surfaced pavements.

| <b>Distress Type</b>      | <b>Severity Level</b> | <b>Maintenance Action</b> |
|---------------------------|-----------------------|---------------------------|
| Alligator Cracking        | Low                   | Monitor                   |
| Alligator Cracking        | Medium                | Asphalt Patch             |
| Alligator Cracking        | High                  | Asphalt Patch             |
| Bleeding                  | N/A                   | Monitor                   |
| Block Cracking            | Low                   | Monitor                   |
| Block Cracking            | Medium                | Crack Seal—Asphalt        |
| Block Cracking            | High                  | Crack Seal—Asphalt        |
| Corrugation               | Low                   | Monitor                   |
| Corrugation               | Medium                | Asphalt Patch             |
| Corrugation               | High                  | Asphalt Patch             |
| Depression                | Low                   | Monitor                   |
| Depression                | Medium                | Monitor                   |
| Depression                | High                  | Asphalt Patch             |
| Jet-Blast Erosion         | N/A                   | Asphalt Patch             |
| Joint Reflection Cracking | Low                   | Monitor                   |
| Joint Reflection Cracking | Medium                | Crack Seal—Asphalt        |
| Joint Reflection Cracking | High                  | Crack Seal—Asphalt        |
| L&T Cracking              | Low                   | Monitor                   |
| L&T Cracking              | Medium                | Crack Seal—Asphalt        |
| L&T Cracking              | High                  | Crack Seal—Asphalt        |
| Oil Spillage              | N/A                   | Asphalt Patch             |
| Patching                  | Low                   | Monitor                   |
| Patching                  | Medium                | Asphalt Patch             |
| Patching                  | High                  | Asphalt Patch             |
| Polished Aggregate        | N/A                   | Monitor                   |
| Raveling                  | Low                   | Monitor                   |
| Raveling                  | Medium                | Asphalt Patch             |
| Raveling                  | High                  | Asphalt Patch             |
| Rutting                   | Low                   | Monitor                   |
| Rutting                   | Medium                | Monitor                   |
| Rutting                   | High                  | Asphalt Patch             |
| Shoving                   | Low                   | Monitor                   |
| Shoving                   | Medium                | Asphalt Patch             |
| Shoving                   | High                  | Asphalt Patch             |
| Slippage Cracking         | N/A                   | Asphalt Patch             |
| Swelling                  | Low                   | Monitor                   |
| Swelling                  | Medium                | Monitor                   |
| Swelling                  | High                  | Asphalt Patch             |
| Weathering                | Low                   | Monitor                   |
| Weathering                | Medium                | Monitor                   |
| Weathering                | High                  | Asphalt Patch             |

Table E-2. Localized preventive maintenance policy, PCC pavements.

| <b>Distress Type</b>        | <b>Severity Level</b> | <b>Maintenance Action</b> |
|-----------------------------|-----------------------|---------------------------|
| ASR                         | Low                   | Monitor                   |
| ASR                         | Medium                | Slab Replacement          |
| ASR                         | High                  | Slab Replacement          |
| Blowup                      | Low                   | Slab Replacement          |
| Blowup                      | Medium                | Slab Replacement          |
| Blowup                      | High                  | Slab Replacement          |
| Corner Break                | Low                   | Crack Seal—PCC            |
| Corner Break                | Medium                | Full Depth PCC Patch      |
| Corner Break                | High                  | Full Depth PCC Patch      |
| Durability Cracking         | Low                   | Monitor                   |
| Durability Cracking         | Medium                | Full Depth Patch          |
| Durability Cracking         | High                  | Slab Replacement          |
| Faulting                    | Low                   | Monitor                   |
| Faulting                    | Medium                | Grinding                  |
| Faulting                    | High                  | Slab Replacement          |
| Joint Seal Damage           | Low                   | Monitor                   |
| Joint Seal Damage           | Medium                | Joint Seal                |
| Joint Seal Damage           | High                  | Joint Seal                |
| LTD Cracking                | Low                   | Monitor                   |
| LTD Cracking                | Medium                | Crack Seal—PCC            |
| LTD Cracking                | High                  | Slab Replacement          |
| Patching (Small and Large)  | Low                   | Monitor                   |
| Patching (Small and Large)  | Medium                | Full Depth PCC Patch      |
| Patching (Small and Large)  | High                  | Full Depth PCC Patch      |
| Popouts                     | N/A                   | Monitor                   |
| Pumping                     | N/A                   | Monitor                   |
| Scaling                     | Low                   | Monitor                   |
| Scaling                     | Medium                | Partial Depth PCC Patch   |
| Scaling                     | High                  | Slab Replacement          |
| Shattered Slab              | Low                   | Crack Seal—PCC            |
| Shattered Slab              | Medium                | Slab Replacement          |
| Shattered Slab              | High                  | Slab Replacement          |
| Shrinkage Cracking          | N/A                   | Monitor                   |
| Spalling (Joint and Corner) | Low                   | Monitor                   |
| Spalling (Joint and Corner) | Medium                | Partial Depth PCC Patch   |
| Spalling (Joint and Corner) | High                  | Partial Depth PCC Patch   |



Table E-3. 2022 unit costs for preventive maintenance actions.

| Maintenance Action                      | Unit Cost  |
|---|------------|
| Asphalt Patch—Asphalt-Surfaced Pavement | \$14.66/sf |
| Crack Sealing—Asphalt-Surfaced Pavement | \$2.51/lf  |
| Partial Depth PCC Patch—PCC Pavement    | \$37.54/sf |
| Full Depth PCC Patch—PCC Pavement       | \$16.76/sf |
| Crack Sealing—PCC Pavement              | \$3.02/lf  |
| Joint Sealing—PCC Pavement              | \$3.02/lf  |
| Grinding—PCC Pavement                   | \$0.36/sf  |
| Slab Replacement—PCC Pavement           | \$16.76/sf |

Table E-4. 2022 unit costs (per square foot) based on pavement type and PCI ranges.

| Pavement Type | PCI Range 0–40 | PCI Range 40–50 | PCI Range 50–60 | PCI Range 60–70 | PCI Range 70–80 | PCI Range 80–90 | PCI Range 90–100 |
|---------------|----------------|-----------------|-----------------|-----------------|-----------------|-----------------|------------------|
| AC            | \$10.41        | \$4.93          | \$4.93          | \$4.93          | \$0.00          | \$0.00          | \$0.00           |
| PCC           | \$17.38        | \$8.22          | \$8.22          | \$8.22          | \$0.00          | \$0.00          | \$0.00           |

## **APPENDIX F**

# **YEAR 2022 LOCALIZED PREVENTIVE MAINTENANCE DETAILS**

Table F-1. Year 2022 localized preventive maintenance details.

| Branch | Section | Distress Type       | Severity | Distress Quantity | Distress Unit | Maintenance Action           | Unit Cost | 2022 Estimated Cost |
|--------|---------|---------------------|----------|-------------------|---------------|------------------------------|-----------|---------------------|
| A02KN  | 01      | Joint Seal Damage   | Medium   | 261               | Slabs         | Joint Seal (Localized)       | \$3.02    | \$17,483            |
| A02KN  | 01      | Joint Spalling      | Medium   | 4                 | Slabs         | Patching - PCC Partial Depth | \$37.54   | \$867               |
| A02KN  | 02      | Corner Break        | Low      | 3                 | Slabs         | Crack Sealing - PCC          | \$3.02    | \$63                |
| A02KN  | 02      | Joint Seal Damage   | Medium   | 25                | Slabs         | Joint Seal (Localized)       | \$3.02    | \$1,657             |
| A02KN  | 02      | LTD Cracking        | Medium   | 4                 | Slabs         | Crack Sealing - PCC          | \$3.02    | \$137               |
| A02KN  | 02      | Shattered Slab      | Low      | 1                 | Slabs         | Crack Sealing - PCC          | \$3.02    | \$91                |
| R15KN  | 02      | Corner Spalling     | Medium   | 11                | Slabs         | Patching - PCC Partial Depth | \$37.54   | \$1,068             |
| R15KN  | 02      | Joint Spalling      | Medium   | 3                 | Slabs         | Patching - PCC Partial Depth | \$37.54   | \$641               |
| T01KN  | 01      | Joint Spalling      | Medium   | 2                 | Slabs         | Patching - PCC Partial Depth | \$37.54   | \$466               |
| T03KN  | 01      | Corner Break        | Medium   | 3                 | Slabs         | Patching - PCC Full Depth    | \$16.76   | \$1,447             |
| T03KN  | 01      | Corner Spalling     | Medium   | 3                 | Slabs         | Patching - PCC Partial Depth | \$37.54   | \$270               |
| T03KN  | 01      | Joint Seal Damage   | Medium   | 385               | Slabs         | Joint Seal (Localized)       | \$3.02    | \$23,209            |
| T03KN  | 01      | Joint Spalling      | Medium   | 3                 | Slabs         | Patching - PCC Partial Depth | \$37.54   | \$648               |
| T03KN  | 01      | LTD Cracking        | Medium   | 11                | Slabs         | Crack Sealing - PCC          | \$3.02    | \$392               |
| T03KN  | 02      | ASR                 | Medium   | 3                 | Slabs         | Slab Replacement - PCC       | \$16.76   | \$8,367             |
| T03KN  | 02      | Corner Spalling     | Medium   | 3                 | Slabs         | Patching - PCC Partial Depth | \$37.54   | \$343               |
| T03KN  | 02      | Joint Seal Damage   | Medium   | 571               | Slabs         | Joint Seal (Localized)       | \$3.02    | \$34,476            |
| T03KN  | 03      | Durability Cracking | Medium   | 1                 | Slabs         | Patching - PCC Full Depth    | \$16.76   | \$694               |

Table F-1. Year 2022 localized preventive maintenance details (continued).

| Branch | Section | Distress Type     | Severity | Distress Quantity | Distress Unit | Maintenance Action     | Unit Cost | 2022 Estimated Cost |
|--------|---------|-------------------|----------|-------------------|---------------|------------------------|-----------|---------------------|
| T03KN  | 03      | Joint Seal Damage | Medium   | 47                | Slabs         | Joint Seal (Localized) | \$3.02    | \$2,468             |
| T03KN  | 04      | Joint Seal Damage | Medium   | 21                | Slabs         | Joint Seal (Localized) | \$3.02    | \$1,057             |
| TH01KN | 02      | Corner Break      | Low      | 3                 | Slabs         | Crack Sealing - PCC    | \$3.02    | \$70                |
| TH01KN | 02      | Joint Seal Damage | Medium   | 28                | Slabs         | Joint Seal (Localized) | \$3.02    | \$1,759             |

## Table Notes:

1. See Figure 3 for the location of the branch and section.
2. Distress types are defined by ASTM D5340-20. L&T Cracking = Longitudinal and Transverse Cracking; LTD Cracking = Longitudinal, Transverse, and Diagonal Cracking; ASR = Alkali-Silica Reaction.
3. The costs provided are of a general nature for the entire state and may require adjustment to reflect specific conditions at Knoxville Municipal Airport.



**PREPARED FOR**

Iowa Department of Transportation  
Modal Transportation Bureau — Aviation  
800 Lincoln Way  
Ames, Iowa 50010  
515-239-1691  
[iowadot.gov/aviation](http://iowadot.gov/aviation)

**JULY 2022**