

SPECIAL PROVISIONS FOR ASBESTOS ABATEMENT

Johnson County HDP-3715(652)--71-52

Effective Date April 19, 2016

THE STANDARD SPECIFICATIONS, SERIES 2015, ARE AMENDED BY THE FOLLOWING MODIFICATIONS AND ADDITIONS. THESE ARE SPECIAL PROVISIONS AND THEY SHALL PREVAIL OVER THOSE PUBLISHED IN THE STANDARD SPECIFICATIONS.

156041.01 DESCRIPTION

Removal, transport, and disposal of asbestos containing materials for structures scheduled for demolition. Work shall be completed in accordance with Environmental Protection Agency (EPA) 40 Code of Federal Regulations (CFR) 61 Subparts A and M, National Emissions Standards for Hazardous Air Pollutants (NESHAP); applicable Office of Safety and Health Administration (OSHA) regulations under 29 CFR 1910 (general industry) and 1926 (construction); and all federal, state and local regulations as applicable. The work will be detailed in the contract documents.

156041.02 QUALIFICATIONS AND IDENTIFICATION OF WORK

A. Qualifications

- 1. The Abatement Contractor shall have an adequate number of qualified personnel available for the project. The work shall be performed by qualified, trained and lowa-licensed asbestos abatement workers and and/or lowa-licensed abatement contractor/supervisors, in accordance with lowa 875, Chapter 155. One lowa-licensed abatement contractor/supervisor shall be dedicated for the duration of the project.
- 2. The Contractor shall carry liability insurance for asbestos abatement work.
- **3.** Contractors shall not have been cited or been a defending party of any legal action for violation of asbestos regulations during the last 3 years.

B. Identification of Work

- 1. The Contracting Authority will have inspected structures for the presence of asbestos. Accessible, suspect materials will have been sampled and tested. Terracon's Asbestos and Hazardous Materials Survey Report Revised dated December 8, 2015 (72 pages) is included to this Special Provisions for Asbestos Abatement.
- **2.** Access to the structures by prospective bidders will be allowed. Arrangements for access will be made by the Contracting Authority, on request.
- **3.** The Contracting Authority assumes no responsibility for the condition of the existing buildings and structures.
- **4.** Inspect the site(s) identified in the contract documents from which asbestos is to be removed prior to submittal of a bid.
- 5. The Contractor will furnish all labor, supervision, materials, services, insurance, equipment, lighting/power, necessary for the removal of asbestos-containing materials (ACM) and the other regulated/hazardous materials listed in the documents herein.
- 6 The Contractor acknowledges that they have investigated and satisfied themselves as to:
 - The conditions affecting the work, including, but not limited to, physical conditions of the site which may bear upon site access, handling and storage of tools and materials, access to water, electric or other utilities or otherwise affect performance of required activities.
 - The character and quantity of all surfaces and subsurface materials or obstacles to be
 encountered in so far as this information is reasonably ascertainable from an inspection of
 the site, exploratory work done by the Contracting Authority, or designated consultants
 and information presented herein.
 - The environmental condition, including the presence, location, and condition of asbestoscontaining materials (ACM) and other regulated/hazardous materials at the site. Any failure by the Contractor to acquaint themselves with available information will not relieve them from the responsibility for estimating properly the difficulty or cost of successfully performing the work.
- 7. Under no circumstances shall the Contractor rely on the material quantities indicated in this contract documents as the total basis for the bid price. All quantities indicated are approximate and intended to alert the Contractor to the general scope of the project. Scheduled quantities refer only to materials the Contractor may expect to encounter and are used to generate a lump-sum price from the Contractors. The Contractor is required to perform abatement from the areas indicated on the Survey Report Exhibits. No increase in contract cost will be considered due to the Contractor's failure to physically verify all quantities of the ACM specified for removal.

- **8.** The Contracting Authority is not responsible for any conclusions or interpretations made by the Contractor on the basis of the information made available by the Contracting Authority or their representatives.
- 9. Furnish, install, and maintain critical barriers, where required, during the contract period.

156041.03 SUBMITTALS AND CONTRACTOR DOCUMENTATION

A. Submittals

- **1.** Prior to commencement of the work, the Contractor shall present, in writing, to the Engineer, the following:
 - Copies of the Contractor's required permits, licenses, and insurance.
 - Copies of abatement worker licenses, certificates, medical determination, and respirator fit testing documentation for each employee assigned to the project.
 - A plan for preparation of the work site.
 - Description of protective clothing and approved respirators to be used.
 - Delineation of responsibility of work site supervision including a listing of emergency home telephone numbers.
 - Explanation of regulated area containment and isolation techniques
 - Brief description of removal methods to be used and equipment to be utilized.
 - Description of the final clean-up procedures to be used.
 - Explanation of the handling of ACM and asbestos-contaminated waste, and hazardous waste and the disposal site(s) to be utilized.
 - Written negative exposure assessment for a similar project, if available.
- **2.** In-progress abatement submittals:
 - Laboratory results as indicated in Article 156041.05.
- 3. Submittals at completion of abatement:
 - The Contractor shall submit a project report consisting (at a minimum) of the daily logbook and the documentation of events during abatement including Contractor's Request for Final Visual Inspection Forms, personal air monitoring data, and the disposal manifests signed by the operator of the licensed landfill or disposal facility.

B. Contractor Documentation

- 1. The Contractor shall have the following items available for review on the site:
 - · A copy of the Health and Safety Plan
 - A copy of the Respiratory Protection Plan
 - A copy of the Hazard Communication Program
 - Standard Operating Procedures
 - Glove-bag Instructions, if Glove-bags are to be utilized on the project.

156041.04 ABATEMENT

A. Notification

- 1. The Contractor shall send written notification, as required by EPA NESHAP asbestos regulations (40 CFR 61 Subpart M) and the IAC, to the Iowa Department of Natural Resources (IDNR) and the Iowa Division of Labor Services (IDLS) at least 10 working days prior to beginning work on abatement of asbestos-containing materials. In addition, obtain all necessary authorizations for the work. Provide copies of all notification and authorization information to the Engineer prior to starting work.
- 2. Specific reporting, authorization, and notification requirements may be specified in the contract documents.

B. Removal

- Remove, transport, and dispose of all asbestos specified in the contract documents.
 Perform this work in compliance with current applicable local laws, rules, regulations, and
 ordinances and requirements of the U.S. EPA, OSHA, the lowa DNR, and the lowa
 Workforce Development.
- 2. Comply with current EPA, State, and Federal regulations. At all times, take necessary precautions and provide necessary equipment to all persons employed on the project. The Contractor is expected to be fully knowledgeable of these requirements.
- 3. Provide workers licensed and trained in asbestos abatement according to Iowa 875, Chapter 155. All Class I and II Work (as defined by OSHA), including installation and operation shall be supervised by a competent person as defined in 29 CFR 1926.1101.
- 4. The Contractor shall establish and demarcate regulated areas where Class I, Class II, and Class III asbestos work occur. In addition, this may include any other adjoining area where debris and waste from such asbestos work may accumulate. The Contractor shall provide warning signs at each approach to the regulated areas per OSHA requirements.
- 5. The Contractor shall be responsible for preparing the entire work area for asbestos removal. This includes preliminary work area preparation, work area isolation, and worker decontamination systems.
- **6.** Use amended water for wetting of asbestos-containing materials (ACM) prior to removal.
- 7. The Contractor is responsible for providing all materials and equipment for worker decontamination. Although not required on Class II outdoor work, a personal decontamination facility (shower) outside the work area where persons will enter or exit the work area is recommended.
- **8.** Salvage will not be permitted.

9. To the extent feasible, the asbestos material shall be removed in an intact state. Some of the asbestos may not be friable. It may be possible to remove and dispose of this material in a manner to maintain its non-friable condition.

C. Safety Rules

1. The Contractor is solely responsible for enforcement of the safety rules for employees and any person the Contractor authorizes for entry into the work area. The Engineer will have a right of entry to the work area, and they will comply with the Contractor's safety rules.

156041.05 MONITORING

A. General

- 1. Throughout abatement work, the Contractor shall perform monitoring, inspection, and testing inside the work area in accordance with OSHA requirements. The competent person shall periodically inspect and oversee the performance of the Contractor's workers. The competent person shall continuously inspect and monitor conditions inside the work area to ensure compliance with applicable regulations. In addition, the competent person shall personally manage air sample collection, analysis, and evaluation of personnel samples to satisfy OSHA requirements. The competent person is responsible for managing all personnel monitoring, inspecting, and testing required by these specifications, the OSHA regulation 29 CFR 1926.1101, and for continuous monitoring of all sub-systems and procedures affecting the safety of the Contractor's employees. Safety of the Contractor's employees and providing safe conditions inside and outside the work area shall be the primary concern of the competent person.
 - Personal air samples shall be collected from the breathing zone of a minimum of 20% of the workers performing asbestos removal. Full shift, 8-hour time-weighted average (TWA) and 30-minute excursion samples shall be collected, daily.
 - The sampling volume shall be 240 to 1,200 liters, with a flow rate of 0.5 to 2.5 liters per minute.
 - Results of the OSHA personal air samples must be posted at the jobsite (typically, inside the clean room, if present) within 24 hours of sample collection.

B. Analytical Results

- Analysis shall be completed in accordance with the NIOSH Manual of Analytical Methods, Method 7400 Asbestos Fibers by PCM, A counting rules
- 2. The analytical laboratory used by the Contractor to analyze the samples shall participate in the NIOSH asbestos proficiency analytical testing (PAT) rounds as administered by the AIHA® Laboratory Accreditation Programs, LLC under the Industrial Hygiene Laboratory Accreditation Program (IHLAP), at a minimum.

- **3.** Keep a daily log of personal samples taken and analyzed and make such log available to the Engineer. The daily log for personnel shall contain:
 - information on the person sampled,
 - the date of sample collection,
 - the time of sample start and finish,
 - flow rate,
 - sample volume,
 - and results in f/cc.
- **4.** Provide the Engineer with test results including the chain-of-custody for all air monitoring events within 24 hours after the sampling has been completed.

156041.06 CLEARANCE

A. General

- Contractor shall notify Engineer in advance for the performance of the final visual clearance inspection. The final visual inspection will be performed by the Contracting Authority's representatives at the conclusion of the first cleaning.
- 2. Final inspection will include the entire work area, platforms, barges, or other equipment utilized during the removal process, the personnel decontamination facilities, if utilized, and all plastic sheeting. If any debris, residue on surfaces, dust, or other matter is detected, cleaning shall be repeated. Bulk/dust sampling or air sampling in accordance with NIOSH 7400 may be completed and analyzed to confirm visual findings. If significant quantities, as determined by the Contracting Authorities' Representative, are found, then the entire area affected shall be decontaminated as specified previously.

156041.07 DISPOSAL

A. Waste Removal

- 1. The Contractor is responsible for all waste removal and decontamination systems. In addition, the Contractor is responsible for keeping the material adequately wet during the entire operation from initial bagging through waste disposal.
- **2.** All asbestos waste shall be stored, transported, and disposed of as per, but not limited to, the following regulations:
 - All applicable federal, state, and local statutes.
 - EPA Asbestos NESHAP 40 CFR 61.
 - EPA Asbestos Waste Management Guidance EPA-530-SW-85-007.
 - US DOT 49 CFR 171-180.
 - Transporters or Haulers
- **3.** The following general procedures apply:

- The Contractor shall place caution labels on the containers in accordance with OSHA regulation 29 CFR 1926.1101.
 - o These caution labels shall be clearly visible and shall contain the following statements:

DANGER
CONTAINS ASBESTOS FIBERS
MAY CAUSE CANCER
CAUSES DAMAGE TO LUNGS
DO NOT BREATHE DUST
AVOID CREATING DUST

4. As required by US DOT, warning labels on bags or waste containers shall contain the following statements:

Asbestos NA2212

<u>Generator's Name and Location</u>,
and a Class 9 Label.

- 5. As required by EPA 40 CFR 61 NESHAP, each individual waste container shall be tagged with the name or EPA identification number of the waste generator and the location at which the waste was generated.
- **6.** The Contractor's transporter and disposal site shall be approved by the Contracting Authority. It is requested that the Contractor utilize the lowa City Landfill, when feasible.

B. Waste Containers and Transporters

- 1. Containers shall be placed at locations designated by the Contracting Authority or Engineer.
- 2. The asbestos waste hauling containers shall be plasticized and sealed with a minimum of one layer of 6-mil polyethylene on the sides and two layers of 6-mil polyethylene on the floors.
- **3.** The Contractor shall have the transporter give the dates and times of arrival at the disposal site.
- **4.** The transporter shall inspect all the transport containers with the Contractor prior to taking possession and signing the asbestos waste manifest. The transporter shall not have any off-site transfers or combine this asbestos waste with any other site's asbestos materials.
- **5.** The waste transport container (truck, dumpster) must have the Class 9 placard with the asbestos ID number NA2212.

C. Waste Disposal Manifest

- 1. An asbestos waste manifest as provided for under NESHAP and/or individual states shall be provided by the Contractor and is the only manifest to be utilized.
- 2. The Contractor shall complete the manifest and verify that all information and amounts are accurate and that the proper signatures are in place.
- **3.** The manifest shall have the signatures of the Contractor and the transporter prior to any waste being removed from the work site.
- **4.** The manifest shall be signed by the disposal facility or operator to certify receipt of the asbestos-containing materials covered by the manifest.
- **5.** An original copy of the completed manifest shall be returned to the Contracting Authority and their representatives by the Contractor within 30 days of removal from the site.

156041.08 METHOD OF MEASUREMENT

A. Measurement for the removal of asbestos will be on a Lump Sum basis.

156041.09 BASIS OF PAYMENT

- **A.** Payment for Removal of Asbestos identified in the contract documents will be the lump sum contract price.
- **B.** Payment is full compensation for:
 - Removal of asbestos, transporting asbestos, and disposal of asbestos at an approved disposal site, and
 - The cost of all labor, monitoring, materials, equipment, permits, disposal fees, and preparation of and filing reports, notifications, and records.
- **C.** Adjustment of contract price for Removal of Asbestos which is identified in the contract documents will not be allowed should any buildings or structures from which asbestos is to be removed be altered or damaged by others during the period of time between inspection by bidders and asbestos removal.
- **D.** Partial payments may be paid as the work progresses, as authorized by the Engineer.
- **E.** Should asbestos be discovered, in addition to that identified in the contract documents, removal of the additional asbestos will be paid for as extra work according to Article 1109.03, B of the Standard Specifications.

Asbestos and Hazardous Materials Survey Report - Revised

Iowa City Gateway Project North Dubuque Street, Park Road, and Park Road Bridge Iowa City, Iowa

> December 8, 2015 Terracon Project No.06157085



Prepared for:

The City of Iowa City Engineering Division Iowa City, Iowa

Prepared by:

Terracon Consultants, Inc. Cedar Rapids, Iowa



terracon.com



December 8, 2015



City of Iowa City Engineering Division 410 East Washington Street Iowa City, Iowa 52240

Attn: Ms. Melissa Clow, Special Projects Administrator

P: (319) 356-5413

E: Melissa-clow@iowa-city.org

Re: Asbestos and Hazardous Materials Survey Report - Revised

Iowa City Gateway Project

North Dubuque Street, Park Road, and Park Road Bridge

lowa City, Iowa 52240

Terracon Project No.06157085

Dear Ms. Clow:

Terracon Consultants, Inc. (Terracon) is pleased to submit the attached revised survey report to the City of Iowa City, Iowa (the City) for the above referenced Iowa City Gateway Project. The purpose of this survey report is to present the results of an asbestos, painted surface coating, and hazardous/special materials survey performed on November 24, 2015. This survey was conducted in general accordance with the City's Consultant Agreement dated November 18, 2015 and Terracon's Proposal to Provide Environmental Consulting Services dated October 20, 2015. We understand that the project includes elevating North Dubuque Street between Foster Road at the north and Brown Street at the south. In addition, Park Road Bridge will be elevated and Park Road will be improved to North Riverside Drive.

Terracon appreciates the opportunity to provide this service to the City. If you have questions regarding this report, please contact Eric at 319-221-7321.

Sincerely,

Terracon Consultants, Inc.

Eur Ala

Eric W. Harris

Project Manager

Cindy A. Baldwin, CIH, FAIHA Senior Industrial Hygienist

EWH/CAB n:\projects\2015\06157085\project documents (reports-letters-drafts to clients)\survey report\revised 12.8.15\06157085.12815.coic.gateway project.asbestos.hazardous materials survey report.docx Copies to: Addressee (2)



Terracon Consultants, Inc. 2640 12th Street SW Cedar Rapids, Iowa 52404
P [319] 366-8321 F [319] 366-0032 terracon.com

i

TABLE OF CONTENTS

1.0	INTR	INTRODUCTION					
	1.1	Documentation Review					
	1.2	Project Objective	2				
	1.3	Reliance					
2.0	FIELD	O ACTIVITIES					
	2.1	Asbestos Survey					
		2.1.1 Asbestos Visual Assessment	3				
		2.1.2 Asbestos Physical Assessment					
		2.1.3 Asbestos Sample Collection					
		2.1.4 Asbestos Sample Analysis					
	2.2	Painted Surface Coating Assessment					
	2.3	Mercury Survey					
	2.4	Polychlorinated Biphenyls Survey					
3.0	REGU	JLATÓRY OVERVIEW	(
	3.1	Asbestos	6				
	3.2	Cadmium					
	3.3	Chromium	7				
	3.4	LBP	8				
	3.5	Mercury					
	3.6	Polychlorinated Biphenyls					
4.0	FIND	INGS	9				
	4.1	Asbestos Survey Findings	9				
	4.2	Painted Surface Coating Findings	11				
	4.3	Mercury Survey Findings					
	4.4	Polychlorinated Biphenyls Survey Findings	12				
5.0	LIMIT	ATIONS/GENERAL COMMENTS					

Asbestos and Hazardous Materials Survey - Revised

Gateway Project ■ Iowa City, Iowa

December 8, 2015 Terracon Project No. 06157085



APPENDICES

APPENDIX A ASBESTOS INSPECTOR LICENSES

APPENDIX B TABLES

TABLE 1 - IDENTIFIED ASBESTOS-CONTAINING MATERIALS BY HOMOGENEOUS AREA (HA)

TABLE 2 - ASBESTOS SURVEY SAMPLE LOCATION SUMMARY

TABLE 3 - PAINTED SURFACE COATING SAMPLE SUMMARY

TABLE 4 - MERCURY, PCBs, AND OTHER POTENTIALLY REGULATED MATERIALS SURVEY

SUMMARY

APPENDIX C ANALYTICAL LABORATORY REPORTS AND COCS

APPENDIX D EXHIBITS

EXHIBIT 1 - PARK ROAD/BRIDGE SAMPLE LOCATION DIAGRAM

EXHIBIT 2 – DUBUQUE/KIMBALL SAMPLE LOCATION DIAGRAM

EXHIBIT 3 – 1966 PARK BRIDGE PLAN

APPENDIX E PHOTOGRAPHIC DOCUMENTATION

ASBESTOS AND HAZARDOUS MATERIAL SURVEY - REVISED Gateway Project North Dubuque Street, Park Road, and Park Road Bridge Iowa City, Iowa

Terracon Project No.06157085 December 8, 2015

1.0 INTRODUCTION

On November 24, 2015, Terracon Consultants, Inc. (Terracon) conducted an asbestos, painted surface coatings, and hazardous/special material survey (the survey) of the Gateway project. The Gateway project includes elevating North Dubuque Street between Foster Road at the north and Brown Street at the south. In addition, Park Road Bridge will be elevated and Park Road will be improved to North Riverside Drive. The survey was conducted by state of lowa licensed asbestos inspectors in general accordance with Terracon's Proposal to Provide Environmental Consulting Services dated October 20, 2015 and the City of Iowa City's (City) Consultant Agreement dated November 18, 2015.

As part of the survey activities, accessible bridge and infrastructure components (including but not limited to vaults, manholes, access hatches, culverts, fencing, etc.) were inspected. Homogeneous areas of suspect asbestos-containing materials (ACM) were visually identified and documented. A painted surface coating survey was also completed on accessible painted materials that may be impacted as part of the project. The painted surface coating survey included the collection of paint chips from painted surfaces and submittal to an accredited laboratory for analysis of cadmium, chromium, and lead. A hazardous/special materials survey included an inspection of the project alignment, noting components and equipment that may contain regulated materials.

At the time of survey activities, the roadways along the alignment and Park Road Bridge were open and conveying traffic normally. Discharge at the Iowa River below Coralville Lake was 2,500 cubic feet per second at 08:00 central standard time on November 24, 2015¹; the underside of Park Road Bridge was not accessible on the east side. Additionally, Terracon estimated approximately 13-feet to the water level from the underside of the girders. Access to infrastructure below the ground surface was not provided at the time of the survey activities; although, Terracon made visual observations in accessible manholes, utility vaults, etc., we typically could not identify suspect ACMs. Due to the aforementioned factors, our survey services were limited.

-

¹ Posted at: http://waterdata.usgs.gov/usa/nwis/uv?site_no=05453520, accessed December 2, 2015

Asbestos and Hazardous Materials Survey - Revised Gateway Project • Iowa City, Iowa

December 8, 2015 Terracon Project No. 06157085



Although reasonable effort was made to survey accessible suspect materials, additional suspect but unsampled materials could be located in the subsurface, in walls, in voids, or in other concealed areas or areas where investigation was not feasible without significant damage and/or excavation. Suspect ACM samples were collected in general accordance with the sampling protocols outlined in United States Environmental Protection Agency (USEPA) 40 Code of Federal Regulations (CFR) Part 763-Asbestos, Subpart E-Asbestos-Containing Materials in Schools. Samples were delivered to an accredited laboratory for analysis by polarized light microscopy (PLM).

1.1 Documentation Review

On November 16, 2015, the City provided Terracon Plans and Specifications for Water System Improvements dated June 2, 1966 (the 1966 Plans) for the Dubuque Street Main project. Prior to field activities, Terracon reviewed the 1966 Plans to identify suspect ACMs both on the surface and subsurface. Based on review of the 1966 Plans, asbestos cement piping under Park Road Bridge was indicated on drawing 11614-9. Additionally, it appears that the asbestos cement piping extends beyond the abutments. In addition, Terracon identified the following information in the 1966 Plans:

- Page NH-1 indicated that 7,050 linear feet (LF) of cast iron or asbestos cement water main were specified; furthermore,
 - Part 3 Water Mains and Appurtenances, Section 3 Pipe materials (page 3-2) indicate that either cast pipe or asbestos cement pipe could have been used.
 - Additionally, the Plans are labeled "As Constructed" and only indicate that the side streets are cast iron (notes for auguring or pushing X feet of "C.I." pipe). The main along Dubuque does not appear to have a unique marking (either C.I, cast iron or A.C. asbestos cement, per the legend).
- Page 3-2 also specifies that a bituminous seal coat was to be applied on the surface lining of the cast.

On November 30, 2015 and following field activities, the City provided Terracon a compact disk with several other reports, plans/specifications, and studies related to the Gateway project alignment.

1.2 Project Objective

Asbestos survey services were conducted at the Gateway project to satisfy requirements of the USEPA regulations under 40 CFR Part 61, Subpart M, National Emission Standards for Hazardous Air Pollutants (NESHAP), which apply when structures are renovated or demolished.

Asbestos and Hazardous Materials Survey - Revised

Gateway Project ■ Iowa City, Iowa

December 8, 2015 ■ Terracon Project No. 06157085



A painted surface coatings survey was completed to identify cadmium, chromium, and lead containing paints on painted components so that proper worker protection and environmental protection and proper disposal can be completed.

Disposal of PCB-containing fluorescent light ballasts, caulks, transformers, and oils is regulated by the USEPA under 40 CFR 761 Polychlorinated Biphenyls (PCBs) Manufacturing, Processing, Distribution in Commerce, and Use Prohibitions. Disposal of mercury-containing fluorescent light tubes as universal waste is regulated under 40 CFR 273 Standards for Universal Waste Management. Disposal of mercury from other sources is regulated under 40 CFR 260-262 Hazardous Waste standards.

Although regulations requiring pre-demolition surveys do not exist for mercury-containing light tubes and equipment or PCB-containing equipment, contractors should be notified of the presence of these materials in areas where demolition activities might result in potential employee exposure to mercury, PCBs, or other hazardous materials, so that they can take the necessary actions to comply with Occupational Safety and Health Administration (OSHA) requirements and USEPA disposal requirements.

1.3 Reliance

This report is for the exclusive use of the City of Iowa City. Reliance by any other party is prohibited without written authorization of Terracon and the City of Iowa City. Reliance on this report by the City of Iowa City and all authorized parties is subject to the terms, conditions, and limitations stated in the Contract Agreement and this report.

2.0 FIELD ACTIVITIES

2.1 Asbestos Survey

The asbestos survey was conducted by Mr. Eric W. Harris, and Mr. Jake Stahl, state of Iowa licensed asbestos inspectors (license #s 15-4989 and 15-5108, respectively). Copies of their asbestos inspector licenses are attached as Appendix A. The asbestos survey was conducted in general accordance with the sample collection protocols established in USEPA 40 CFR 763.86, Sampling. A summary of survey activities is provided below.

2.1.1 Asbestos Visual Assessment

Survey activities were initiated with visual observation of the Park Road Bridge and accessible areas along the Gateway project alignment to identify homogeneous areas of suspect ACM. A

Asbestos and Hazardous Materials Survey - Revised Gateway Project ■ Iowa City, Iowa December 8, 2015 ■ Terracon Project No. 06157085



homogeneous area (HA) consists of materials that appear similar throughout in terms of color and texture with consideration given to the date of application.

Terracon removed infrastructure components (including, but not limited to, vaults, manholes, access hatches, culverts, fencing, etc.) to inspect for suspect ACMs and to identify HAs. Please note that limited observations were made and Terracon did not enter these spaces, as there was limited to no access and they are considered confined spaces. Other subsurface suspect materials as described in Section 1.1 were not readily observed in the select access points. It should be noted that power along the alignment and to the light poles and traffic controls was considered active during the assessment; consequently, Terracon did not sample electrical related items. Wiring did not appear to be suspect based on our limited visual observations. Electrical equipment such as paper backers, wire jackets, and fuse housings has been known to contain asbestos insulation materials.

As noted in Section 1.0, access to materials under the bridge and associated abutments was generally limited to the west side of the bridge. The description of the cement piping in the 1966 plans is generally accurate; however, observations past the abutments could not be made; therefore, the extent of the cement piping is unknown. These restrictions were limiting factors in completion of the survey.

2.1.2 Asbestos Physical Assessment

A physical assessment of each HA of suspect ACM was conducted to assess the friability and condition of the materials. A friable material is defined by the USEPA as a material that can be crumbled, pulverized, or reduced to powder by hand pressure when dry. Friability was assessed by physically touching suspect materials.

2.1.3 Asbestos Sample Collection

Based on results of the visual observation, bulk samples of suspect ACM were collected in general accordance with USEPA sampling protocols. Samples of suspect materials were collected from randomly selected locations in each homogeneous area. Bulk samples were collected using wet methods as applicable to reduce the potential for fiber release. Samples were placed in sealable containers and labeled with unique sample numbers using an indelible marker.

The selection of sample locations and frequency of sampling were based on Terracon's observations and the assumption that like materials in the same area are homogeneous in content. Terracon collected 30 bulk samples from 10 homogeneous areas of suspect ACM. A summary of suspect ACM samples collected during the survey is included as part of the chain of custody (COC) and is provided in Table 2 in Appendix B. The lab report and the COC are provided in Appendix C.

Gateway Project ■ Iowa City, Iowa

December 8, 2015 Terracon Project No. 06157085



2.1.4 Asbestos Sample Analysis

Bulk samples were submitted under COC to EMSL Analytical, Inc. (EMSL) in Cinnaminson, New Jersey for analysis by PLM with dispersion staining techniques per USEPA's *Method for the Determination of Asbestos in Bulk Building Materials* (600/R-93-116). EMSL is accredited under the National Voluntary Laboratory Accreditation Program (NVLAP Accreditation No. 101048-0). The percentage of asbestos, if present, was determined by microscopic visual estimation. As a result of laboratory analysis, EMSL further separated out individual layers from the materials submitted; consequently, 33 samples were analyzed.

Based on the initial laboratory results, Terracon contacted the analytical laboratory to have a 400-point count analysis performed on select positive results. Three samples were analyzed on a 24-hour turnaround time (TAT) utilizing the 400-point count procedure.

2.2 Painted Surface Coating Assessment

In addition to the collection of bulk asbestos samples, Terracon collected paint chip samples from painted components utilizing a wood chisel and sample bags. Terracon collected paint chips samples from line striping, light/traffic control poles, and a vault lid. The paint chip samples were submitted under COC to TestAmerica Laboratories, Inc. (TestAmerica) in Cedar Falls, Iowa for analysis of cadmium, chromium (total), and lead by USEPA method SW846-6010C on a 3-day TAT. TestAmerica is accredited by the AIHA® Laboratory Accreditation Programs, LLC under the Industrial Hygiene Laboratory Accreditation Program (IHLAP) – certification number 101044 and under the State of Iowa, state program – certification ID 007.

2.3 Mercury Survey

The mercury portion of the survey (the mercury survey) consisted of a visual survey for potential mercury-containing lamps and fluorescent light tubes.

2.4 Polychlorinated Biphenyls Survey

The PCB portion of the survey (the PCB survey) was conducted concurrently with the mercury survey. Terracon estimated the number of potential ballasts for contractor verification and proper disposal.

Asbestos and Hazardous Materials Survey - Revised Gateway Project ■ Iowa City, Iowa December 8, 2015 ■ Terracon Project No. 06157085



3.0 REGULATORY OVERVIEW

3.1 Asbestos

In Iowa, asbestos activities are regulated by the Iowa Department of Natural Resources (IDNR) and Iowa Workforce Development (IWD), Division of Labor. IDNR regulates asbestos fiber emissions under Iowa Administrative Code 567 Chapter 23 (IAC 567–23) and asbestos-containing waste disposal under IAC 567–109. IWD regulates occupational exposure to asbestos under IAC 875–10 and asbestos removal and encapsulation activities under IAC 875–155.

IAC 567–23.1(3) adopts USEPA's asbestos NESHAP (40 CFR Part 61, Subpart M) by reference. Subpart M regulates asbestos fiber emissions and asbestos waste disposal practices. It also requires the identification and classification of existing building materials prior to demolition or renovation activity. Under NESHAP, asbestos-containing building materials are classified as friable, Category I nonfriable, or Category II nonfriable ACM. Friable materials are those that, when dry, may be crumbled, pulverized, or reduced to powder by hand pressure. Category I nonfriable ACM includes packings, gaskets, resilient floor coverings, and asphalt roofing products containing more than 1% asbestos. Category II nonfriable ACM are any materials other than Category I materials that contain more than 1% asbestos.

Regulated ACM (RACM) must be removed before renovation or demolition activities that will disturb the materials. RACM includes:

- Friable ACM;
- Category I nonfriable ACM that has become friable or will be subjected to drilling, sanding, grinding, cutting, or abrading; and
- Category II nonfriable ACM that could be crumbled, pulverized, or reduced to powder during renovation or demolition activities.

The owner or operator must provide the IDNR and IWD with written notification of planned removal activities at least 10 working days prior to the commencement of asbestos abatement activities. Removal of RACM must be conducted by an Iowa-permitted asbestos abatement contractor.

IAC 875–155 Asbestos Removal and Encapsulation requires that any asbestos-related activity conducted in a public building be performed by personnel licensed or permitted by the IWD. Inspections for ACM must be conducted by IWD-licensed inspectors. Asbestos abatement must be performed by IWD-permitted asbestos abatement contractors. Management plans developed for the in-place management of asbestos-containing materials must be developed by an IWD-licensed management planner. When an abatement project design is prepared, it must be prepared by an IWD-licensed project designer.

Asbestos and Hazardous Materials Survey - Revised

Gateway Project ■ Iowa City, Iowa

December 8, 2015 Terracon Project No. 06157085



IAC 875–10 adopts the Occupational Safety and Health Administration (OSHA) Asbestos standard for construction (29 CFR 1926.1101) by reference. The OSHA standard requires that employee exposure to airborne asbestos fibers be maintained below the permissible exposure limits (PEL) of 0.1 asbestos fiber per cubic centimeter of air (0.1 f/cc) as an 8-hour time-weighted average and 1.0 f/cc as a 30-minute excursion. The OSHA standard classifies construction and maintenance activities that could disturb ACM and specifies work practices and precautions that employers must follow when engaging in each class of regulated work.

3.2 Cadmium

Cadmium waste from renovation or demolition activities, such as debris, paint chips, dust, and sludges, that exhibit the toxicity characteristic must be managed and disposed as a hazardous waste under the Resource Conservation and Recovery Act (RCRA). A composite, representative sample of the demolition debris must be tested to determine if it is regulated as hazardous waste under 40 CFR 261 Identification and Listing of Hazardous Waste.

The OSHA cadmium standard 29 CFR 1910.1027 establishes an action level (AL) of 2.5 micrograms per cubic meter (μ g/m³) and a PEL of 5.0 μ g/m³, both as 8-hour time-weighted averages (8-hr TWA). The standard requires exposure monitoring to evaluate employee exposures. If results are below the AL or PEL, no further action is required.

3.3 Chromium

Chromium waste from renovation or demolition activities, such as debris, paint chips, dust, and sludges, that exhibit the toxicity characteristic must be managed and disposed as a hazardous waste under RCRA. A composite, representative sample of the demolition debris must be tested to determine if it is regulated as hazardous waste under 40 CFR 261 Identification and Listing of Hazardous Waste.

OSHA regulates occupational exposure to chromium metal and inorganic Cr(III) and Cr(VI) compounds under 29 CFR 1910.1000 Air Contaminants Tables Z–1 and Z–2. The PEL for chromium are as follows:

chromium metal	1.0 mg/m ³	8-hr TWA ²
inorganic chromium (III) compounds (as chromium)	0.5 mg/m ³	8-hr TWA
inorganic chromium (VI) compounds (as chromate)	0.1 mg/m ³	ceiling limit

OSHA regulates occupational exposure to hexavalent chromium [Cr(VI)] under 29 CFR 1910.1026 (general industry) and 1926.1126 (construction). The Cr(VI) standards establish an

_

² 8-hr TWA = 8-hour time-weighted average

Asbestos and Hazardous Materials Survey - Revised Gateway Project ■ Iowa City, Iowa December 8, 2015 ■ Terracon Project No. 06157085



AL of 2.5 micrograms of Cr(VI) per cubic meter of air (μ g/m³, equivalent to 0.0025 mg/m³) as an 8-hr TWA. The PEL for Cr(VI) is 5.0 μ g/m³ (equivalent to 0.005 mg/m³) as an 8-hr TWA.

3.4 LBP

USEPA has defined LBP as containing 1.0 mg/cm² or 0.5 % by weight. LBP waste from renovation or demolition activities, such as debris, paint chips, dust, and sludges, that exhibit the toxicity characteristic must be managed and disposed as a hazardous waste under RCRA, with the exception of whole-building demolition debris. Whole-building demolition debris is considered a non-hazardous waste with regard to lead. Therefore, no sampling/analysis of painted components for lead is required for disposal as non-hazardous waste. If it is not a whole-building demolition debris, a composite, representative sample of the demolition debris must be tested to determine if it is regulated as hazardous waste under 40 CFR 261 Identification and Listing of Hazardous Waste.

IAC 875-10 adopts the OSHA Lead standard for construction (29 CFR 1926.62) by reference. For the purpose of the standard, lead includes metallic lead, all inorganic lead compounds, and organic lead soaps. The OSHA standard does not define the amount of lead in paint that constitutes LBP and it applies to all construction work where an employee may be occupationally exposed to lead. All work related to construction, alteration or repair (including painting and decorating) is included. The standard applies to any detectable concentration of lead in paint, as even small concentrations of lead can result in unacceptable employee exposures depending upon on the method of removal and other workplace conditions. Under this standard, construction includes, but is not limited to, the following:

- Demolition or salvage of structures where lead or materials containing lead are present
- Removal or encapsulation of materials containing lead
- New construction, alteration, repair, or renovation of structures, substrates, or portions containing lead, or materials containing lead
- Installation of products containing lead
- Lead contamination/emergency clean-up
- Transportation, disposal, storage, or containment of lead or materials containing lead on the site or location at which construction activities are performed
- Maintenance operations associated with construction activities described above

Employers must assure that no employee will be exposed to lead at concentrations greater than the permissible exposure limit of $50 \,\mu g/m^3$ averaged over an eight-hour period without adequate protection. The OSHA standard also establishes an action level of $30 \,\mu g/m^3$, which if exceeded, triggers certain requirements, including periodic exposure monitoring and medical monitoring.

Asbestos and Hazardous Materials Survey - Revised

Gateway Project ■ Iowa City, Iowa

December 8, 2015 Terracon Project No. 06157085



3.5 Mercury

Metallic mercury is a silver-white liquid at room temperature. Elemental and inorganic mercury compounds are used in the manufacture of scientific instruments, electric equipment, and mercury vapor and fluorescent electric lamps. Mercury-containing equipment, such as fluorescent light tubes, must be sent to an approved recycling facility that recovers mercury. The USEPA considers mercury a hazardous waste.

USEPA regulates disposal of mercury-containing fluorescent light tubes as universal waste under 40 CFR 273. Disposal of mercury from other sources is regulated under 40 CFR 260-262.

OSHA regulates occupational exposure to mercury under 29 CFR 1910.1000 Air Contaminants, Table Z-1 – Limits for Air Contaminants. The PEL for mercury is 0.1 milligrams per cubic meter (mg/m³) as an 8-hr TWA.

3.6 Polychlorinated Biphenyls

PCBs are clear, oily liquids to white or yellowish waxy solids, depending on the degree of chlorination. They are stable, thermoplastic, and nonflammable materials that were used in hundreds of industrial and commercial applications including electrical, heat transfer, and hydraulic equipment; as plasticizers in paints, caulks, plastics, and rubber products; in pigments, dyes, and carbonless copy paper and many other applications. USEPA regulates transportation, disposal, and spill cleanup of PCB-containing ballasts under the Toxic Substances Control Act (TSCA), which can be found in 40 CFR 761. Fluorescent light ballasts are assumed to contain PCBs unless clearly marked as containing "NO PCB."

OSHA regulates occupational exposure to PCBs under 29 CFR 1910.1000 Air Contaminants, Table Z-1 – Limits for Air Contaminants. The PEL for chlorodiphenyl (42% chlorine) is 1.0 mg/m³ and for chlorodiphenyl (54% chlorine) is 0.5 mg/m³, both as 8-hr TWAs.

4.0 FINDINGS

4.1 Asbestos Survey Findings

Laboratory analysis of bulk samples confirmed the presence of asbestos in samples collected from cement piping under the Park Road Bridge. Drawings showing the approximate asbestos sample locations are provided as Exhibits 1-2 in Appendix D; the confirmed asbestos piping is indicated in Exhibits 1 and 3. Table 1 included in Appendix B identifies the confirmed ACM, its general area, sample locations, and approximate quantity. The lab results and COC are provided

Asbestos and Hazardous Materials Survey - Revised Gateway Project ■ Iowa City, Iowa December 8, 2015 ■ Terracon Project No. 06157085



in Appendix C. Photographs of the confirmed asbestos materials, and general photos are presented in Appendix E.

Asbestos was reported by the analytical laboratory in samples collected of the following materials:

 Asbestos cement pipe containing 20-30% chrysotile and 8-10% crocidolite asbestos approximately 380 LF according to the 1966 Park Bridge Detail Drawing; see Exhibit 3 in Appendix D.

All nonfriable ACMS that may become friable when removed must be removed by a permitted asbestos abatement contractor prior to demolition activities and disposed at an approved landfill.

Based on review of the 1966 Plans and as discussed in Section 1.1, it is unclear if the asbestos piping was utilized in other areas of the 1966 Dubuque Water Main Project. We do understand that the asbestos cement piping extends beyond the Park Road Bridge abutments. Once excavation begins, this should be confirmed; see below for additional details regarding coatings on cast pipe.

Based on the 400-point count procedure conducted by EMSL, the lab reported asbestos concentrations less than 1% in gray caulking under the guardrail newel posts on the Park Road Bridge. These materials are not considered asbestos-containing according to the USEPA definition; however, portions of OSHA's asbestos standards will be applicable regardless. Contractors should be notified of the presence of asbestos in such materials. It should be noted that general contractors typically have an asbestos exclusion clause under their insurance policy; therefore, they typically are barred from working with materials that contain asbestos, regardless of content. Those materials are identified in Table 2 in Appendix B. Terracon recommends that contract documents clearly define these materials.

As stated above, suspect ACMs may be present in inaccessible areas, primarily below the roadway/right-of-way surface. Additionally, ACMs may be discovered during earthwork and demolition activities. Unsampled suspect materials are assumed to contain asbestos (assumed ACM) and should be sampled after exposing the materials and prior to disturbance. Based on review of City provided plans for historic projects along the Gateway project alignment, suspect ACMs include but are not limited to the following:

- Bituminous coatings on subsurface infrastructure indicated on several different City provided plans on cast piping, concrete manholes, etc.
- Seals/gaskets on subsurface infrastructure indicated on several different City provided plans on cast piping, hydrants, concrete manholes, etc.

Per our contract, Terracon will develop an asbestos abatement specification and will perform abatement observation in order to confirm that ACMs are removed and disposed properly prior to

Asbestos and Hazardous Materials Survey - Revised

Gateway Project ■ Iowa City, Iowa

December 8, 2015 Terracon Project No. 06157085



demolition activities. Terracon can also assist with preparing abatement bid documents and can assist the City with securing a qualified abatement firm through a bidding process.

4.2 Painted Surface Coating Findings

The analytical laboratory reported the following:

- Chromium concentrations in all of the paint chip samples submitted:
- Lead concentrations in six of the paint chip samples submitted; and
- Cadmium in one paint chip sample submitted.

Please refer to Table 3 in Appendix B for further details.

Terracon recommends that the contractor(s) involved in the demolition be notified of the presence of lead, cadmium, and chromium-containing coatings on painted components. OSHA's lead and hexavalent chromium³ [Cr(VI)] standards for construction (29 CFR 1926.62 and 1926.1126, respectively) apply regardless of the concentrations and contractor(s) will need to provide appropriate personal protective equipment and conduct personal exposure monitoring, at a minimum. Terracon recommends the contractor(s) review the specified work tasks and methods involved in the demolition process and prepare a detailed lead/chromium management plan. The management plan should identify the work procedures and health and safety measures to be used in the lead/chromium material removal.

OSHA's lead regulation for construction (29 CFR 1926.62) covers metallic lead, all inorganic lead compounds (lead oxides and lead salts), and a class of organic compounds called soaps; all other lead compounds are excluded. The lead standard establishes an AL of 30 $\mu g/m^3$ as an 8-hr TWA. The PEL for lead is 50 $\mu g/m^3$ as an 8-hr TWA. The standard requires initial monitoring to evaluate employee exposures. If results are below the AL, no further action is required. If results exceed the AL, exposure monitoring must be repeated every six months, a medical surveillance program must be instituted, and employees must be provided with training about lead. If results exceed the PEL, additional requirements are triggered.

OSHA regulates occupational exposure to Cr(VI) in construction under 29 1926.1126. The AL is 2.5 $\mu g/m^3$ as an 8-hr TWA. The PEL is 5.0 $\mu g/m^3$ as an 8-hr TWA. The standard requires initial monitoring to evaluate employee exposures. If results are below the AL, no further action is required. If results exceed the AL, exposure monitoring must be repeated every six months, a medical surveillance program must be instituted, and Cr(VI) hazards must be communicated to employees. If results exceed the PEL, additional requirements are triggered.

³ Although the samples were analyzed for total chromium, the hexavalent form is often found in paint or may be generated by torch cutting.

Asbestos and Hazardous Materials Survey - Revised Gateway Project ■ Iowa City, Iowa December 8, 2015 ■ Terracon Project No. 06157085



If waste materials containing lead or chromium are generated, they may be regulated as hazardous waste. Waste from demolition activities, such as debris, paint chips, dust, and sludges, that exhibit the toxicity characteristic must be managed and disposed of as a hazardous waste under the Resource Conservation and Recovery Act (RCRA). Waste from demolition activities, that exhibit the toxicity characteristic must be managed and disposed as a hazardous waste under the RCRA. A composite, representative sample of the demolition debris/waste must be tested by the Toxicity Characteristic Leaching Procedure (TCLP) to determine if it is regulated as hazardous waste under 40 CFR 261 Identification and Listing of Hazardous Waste. Per Section 10.54 of the lowa Department of Transportation Construction Manual, revised January 31, 2014, all waste generated during removal operations shall be sampled and analyzed by the contractor. The waste sample shall be submitted to a laboratory for a TCLP heavy metals analysis, including, arsenic, barium, cadmium, chromium, lead, mercury, selenium and silver.

Recycling of painted components may not require TCLP testing. Terracon recommends contacting the recycling recipient to confirm that they will accept the material. Certain painted materials may have to be abated by a qualified contractor prior to torch cutting or other means of dismantling. Waste generated from abated areas would likely require TCLP testing as indicated above.

4.3 Mercury Survey Findings

During the mercury survey visual inspection, Terracon identified street lamp and traffic control lights suspected of containing mercury. A summary of mercury-containing devices is included as Table 4 in Appendix B.

Terracon recommends that a qualified contractor remove and dispose of the mercury devices in accordance with local, state, and federal regulations. Written evidence should be provided by the disposal company certifying that the hazardous waste treatment, storage, or disposal facility is approved for mercury disposal by the USEPA and state or local regulatory agencies. Disposal of mercury-containing fluorescent light tubes as universal waste is regulated under 40 CFR 273. Disposal of mercury from other sources is regulated under 40 CFR 260-262.

4.4 Polychlorinated Biphenyls Survey Findings

Terracon was not able to physically assess for PCB containing ballasts in light poles along the right-of-way. We estimated one ballast per light pole/traffic signal light; for the purposes of this survey, the reported number of ballasts should be treated as if all were PCB containing. Pole mounted transformers were identified along the roadway/right-of-way. Subsurface transformer vaults were not readily observed. Typically, the power company is responsible for the removal and disposal of PCB waste generated from transformers.

A summary of potential PCB devices is included in Table 4 in Appendix B.

Asbestos and Hazardous Materials Survey - Revised Gateway Project • Iowa City, Iowa December 8, 2015 • Terracon Project No. 06157085



5.0 LIMITATIONS/GENERAL COMMENTS

Terracon did not perform sampling which required dismantling of equipment or removal of protective coverings. Reasonable efforts to access suspect materials within known areas of restricted access (e.g., manholes, vaults, subsurface infrastructure, electrical equipment) were made; however, as explained in the text, certain materials were not sampled.

This survey was conducted in a manner consistent with the level of care and skill ordinarily exercised by members of the profession currently practicing under similar conditions in the same locale. The results, findings, conclusions, and recommendations expressed in this report are based on conditions observed during our survey of the building. The information contained in this report is relevant to the date on which this survey was performed, and should not be relied upon to represent conditions at a later date. This report has been prepared on behalf of and exclusively for use by the City of lowa City for specific application to their project as discussed. This report is not a bidding document. Contractors or consultants reviewing this report must draw their own conclusions regarding further investigation or remediation deemed necessary. Terracon does not warrant the work of regulatory agencies, laboratories, or other third parties supplying information that may have been used in the preparation of this report. No warranty, express or implied is made.

APPENDIX A ASBESTOS INSPECTOR LICENSES

ERIC HARRIS

DOB: 07/02/1986

Issued: 07/27/2015



This person is licensed to perform asbestos work in the State of Iowa. ID card is intended for official use only and must be present on jobsite.

License type	Number	Expires			
SUPERVISOR	15-4988	05-04-2016			
INSPECTOR	15-4989	07-20-2016			
	MARL AM	en e			
BESTOS	Michael A. Mauro Labor Commissioner				

JACOB STAHL

DOB: 11/12/1987

Issued: 08/20/2015



This person is licensed to perform asbestos work in the State of Iowa. ID card is intended for official use only and must be present on jobsite.

License type	Number	Expires
INSPECTOR	15-5108	07-20-2016



TV MALL A TIPLE

Michael A. Mauro Labor Commissioner

APPENDIX B

TABLES

TABLE 1 – IDENTIFIED ASBESTOS-CONTAINING MATERIALS BY HOMOGENEOUS AREA (HA)

TABLE 2 - ASBESTOS SAMPLE SUMMARY

TABLE 3 – PAINTED SURFACE COATING SAMPLE SUMMARY

TABLE 4 – MERCURY, PCBS, AND OTHER POTENTIALLY REGULATED MATERIALS SURVEY SUMMARY

Asbestos and Hazardous Materials Survey - Revised

Gateway Project ■ Iowa City, Iowa

December 8, 2015 Terracon Project No. 06157085



Table 1 - IDENTIFIED ASBESTOS-CONTAINING MATERIALS BY HOMOGENEOUS AREA (HA)

The materials listed in this table have been sampled and determined to contain asbestos in concentrations greater than 1%. When disturbed, various federal, state, and local regulations will apply. See Appendix C for detailed analytical results and the sample sheets.

HA		MATERIAL				ESTIMATED
#	SAMPLE#	DESCRIPTION	GENERAL AREA PRESENT	SAMPLE LOCATIONS	LAB RESULTS	QUANTITY ¹
	05-CP2-013	Cement pipe and	Under Park Road Bridge, 3rd	On collar under Park	25%	380 LF ²
		associated collars (1966	girder span from the south	Road Bridge at west	Chrysotile, 8%	
		plans indicate 12-inch		abutment	Crocidolite	
	05-CP2-014	inside diameter)		Far west pipe run of pipe	30%	
				under Park Road Bridge,	Chrysotile,	
05				as it enters the west	10%	
				abutment	Crocidolite	
	05-CP2-015			East of the pipe collar on	30%	
				the west side of the Park	Chrysotile,	
				Road Bridge abutment	10%	
					Crocidolite	

¹ Estimated quantities are based on a cursory field evaluation, and actual quantities may vary significantly, especially if asbestos-containing materials are present in hidden and/or inaccessible areas not evaluated as part of this survey.

² LF – indicates linear-feet; quantity based on that listed in the 1966 Plans



TABLE 2 - ASBESTOS SURVEY SAMPLE LOCATION SUMMARY

HA#	SAMPLE#	MATERIAL DESCRIPTION	GENERAL AREA PRESENT	SAMPLE LOCATION	LAB RESULTS
	01-CA5-001	Gray sealant	Park Road bridge, under	Park Road bridge, north side, 2 nd guardrail	0.5% Chrysotile ²
			guardrail newel posts (only on	post from the west, base	
	01-CA5-002		bridge) ¹	North side of Park Road bridge, right newel	<0.25%
01				post of the 3 rd concrete pillar on guardrail from	Chrysotile
				the west	
	01-CA5-003			South side of Park Road bridge, 15th guard rail	0.5% Chrysotile
				post from the east	
	02-MS5-004	Foam pad, off white	Park Road bridge abutments -	Park Road bridge west side abutment, north	None detected
		Mastic, brown	expansion joints	side	None detected
02	02-MS5-005	Foam pad, off white		Park Road bridge east side abutment, north	None detected
02		Mastic, brown		face 4' above the ground surface	None detected
	02-MS5-006	Foam pad, off white		Park Road bridge east abutment, south face	None detected
		Mastic, brown		above PVC pipe	None detected
	03-SG5-007	Black rocker pad	Park Road bridge rocker	Park Road bridge west side abutment, 5 th	None detected
			pads/girder plates	girder from south	
03	03-SG5-008			Park Road bridge west side abutment, 5 th	None detected
00				girder from south, south side	
	03-SG5-009			West side abutment center below bridge, on	None detected
				girder	
	04-RF2-010	Tar paper	Asbestos cement pipe	Park Road bridge west abutment hanger under	None detected
			hangars under HA #05	bridge furthest south	
	04-RF2-011			Hanger east of sample #10	None detected
	04-RF2-012			3 rd hanger east of west abutment	None detected
04					

¹ The east side "wing" guardrails were replaced circa 2004 based on review of provided project plans; the trace asbestos material was not observed in these areas.

² Italics indicate asbestos concentrations less than 1% (based on 400-point count – PLM) and do not meet USEPA definitions of asbestos-containing materials; however, OSHA asbestos provisions under 29 CFR 1926.1101 apply to the contractors. These materials should be brought to their attention.

SP-156041 **Page 32 of 80**

Asbestos and Hazardous Materials Survey - Revised

Gateway Project Iowa City, Iowa
December 8, 2015 Terracon Project No. 06157085



HA#	SAMPLE#	MATERIAL DESCRIPTION	GENERAL AREA PRESENT	SAMPLE LOCATION	LAB RESULTS
	05-CP2-013	Cement pipe and	Under park road bridge, 3 rd	On collar under park road bridge at west	25% Chrysotile,
		associated collars (1966	girder span from the south	abutment	8% Crocidolite
05	05-CP2-014	plans indicate 12-inch inside		Far west pipe run of pipe under park road	30% Chrysotile,
05		diameter)		bridge, as it enters the west abutment	10% Crocidolite
	05-CP2-015			East of the pipe collar on the west side of the	30% Chrysotile,
				park road bridge abutment	10% Crocidolite
	06-SC2-016	Black bituminous coating	Gas main under park road	Park Road bridge south side of west abutment	None detected
06			bridge, girder south of HA #05	on hanging gas main	
00	06-SC2-017			At the sticker under the west abutment	None detected
	06-SC2-018			10' east of sample #17	None detected
	07-CA5-019	Cream/rose colored caulk	PVC pipe elbow on the park	Bottom side of 45 degree elbow, east side of	None detected
			road bridge east abutment	bridge on PVC	
07	07-CA5-020			Left of sample #019	None detected
	07-CA5-021			On top of 45 degree PVC elbow near sample	None detected
				#019	
	08-PI5-022	Black tarry pipe coating	Park Road Bridge, east side	West pipe at eastern most light pole access	None detected
			median, sub surface conduit	vault	
80	08-PI5-023			East pipe at eastern most light pole access	None detected
				vault	
	08-PI5-024			Inner pipe of sample #23	None detected
	09-SC5-025	Black expansion joint	Road way expansion joints	Park Road western cross walk, south side, just	None detected
				west of Park Road Bridge	
09	09-SC5-026			Park Road, north side of road across from	None detected
				sample #25	
	09-SC5-027			Dubuque Street, east of sample #30	None detected
	10-SC5-028	Off-white/cream glue	Box culvert chain-link fence	Southeast post for chain link fence, north side	None detected
			posts bases west of Kimball	at box culvert	
10	10-SC5-029		and fencing along the west	Southeast post for chain link fence, south side	None detected
10			side of Dubuque Street, south	at box culvert	
	10-SC5-030		of the Iowa City sign	Chain-link fence west of Dubuque Street, 10 th	None detected
				post south of the north edge (lowa City sign)	

Gateway Project ■ Iowa City, Iowa

December 8, 2015 Terracon Project No. 06157085



TABLE 3 - PAINTED SURFACE COATING SAMPLE SUMMARY

Sample #	Location	Substrate	Color	Cadmium Concentration (% by weight)	Chromium Concentration (% by weight)	Lead Concentration (% by weight)
Chip 1 ³	Park Road, 1 st light stanchion west of bridge on the north side of the road	Metal	Silver over red	BLQ⁴	0.118	21.3
Chip 2	Vault lid on the Park Road Bridge east side abutment, south side of the road, underside of lid	Metal	Red	BLQ	0.0111	BLQ
Chip 3	East side of Park Road Bridge, median line striping, by light pole	Concrete	Yellow	BLQ	0.251	1.15
Chip 4	East side of Park Road Bridge, line paint at cross walk of Dubuque	Concrete	White	BLQ	0.000677	0.00306
Chip 5	Traffic control pole at Dubuque Street and Park Road, west side of the pole and west side of Dubuque Street	Metal	Hunter green over yellow	BLQ	2.78	4.14
Chip 6	Fire hydrant on the east side of Dubuque Street at the intersection of Park Road	Metal	Red	BLQ	0.00301	0.0171
Chip 7	Traffic control box west side of Dubuque Street, north of Park Road intersection	Metal	Brown	0.00189	0.855	0.803

Note: Paint on similar infrastructure (hydrants, lampposts, traffic control posts) is considered homogenous

³ The analytical laboratory indicated two qualifiers (F1 and F2) for this sample and indicated that the MS and/or MSD Recover is outside acceptable limits, and MS/MSD RPD exceeds control limits.

⁴ BLQ – indicates below the laboratory level of quantitation. For example, the laboratory quantitation level for cadmium is 0.001 % by weight. BLQ means that less than 0.001 % of cadmium was collected in the sample; it does not mean that cadmium was not present.

Asbestos and Hazardous Materials Survey - Revised

Gateway Project ■ Iowa City, Iowa

December 8, 2015 Terracon Project No. 06157085



Table 4 – MERCURY, PCBs, AND OTHER POTENTIALLY REGULATED MATERIALS SURVEY SUMMARY

Product Name, Equipment or Chemical Name	Estimated Quantity	Unit of Measure	
Street lights: lamps (unknown if metal halide, high pressure sodium or other) and assumed a single ballast (PCB or non-PCB)	50	Each	
Traffic control lamps	20	Each	
Pole mounted transformers (potential PCBs)	Not quantified, assumed responsibility of power company		

Note: The traffic control and lighting items are likely to be removed by the general contractor or the City for reuse.

APPENDIX C

LABORATORY ANALYTICAL REPORTS AND COCS



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077 Phone/Fax: (800) 220-3675 / (856) 786-5974 http://www.EMSL.com / cinnasblab@EMSL.com EMSL Order ID: Customer ID: Customer PO:

Project ID:

12/02/2015

041535095

ACON77

Attn: Phone: Eric Harris (319) 366-8321 Terracon Consultants, Inc. Fax: (319) 366-0032 Collected: 11/24/2015 2640 12th Street Southwest Received: 11/25/2015 Cedar Rapids, IA 52404

Proj: 06157085 / Iowa City Gateway / Dubuque Street/Park Road / Iowa City, Iowa

Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116 Method via **Polarized Light Microscopy**

Analyzed:

Lab Sample ID: 041535095-0001 Client Sample ID: 01-CA5-001

Sample Description: Park Rd Bridge N.Side/2nd Guard Rail Post from W/Gray Sealant

	Analyzed		Non-	-Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	12/01/2015	Gray	0%	100%	<1% Chrysotile	System ID:	
400 PLM Pt Ct	12/02/2015	Gray	0%	99.50%	0.50% Chrysotile	System_ID:	

Lab Sample ID: 041535095-0002 Client Sample ID: 01-CA5-002

Sample Description: N Side of Bridge/R Newell Post of 3rd Con. Pillar/Gray Sealant

	Analyzed		Non	-Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	12/01/2015	Gray	0%	98%	2% Chrysotile		
						System_ID:	
400 PLM Pt Ct	12/02/2015	Gray	0%	100%	<0.25% Chrysotile		
						System_ID:	

Lab Sample ID: 041535095-0003 Client Sample ID: 01-CA5-003

Sample Description: S Side of Bridge/15th Guard Rail Post from E/Gray Sealant

	Analyzed		Non-	-Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	12/01/2015	Gray/Silver	0%	98%	2% Chrysotile		
						System_ID:	
400 PLM Pt Ct	12/02/2015	Gray/Silver	0%	99.50%	0.50% Chrysotile		
						System_ID:	
Client Sample ID:	02-MS5-004-Foam Pad					Lab Sample ID:	041535095-0004

Sample Description: Park Rd Bridge W Side Abutment/N Side/Off White Foam Pad

	Analyzed		Non-Asbestos			
TEST	Date	Color	Fibrous Non-Fibrous	Asbestos	Comment	
PLM	12/01/2015	Tan	0% 100%	None Detected		
					System_ID:	
Client Sample ID:	02-MS5-004-Mastic	•			Lab Sample ID:	041535095-0004A

Client Sample ID: Lab Sample ID: 02-MS5-004-Mastic

Sample Description: Park Rd Bridge W Side Abutment/N Side/Brown Mastic

	Analyzed		Non-Asbestos			
TEST	Date	Color	Fibrous Non-Fibrous	Asbestos	Comment	
PLM	12/01/2015	Brown	0% 100%	None Detected		
					System_ID:	
Client Sample ID:	02-MS5-005-Foam Pad				Lab Sample ID:	041535095-0005

Sample Description: Park Rd Bridge Rail Side Abutment/N Face 4' AGS/Off White Foam Pad

	Analyzed		Non-	-Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	12/01/2015	Tan	0%	100%	None Detected		
						System_ID:	



200 Route 130 North Cinnaminson, NJ 08077 Phone/Fax: (800) 220-3675 / (856) 786-5974 http://www.EMSL.com / cinnasblab@EMSL.com EMSL Order ID: Customer ID: Customer PO:

Project ID:

041535095

ACON77

Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116 Method via **Polarized Light Microscopy**

a	00 1405 005 14					Lab Camele ID	044505005 0005
Client Sample ID:	02-MS5-005-Mastic					Lab Sample ID:	041535095-0005A
Sample Description:	Park Rd Bridge Rail Side Ab	utment/N Face 4	AGS/Brown Mas	stic			
	Analyzed		Non-A	sbestos			
TEST	Date	Color		lon-Fibrous	Asbestos	Comment	
PLM	12/01/2015	Brown	0%	100%	None Detected	System ID:	
Client Sample ID:	02-MS5-006-Foam Pad					System_ID: Lab Sample ID:	041535095-0006
Sample Description:		/ S Eago above D	/C/Off White Fee	am Dad		Lub Gumpre 12.	041000000
oumpre Decompaism.	Park Rd Bridge E Abutment	3 race above r	VC/OII WIIILE FUA	alli Fau			
	Analyzed		Non-A	sbestos			
TEST	Date	Color	Fibrous N	lon-Fibrous	Asbestos	Comment	
PLM	12/01/2015	Gray	0%	100%	None Detected	System_ID:	
Client Sample ID:	02-MS5-006-Mastic					Lab Sample ID:	041535095-0006A
Sample Description:	Park Rd Bridge E Abutment	S Face above P	VC/Brown Mastic	:			
	ŭ						
	Analyzed			sbestos		_	
TEST	Date	Color		lon-Fibrous	Asbestos	Comment	
PLM	12/01/2015	Yellow	0%	100%	None Detected	System_ID:	
Client Sample ID:	03-SG5-007					Lab Sample ID:	041535095-0007
Sample Description:	Park Rd Bridge/W Side Abu	ment 5/5th Guard	from S/Black Ra	ake Pad		,	
	r ant rta bhagaitt clacitiba						
	Analyzed			sbestos			
TEST	Analyzed Date	Color	Non-A		Asbestos	Comment	
	=		Non-A	sbestos	Asbestos None Detected		
PLM	Date 12/01/2015	Color	Non-A Fibrous N	sbestos lon-Fibrous		System_ID:	041535095-0008
PLM Client Sample ID:	Date 12/01/2015 03-SG5-008	Color Black	Non-A Fibrous N 10%	sbestos Non-Fibrous 90%			041535095-0008
PLM Client Sample ID:	Date 12/01/2015	Color Black	Non-A Fibrous N 10%	sbestos Non-Fibrous 90%		System_ID:	041535095-0008
PLM Client Sample ID:	Date 12/01/2015 03-SG5-008	Color Black	Non-As Fibrous N 10%	sbestos Non-Fibrous 90%		System_ID:	041535095-0008
PLM Client Sample ID:	03-SG5-008 Park Rd Bridge/W Side Abu	Color Black	Non-As Fibrous N 10% d S Side/Black Ra Non-As	sbestos Non-Fibrous 90% ake Pad		System_ID:	041535095-0008
Client Sample ID: Sample Description: TEST	Date 12/01/2015 03-SG5-008 Park Rd Bridge/W Side Abur	Color Black tment 5/5th Guard	Non-As Fibrous N 10% d S Side/Black Ra Non-As	sbestos lon-Fibrous 90% ake Pad sbestos	None Detected	System_ID: Lab Sample ID: Comment	041535095-0008
PLM Client Sample ID: Sample Description: TEST PLM	Date 12/01/2015 03-SG5-008 Park Rd Bridge/W Side Abur Analyzed Date 12/01/2015	Color Black tment 5/5th Guard Color	Non-As Fibrous N 10% IS Side/Black Ra Non-As Fibrous N	sbestos 90% ake Pad sbestos	None Detected Asbestos	System_ID: Lab Sample ID: Comment System_ID:	
PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID:	Date 12/01/2015 03-SG5-008 Park Rd Bridge/W Side Abur Analyzed Date 12/01/2015	Color Black tment 5/5th Guard Color Black	Non-As Fibrous N 10% IS Side/Black Ra Non-As Fibrous N	sbestos 90% ake Pad sbestos	None Detected Asbestos	System_ID: Lab Sample ID: Comment	041535095-0008 041535095-0009
Client Sample ID: Sample Description: TEST PLM Client Sample ID:	Date 12/01/2015 03-SG5-008 Park Rd Bridge/W Side Abur Analyzed Date 12/01/2015	Color Black tment 5/5th Guard Color Black	Non-As Fibrous N 10% IS Side/Black Ra Non-As Fibrous N	sbestos 90% ake Pad sbestos	None Detected Asbestos	System_ID: Lab Sample ID: Comment System_ID:	
PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID:	Date 12/01/2015 03-SG5-008 Park Rd Bridge/W Side Abur Analyzed Date 12/01/2015 03-SG5-009 West Side Abutment/Center.	Color Black tment 5/5th Guard Color Black	Non-As Fibrous N 10% IS Side/Black Ra Non-As Fibrous N 10%	sbestos 90% ake Pad sbestos Non-Fibrous 90%	None Detected Asbestos	System_ID: Lab Sample ID: Comment System_ID:	
PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID:	Date 12/01/2015 03-SG5-008 Park Rd Bridge/W Side Abur Analyzed Date 12/01/2015	Color Black tment 5/5th Guard Color Black	Non-As Fibrous N 10% IS Side/Black Ra Non-As Fibrous N 10%	sbestos 90% ake Pad sbestos	None Detected Asbestos	System_ID: Lab Sample ID: Comment System_ID:	
Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description:	Date 12/01/2015 03-SG5-008 Park Rd Bridge/W Side Abur Analyzed Date 12/01/2015 03-SG5-009 West Side Abutment/Center. Analyzed	Color Black Color Black /Black Rake Pad	Non-As Fibrous N 10% IS Side/Black Ra Non-As Fibrous N 10%	sbestos 90% ake Pad sbestos 90%	Asbestos None Detected	System_ID: Lab Sample ID: Comment System_ID: Lab Sample ID: Comment	
Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM	Date 12/01/2015 03-SG5-008 Park Rd Bridge/W Side Abur Analyzed Date 12/01/2015 03-SG5-009 West Side Abutment/Center Analyzed Date	Color Black Color Black /Black Rake Pad Color	Non-Add S Side/Black Rate Non-Add S Side/Black Rate Non-Add Side/Black Rate Non-Add Side Non-Add	sbestos Non-Fibrous 90% ake Pad sbestos Non-Fibrous 90% sbestos Non-Fibrous	Asbestos Asbestos	System_ID: Lab Sample ID: Comment System_ID: Lab Sample ID: Comment System_ID:	041535095-0009
Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM	Date 12/01/2015 03-SG5-008 Park Rd Bridge/W Side Abur Analyzed Date 12/01/2015 03-SG5-009 West Side Abutment/Center Analyzed Date	Color Black Color Black /Black Rake Pad Color	Non-Add S Side/Black Rate Non-Add S Side/Black Rate Non-Add Side/Black Rate Non-Add Side Non-Add	sbestos Non-Fibrous 90% ake Pad sbestos Non-Fibrous 90% sbestos Non-Fibrous	Asbestos Asbestos	System_ID: Lab Sample ID: Comment System_ID: Lab Sample ID: Comment	
Client Sample ID: Sample Description: TEST Client Sample ID: Sample Description: TEST Client Sample ID: Client Sample ID:	Date 12/01/2015 03-SG5-008 Park Rd Bridge/W Side Abur Analyzed Date 12/01/2015 03-SG5-009 West Side Abutment/Center. Analyzed Date 12/01/2015	Color Black Color Black /Black Rake Pad Color Black	Non-As Fibrous Non-As	sbestos 90% ake Pad sbestos Non-Fibrous 90% sbestos 90%	Asbestos Asbestos	System_ID: Lab Sample ID: Comment System_ID: Lab Sample ID: Comment System_ID:	041535095-0009
PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Client Sample ID:	Date 12/01/2015 03-SG5-008 Park Rd Bridge/W Side Abur Analyzed Date 12/01/2015 03-SG5-009 West Side Abutment/Center. Analyzed Date 12/01/2015 04-RF2-010 Park Rd Bridge W Abutment	Color Black Color Black /Black Rake Pad Color Black	Non-As Fibrous Non-As	sbestos Non-Fibrous 90% ake Pad sbestos Non-Fibrous 90% sbestos Non-Fibrous 90%	Asbestos Asbestos	System_ID: Lab Sample ID: Comment System_ID: Lab Sample ID: Comment System_ID:	041535095-0009
PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Client Sample ID:	Date	Color Black Color Black /Black Rake Pad Color Black	Non-Aside W.Sid/Tar Pa	sbestos 90% ake Pad sbestos Non-Fibrous 90% sbestos 90%	Asbestos Asbestos	System_ID: Lab Sample ID: Comment System_ID: Lab Sample ID: Comment System_ID:	041535095-0009
PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description:	Date 12/01/2015 03-SG5-008 Park Rd Bridge/W Side Abur Analyzed Date 12/01/2015 03-SG5-009 West Side Abutment/Center. Analyzed Date 12/01/2015 04-RF2-010 Park Rd Bridge W Abutment Analyzed	Color Black Tement 5/5th Guard Color Black /Black Rake Pad Color Black	Non-Aside W.Sid/Tar Pa	sbestos Non-Fibrous 90% ake Pad sbestos Non-Fibrous 90% sbestos Non-Fibrous 90% sper sbestos	Asbestos None Detected Asbestos None Detected Asbestos	System_ID: Lab Sample ID: Comment System_ID: Lab Sample ID: Comment System_ID: Lab Sample ID:	041535095-0009



200 Route 130 North Cinnaminson, NJ 08077 Phone/Fax: (800) 220-3675 / (856) 786-5974 http://www.EMSL.com / cinnasblab@EMSL.com EMSL Order ID: Customer ID:

041535095 ACON77

Customer PO: Project ID:

Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116 Method via

		P	olarized Ligi	IL MIICIOS	сору		
Client Sample ID:	04-RF2-011					Lab Sample ID:	041535095-0011
Sample Description:	Hanger East of Sample #10	Tar Paper					
	Analyzed		Non-Asi				
PLM	Date	Color	Fibrous No	85%	Asbestos	Comment	
PLIVI	12/01/2015	Black	15%	85%	None Detected	System_ID:	
Client Sample ID:	04-RF2-012					Lab Sample ID:	041535095-0012
Sample Description:	3rd Hanger East of West Ab	utment/Tar Paper					
	J	·					
	Analyzed		Non-Asi	oestos			
TEST	Date	Color	Fibrous No		Asbestos	Comment	
PLM	12/01/2015	Black	40%	60%	None Detected	System_ID:	
Client Sample ID:	05-CP2-013					Lab Sample ID:	041535095-0013
Sample Description:		A b t	da/Carrant Dina			Lab Gampie IB.	041000000-0010
Sample Description.	Under Park Rd Bridge at W	Abutment & S. Si	de/Cement Pipe				
	Analyzed		Non-Asi	estos			
TEST	Date	Color	Fibrous No	n-Fibrous	Asbestos	Comment	
PLM	12/01/2015	Gray	0%	67%	25% Chrysotile		
					8% Crocidolite	System_ID:	
					6% Crocidonte	System_ID:	
Client Sample ID:	05-CP2-014					Lab Sample ID:	041535095-0014
Sample Description:	Far West Run of Pipe Under	Bridge/Cement I	Pipe				
	, , , , , , , , , , , , , , , , , , ,	3	r -				
	Analyzed		Non-Asi	oestos			
TEST	Date	Color	Fibrous No	n-Fibrous	Asbestos	Comment	
PLM	12/01/2015	Gray	0%	60%	30% Chrysotile	System ID:	
						System_ID:	
					10% Crocidolite		
					10% Crocidolite	System_ID:	
Client Sample ID:	05-CP2-015				10% Grocidolite	System_ID: Lab Sample ID:	041535095-0015
Client Sample ID: Sample Description:	05-CP2-015 E Pipe/E of Collar on Pipe o	n W Abutment/Ce	ement Pipe		10% Crocidolite		041535095-0015
•		n W Abutment/Ce	ement Pipe		10% Crocidolite		041535095-0015
Sample Description:	E Pipe/E of Collar on Pipe o		Non-Asi			Lab Sample ID:	041535095-0015
Sample Description:	E Pipe/E of Collar on Pipe o Analyzed Date	Color	Non-Asl Fibrous No	n-Fibrous	Asbestos		041535095-0015
Sample Description:	E Pipe/E of Collar on Pipe o		Non-Asi			Lab Sample ID: Comment	041535095-0015
Sample Description:	E Pipe/E of Collar on Pipe o Analyzed Date	Color	Non-Asl Fibrous No	n-Fibrous	Asbestos	Comment System_ID:	041535095-0015
Sample Description: TEST PLM	E Pipe/E of Collar on Pipe o Analyzed Date 12/01/2015	Color	Non-Asl Fibrous No	n-Fibrous	Asbestos 20% Chrysotile	Comment System_ID: System_ID:	
TEST PLM Client Sample ID:	E Pipe/E of Collar on Pipe o Analyzed Date	Color	Non-Asl Fibrous No	n-Fibrous	Asbestos 20% Chrysotile	Comment System_ID:	041535095-0015 041535095-0016
Sample Description: TEST PLM Client Sample ID:	E Pipe/E of Collar on Pipe o Analyzed Date 12/01/2015	Color Gray	Non-Asl Fibrous No 0%	n-Fibrous	Asbestos 20% Chrysotile	Comment System_ID: System_ID:	
TEST PLM Client Sample ID:	E Pipe/E of Collar on Pipe o Analyzed Date 12/01/2015 06-SC2-016 Park Rd Brige S Side/W Abu	Color Gray	Non-Asl Fibrous No 0%	70%	Asbestos 20% Chrysotile	Comment System_ID: System_ID:	
TEST PLM Client Sample ID: Sample Description:	E Pipe/E of Collar on Pipe o Analyzed Date 12/01/2015 06-SC2-016 Park Rd Brige S Side/W Abu	Color Gray 	Non-Asi Fibrous No 0% minous Coating	70%	Asbestos 20% Chrysotile 10% Crocidolite	Comment System_ID: System_ID: Lab Sample ID:	
TEST PLM Client Sample ID: Sample Description:	E Pipe/E of Collar on Pipe o Analyzed Date 12/01/2015 06-SC2-016 Park Rd Brige S Side/W Abu Analyzed Date	Color Gray utment/Black Bitu	Non-Asl Fibrous Non-Asl Fibrous Non-Asl	n-Fibrous 70% pestos n-Fibrous	Asbestos 20% Chrysotile 10% Crocidolite Asbestos	Comment System_ID: System_ID:	
TEST PLM Client Sample ID: Sample Description:	E Pipe/E of Collar on Pipe o Analyzed Date 12/01/2015 06-SC2-016 Park Rd Brige S Side/W Abu	Color Gray 	Non-Asi Fibrous No 0% minous Coating	70%	Asbestos 20% Chrysotile 10% Crocidolite	Comment System_ID: System_ID: Lab Sample ID:	
TEST PLM Client Sample ID: Sample Description: TEST PLM	E Pipe/E of Collar on Pipe o Analyzed Date 12/01/2015 06-SC2-016 Park Rd Brige S Side/W Abu Analyzed Date	Color Gray utment/Black Bitu	Non-Asl Fibrous Non-Asl Fibrous Non-Asl	n-Fibrous 70% pestos n-Fibrous	Asbestos 20% Chrysotile 10% Crocidolite Asbestos	Comment System_ID: System_ID: Lab Sample ID: Comment	
TEST PLM Client Sample ID: Sample Description: TEST PLM	E Pipe/E of Collar on Pipe o Analyzed Date 12/01/2015 06-SC2-016 Park Rd Brige S Side/W Abu Analyzed Date 12/01/2015	Color Gray utment/Black Bitu Color Black	Non-Asl Fibrous Non-Asl Fibrous Non-Asl	n-Fibrous 70% pestos n-Fibrous	Asbestos 20% Chrysotile 10% Crocidolite Asbestos	Comment System_ID: System_ID: Lab Sample ID: Comment System_ID:	041535095-0016
TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID:	Analyzed Date 12/01/2015 06-SC2-016 Park Rd Brige S Side/W Abu Analyzed Date 12/01/2015	Color Gray utment/Black Bitu Color Black	Non-Asl Fibrous Non-Asl Fibrous Non-Asl	n-Fibrous 70% pestos n-Fibrous	Asbestos 20% Chrysotile 10% Crocidolite Asbestos	Comment System_ID: System_ID: Lab Sample ID: Comment System_ID:	041535095-0016
TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description:	Analyzed Date 12/01/2015 06-SC2-016 Park Rd Brige S Side/W Abu Analyzed Date 12/01/2015	Color Gray utment/Black Bitu Color Black	Non-Asl Fibrous No 0% minous Coating Non-Asl Fibrous No 0%	pestos 100%	Asbestos 20% Chrysotile 10% Crocidolite Asbestos	Comment System_ID: System_ID: Lab Sample ID: Comment System_ID: Lab Sample ID:	041535095-0016
TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID:	Analyzed Date 12/01/2015 06-SC2-016 Park Rd Brige S Side/W Abu Analyzed Date 12/01/2015 06-SC2-017 On West Side/Black Bitumin	Color Gray utment/Black Bitu Color Black	Non-Asl Fibrous No 0% minous Coating Non-Asl Fibrous No 0%	pestos 100%	Asbestos 20% Chrysotile 10% Crocidolite Asbestos	Comment System_ID: System_ID: Lab Sample ID: Comment System_ID:	041535095-0016



200 Route 130 North Cinnaminson, NJ 08077 Phone/Fax: (800) 220-3675 / (856) 786-5974 http://www.EMSL.com / cinnasblab@EMSL.com EMSL Order ID: Customer ID:

Project ID:

041535095

ACON77 Customer PO:

Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116 Method via **Polarized Light Microscopy**

						1 . 1 . 0	A / / BABAA =
Client Sample ID:	06-SC2-018					Lab Sample ID:	041535095-0018
Sample Description:	10' East of #17/Black Bitumin	ous Coating					
	Analyzad		Me-	-Asbestos			
TEST	Analyzed Date	Color		-Aspestos Non-Fibrous	Asbestos	Comment	
PLM	12/01/2015	Black	15%	85%	None Detected	Commone	
· -···	·			 		System_ID:	
Client Sample ID:	07-CA5-019					Lab Sample ID:	041535095-0019
Sample Description:	Bottom Side of 45 elbow/E side	de of Bridge on F	PVC/Cream/Ro	se Colored Caulk			
	Analyzed		Non-	-Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	12/01/2015	Tan	0%	100%	None Detected	Custom ID:	
011	07.045.000					System_ID:	041535095-0020
Client Sample ID:	07-CA5-020					Lab Sample ID:	041535095-0020
Sample Description:	Left of Sample #019/Cream/F	Rose Colored Ca	ulk				
	Analyzed		Non	-Asbestos			
TEST	Date	Color		Non-Fibrous	Asbestos	Comment	
PLM	12/01/2015	Tan	0%	100%	None Detected		
						System_ID:	
Client Sample ID:	07-CA5-021					Lab Sample ID:	041535095-0021
Chefft Sample ID.	07 0710 021						
•	On top of 45 PVC elbow Nea	r #019/Cream/Ro	ose Colored Ca	aulk			
•		r #019/Cream/Ro	ose Colored Ca	aulk			
Sample Description:		r #019/Cream/Ro	Non-	-Asbestos			
Sample Description:	On top of 45 PVC elbow Nea Analyzed Date	Color	Non- Fibrous	-Asbestos Non-Fibrous	Asbestos	Comment	
Sample Description:	On top of 45 PVC elbow Nea Analyzed		Non-	-Asbestos Non-Fibrous	Asbestos None Detected		
Sample Description: TEST PLM	On top of 45 PVC elbow Nea Analyzed Date 12/01/2015	Color	Non- Fibrous	-Asbestos Non-Fibrous		System_ID:	041535095-0022
TEST PLM Client Sample ID:	On top of 45 PVC elbow Nea Analyzed Date 12/01/2015	Color Tan	Non- Fibrous 0%	Asbestos Non-Fibrous 100%			041535095-0022
TEST PLM Client Sample ID:	On top of 45 PVC elbow Nea Analyzed Date 12/01/2015	Color Tan	Non- Fibrous 0%	Asbestos Non-Fibrous 100%		System_ID:	041535095-0022
TEST PLM Client Sample ID:	On top of 45 PVC elbow Nea Analyzed Date 12/01/2015 08-PI5-022 W Pipe at Eastern Mast Light	Color Tan	Non- Fibrous 0% Black Tarry Pip	Asbestos Non-Fibrous 100% De Coating		System_ID:	041535095-0022
TEST PLM Client Sample ID:	On top of 45 PVC elbow Nea Analyzed Date 12/01/2015	Color Tan	Non- Fibrous 0% Black Tarry Pip	Asbestos Non-Fibrous 100%		System_ID:	041535095-0022
TEST PLM Client Sample ID: Sample Description: TEST	On top of 45 PVC elbow Nea Analyzed Date 12/01/2015 08-PI5-022 W Pipe at Eastern Mast Light Analyzed	Color Tan	Non- Fibrous 0% Black Tarry Pip	Asbestos Non-Fibrous 100% De Coating Asbestos Non-Fibrous	None Detected	System_ID: Lab Sample ID:	041535095-0022
TEST PLM Client Sample ID: Sample Description:	On top of 45 PVC elbow Nea Analyzed Date 12/01/2015 08-PI5-022 W Pipe at Eastern Mast Light Analyzed Date	Color Tan Station Access/I	Non- Fibrous 0% Black Tarry Pip Non- Fibrous	Asbestos Non-Fibrous 100% De Coating Asbestos Non-Fibrous	None Detected Asbestos	System_ID: Lab Sample ID:	041535095-0022
TEST PLM Client Sample ID: Sample Description: TEST PLM	On top of 45 PVC elbow Nea Analyzed Date 12/01/2015 08-PI5-022 W Pipe at Eastern Mast Light Analyzed Date	Color Tan Station Access/I	Non- Fibrous 0% Black Tarry Pip Non- Fibrous	Asbestos Non-Fibrous 100% De Coating Asbestos Non-Fibrous	None Detected Asbestos	System_ID: Lab Sample ID: Comment	041535095-0022 041535095-0023
TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID:	On top of 45 PVC elbow Nea Analyzed Date 12/01/2015 08-PI5-022 W Pipe at Eastern Mast Light Analyzed Date 12/01/2015	Color Station Access/l Color Black	Non- Fibrous 0% Black Tarry Pip Non- Fibrous 15%	Asbestos Non-Fibrous 100% De Coating Asbestos Non-Fibrous 85%	None Detected Asbestos	System_ID: Lab Sample ID: Comment System_ID:	
TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID:	On top of 45 PVC elbow Nea Analyzed Date 12/01/2015 08-PI5-022 W Pipe at Eastern Mast Light Analyzed Date 12/01/2015 08-PI5-023 E Pipe at Eastern Mast Light	Color Station Access/l Color Black	Non- Fibrous 0% Black Tarry Pip Non- Fibrous 15% ck Tarry Pipe C	Asbestos Non-Fibrous 100% De Coating Asbestos Non-Fibrous 85% Coating	None Detected Asbestos	System_ID: Lab Sample ID: Comment System_ID:	
TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description:	On top of 45 PVC elbow Nea Analyzed Date 12/01/2015 08-PI5-022 W Pipe at Eastern Mast Light Analyzed Date 12/01/2015 08-PI5-023 E Pipe at Eastern Mast Light Analyzed Analyzed	Color Tan Station Access/I Color Black Pole Access/Black	Non- Fibrous Black Tarry Pip Non- Fibrous 15% ck Tarry Pipe C	Asbestos Non-Fibrous 100% De Coating Asbestos Non-Fibrous 85% Coating	Asbestos None Detected	System_ID: Lab Sample ID: Comment System_ID: Lab Sample ID:	
TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description:	On top of 45 PVC elbow Nea Analyzed Date 12/01/2015 08-PI5-022 W Pipe at Eastern Mast Light Analyzed Date 12/01/2015 08-PI5-023 E Pipe at Eastern Mast Light Analyzed Date Analyzed Date	Color Tan Station Access/I Color Black Pole Access/Black Color	Non- Fibrous O% Black Tarry Pip Non- Fibrous 15% ck Tarry Pipe C Non- Fibrous	Asbestos Non-Fibrous 100% De Coating Asbestos Non-Fibrous 85% Coating Asbestos Non-Fibrous	Asbestos Asbestos Asbestos	System_ID: Lab Sample ID: Comment System_ID:	
TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description:	On top of 45 PVC elbow Nea Analyzed Date 12/01/2015 08-PI5-022 W Pipe at Eastern Mast Light Analyzed Date 12/01/2015 08-PI5-023 E Pipe at Eastern Mast Light Analyzed Analyzed	Color Tan Station Access/I Color Black Pole Access/Black	Non- Fibrous Black Tarry Pip Non- Fibrous 15% ck Tarry Pipe C	Asbestos Non-Fibrous 100% De Coating Asbestos Non-Fibrous 85% Coating Asbestos Non-Fibrous	Asbestos None Detected	System_ID: Lab Sample ID: Comment System_ID: Lab Sample ID: Comment	
TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM TEST PLM TEST	On top of 45 PVC elbow Nea Analyzed Date 12/01/2015 08-PI5-022 W Pipe at Eastern Mast Light Analyzed Date 12/01/2015 08-PI5-023 E Pipe at Eastern Mast Light Analyzed Date 12/01/2015	Color Tan Station Access/I Color Black Pole Access/Black Color	Non- Fibrous O% Black Tarry Pip Non- Fibrous 15% ck Tarry Pipe C Non- Fibrous	Asbestos Non-Fibrous 100% De Coating Asbestos Non-Fibrous 85% Coating Asbestos Non-Fibrous	Asbestos Asbestos Asbestos	System_ID: Lab Sample ID: Comment System_ID: Lab Sample ID: Comment System_ID:	041535095-0023
TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description:	On top of 45 PVC elbow Nea Analyzed Date 12/01/2015 08-PI5-022 W Pipe at Eastern Mast Light Analyzed Date 12/01/2015 08-PI5-023 E Pipe at Eastern Mast Light Analyzed Date 12/01/2015	Color Tan Station Access/I Color Black Pole Access/Black Color Black	Non- Fibrous 15% Ck Tarry Pipe C Non- Fibrous 10%	Asbestos Non-Fibrous 100% De Coating Asbestos Non-Fibrous 85% Coating Asbestos Non-Fibrous	Asbestos Asbestos Asbestos	System_ID: Lab Sample ID: Comment System_ID: Lab Sample ID: Comment	
TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description:	On top of 45 PVC elbow Nea Analyzed Date 12/01/2015 08-PI5-022 W Pipe at Eastern Mast Light Analyzed Date 12/01/2015 08-PI5-023 E Pipe at Eastern Mast Light Analyzed Date 12/01/2015	Color Tan Station Access/I Color Black Pole Access/Black Color Black	Non- Fibrous 15% Ck Tarry Pipe C Non- Fibrous 10%	Asbestos Non-Fibrous 100% De Coating Asbestos Non-Fibrous 85% Coating Asbestos Non-Fibrous	Asbestos Asbestos Asbestos	System_ID: Lab Sample ID: Comment System_ID: Lab Sample ID: Comment System_ID:	041535095-0023
TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description:	On top of 45 PVC elbow Nea Analyzed Date 12/01/2015 08-PI5-022 W Pipe at Eastern Mast Light Analyzed Date 12/01/2015 08-PI5-023 E Pipe at Eastern Mast Light Analyzed Date 12/01/2015 08-PI5-024 Main Pipe of Sample #23/Bla	Color Tan Station Access/I Color Black Pole Access/Black Color Black	Non- Fibrous O% Black Tarry Pip Non- Fibrous 15% Ck Tarry Pipe C Non- Fibrous 10% ating	Asbestos Non-Fibrous 100% De Coating Asbestos Non-Fibrous 85% Coating Asbestos Non-Fibrous 90%	Asbestos Asbestos Asbestos	System_ID: Lab Sample ID: Comment System_ID: Lab Sample ID: Comment System_ID:	041535095-0023
TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description:	On top of 45 PVC elbow Nea Analyzed Date 12/01/2015 08-PI5-022 W Pipe at Eastern Mast Light Analyzed Date 12/01/2015 08-PI5-023 E Pipe at Eastern Mast Light Analyzed Date 12/01/2015	Color Tan Station Access/I Color Black Pole Access/Black Color Black	Non- Fibrous Non- Fibrous 15% Ck Tarry Pipe C Non- Fibrous 10% ating Non-	Asbestos Non-Fibrous 100% De Coating Asbestos Non-Fibrous 85% Coating Asbestos Non-Fibrous	Asbestos Asbestos Asbestos	System_ID: Lab Sample ID: Comment System_ID: Lab Sample ID: Comment System_ID:	041535095-0023
TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description:	On top of 45 PVC elbow Nea Analyzed Date 12/01/2015 08-PI5-022 W Pipe at Eastern Mast Light Analyzed Date 12/01/2015 08-PI5-023 E Pipe at Eastern Mast Light Analyzed Date 12/01/2015 08-PI5-024 Main Pipe of Sample #23/Bla	Color Tan Station Access/I Color Black Pole Access/Black Color Black Color	Non- Fibrous Non- Fibrous 15% Ck Tarry Pipe C Non- Fibrous 10% ating Non-	Asbestos Non-Fibrous 100% De Coating Asbestos Non-Fibrous 85% Coating Asbestos Non-Fibrous 90% Asbestos Non-Fibrous	Asbestos None Detected Asbestos None Detected	System_ID: Lab Sample ID: Comment System_ID: Lab Sample ID: Comment System_ID: Lab Sample ID:	041535095-0023



200 Route 130 North Cinnaminson, NJ 08077 Phone/Fax: (800) 220-3675 / (856) 786-5974 http://www.EMSL.com / cinnasblab@EMSL.com EMSL Order ID: Customer ID: Customer PO:

Project ID:

041535095

ACON77

Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116 Method via **Polarized Light Microscopy**

Client Sample ID:	09-SC5-025			<u>J </u>	-1.7	Lab Sample ID:	041535095-0025
Sample Description:	Park Rd/Western Cross Wa	Jk/S Sido/juot W.	of Pridgo/Plack F	Expansion laint		_aa cap.c	041000000 0020
ample Description.	Park Ru/Western Cross Wa	lik/S Side/just vv t	or bridge/black b	expansion Joint			
	Analyzed		Non-	Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	12/01/2015	Black	0%	100%	None Detected	0 / 10	
						System_ID:	044505005.000
Client Sample ID:	09-SC5-026					Lab Sample ID:	041535095-0026
Sample Description:	Park Rd/Opposite Side of S	ample #025/Blac	k Expansion Joir	nt			
	Analyzed		Non-	Asbestos			
TEST	Date	Color		Non-Fibrous	Asbestos	Comment	
PLM	12/01/2015	Black	0%	100%	None Detected		
						System_ID:	
Client Sample ID:	09-SC5-027					Lab Sample ID:	041535095-0027
Sample Description:	Dubuque Rd/East of Sampl	e #30/Black Expa	ansion Joint				
	Analyzed		Non	Asbestos			
TEST	Date	Color		Non-Fibrous	Asbestos	Comment	
PLM	12/01/2015	Black	0%	100%	None Detected		
						System_ID:	
Client Sample ID:	10-SC5-028					Lab Sample ID:	041535095-0028
Sample Description:	Southeast Post for Chain Li	nk Fence/N Side	Off-White/Crean	n Glue			
	Analyzod		Non	Asbestos			
TEST	Analyzed Date	Color		Non-Fibrous	Asbestos	Comment	
PLM	12/01/2015	Tan	0%	100%	None Detected		
						System_ID:	
Client Sample ID:	10-SC5-029					Lab Sample ID:	041535095-0029
Sample Description:	Southeast Post for Chain Li	nk Fence/S Side/	Off-White/Crean	n Glue			
TEST	Analyzed Date	Color		Asbestos Non-Fibrous	Asbestos	Comment	
PLM	12/01/2015	Tan	0%	100%	None Detected	Commone	
						System_ID:	
Client Sample ID:	10-SC5-030					Lab Sample ID:	041535095-0030
Sample Description:	Chain Link Fence/W of Dub	uque St/10th Pos	st S of N/Off-Whi	te/Cream Glue			
				A = b = = 4 = =			
TEST	Analyzed Date	Color		Asbestos Non-Fibrous	Asbestos	Comment	
PLM	12/01/2015	Tan	0%	100%	None Detected	- Commont	
			0,0		= 3.00	System_ID:	



200 Route 130 North Cinnaminson, NJ 08077 Phone/Fax: (800) 220-3675 / (856) 786-5974 http://www.EMSL.com / cinnasblab@EMSL.com EMSL Order ID: Customer ID: 041535095 ACON77

Customer PO:
Project ID:

Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116 Method via Polarized Light Microscopy

Analyst(s):

Andrew Coward PLM (22)
Samantha Rundstorm-Cruz PLM (11)

William Nguyen 400 PLM Pt Ct (3)

Reviewed and approved by:

Benjamin Ellis, Laboratory Manager or Other Approved Signatory

H

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. This test report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. EMSL bears no responsibility for sample collection activities or analytical method limitations. The laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. PLM alone is not consistently reliable in detecting asbestos in floor coverings and similar NOBs

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NVLAP Lab Code 101048-0, AIHA-LAP, LLC-IHLAP Lab 100194, NYS ELAP 10872, NJ DEP 03036

Report amended: 12/02/201516:15:10 Replaces initial report from: 12/02/201507:04:29 Reason Code: Client-Additional Analysis

OrderID: 041535095

9415350A Select a Laboratory:

Lab Order ID:

Lab Location: HQ - Cinnaminson, NJ 101048-0

SP-156041 Page 42 of 80

Asbestos Bulk Sample and Chain of Custody Form

Cedar Rapids: 2640 12th St., SW, Cedar Rapids, IA 52404 (319) 366 8321

Terracon

lowa City, lowa 06157085 Project Number: City/State / Zip:

eric.harris@terracon.com **Eric Harris** Project Manager: Email Results To:

Dubuque St./Park Rd Dubuque St./Park Rd lowa City Gateway Project Address: Site/Building: Project Name:

		A CAMPAGE AND A		Material		:	
	Sample Identification BS Sample HA Code #	Sample Location Description	HA General Location	ت و ا	Quantity NESHAP (SF, LF, Cubic Classification ¹ Ft, Units)	NESHAP Classification ¹	Notes/Physical Condition ²
	ā	Part Rd. Bridge Novide; 2nd Newers park mil 1964	Pan Rd. Brda	<u> </u>	10" K 0"e,	F C1 (C)	os 🐠 s
	60g	New Site of Bridge light Murell part of the 3rd Course	under Kennelds Webzit				કે આ દુ
	01 - CAS 03>	Sout sites bridge, 15t gues in fact there East	rosts (on state)		jet tal		g was rails
P	102 - MSY - 204	Park Red. Bridge west wite otherment. N. side	Park Road Bridge	- Bem Pas	Cont. a.a.	F C1 🙆	os 🔘 🤋
age	62 -M58 - 005	Park Pura Bridge Court S. dy colone mar N. Fale 4' Als	Charmen's foun	hour mash			
1 0	100 - 78M- 20	02 Mss - 006 Pave Rd Bridge 82, 4 abutrant, south fear above Pur					
f	03 -565 204	Perk Rais bridge west side stephens, 5th goder how	Parl Paul Bridge	אלנע	Serienary.	F C1 🕭	os 🚱 o
2	35 - 525 - 506	" Such site	Rue Aust	Andrew Park	•	15	C
		West side abstract, with	given plake	!		LLA .	ΙΝΝΔ
		Rest Rud boilde wast chatment hinger with mist	Astrobo Concert	190 paper	4 sefranza		as elying
	110 - 15th - 1011	Narger earl of Semple #10	Shearyer	-		AM IC	/::L SOM,
	10 -757 ho	3.4 hense Bast of weitherthent					ИJ
	05 - CD2 - 013 U	Under Peril Ad- Inside at west multiplents side and	South Side		Paret	F C C	os o (9)
	رور - مام - مام	Far wer han of our water bridge	Ope cart	gent of	\$0x3		
	05-42- 215	east Pipe/pastel (eller on pire or west abultunt	Park lid. Brish		38°L		
	Sampling Date: 1/124/19	4/15 Collected by (print): Ent Hans & Jake	おから Inspector's Signature:	ure:	1		
			•				

Number of samples:

Stop Positive:

Terracon ARMS: X

Instructions:

Date/Time: |

D

ENSL FF

Received by:

1450

Date/Time: ///2-1/15

Analysis: PLM EPA 600/R-93/116 🗷 PLM 400 Point Count 🗆 TEM 🗇 Other Turnaround Time: 6 Hrs 🗆 24 Hrs 🗀 2 Days 🗔 3 Days 🖨 5 Days 🔣 Other

Relinquished by:

¹ F = Friable; C1 = Category I: packings, gaskets, asphaltic roofing products, resilient flooring; C2 = Category II Non-Friable: any materials other than Cat. I containing >1% asbestos ² G = Good (<1%); D = Damaged (<10% distributed or >25% localized); or SD = Significantly Damaged (>10% distributed or >25% localized)

OrderID: 041535095

Asbestos Bulk Sample and Chain of Custody Form Cedar Rapids: 2640 12th St., SW, Cedar Rapids, 1A 52404 (319) 366 8321

() O 41535095 Select a Laboratory: Page 2 of Lab Location: HQ - Cinnaminson, NJ 101048-0

Lab Order ID:

í	Total Indiana				Ouantity		
Š	ほこし	Sample Location Description	HA General Location	Material Description (Type;	(SF, LF, Cubic Ft,	NESHAP ¹ Classification	Notes/Physical Condition ²
HA -	BS Sample			Color/Texture)	Units)	70	9
3	36- 71-	D. A. C. C. S.	Gas mair	Bleck			
5	30		14 A A A A	Giften bors	3. cr		
ర	75 -12 -30 -30	at still on west site	Perie Fa.	(8.13	; }		
<u> </u>	Gl = 1, 7 =		1×1×1×1				
ರ	317 775 80		7000	Cream		F C1	s So
5	NJ - CAS - CAS	Differ size of 450 plbin exitsize of bridge or Pre	rve Fr	(PX			
<u> </u>			K-1-2	ColorAct	95,		
40	70 - 247 - 60	124 of Senes + 019	Bridge Gust	coulk	_		
	11 - H7 - 40	9	Gorber				
_	70		0. 61 hills	9 ii.	,	п П	© SO
g e	70x - 514-	West pile at Duston most light staden alles	400 TO 100 TO 10	15 fe ce + 4.4.79	-		
2	,		Median Best	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
Of	670 - 570 - 30	East Pipe at parter Mast light fix access	×1.4	1000000			
<u> </u>	- CXX - 2*	** ** ** ** ** ** ** ** ** ** ** ** **		\$ earson			ļ
	०५ १० १०	IMA FILE OF SUMMY # 63	(2		4	л П	OS (Q) 9
2	m - 545 - 225	The Road toward will a such often your Real for the	יייייייייייייייייייייייייייייייייייייי	10 (2 K)	CARCHANA)
5			ر مارد ر	7 X		1!	()
8	-5x5 - 026	Par land office we side of sample of east		<u>,</u>		5 N	; [A]
<u> </u>	-465- 272					OA	
5		Cubingue Rose and Ot Survey	Red to mak	č		7 U	as Pub
0	320 -55-	Scutteres post 6 Charling And North	31717040	14:50-40		, F	_
	%20 =		10 to 10 to	Š		in i	JM.
<u></u>	xx 0		Windram And Control	1 9 E		<u> </u>	₩.
	10-56- ca	Chan link figure, wa	Dalens +	عـــ	T.C. 519	4	
2	3	STATES BOX HIS				F C1 C2	OS O 9
	ı						
l							
	1				_	_	

<u>TestAmerica</u>

THE LEADER IN ENVIRONMENTAL TESTING

ANALYTICAL REPORT

TestAmerica Laboratories, Inc.

TestAmerica Cedar Falls 704 Enterprise Drive Cedar Falls, IA 50613 Tel: (319)277-2401

TestAmerica Job ID: 310-70018-1 Client Project/Site: Gateway Project

For:

Terracon Consulting Eng & Scientists 2640 12th Street SW Cedar Rapids, Iowa 52404

Attn: Eric Harris

angela Muchling

Authorized for release by: 12/4/2015 10:32:04 AM Angela Muehling, Project Manager I angela.muehling@testamericainc.com

Designee for

Shawn Hayes, Project Manager II (319)277-2401

shawn.hayes@testamericainc.com

.....LINKS

Review your project results through
Total Access

Have a Question?



Visit us at: www.testamericainc.com

This report has been electronically signed and authorized by the signatory. Electronic signature is intended to be the legally binding equivalent of a traditionally handwritten signature.

Results relate only to the items tested and the sample(s) as received by the laboratory.

TestAmerica Job ID: 310-70018-1

Client: Terracon Consulting Eng & Scientists Project/Site: Gateway Project

Table of Contents

Cover Page	1
Table of Contents	2
Case Narrative	3
Sample Summary	4
Detection Summary	5
Client Sample Results	6
Definitions	13
QC Sample Results	14
QC Association	15
Chronicle	16
Certification Summary	18
Method Summary	19
Chain of Custody	20
Receipt Checklists	22

9

4

5

7

9

10

12

13

Case Narrative

Client: Terracon Consulting Eng & Scientists

Project/Site: Gateway Project

TestAmerica Job ID: 310-70018-1

Job ID: 310-70018-1

Laboratory: TestAmerica Cedar Falls

Narrative

Job Narrative 310-70018-1

Comments

No additional comments.

Receipt

The samples were received on 12/1/2015 10:15 AM; the samples arrived in good condition, properly preserved and, where required, on ice.

Metals

Method(s) 6010C: The following sample was diluted due to the presence of an interferent: Chip 2 (310-70018-2). Elevated reporting limits (RLs) are provided.

No additional analytical or quality issues were noted, other than those described above or in the Definitions/Glossary page.

Sample Summary

Client: Terracon Consulting Eng & Scientists Project/Site: Gateway Project

TestAmerica Job ID: 310-70018-1

Lab Sample ID	Client Sample ID	Matrix	Collected	Received
310-70018-1	Chip 1	Paint Chips	11/24/15 00:00	12/01/15 10:15
310-70018-2	Chip 2	Paint Chips	11/24/15 00:00	12/01/15 10:15
310-70018-3	Chip 3	Paint Chips	11/24/15 00:00	12/01/15 10:15
310-70018-4	Chip 4	Paint Chips	11/24/15 00:00	12/01/15 10:15
310-70018-5	Chip 5	Paint Chips	11/24/15 00:00	12/01/15 10:15
310-70018-6	Chip 6	Paint Chips	11/24/15 00:00	12/01/15 10:15
310-70018-7	Chip 7	Paint Chips	11/24/15 00:00	12/01/15 10:15

Detection Summary

Client: Terracon Consulting Eng & Scientists

Project/Site: Gateway Project

Client Sample ID: Chip 1

TestAmerica Job ID: 310-70018-1

Lab Sample ID: 310-70018-1

Result Qualifier RL **MDL** Unit Dil Fac D Method Analyte Prep Type 6010C 0.118 F1 F2 0.00100 % by Wt Chromium Total/NA % by Wt 6010C Total/NA Lead 21.3 0.00500

Client Sample ID: Chip 2 Lab Sample ID: 310-70018-2

Analyte Result Qualifier RL **MDL** Unit Dil Fac D Method Prep Type Chromium 0.0111 0.00288 % by Wt 6010C Total/NA

Client Sample ID: Chip 3 Lab Sample ID: 310-70018-3

Analyte Result Qualifier RL **MDL** Unit Dil Fac D Method **Prep Type** Chromium 0.251 % by Wt 0.000980 6010C Total/NA 6010C Total/NA Lead 1.15 0.00490 % by Wt

Client Sample ID: Chip 4 Lab Sample ID: 310-70018-4

Analyte Result Qualifier RL MDL Unit Dil Fac D Method **Prep Type** Chromium 0.000677 0.000588 % by Wt 6010C Total/NA Lead 0.00306 0.00294 % by Wt 6010C Total/NA

Client Sample ID: Chip 5 Lab Sample ID: 310-70018-5

Analyte Result Qualifier RL MDL Unit Dil Fac D Method Prep Type Chromium 2.78 0.000654 % by Wt 6010C Total/NA Lead 4.14 0.00327 % by Wt 6010C Total/NA

Client Sample ID: Chip 6 Lab Sample ID: 310-70018-6

Result Qualifier **MDL** Unit Analyte RL Dil Fac D Method **Prep Type** Chromium 0.00301 0.000826 % by Wt 6010C Total/NA % by Wt 6010C Total/NA Lead 0.0171 0.00413

Client Sample ID: Chip 7 Lab Sample ID: 310-70018-7

Dil Fac D Analyte Result Qualifier RL **MDL** Unit Method **Prep Type** 6010C Cadmium 0.00189 0.000952 % by Wt Total/NA Chromium 0.855 0.000952 % by Wt 6010C Total/NA 1 % by Wt Lead 0.803 0.00476 6010C Total/NA

Client: Terracon Consulting Eng & Scientists

Project/Site: Gateway Project

TestAmerica Job ID: 310-70018-1

Lab Sample ID: 310-70018-1

Matrix: Paint Chips

Client Sample ID: Chip 1
Date Collected: 11/24/15 00:00
Date Received: 12/01/15 10:15

Method: 6010C - Metals (ICP)							
Analyte	Result Qualifier	RL	MDL Unit	D	Prepared	Analyzed	Dil Fac
Cadmium	<0.00100	0.00100	% by Wt		12/02/15 08:48	12/02/15 23:37	1
Chromium	0.118 F1 F2	0.00100	% by Wt		12/02/15 08:48	12/02/15 23:37	1
Lead	21.3	0.00500	% by Wt		12/02/15 08:48	12/02/15 23:37	1

L.

6

8

46

11

13

Client: Terracon Consulting Eng & Scientists

Project/Site: Gateway Project

TestAmerica Job ID: 310-70018-1

Lab Sample ID: 310-70018-2

Matrix: Paint Chips

Date Collected: 11/24/15 00:00 Date Received: 12/01/15 10:15

Client Sample ID: Chip 2

Method: 6010C - Metals (ICP)									
Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Cadmium	<0.00288		0.00288		% by Wt		12/02/15 08:48	12/03/15 17:09	4
Chromium	0.0111		0.00288		% by Wt		12/02/15 08:48	12/03/15 17:09	4
Lead	<0.0144		0.0144		% by Wt		12/02/15 08:48	12/03/15 17:09	4
L									

4

5

7

8

10

12

13

Client: Terracon Consulting Eng & Scientists

Project/Site: Gateway Project

TestAmerica Job ID: 310-70018-1

Lab Sample ID: 310-70018-3

Matrix: Paint Chips

Client Sample ID: Chip 3
Date Collected: 11/24/15 00:00
Date Received: 12/01/15 10:15

Method: 6010C - Metals (ICP) Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Cadmium	<0.000980		0.000980		% by Wt		12/02/15 08:48	12/03/15 00:07	1
Chromium	0.251		0.000980		% by Wt		12/02/15 08:48	12/03/15 00:07	1
Lead	1.15		0.00490		% by Wt		12/02/15 08:48	12/03/15 00:07	1

6

R

9

11

13

Client: Terracon Consulting Eng & Scientists

Project/Site: Gateway Project

TestAmerica Job ID: 310-70018-1

Lab Sample ID: 310-70018-4

Matrix: Paint Chips

Date Collected: 11/24/15 00:00 Date Received: 12/01/15 10:15

Client Sample ID: Chip 4

Method: 6010C	- Metals (ICP)						
Analyte	Result C	Qualifier RL	MDL Unit	D	Prepared	Analyzed	Dil Fac
Cadmium	<0.000588	0.000588	% by Wt	= =	12/02/15 08:48	12/03/15 00:11	1
Chromium	0.000677	0.000588	% by Wt		12/02/15 08:48	12/03/15 00:11	1
Lead	0.00306	0.00294	% by Wt		12/02/15 08:48	12/03/15 00:11	1

6

9

10

12

13

Client: Terracon Consulting Eng & Scientists

Project/Site: Gateway Project

TestAmerica Job ID: 310-70018-1

Client Sample ID: Chip 5

Date Collected: 11/24/15 00:00

Lab Sample ID: 310-70018-5

Matrix: Paint Chips

Date Received: 12/01/15 10:15

Method: 6010C - Metals (ICP) Analyte	Result Qualifier	RL	MDL Unit	D	Prepared	Analyzed	Dil Fac
Cadmium	<0.000654	0.000654	% by Wt	_	12/02/15 08:48	12/03/15 00:16	1
Chromium	2.78	0.000654	% by Wt		12/02/15 08:48	12/03/15 00:16	1
Lead	4 14	0.00327	% by Wt		12/02/15 08:48	12/03/15 00:16	1

-0

Ė

C

9

11

Client: Terracon Consulting Eng & Scientists

Project/Site: Gateway Project

TestAmerica Job ID: 310-70018-1

Lab Sample ID: 310-70018-6

Matrix: Paint Chips

Client Sample ID: Chip 6 Date Collected: 11/24/15 00:00 Date Received: 12/01/15 10:15

od: 6010C - Metals (ICP) te	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
um	<0.000826		0.000826		% by Wt		12/02/15 08:48	12/03/15 00:20	1
nium	0.00301		0.000826		% by Wt		12/02/15 08:48	12/03/15 00:20	1
	0.0171		0.00413		% by Wt		12/02/15 08:48	12/03/15 00:20	1
i	te ium mium	te Result ium <0.000826	te Result companies Qualifier companies nium <0.000826	te Result out Qualifier out RL out sium out <0.000826	te Result out Qualifier out RL out MDL out sium <0.000826	te Result ium Qualifier RL 0.000826 MDL 70.000826 Unit 70.000826 % by Wt 70.000826 %	te Result jum Qualifier RL jum MDL jum Unit jum D jum mium <0.000826	te Result jum Qualifier of lum RL of lum MDL of lum Unit of lum D of lum Prepared of lum of lum mium 0.00301 0.000826 % by Wt 12/02/15 08:48	te Result ium Qualifier output RL output MDL output Unit output D output Prepared output Analyzed output ium output <0.000826

5

6

8

40

11

13

Client: Terracon Consulting Eng & Scientists

Project/Site: Gateway Project

TestAmerica Job ID: 310-70018-1

Client Sample ID: Chip 7

Date Collected: 11/24/15 00:00

Lab Sample ID: 310-70018-7

Matrix: Paint Chips

Date Received: 12/01/15 10:15

Method: 6010C - Metals (ICP) Analyte	Result Qualifier	r RL	MDL Unit	D	Prepared	Analyzed	Dil Fac
Cadmium	0.00189	0.000952	% by Wt		12/02/15 08:48	12/03/15 00:25	1
Chromium	0.855	0.000952	% by Wt		12/02/15 08:48	12/03/15 00:25	1
Lead	0.803	0.00476	% by Wt		12/02/15 08:48	12/03/15 00:25	1

1

5

6

8

3

11

12

Definitions/Glossary

Client: Terracon Consulting Eng & Scientists

Project/Site: Gateway Project

TestAmerica Job ID: 310-70018-1

Qualifiers

Metals

Qualifier	Qualifier Description
F1	MS and/or MSD Recovery is outside acceptance limits.
F2	MS/MSD RPD exceeds control limits
4	MS, MSD: The analyte present in the original sample is greater than 4 times the matrix spike concentration; therefore, control limits are not applicable.

Glossary

RPD

TEF

TEQ

Abbreviation	These commonly used abbreviations may or may not be present in this report.
¤	Listed under the "D" column to designate that the result is reported on a dry weight basis
%R	Percent Recovery
CFL	Contains Free Liquid
CNF	Contains no Free Liquid
DER	Duplicate error ratio (normalized absolute difference)
Dil Fac	Dilution Factor
DL, RA, RE, IN	Indicates a Dilution, Re-analysis, Re-extraction, or additional Initial metals/anion analysis of the sample
DLC	Decision level concentration
MDA	Minimum detectable activity
EDL	Estimated Detection Limit
MDC	Minimum detectable concentration
MDL	Method Detection Limit
ML	Minimum Level (Dioxin)
NC	Not Calculated
ND	Not detected at the reporting limit (or MDL or EDL if shown)
PQL	Practical Quantitation Limit
QC	Quality Control
RER	Relative error ratio
RL	Reporting Limit or Requested Limit (Radiochemistry)

Relative Percent Difference, a measure of the relative difference between two points

Toxicity Equivalent Factor (Dioxin)

Toxicity Equivalent Quotient (Dioxin)

TestAmerica Cedar Falls

QC Sample Results

Client: Terracon Consulting Eng & Scientists

Project/Site: Gateway Project

Method: 6010C - Metals (ICP)

TestAmerica Job ID: 310-70018-1

Client Sample ID: Method Blank

Prep Batch: 110863

Lab Sample ID: MB 310-110863/1-A **Matrix: Solid Prep Type: Total/NA Analysis Batch: 111025** MB MB

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Cadmium	<0.0000861		0.0000861		% by Wt		12/02/15 08:48	12/02/15 23:24	1
Chromium	<0.0000861		0.0000861		% by Wt		12/02/15 08:48	12/02/15 23:24	1
Lead	<0.000431		0.000431		% by Wt		12/02/15 08:48	12/02/15 23:24	1

Lab Sample ID: LCS 310-110863/2-A **Client Sample ID: Lab Control Sample Matrix: Solid** Prep Type: Total/NA **Analysis Batch: 111025 Prep Batch: 110863** Spike LCS LCS %Rec. Analyte Added Result Qualifier Unit D %Rec Limits Cadmium 0.00943 % by Wt 95 80 - 120 0.008997 Chromium 0.00943 0.009498 % by Wt 101 80 - 120 0.0189 % by Wt 95 80 - 120 Lead 0.01790

Lab Sample ID: 310-70018-1 MS Client Sample ID: Chip 1 **Matrix: Paint Chips** Prep Type: Total/NA **Analysis Batch: 111025 Prep Batch: 110863** Sample Sample MS MS Spike %Rec. Result Qualifier Added Limits Analyte Result Qualifier Unit D %Rec Cadmium <0.00100 0.0870 0.08057 % by Wt 92 75 - 125 Chromium 0.118 F1 F2 0.0870 0.2857 F1 % by Wt 193 75 - 125 % by Wt 75 - 125 Lead 21.3 0.174 19.52 4 -1035

Lab Sample ID: 310-70018-1 MSD Client Sample ID: Chip 1 **Matrix: Paint Chips** Prep Type: Total/NA **Analysis Batch: 111025 Prep Batch: 110863** MSD MSD RPD Sample Sample Spike %Rec. Result Qualifier Analyte Added Result Qualifier Unit D %Rec Limits **RPD** Limit Cadmium <0.00100 0.0971 0.09295 % by Wt 95 75 - 125 20 Chromium 0.118 F1 F2 0.0971 0.2016 F2 % by Wt 86 75 - 125 34 20 % by Wt Lead 21.3 0.194 21.65 4 171 75 - 125 10 20

12/4/2015

QC Association Summary

Client: Terracon Consulting Eng & Scientists

Project/Site: Gateway Project

TestAmerica Job ID: 310-70018-1

Metals

Prep Batch: 110863

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
310-70018-1	Chip 1	Total/NA	Paint Chips	3050B	
310-70018-1 MS	Chip 1	Total/NA	Paint Chips	3050B	
310-70018-1 MSD	Chip 1	Total/NA	Paint Chips	3050B	
310-70018-2	Chip 2	Total/NA	Paint Chips	3050B	
310-70018-3	Chip 3	Total/NA	Paint Chips	3050B	
310-70018-4	Chip 4	Total/NA	Paint Chips	3050B	
310-70018-5	Chip 5	Total/NA	Paint Chips	3050B	
310-70018-6	Chip 6	Total/NA	Paint Chips	3050B	
310-70018-7	Chip 7	Total/NA	Paint Chips	3050B	
LCS 310-110863/2-A	Lab Control Sample	Total/NA	Solid	3050B	
MB 310-110863/1-A	Method Blank	Total/NA	Solid	3050B	

Analysis Batch: 111025

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
310-70018-1	Chip 1	Total/NA	Paint Chips	6010C	110863
310-70018-1 MS	Chip 1	Total/NA	Paint Chips	6010C	110863
310-70018-1 MSD	Chip 1	Total/NA	Paint Chips	6010C	110863
310-70018-3	Chip 3	Total/NA	Paint Chips	6010C	110863
310-70018-4	Chip 4	Total/NA	Paint Chips	6010C	110863
310-70018-5	Chip 5	Total/NA	Paint Chips	6010C	110863
310-70018-6	Chip 6	Total/NA	Paint Chips	6010C	110863
310-70018-7	Chip 7	Total/NA	Paint Chips	6010C	110863
LCS 310-110863/2-A	Lab Control Sample	Total/NA	Solid	6010C	110863
MB 310-110863/1-A	Method Blank	Total/NA	Solid	6010C	110863

Analysis Batch: 111180

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
310-70018-2	Chip 2	Total/NA	Paint Chips	6010C	110863

3

5

_

10

11

13

Lab Chronicle

Client: Terracon Consulting Eng & Scientists

Project/Site: Gateway Project

TestAmerica Job ID: 310-70018-1

Lab Sample ID: 310-70018-1

Matrix: Paint Chips

Client Sample ID: Chip 1 Date Collected: 11/24/15 00:00 Date Received: 12/01/15 10:15

	Batch	Batch		Dilution	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	3050B			110863	12/02/15 08:48	JNR	TAL CF
Total/NA	Analysis	6010C		1	111025	12/02/15 23:37	OAD	TAL CF

Lab Sample ID: 310-70018-2 Client Sample ID: Chip 2

Date Collected: 11/24/15 00:00 **Matrix: Paint Chips**

Date Received: 12/01/15 10:15

_	Batch	Batch		Dilution	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	3050B			110863	12/02/15 08:48	JNR	TAL CF
Total/NA	Analysis	6010C		4	111180	12/03/15 17:09	OAD	TAL CF

Client Sample ID: Chip 3 Lab Sample ID: 310-70018-3

Date Collected: 11/24/15 00:00 **Matrix: Paint Chips**

Date Received: 12/01/15 10:15

	Batch	Batch		Dilution	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	3050B			110863	12/02/15 08:48	JNR	TAL CF
Total/NA	Analysis	6010C		1	111025	12/03/15 00:07	OAD	TAL CF

Client Sample ID: Chip 4 Lab Sample ID: 310-70018-4 **Matrix: Paint Chips**

Date Collected: 11/24/15 00:00

Date Received: 12/01/15 10:15

	Batch	Batch		Dilution	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	3050B			110863	12/02/15 08:48	JNR	TAL CF
Total/NA	Analysis	6010C		1	111025	12/03/15 00:11	OAD	TAL CF

Client Sample ID: Chip 5 Lab Sample ID: 310-70018-5

Date Collected: 11/24/15 00:00

Date Received: 12/01/15 10:15

	Batch	Batch		Dilution	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	3050B			110863	12/02/15 08:48	JNR	TAL CF
Total/NA	Analysis	6010C		1	111025	12/03/15 00:16	OAD	TAL CF

Client Sample ID: Chip 6 Lab Sample ID: 310-70018-6 **Matrix: Paint Chips**

Date Collected: 11/24/15 00:00 Date Received: 12/01/15 10:15

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Prepared or Analyzed	Analyst	Lab
Total/NA	Prep	3050B			110863	12/02/15 08:48	JNR	TAL CF
Total/NA	Analysis	6010C		1	111025	12/03/15 00:20	OAD	TAL CF

TestAmerica Cedar Falls

Matrix: Paint Chips

Lab Chronicle

Client: Terracon Consulting Eng & Scientists

Project/Site: Gateway Project

TestAmerica Job ID: 310-70018-1

Lab Sample ID: 310-70018-7

Matrix: Paint Chips

Date Collected: 11/24/15 00:00 Date Received: 12/01/15 10:15

Client Sample ID: Chip 7

	Batch	Batch		Dilution	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	3050B			110863	12/02/15 08:48	JNR	TAL CF
Total/NA	Analysis	6010C		1	111025	12/03/15 00:25	OAD	TAL CF

Laboratory References:

TAL CF = TestAmerica Cedar Falls, 704 Enterprise Drive, Cedar Falls, IA 50613, TEL (319)277-2401

Certification Summary

Client: Terracon Consulting Eng & Scientists

Project/Site: Gateway Project

TestAmerica Job ID: 310-70018-1

Laboratory: TestAmerica Cedar Falls

All certifications held by this laboratory are listed. Not all certifications are applicable to this report.

Authority	Program	EPA Region	Certification ID	Expiration Date
AIHA-LAP, LLC	IHLAP		101044	11-01-16
Georgia	State Program	4	N/A	09-29-16
Illinois	NELAP	5	200024	11-29-16
Iowa	State Program	7	007	12-01-15 *
Kansas	NELAP	7	E-10341	01-31-15 *
Minnesota	NELAP	5	019-999-319	12-31-15
Minnesota (Petrofund)	State Program	1	3349	08-22-16
North Dakota	State Program	8	R-186	09-29-16
Oregon	NELAP	10	IA100001	09-29-16
Wisconsin	State Program	5	999917270	08-31-16

^{*} Certification renewal pending - certification considered valid.

Method Summary

Client: Terracon Consulting Eng & Scientists

Project/Site: Gateway Project

TestAmerica Job ID: 310-70018-1

Method	Method Description	Protocol	Laboratory
6010C	Metals (ICP)	SW846	TAL CF

Protocol References:

SW846 = "Test Methods For Evaluating Solid Waste, Physical/Chemical Methods", Third Edition, November 1986 And Its Updates.

Laboratory References:

TAL CF = TestAmerica Cedar Falls, 704 Enterprise Drive, Cedar Falls, IA 50613, TEL (319)277-2401

3

4

7

9

10

12

13





Cooler/Sample Receipt and Temperature Log Form

Client Information	
Client: Terrais	
City/State:	Project:
Receipt Information	
Date/Time Received:12-1-15 10:	IS Received By: CH
Delivery Type: UPS DedEx	FedEx Ground US Mail Spee-Dee
TA Courier TA Field Serv	rices Client Drop-off Other:
Condition of Cooler/Containers	
Sample(s) received in Cooler? Yes	No If yes: Cooler ID:
Multiple Coolers?	No If yes: Cooler# of
Cooler Custody Seals Present? Yes	No If yes: Cooler custody seals intact? Yes No
Sample Custody Seals Present? Yes	No If yes: Sample custody seals intact? Yes
Trip Blank Present?	No If yes: Which VOA samples are in cooler? ↓
Temperature Record	FIF AND THE RESIDENCE OF THE PARTY OF THE PA
	Dry ice Other: Dry ice
Temperature Blank? Yes No	ID & Bottle Type:
	If no, specify sample ID(s) and bottle type used to take measurement.
Thermometer ID:	Correction Factor (°C):
Uncorrected Temp (°C):	Corrected Temp (°C):
Exceptions Noted	
If temperature exceeds criteria, was sample(sa) If yes: Is there evidence that the chilling	
(e.g., bulging septa, broken/cracked bottles?	,
Note: If yes, contact PM before proceeding. If no, pro	ceed with login
Additional Comments	
remp not tal	Ken
faint chips	
9	

Document: CF-LG-WI-002

Revision: 21 Date: 7/28/2015 TestAmerica

TestAmerica Cedar Falls 704 Enterprise Drive

Chain of Custody Record

Client Contact	Duniant Blanch	Child in contract	- Chamina			Otto Contract.	Doto: 44/20/4F	ion COC
	Project Manager: Eric Harris	ager: Eric	Harris			Site Contact:	Date: 11/30/15	,
Terracon Consultants, Inc.	Tel/Fax: 319-221-7315	3-221-7315				Lab Contact:	Carrier:	1 of1 COCs
2640 12th St. SW		Ana	Analysis Turnaround Time	around	Time			Sampler:
Cedar Rapids, Iowa 52404	CALENDAR DAYS		✓ WORK	✓ WORKING DAYS		rb		For Lab Use Only:
319-366-8321 Phone		TAT if diffe	TAT if different from Below		3 days			Walk-in Client:
319-366-0032 FAX		2 weeks	eks			/٨		Lab Sampling:
Project Name: Iowa City Gateway		1 week	ak a) a		
Site: Gateway project		2 days	S			SW		Job / SDG No.:
P O # 06157085		1 day				/ SI		
Sample Identification	Sample Date	Sample	Sample Type (C=Comp, G=Grab)	Matrix	Color of Paint	Filtered Sa Perform N Cd, Cr and		Sample Location:
Chip 1	11/24/2015 N/A			Solid	silver over red	×		Park road; 1st light stantion west of bridge on the north side of the road
Chip 2	11/24/2015 N/A				red	×		Vault lid on bridge east abutment, south side of the road
Chip 3	11/24/2015 N/A		O	Solid	yellow	×		East side of Park Road Bridge, median line striping, by
	11/24/2015 N/A			Solid	white	×		East side of Park Road Bridge white line paint, at cross walk
Chip 5	11/24/2015 N/A		9	Solid	hunter green over yellow	×		Traffic control pole at Dubuque Street and Park Road, west side of
	11/24/2015 N/A		9	Solid	red	×		Fire Hydrant on the east side of Dubuque Street at intersection of
Chip 7	11/24/2015 N/A		9	Solid	brown	×		Traffic control box west side of Dubuque, north of Park Road
Preservation Used: 1= Ice, 2= HCI; 3= H2SC	2= HCI; 3= H2SO4; 4=HNO3; 5=NaOH; 6= Other	OH; 6= Oth	er					· · · · · · · · · · · · · · · · · · ·
Possible Hazard Identification: Are any samples from a listed EPA Hazardous Waste? Please List any EPA Waste Codes for the sample in the Comments Section if the lab is to dispose of the sample.	Naste? Please List	any EPA W	aste Code	s for the	sample in the Comment	-	e may be assessed if sa	Sample Disposal (A fee may be assessed if samples are retained longer than 1 month)
	Skin Irritant Poison B		Unknown	'n		Return to Client	Misposal by Lab	Archive for Months
actions/QC Requirements & Christ	2° by	weight	4	d, C,	Cd, Cr(teri) and Pb		is.	
Custody Seals Intact: Tes No	Custody Seal No.:	II No.:				Cooler Temp. (C): Obs'd		Corr'd: Therm ID No.:
Relinquished by:	Company:	Evaci		Date/Time:	me: 12,(15 1558	Received by:	Company:	Date/Time:
Relinquished by:	Company:			Date/Time:	ne:	Received by:	Company:	Date/Time:
Relinquished by:	Company:			Date/Time:	ne:	Received in Laboratory by:	by: Company:	Date/Time:

Login Sample Receipt Checklist

Client: Terracon Consulting Eng & Scientists

Job Number: 310-70018-1

Login Number: 70018 List Source: TestAmerica Cedar Falls

List Number: 1

Creator: Worthy, Ashley L

Creator. Worthly, Ashley L		
Question	Answer	Comment
Radioactivity wasn't checked or is = background as measured by a survey meter.</td <td>N/A</td> <td></td>	N/A	
The cooler's custody seal, if present, is intact.	N/A	
Sample custody seals, if present, are intact.	N/A	
The cooler or samples do not appear to have been compromised or tampered with.	True	
Samples were received on ice.	False	
Cooler Temperature is acceptable.	True	Thermal preservation not required.
Cooler Temperature is recorded.	False	
COC is present.	True	
COC is filled out in ink and legible.	True	
COC is filled out with all pertinent information.	True	
Is the Field Sampler's name present on COC?	True	
There are no discrepancies between the containers received and the COC.	True	
Samples are received within Holding Time.	True	
Sample containers have legible labels.	True	
Containers are not broken or leaking.	True	
Sample collection date/times are provided.	True	
Appropriate sample containers are used.	True	
Sample bottles are completely filled.	True	
Sample Preservation Verified.	True	
There is sufficient vol. for all requested analyses, incl. any requested MS/MSDs	True	
Containers requiring zero headspace have no headspace or bubble is <6mm (1/4").	True	
Multiphasic samples are not present.	True	
Samples do not require splitting or compositing.	True	
Residual Chlorine Checked.	N/A	

APPENDIX D

EXHIBITS

EXHIBIT 1 – PARK ROAD/BRIDGE SAMPLE LOCATION DIAGRAM

EXHIBIT 2 – DUBUQUE/KIMBALL SAMPLE LOCATION DIAGRAM


EXHIBIT 3 – 1966 PARK BRIDGE PLAN



00X - APPROXIMATE LOCATION TRACE ASBESTOS SAMPLE LOCATION (<1%)

- APPROXIMATE LOCATION OF ASBESTOS CEMENT PIPE
- APPROXIMATE LOCATION OF TRACE ASBESTOS CONTAINING CAULKING ON NEWEL POSTS
CHIP X - APPROXIMATE LOCATION OF PAINT CHIP SAMPLE

THIS DRAWING IS INTENDED FOR GENERAL LOCATION PURPOSES ONLY. BASE DRAWING OBTAINED FROM THE JOHNSON COUNTY PIV WEBSITE.




_	_		
1	F	Project No.	Date:
l		06157085	12-2015
ı	F	Project Mngr:	Drawn By:
l		EWH	EWH
ı	F	ile Name:	
;	L		RVEY REP.dwg
ı	Ī	_ayout Name:	

	06157085 12-2015 Project Mngr: Drawn By: EWH FWH	Terracon
s	File Name: 06157085.SURVEY REP.dwg	Consulting Engineers and Scientists
1	Layout Name:	2640 12TH STREET SW CEDAR RAPIDS, IOWA 52404
-	SAMPLE LOCATION DIAGRAM	PH. (319) 366-8321 FAX. (319) 366-0032

PARK ROAD/BRIDGE SAMPLE LOCATION DIAGRAM
SURVEY REPORT
CITY OF IOWA CITY
GATEWAY PROJECT
IOWA CITY, IOWA

EXHIBIT#



<u>LEGEND</u>

00X - APPROXIMATE ASBESTOS BULK SAMPLE LOCATION (NON-ACM)

THIS DRAWING IS INTENDED FOR GENERAL LOCATION PURPOSES ONLY. BASE DRAWING OBTAINED FROM THE JOHNSON COUNTY PIV WEBSITE.




	Project No.	Date:
	06157085	12-2015
	Project Mngr:	Drawn By:
	EWH	EWH
	File Name:	
s	06157085.SURVEY REP.dwg	
	Layout Name:	
	SAMPLETO	CATION


	3CON neers and Scientists
2640 12TH STREET SW	CEDAR RAPIDS, IOWA 52404
PH. (319) 366-8321	FAX. (319) 366-0032

DUBUQUE/KIMBALL SAMPLE LOCATION DIAGRAM
SURVEY REPORT

SURVEY REPORT CITY OF IOWA CITY GATEWAY PROJECT IOWA CITY, IOWA EXHIBIT#



THIS DRAWING IS INTENDED FOR GENERAL LOCATION PURPOSES ONLY. DRAWING PROVIDED BY CITY OF IOWA CITY. COMPLETED BY VEENSTRA AND KIMM "PARK BRIDGE DETAILS" WATER SYSTEM IMPROVEMENTS, SHEET 1 OF 4 DWG NO. 11614-9. DATED JUNE 2, 1966



	Project No.	Date:
	06157085	12-2015
	Project Mngr:	Drawn By:
	EWH	EWH
	File Name:	
S 06157085.SURVEY REP.dw		
	Layout Name:	
	1966 BRIDGE PLAN	

	Terr	TACON gineers and Scientists
1	2640 12TH STREET SW	CEDAR RAPIDS, IOWA 52404
١	PH. (319) 366-8321	FAX. (319) 366-0032

1966 PARK BRIDGE PLAN	EXHIBIT #
SURVEY REPORT	
CITY OF IOWA CITY	
GATEWAY PROJECT	03
IOWA CITY, IOWA	

APPENDIX E PHOTOGRAPHIC DOCUMENTATION





Photo 1: View of Park Road Bridge looking west.



Photo 2: View of asbestos cement pipe under Park Road Bridge, looking east.





Photo 3: View of asbestos cement pipe as it enters the west abutment.



Photo 4: View of asbestos cement pipe hanger.






Photo 5: Photo showing trace asbestos under the guardrail post on Park Road Bridge.



Photo 6: View of the girder layout under the east side of the Park Road Bridge.





Photo 7: Photo showing chip location #1, and wiring inside of light post.



Photo 8: Photo of paint chip sample #2, under vault lid, south side of Park Road Bridge.






Photo 9: View of chip sample #3, median of Park Road Bridge and asbestos samples 22-24, in vault access.



Photo 10: Vie of intersection of Park Road and Dubuque Street, with chip sample on cross walk markings (chip sample 4).





Photo 11: View of chip sample #5 on the traffic control pole, at the intersection of Dubuque Street and Park Road.



Photo 12: View of paint chip sample #6 on fire hydrant along Dubuque Street.





Photo 13: View of traffic control box north of Park Road, along Dubuque Street, chip sample #7.



Photo 14: View looking south along Dubuque Street, south of Park Road.






Photo 15: View looking west down Park Road, west of the bridge.



Photo 16: View of intersection of Kimball Road and Dubuque Street, looking northwest.





Photo 17: View of pole mounted transformer along Kimball Road.



Photo 18: View of culvert east of Kimball Road; asbestos samples 28 and 29.





Photo 19: View along Dubuque Street, looking north from Mayflower Residence Hall parking area.



Photo 20: View of intersection at Dubuque Street and Taft Speedway St.