
COURSE SUMMARY

Below is a list of supplies that are necessary for the certification courses:

- Pencils and paper
- Calculator - No computers or programmable calculators are allowed. Prestress Technician class students need a scientific calculator that shows a MINIMUM of 10 digits.
- Safety glasses and steel toe shoes will be required when working in the labs. The classes that will require safety apparel are HMA Level I and II, PCC Level I, Aggregate Technician, and Soils. Gloves will be provided. No one will be allowed in the laboratories without the required personal protective equipment. The TTCP classes will have a few extra glasses and steel toe attachments, but it is highly recommended that students bring/wear their own equipment.

Cell Phones are to be shut-off or put on vibratory mode when entering the classroom. All cell phones will be shut-off completely during examinations.

Weather-related cancellations

If the weather conditions cause a class delay or cancellation:

For all classes at DMACC - Boone: If DMACC cancels classes, the TTCP classes are also cancelled for that day. If DMACC classes are delayed, TTCP classes scheduled in Boone will also be delayed. The decision to cancel DMACC classes should be made by 7:00 am and a recording will be placed on Dawn Walker's voice mail at 515-433-5232. You can also visit DMACC's website at www.dmacc.edu. Late starts, early closures and cancellations are listed at the top of the page.

For all other classes: Call the contact person for the location that your class is being held. Contact information is available [here](#) . If a large, weather event is forecasted and classes are cancelled for the following day, efforts will be made to contact you by telephone and email.