7152
10-15-13



1 Granular Shoulder Repair. Estimated at 4 tons/Sta.

TYPICAL SECTION
RETROFIT HOT MIX ASPHALT PAVED SHOULDER

Location				E	G
Road Identification	Station to Station		Side	Feet	Feet