

IOWA DEPARTMENT OF TRANSPORTATION

To Office Bridges & Structures, Local Systems, Research & Technology Date Nov. 1, 2008
Attention All Employees in Bridge, LeRoy Bergmann, and Mark Dunn Ref No. 521.1
From Gary Novey
Office Bridges and Structures
Subject Correction to CADD standards 4784, 4787, 4789, and 4790 Beam Standards.
(CADD M0130)

Electronic copies are available in the following Office of Bridges and Structures standard directory **W:\Highway\BridgeStandardsBridges** and on the Internet:

<http://www.dot.state.ia.us/bridge/standard.htm>

The CADD Standards 4784, 4787, 4789, and 4790 have been corrected as follows:

1. Section A-A Detail showing the strand spacing in the bottom flange has been corrected to show the correct summation of 13 spaces at $2'' = 2'-2$.

These corrected standards should be used on all new projects using these beam sizes. If you have any questions on the issued standards, please check with Thayne Sorenson or Dean Bierwagen.

GAN/dgb/bj