

**IOWA DEPARTMENT OF TRANSPORTATION**

To Office Bridges & Structures Date Jan. 1, 2009  
Attention All Bridge Employees Ref No. 521.1  
From Gary Novey  
Office Bridges and Structures  
Subject Correction of 4561-BTC-6 Standard for 40' Roadway BTC Beams with a Symmetrical  
Crown.  
(CADD M0133)

Electronic copies are available in the following Office of Bridges and Structures standard directory **W:\Highway\Bridge\Standards\Bridges** and on the Internet:

<http://www.dot.state.ia.us/bridge/standard.htm>

The 4561-BTC-6 Standard has been corrected as follows:

5b1 bars were added in the slab over the beams in the 'Half Section Near Abutment' cross section.

This corrected standard should be used on all new projects with stub abutment symmetrical crown bridges. If you have any questions on the issued standards, please check with Thayne Sorenson or Dean Bierwagen.

GAN/dgb/bj