

The purpose of this file is to document changes to various Standard Road Plan pages. Our revision cycle is April and October, with changes to the page occurring in November (for the upcoming April revision) and May (for the upcoming October revision). Occasionally, updates to the files available on the page occur between those times. Those updates, and subsequent changes to the pages, are listed below.

Date	File Updated	Update Type	Files Affected
Monday, November 2, 2020	All files listed in April Revision Packet	Release of April 2021 revision	All
Tuesday, April 14, 2020	All files listed in October Revision Packet	Release of October 2020 revision	All
Tuesday, November 12, 2019	SW-542	Interim	esw542.dgn; esw542.pdf
Wednesday, November 6, 2019	All files listed in April Revision Packet	Release of April 2020 revision	All
Monday, July 1, 2019	BA-100 BA-102 BA-103 DR-103 PR-102 PR-103 PR-105 PR-120 PR-121 PV-410 PV-411 PV-412 PV-414	Interim	eba100.dgn; eba100.pdf eba102.dgn; eba102.pdf eba103.dgn; eba103.pdf edr103.dgn; edr103.pdf epr102.dgn; epr102.pdf epr103.dgn; epr103.pdf epr105.dgn; epr105.pdf epr120.dgn; epr120.pdf epr121.dgn; epr121.pdf epv410.dgn; epv410.pdf epv411.dgn; epv411.pdf epv412.dgn; epv412.pdf epv414.dgn; epv414.pdf
Thursday, May 2, 2019	All files listed in October Revision Packet	Release of October 2019 revision	All
Wednesday November 6, 2019	Index Sheets Entire Book Entire Section	SI-881 had incorrect revision date in TOC SI-881 had incorrect revision date in TOC SI-881 had incorrect revision date in TOC	SRP_EnglishIndex.xls eentirebook.pdf esi_section.pdf
Thursday November 1, 2019	All files listed in April Revision Packet	Release of April 2019 revision	All
Wednesday, October 24, 2018	Index Sheets Entire Book Entire Section	EC-303 was entered as ED-303. EC-303 was entered as ED-303. EC-303 was entered as ED-303.	SRP_EnglishIndex.xls eentirebook.pdf eec_section.pdf
Thursday, June 14, 2018	EW-204 EW-301	3D image in PDF was not working 3D image in PDF was not working	eew204.pdf eew204.dgn eew301.pdf eew301.dgn eew_section.pdf eentirebook.pdf
Monday, May 21, 2018	EC-602 PV-101	Corrected Designer Info hyperlink from Design Manual 1C-6 to 1E-6. Removed DRAFT from pages after SUDAS Board approval.	eec602.pdf eec602.dgn eec_section.pdf epv_section.pdf epv101.pdf

Date	File Updated	Update Type	Files Affected
	SW-603 TC-102 Traffic Signal Pole Foundation	Removed DRAFT from pages after SUDAS Board approval. Removed DRAFT from pages after SUDAS Board approval. Changed RQD to rock quality designation.	esw_section.pdf esw603.pdf ets102.pdf ets_section.pdf eentirebook.pdf
Wednesday, May 9, 2018	All files listed in October Revision Packet	Release of October 2018 revision	All
Tuesday, April 17, 18	TC-61 Two-lane, Two-Way Operation TC-418 Lane Closed On Divided Highway TC-421 Lane Closure with TBR TC-422 Closure Of Two Adjacent Lanes On Divided Highway	Interim	etc61.pdf etc61.dgn etc418.pdf etc418.dgn etc421.pdf etc421.dgn etc422.pdf etc422.dgn
Thursday, January 25, 2018	PV-410 Deceleration Taper for 16' Exit Ramp PV-411 Acceleration Taper for 16' Entrance Ramp PV-412 Deceleration Taper for 18' Exit Loop PV-414 Acceleration Taper for 18' Entrance Loop	Interim	epv410.pdf epv410.dgn epv411.pdf epv411.dgn epv412.pdf epv412.dgn epv414.pdf epv414.dgn
Thursday, November 30, 2017	PR-107 Partial Depth PCC Finish Patches	Modified	epr107.pdg
Wednesday, November 1, 2017	All files listed in April Revision Packet	Release of April 2018 revision	All
Tuesday, June 6, 2017	EW-101 Embankments and Rebuilding Embankments	Corrected Designer Info hyperlink from Design Manual 7A-4 to 7D-4.	eew101.pdf eew101.dgn eew_section.pdf eentirebook.pdf octoberupdate.pdf
Monday, June 5, 2017	PV-101 Joints SW-405 Tee-Section Storm Sewer Manhole	Removed DRAFT from pages after SUDAS Board approval.	epv101.pdf esw405.pdf epv_section.pdf esw_section.pdf eentirebook.pdf
Monday, May 1, 2017	All files listed in October Revision Packet	Release of October 2017 revision	All
Friday, February 24, 2017	TC-233 Pavement Marking Operations Two-Lane TC-234 Strip Sealing Operations TC-431 Slow Moving Vehicle Operating in the Traffic Lane	Interim	etc233.pdf etc233.dgn etc234.pdf

Date	File Updated	Update Type	Files Affected
	TC-432 Shoulder Rumble Strip Operations TC-433 Pavement Marking Operations		etc234.dgn etc431.pdf etc431.dgn etc432.pdf etc432.dgn etc433.pdf etc433.dgn etc433.dgn etc_section.pdf eentirebook.pdf
Thursday, December 22, 2016	BA-225 Steel Beam Guardrail Tangent End Terminal (MASH TL-2)	Re-release of interim for April 2017 revision. No updates made.	eba_section.pdf eentirebook.pdf
Tuesday, November 1, 2016	All files listed in April Revision Packet	Release of April 2017 revision	All
Thursday, June 23, 2016	BA-225 Steel Beam Guardrail Tangent End Terminal (MASH TL-2)	Interim	eba225.pdf eba225.dgn eba_section.pdf eentirebook.pdf
Monday, May 2, 2016	All files listed in October Revision Packet	Release of October 2016 revision	All
Tuesday, January 5, 2016	EC-204 Perimeter and Slope Sediment Control Devices	Corrected revision date from 04-19-15 to 04-19-16	eec204.pdf eec204.dgn eec_section.pdf eEntireBook.pdf aprilupdate.pdf
Monday, November 2, 2015	All files listed in April Revision Packet	Release of April 2016 revision	All
Friday, May 1, 2015	All files listed in October Revision Packet	Release of October 2015 revision	All
Friday, November 21, 2014	All files listed in April Revision Packet	Release of April 2015 revision	All
Monday, May 19, 2014	Standard Road Plan Index	Supporting Information	SRP_EnglishIndex.xls
Friday, May 16, 2014	TC-61 Two-Lane, Two-Way Operation	Interim	etc061.pdf etc061.dgn etc_section.pdf eentirebook.pdf
Friday, May 2, 2014	All files listed in October Revision Packet	Release of October 2014 revision	All