


Reference Display On & Off

Design Manual
Chapter 21
Automation Tools
Instructions

Originally Issued: 05-29-09
Revised: 02-26-10

This tool can be accessed from the Geopak: D&C Manager, as shown at the right:

*(If the item is not found as shown, use the **D&C > Edit > Find** tool to locate it.)*



When the **Reference Display On/Off** command is *double-clicked*, the dialog at the right will display.

Select the desired:
Reference File Name,
Reference Model Name,
and all desired Models.

By *clicking* the **Display On** or **Display OFF** buttons, the display of the selected reference attachment will be manipulated, (ON or OFF), in all selected Models, without having to open each model separately and manually re-select the Reference File and Model and the **Display ON** or **Display Off** tools.

