

IOWA DEPARTMENT OF TRANSPORTATION

To Office Bridges and Structures Date April 1, 2012
Attention All Employees Ref No. 521.1
From Gary Novey
Office Bridges and Structures
Subject Revision of the Bulb Tee Stub Abutment Standards.
(CADD M0259)

Electronic copies are available in the following Office of Bridges and Structures standard directory **W:\Highway\Bridge\Standards\Bridges** and on the Internet:

<http://www.iowadot.gov/bridge/standard.htm>

The standards are located on the Bridge Web site.

- Standards 2092-BTCD and 2092-BTE were revised. The distance from the centerline of abutment bearing to the wing pile location was incorrect in the PILING LAYOUT detail.
- Standard 2092-BTCD – The distance was changed from 5'-11 to 6'-3.
- Standard 2092-BTE - The distance was changed from 7'-11 to 8'-3.

For any questions, please check with Stuart Nielsen or Thayne Sorenson.

GAN/ssn